

Maintenance Log for LV.0039 - Landcruiser Tray Top

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
117602	Reinstall fuel tank - brackets rusted through	22-May-26	22-May-26			
	1 Reinstall fuel tank - brackets rusted through					
117216	Replace U/S battery	11-Mar-26	11-Mar-26			
	1 Replace U/S battery					
116296	Replace seized A/C compressor & service system	22-Oct-25	22-Oct-25			
	1 Replace seized A/C compressor & service system					
115409	Replace corroded fuel filter bowl	12-Jun-25	12-Jun-25			
	1 Replace fuel filter bowl					
115405	Replace windscreen wahser pump	12-Jun-25	12-Jun-25			
	1 Replace pump					
115403	Replace worn CV shafts	12-Jun-25	12-Jun-25	354454		
	1 Replace CV shafts					
115352	Replace wheel nut indicators	04-Jun-25	04-Jun-25	354414		
	1 Replace wheel nut indicators					
115351	Replace rear leaf bushes	04-Jun-25	04-Jun-25	354414		
	1 Replace bushes					
115350	Replace front shocks	04-Jun-25	04-Jun-25	354414		
	1 Replace shocks					
115285	Replace U/S rear brake pads & Rotors	21-May-25	21-May-25	354414		
	1 Replace U/S rear brake pads & Rotors					

Maintenance Log for LV.0039 - Landcruiser Tray Top

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
115282	355000km service	21-May-25	21-May-25	354414		
	1 355000km service					
115022	Repair U/S park brake operation	08-Apr-25	08-Apr-25	353300		
	1 Repair U/S park brake operation					
114523	Replace fuel filters and clean sub tank	11-Feb-25	11-Feb-25	353290		
	1 Clean tank and replace filters					
114299	Replace worn wiper pivot assy	16-Jan-25	16-Jan-25			
	1 Repalce pivot assy					
113932	Repair front DS window winder	12-Nov-24	12-Nov-24			
	1 Repair window					
113354	350,000 km service	12-Aug-24	12-Aug-24	351660		
	1 350,000 km service					
	2 Replace front mud flap					
113054	Replace failed reverse sqwaker	20-Jun-24	20-Jun-24			
	1 Replace sqwaker					
112994	Replace flashing beacon	06-Jun-24	06-Jun-24			
	1 Replace beacon					
112360	Repair Air Con fan not working	26-Feb-24	26-Feb-24			
	1 Repair AC fan					
111563	103 inspection	20-Oct-23	20-Oct-23	344854		
	1 103 inspection					
111493	Rego inspection	11-Oct-23	11-Oct-23			
	1 Rego inspection					

Maintenance Log for LV.0039 - Landcruiser Tray Top

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
2	Replace uni joints in rear tailshaft					
3	Replace failed handbrake switch					
4	Reseal leaking sump					
5	Replace leaking turbo pipe gasket					
6	Fit new wiper blades & replace spray nozzles					
111357	5000km service	20-Sep-23	20-Sep-23	344856		
1	5000km service					
111344	Replace tail lights	19-Sep-23	19-Sep-23			
1	Replace tail lights					
110545	Bulk tank leak	05-Jun-23	05-Jun-23			
1	diesel leak					
110535	Cargo net	02-Jun-23	02-Jun-23			
1	Cargo net					
110409	Install safety equipment	16-May-23	16-May-23			
1	Install safety equipment					
110344	Replace decals	04-May-23	04-May-23			
1	Unit numbers					
110264	Replace front springs	26-Apr-23	26-Apr-23			
1	Front springs					
110250	Fit fuel tank	21-Apr-23	21-Apr-23			
1	Fit fuel tank					
109684	Supply and fit bulk fuel tank	01-Feb-23	01-Feb-23			
1	Bulk fuel tank					

Maintenance Log for LV.0039 - Landcruiser Tray Top

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
109025	Defect repairs to pass rego	20-Oct-22	20-Oct-22			
	1 Replace faulty window regulator (driver side)					
	2 Replace Damaged rear Axle U-bolts					
	3 Repair/ Adjust Park brake					
	4 Rego inspection					
107887	340000 km Service	19-May-22	19-May-22	340005		
	1 340000km Service					
107267	First aid kit	09-Mar-22	09-Mar-22			
	1 First aid kit					
107266	Replace rims and tyres	08-Mar-22	08-Mar-22			
	1 Replace rims and tyres					
107247	General Inspection / repairs	07-Mar-22	07-Mar-22	338863		
	1 Roadworthy inspection/ grease & test drive					
	2 Replace LHR combo light					
	3 Check for lack of power/blowing smoke					
	4 Clean vehicle					
	5 Replace rear shocks					
107233	Replace leaking rear shocks	04-Mar-22	04-Mar-22			
	1 Replace leaking rear shocks					
106482	Replace Worn out Clutch	19-Nov-21	19-Nov-21			
	1 Replace Worn out Clutch					
106236	Repair rusted through Exhaust system	25-Oct-21	25-Oct-21			
	1 Repair rusted through Exhaust system					

Maintenance Log for LV.0039 - Landcruiser Tray Top

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
106235	Replace worn brake pads	25-Oct-21	25-Oct-21	338006		
	1 Replace worn brake pads					
106229	Rego check	22-Oct-21	22-Oct-21	338048		
	1 Rego check					
106165	Replace front sway bar saddle bushes	18-Oct-21	18-Oct-21	337926		
	1 Replace front sway bar saddle bushes					
106164	replace worn rear drive shaft universal joints	18-Oct-21	18-Oct-21	337926		
	1 replace worn rear drive shaft universal joints					
106163	Replace worn out RHS tie rod end	18-Oct-21	18-Oct-21	337926		
	1 Replace worn out RHS tie rod end					
106149	Repair worn & seized brake components	15-Oct-21	15-Oct-21	337926		
	1 Repair worn & seized brake components					
105850	RHS rear Mudguard requires replacement	20-Sep-21	20-Sep-21	337373		
	1 RHS rear Mudguard requires replacement					
105665	Monthly inspection	27-Aug-21	27-Aug-21	336903		
	1 Monthly inspection					
105275	Monthly inspection	07-Jul-21	07-Jul-21	335836		
	1 Monthly inspection					
105149	Blead clutch & tested operation	21-Jun-21	21-Jun-21			
	1 Blead clutch & tested operation					

Maintenance Log for LV.0039 - Landcruiser Tray Top

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
105052	Replace Worn sway bar & rear shackle bushes	07-Jun-21	07-Jun-21	335158		
	1 Replace Worn sway bar & rear shackle bushes					
105006	Monthly inspection and wash	01-Jun-21	01-Jun-21	335158		
	1 Monthly inspection and wash					
104887	335000km service	19-May-21	19-May-21	334798	335337	
	1 335000km service					
104518	Monthly inspection and wash vehicle	08-Apr-21	08-Apr-21			
	1 Inspection & wash vehicle					
104405	6 Monthly Fire extinguisher inspections	25-Mar-21	25-Mar-21			
	12 Monthly Fire Extinguisher Inspection					
104238	Repair siezed 4wd selector	10-Mar-21	10-Mar-21	334438		
	1 Repair 4wd selector					
104237	Carry out monthly inspection and wash vehicle	10-Mar-21	10-Mar-21	334438		
	1 Carryout monthly inspection and wash vehicle					
103906	Replace failed battery	12-Feb-21	12-Feb-21	334107		
	1 Replace failed battery					15/02 Replaced battery - had low cca's cleaned all terminals and checked charge rate
103729	Replace failed alternator	27-Jan-21	27-Jan-21	334067		
	1 Replace failed alternator					28/01 Remove & replaced failed alternator
103076	Clean vehicle	13-Nov-20	13-Nov-20	333479		
	1 Clean vehicle					

Maintenance Log for LV.0039 - Landcruiser Tray Top

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
102898	Wash & clean ute	30-Oct-20	30-Oct-20			
	1 Wash & clean ute					
102862	Rego inspection	28-Oct-20	28-Oct-20	333161		
	1 Rego inspection					
102732	Carry out monthly inspection & repairs for rego	14-Oct-20	14-Oct-20	333079		
	1 Carry out monthly inspection					
	2 Repair broken wires to RHR taillight					
	3 Remove rear rotors, clean hand brake shoes & drums, adjust b					
102696	Replace rusted/unrepairable bull bar	13-Oct-20	13-Oct-20	333198		
	1 Replace rusted/unrepairable bull bar					28/10 Removed and installed new bullbar - 333198km
	2 Wire up lights on bull bar					
	3 Fit flag & UHF aerial					
102559	Remove leaking fuel cooler	29-Sep-20	29-Sep-20			
	1 Remove leaking fuel cooler					
102330	Carry out monthly inspection & wash vehicle	10-Sep-20	10-Sep-20	332658		
	1 Carry out monthly inspection & wash vehicle					
102294	Replace leaking front transfer case output seal	10-Sep-20	10-Sep-20	332658		
	1 Replace leaking front transfer case output seal					17/09 Replaced transfer bearing, seal & pinion.- 332710km
102102	Replace faulty fan spindle	26-Aug-20	26-Aug-20			
	1 Replace faulty fan spindle					10/09 Replaced fan hub bearing - 332658kms

Maintenance Log for LV.0039 - Landcruiser Tray Top

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
101944	Diagnose brake fault & check for coolant leak	14-Aug-20	14-Aug-20			
	1 Diagnose brake fault					New master cylinder required 19/08 Order new master cylinder 26/08 Fit new master cyl & adjust brakes, not adjusted correctly. 332454km
	2 Check for coolant leak					19/08 Water pump leaking 26/08 Fit new water pump - 332454km
101846	Carry out monthly inspection & repairs	06-Aug-20	06-Aug-20	332187		
	1 Carry out monthly inspection					
	2 Check in-op fuel gauge - wires broken					Found gauge wires all broken - repaired broken wires.
	3 Repair leaking brake booster diaphragm					Replace booster due to vacuum leak
	4 Replace worn out LHS draglink end					26/08 fit new drag link end & new tie rod end - 332454km
	5 Replace U/S belt tensioner idler pulley's & belt					13/08 Fit fan belt pulleys - noisy bearings
101789	6 Monthly fire extinguisher inspection	05-Aug-20	05-Aug-20			
	6 Monthly fire extinguisher inspection					
101661	Replace leaking rear transfer case output seal	27-Jul-20	27-Jul-20	331600	332187	
	1 Replace leaking rear transfer case output seal					31/07 Top up transfer with oil 6/08 Fit new rear transfer seal
101589	Wash vehicle	21-Jul-20	21-Jul-20			
	1 Wash vehicle					
101325	Check in-op heater	01-Jul-20	01-Jul-20	331429		
	1 Check in-op heater					Suspect thermostat stuck closed. 26/08 Fit new thermostat - 332454km

Maintenance Log for LV.0039 - Landcruiser Tray Top

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
101254	Replace leaking front transfer case output seals	01-Jul-20	01-Jul-20	331429		
	1 Replace leaking front transfer case output seals					14/07 Re-seal transfer case output seals
101225	Replace worn clutch pedals	29-Jun-20	29-Jun-20	331344	331443	
	1 Replace worn clutch pedals					3/07 Fit new rubber pedal - 331443kms
101183	Wash vehicle & carry out monthly inspection	23-Jun-20	23-Jun-20	331344	331344	
	1 Wash vehicle & carry out monthly inspection					
100985	Wash vehicle	12-Jun-20	12-Jun-20			
	1 Wash vehicle					
100365	Replace RHF brake caliper	12-May-20	12-May-20	330824		
	1 Replace RHF brake caliper					
100364	Carry out monthly inspection & replace wiper blades	12-May-20	12-May-20	330824		
	1 Carry out monthly inspection					
	2 Replace wiper blades					
100320	Replace serpentine belt idler pulley	12-May-20	12-May-20	330852		
	1 Replace serpentine belt idler pulley					
100304	Wash vehicle & start monthly inspection	11-May-20	11-May-20	330824		
	1 Wash vehicle & start monthly inspection					
20150	Carry out inspection & replace wiper blades	01-Apr-20	01-Apr-20	330437		
	1 Carry out inspection & replace wiper blades					

Maintenance Log for LV.0039 - Landcruiser Tray Top

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
20125	Replace RHS front brake caliper & front CV joints (noisy)	02-Apr-20	02-Apr-20	330437		
	1 Replace RHS front brake caliper					
	2 Replace front CV joints (noisy), hubs & wheel bearings					11/05 Replace axle seals, king pin bearings, swivel hub seals, wheel bearings and seals - on both sides of front diff.
19881	Wash vehicle	12-Mar-20	12-Mar-20			
	1 Wash vehicle					
19728	Clean vehicle	28-Feb-20	28-Feb-20			
	1 Clean vehicle					
19410	330000km Service	06-Feb-20	06-Feb-20	329849	330015	
	1 330000km Service					
	2 Repalced blocked grease nipples					
18964	Spec up for mine site	05-Dec-19	05-Dec-19	328744		
	1 Safety					6/12 Fit battery isolator & terminals, Hi-Vis flag. 11/12 Wheel nut indicators.
	2 Body work					6/12 Rust repairs to windscreen.
18928	Replace cracked windscreen	03-Dec-19	03-Dec-19			
	1 Replace cracked windscreen					
18751	Tranpsort to Grafton	18-Nov-19	18-Nov-19			
	1 Maintenance					
18560	Rego Inspection	29-Oct-19	29-Oct-19			
	1 Rego Inspection					
	2 Service & Maintenance					29/10 Check over for rego - replace number plate holder, rewire new lights for number plate, adjust front wheel bearings, remove caliper LHF and replace with V49 (crashed ute). Remove fuel sender unti and fit to V39, wash vehicle and engine.

Maintenance Log for LV.0039 - Landcruiser Tray Top

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
18364	Oct maintenance work order	01-Oct-19	01-Oct-19	324827		
1	Engine work					2/10 Injector swap - Clean old gaskets for injector replacement. 11/10 Re-install injectors 14/10 Fit all injectors
18157	Sept maintenance work order	01-Sep-19	01-Sep-19	322872		
1	Inspection & service work					3/9 Carry out 103 inspection report & grease vehicle. 10/9 Clean & wash for swap over
2	Safety work					3/9 Remove digital UHF & replace with standard UHF.
3	Engine work					11/9 Replace fan belt 30/9 Swap injectors
4	Body work					11/9 Replace sway bar bushes 26/9 Changed out front sway bar bushes
5	Electrical work					11/9 Replace faulty fuel gauge connectors
17986	Aug maintenance work order	01-Aug-19	01-Aug-19	322000		
1	Body work					8/8 Replace rusted bullbar
2	Inspection & service work					9/8 Top up fluids and grease drive line 22/8 Wash vehicle
3	Tyres					14/8 Replace 2 rear tyres 22/8 Change rear tyres for tyre replacement 26/8 Picked up tyres
17796	July maintenance Work Order	01-Jul-19	01-Jul-19	320814		
1	Inspection & service work					10/7 Inspect machine & wash
17571	June maintenance Work Order	01-Jun-19	01-Jun-19	320500		
1	Inspection & Service work					11/6 Wash vehicle 26/06 Wash vehicle
2	Engine work					18/6 Replace faulty primer replacement
3	Body work					18/6 Replace failed steering damper
17326	Vehicle repairs	09-May-19	09-May-19	320000		

Maintenance Log for LV.0039 - Landcruiser Tray Top

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
1	Inspect machine					
2	Body work					Replace worn seat covers & floor mats. Replace u/s steering dampner.
3	Engine work					Replace u/s fuel filter priming pump.
4	Transmission work					Reseal transfer case output seal
5	AC work					Diagnose faulty relay in AC circuit.
6	Safety work					Replace flashing LED light
17181	Repair AC	09-Apr-19	09-Apr-19	318792		
1	Repair AC					
2	Inspect machine					
16968	320000 Km Service	14-Mar-19	14-Mar-19	318500		
1	320000 Km Service					Completed 15/4/19 319368 KM S Budden
2	Electrical work					Repair loom to main fuel tank sender unit.
3	Body work					Cut out & fit new mud flaps
4	Trans work					Free up & lube transfer case linkages
16822	Repair spare tyre	26-Feb-19	21-Jun-19	317400		
1	Repair spare tyre					
16724	Inspect & wash vehicle	08-Feb-19	08-Feb-19	317300		
1	Inspect & wash vehicle					
2	Repair Pos 3 tyre					
16659	6 monthly fire extinguisher testing	01-Feb-19	01-Feb-19			
1	6 monthly fire extinguisher testing					

Maintenance Log for LV.0039 - Landcruiser Tray Top

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
16375	Inspect & wash vehicle	08-Jan-19	08-Jan-19	315500		
	1 Inspect & wash vehicle					
	2 Repair UHF radio					
16136	Inspect & wash vehicle	27-Nov-18	27-Nov-18	315201		
	1 Inspect & wash vehicle					
15886	Rego Check	29-Oct-18	29-Oct-18	315000		
	1 Rego Check					
	2 Repair broken wiring for both number plate lights					
15873	Repair Pos 4 tyre	25-Oct-18	25-Oct-18	314934		
	1 Repair Pos 4 tyre					Repair leaking Pos 4 tyre
15725	Inspect & replace worn brake pads	10-Oct-18	10-Oct-18	314590		
	1 Inspect & replace worn brake pads					Replace both front & back brake pads & hand brake shoes.2/11/18
	2 Inspect & wash vehicle					
	3 Replace rear mud flaps					
	4 Repair RH tail light					
15556	Inspect & wash vehicle	19-Sep-18	19-Sep-18	314000		
	1 Inspect & wash vehicle					Inspect & wash vehicle
15276	Replace faulty drivers side door lock	21-Aug-18	21-Aug-18	313169		
	1 Replace faulty drivers side door lock					
	2 Repair work lights					
14806	310000 Km Service	03-Jul-18	03-Jul-18	309500		
	1 310000 Km Service					
	2 Repair flat Pos 3 tyre					

Maintenance Log for LV.0039 - Landcruiser Tray Top

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
14609	Replace pos 4 tyre	08-Jun-18	08-Jun-18	306727		
	1 Replace pos 4 tyre					Replaced at Gloucester Tyres
14341	300000 Km Service	07-May-18	07-May-18	301729		
	1 300000 Km Service					Completed 5/5/18 301729 km S Budden
	2 Wash ute					
14335	Replace blown Pos 3 tyre	04-May-18	04-May-18	301500		
	1 Replace blown Pos 3 tyre					
	2 Fit first aid kit					
14293	Prep for Stratford	27-Apr-18	27-Apr-18			
	1 Safety work					Fit hi vis unit numbers. Fit step ladder
14088	Fit new tyres X 4	16-Mar-18	16-Mar-18	297132		
	1 Fit new tyres X 4					
13359	Rego check	23-Oct-17	23-Oct-17	2934736		
	1 Rego check					
13322	Replace front shocks	17-Oct-17	17-Oct-17	293473		
	1 Replace front shocks					Broken shock mount & bent LHS shock.. Weld snapped strut mount back on - A Bowden Fit new
13286	Replace clutch slave & master cylinder- warranty	10-Oct-17	10-Oct-17			
	1 Replace clutch slave & master cylinder- warranty					Replace clutch slave & master cylinder- warranty. Re place clutch & rear main seal.
13202	290000km service	13-Sep-17	13-Sep-17	289948		
	1 290000km service					Completed 13/9/17 289948 Km M Lane
	2 Replaced flat Pos 4 tyre					

Maintenance Log for LV.0039 - Landcruiser Tray Top

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
12903	Replace missing fuel cap	10-Aug-17	10-Aug-17	282939		
	1 Replace missing fuel cap					
12729	Replace vandal damaged radio aerial	24-Jul-17	24-Jul-17	280844		
	1 Replace vandal damaged radio aerial					Vandals rip aerial off vehicle in main street
12728	280000 Km Service	24-Jul-17	24-Jul-17	280844		
	1 280000 Km Service					Completed 24/7/17 280844 Km M Lane
12487	270000 Km Service	22-Jun-17	22-Jun-17	274947		
	1 270000 Km Service					Completed 22/6/17 274947 Km
	2 Replace work light globes					
12172	Replace tooling for vehicle	08-May-17	08-May-17			
	1 Replace tooling for vehicle					Replace sledge hammer
12049	Replace RH rear view mirror	18-Apr-17	18-Apr-17	268592		
	1 Replace RH rear view mirror					Replace mirror due to loose mount that cant be tightened
11949	Replace u/s battery	27-Mar-17	27-Mar-17	268500		
	1 Replace u/s battery					
11781	Repair leak in Pos 1 tyre & Investigate black engine smoke	24-Feb-17	24-Feb-17			
	1 Repair leak in Pos 1 tyre					
	2 Engine repairs					Investigate black engine smoke . Replace rusted coolant pipe. Replace starter. Check fuel system issue. Remove main tank & clean out sludge. Thoroughly clean tank & refit. Remove sub tank, clean out sludge & refit. Refit engine parts. Replace No 1 fuel injection pipe. Test turbo waste gate operation. Swap air flow meter & test - Seems to be the issue. Clean air flow meter housing
11509	Tidy up ute & restock	18-Jan-17	18-Jan-17	265043		
	1 Tidy up ute & restock					

Maintenance Log for LV.0039 - Landcruiser Tray Top

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
10957	Repair clutch operation	31-Oct-16	31-Oct-16			
	1 Replace clutch master cylinder & slave cylinder					Replace clutch master cylinder & slave cylinder - Grafton Toyota
	2 Replace bottle jack					
10873	260000 Km Service	20-Oct-16	20-Oct-16	261213		
	1 260000 Km Service					Completed 20/10/16 261213 Km
	2 Adjust wheel bearings					
10872	Rego check	20-Oct-16	20-Oct-16			
	1 Rego check at Bears Tyres					Bears Tyres
10538	Replace tyre after flat	08-Sep-16	08-Sep-16			
	1 Replace tyre after flat					
	2 Clean battery terminals					
10462	Fit 2 front tyres + puncture repair	19-Aug-16	19-Aug-16			
	1 Fit 2 front tyres + puncture repair					