

Maintenance Log for LV.0105 - Hilux 4 x 4 Dual Cab

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
117726	Remove tray and demob for sale	12-Jun-26	12-Jun-26	451232		
	1 Remove tray and demob for sale					
117066	Replace worn tyres full set	16-Feb-26	16-Feb-26			
	1 Replace worn tyres full set					
116827	Rego inspection	13-Jan-26	13-Jan-26			
	1 Rego inspection					
116735	Replace worn out rear brakes	15-Dec-25	15-Dec-25			
	1 Replace worn out rear brakes					
116657	420000km Service	05-Dec-25	05-Dec-25	423000		
	1 420000km Service					
116375	Replace headlight globe	03-Nov-25	03-Nov-25			
	1 Replace globe					
116346	Mount tool box	29-Oct-25	29-Oct-25			
	1 Mount tool box					
115301	410k service	27-May-25	27-May-25	410657		
	1 410k service					
	2 Replace beacon switch					
115071	Clean ute	17-Apr-25	17-Apr-25			
	1 Clean ute					
114553	Wheel align	12-Feb-25	12-Feb-25			
	1 Wheel align					
114319	upgrade rear springs	20-Jan-25	20-Jan-25			
	1 upgrade rear springs					

Maintenance Log for LV.0105 - Hilux 4 x 4 Dual Cab

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
114316	Replace rack ends	20-Jan-25	20-Jan-25			
	1 Replace rack ends					
114315	400k service	20-Jan-25	20-Jan-25	398571		
	1 400k service					
114280	Rego inspection	14-Jan-25	14-Jan-25			
	1 Rego inspection					
113832	390k service	31-Oct-24	31-Oct-24			
	1 390k service					
113440	Replace u/s wiper blades	26-Aug-24	26-Aug-24			
	1 Replace u/s wiper blades					
113406	replace u/s number plates	19-Aug-24	19-Aug-24			
	1 Replace u/s number plates					
113387	Replace worn seat covers	14-Aug-24	14-Aug-24			
	1 Replace worn seat covers					
113302	Remove rear ladder rack and install on v125	01-Aug-24	01-Aug-24			
	1 Remove ladder rack and install on V125					
113137	380k service	04-Jul-24	04-Jul-24			
	1 380k service					
112090	370k service	17-Jan-24	17-Jan-24			
	1 370k service					
112064	Rego Inspection	16-Jan-24	16-Jan-24			
	1 Rego Inspection					

Maintenance Log for LV.0105 - Hilux 4 x 4 Dual Cab

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
111730	Pos 4 puncture repair	13-Nov-23	13-Nov-23			
	1 Pos 4 puncture repair					
111631	360,000km service	30-Oct-23	30-Oct-23			
	1 360,000km service					
111339	Spec up vehicle for Concreters	18-Sep-23	18-Sep-23			
	1 Install fixed Beacon					
	2 Install Roof rack and fabricate rear rack assy					
111330	DPF replacement under Toyota warranty	18-Sep-23	18-Sep-23			
	1 DPF replacement under Toyota warranty					
110653	350,000km service	20-Jun-23	20-Jun-23	349639		
	1 350,000km service					
110497	Puncture repair	30-May-23	30-May-23			
	1 Puncture					
110337	340000km service	03-May-23	03-May-23	341378		
	1 340k service					
	2 rack ends					
	3 tyres					
109834	330000km service	22-Feb-23	22-Feb-23	329249		
	1 330k					
109651	320000km service	24-Jan-23	24-Jan-23	324255		
	1 320k					
109649	Rego inspection	24-Jan-23	24-Jan-23			
	1 Rego inspection					

Maintenance Log for LV.0105 - Hilux 4 x 4 Dual Cab

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
109648	Rego inspections	24-Jan-23	24-Jan-23			
	1 Rego					
108858	310000 km Service	27-Sep-22	27-Sep-22			
	1 310000 km Service					
108829	Replace battery	21-Sep-22	21-Sep-22			
	1 Replace battery					
108772	Puncture repair	12-Sep-22	12-Sep-22			
	1 Puncture					
108290	Replace windscreen	06-Jul-22	06-Jul-22	298283		
	1 Replace windscreen					
108289	300k service	06-Jul-22	06-Jul-22	298283		
	1 300k service					
108288	290k service	22-Apr-22	22-Apr-22	290116		
	1 290k service					
107815	Repair parker lights	10-May-22	10-May-22	292105		
	1 Repair parker light					
107075	280k service	16-Feb-22	16-Feb-22	279693		
	1 280k service					
106886	Rego inspcetion	21-Jan-22	21-Jan-22			
	1 Rego inspection					
106777	270k service	22-Dec-21	22-Dec-21			
	1 270k service					
106513	Repair tail light	23-Nov-21	23-Nov-21			
	1 Repair tail light					

Maintenance Log for LV.0105 - Hilux 4 x 4 Dual Cab

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
106137	260000km service	15-Oct-21	15-Oct-21	258818		
	1 260000km service					
105445	250000km service	03-Aug-21	03-Aug-21	249850		
	1 250000km service					
104932	240000km service	24-May-21	24-May-21	239906	239906	
	1 240000km service					
104924	Repair indicators	21-May-21	21-May-21	239906		
	1 Repair indicators					
104304	230000km service	15-Mar-21	15-Mar-21	229854	229854	
	1 230000km service					
104014	Replace worn front brake pads	23-Feb-21	23-Feb-21	227568		
	1 Replace worn front brake pads					
103711	220000km service	22-Jan-21	22-Jan-21	223389	223389	
	1 220000km service					
102969	LH Front blinker damaged	06-Nov-20	04-Nov-20	211298		
	1 Repair blinker					Pre start defect from kangaroo strike 14591
102764	210000km service	19-Oct-20	19-Oct-20	210105	210105	
	1 210000km service					
102508	Replace battery	24-Sep-20	24-Sep-20			
	1 Replace battery					
102117	200000km Service & replace worn tyres	28-Aug-20	28-Aug-20	200300	200300	
	1 200000km Service					
	2 Replace worn tyres					

Maintenance Log for LV.0105 - Hilux 4 x 4 Dual Cab

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
101333	190000km service	03-Jul-20	03-Jul-20	190205		
	1 190000km service					3/07 Completed
100560	180000km Service	22-May-20	22-May-20	183231	183231	
	1 180000km Service					
100489	6 Monthly fire extinguisher inspection	19-May-20				
	6 Monthly fire extinguisher inspection					
20448	Puncture repair	24-Apr-20	24-Apr-20	177059		
	1 Puncture repair					
20281	puncture repair	16-Apr-20		176000		
	1 puncture repair					
19824	170000km Service	09-Mar-20	09-Mar-20	168498	169903	
	1 170000km Service					13/3/20
	2 Replace drivers side grab handle					
19248	160000km Service	17-Jan-20	17-Jan-20	158581	159295	
	1 160000km Service					17/1 service 17/01 Completed 159295km - D Martin
19145	Replace U/S quick release flag mount fittings.	10-Jan-20	10-Jan-20	157733		
	1 Replace U/S quick release flag mount fittings.					
18962	Replace UHF aerial	04-Dec-19	04-Dec-19			
	1 Replace UHF aerial					
18785	150000 km Service	22-Nov-19	22-Nov-19	149014	149014	
	1 150000km Service					22/11 service items

Maintenance Log for LV.0105 - Hilux 4 x 4 Dual Cab

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
18777	Hi-Vis Unit Numbers	21-Nov-19	21-Nov-19			
1	Hi-Vis unit number					
2	Unit number plate					22/11 galvournised plate
18363	140000 km Service	02-Oct-19	02-Oct-19	139276	139276	
1	140000 km Service					2/10 Completed 139276km's - D Martin
17934	130000 km Service	02-Aug-19	02-Aug-19	129129		
1	130000 Km Service					Completed 2/8/19 129129Km C Thomas
17561	120000 Km Service	11-Jun-19	11-Jun-19	120649		
1	120000 Km Service					Completed 11/6/19 120649 Km C Thomas
17399	Replace battery	17-May-19	17-May-19			
1	Replace battery					Replace battery
17101	110000 Km Service	02-Apr-19	02-Apr-19	110266		
1	110000 Km Service					Completed 2/4/19 110266 Km B Cassin
16563	100000 Km Service	23-Jan-19	23-Jan-19	98900		
1	100000 Km Service					Completed 23/1/19 98516 Km B Cassin
15971	90000 Km Service	08-Nov-18	08-Nov-18	90000		
1	90000 Km Service					Completed 8/11/18 89021 Km J Nash
15577	80000 Km Service	24-Sep-18	24-Sep-18	80000		
1	80000 Km Service					Completed 24/9/18 79114 Km M Lane
2	Replace worn tyres					Marx tyres replace 4 worn tyres
14977	70000 Km Service	23-Jul-18	23-Jul-18	70031		
1	70000 Km Service					Completed 23/7/18 70031 km D Martin

Maintenance Log for LV.0105 - Hilux 4 x 4 Dual Cab

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
14400	60000 Km Service	14-May-18	14-May-18	60000		
	1 60000 Km Service					Completed 14/5/18 59437 km TT Toyota JC 24021782
	2 Replace battery					
14354	Repair flat tyre	08-May-18	08-May-18			
	1 Repair flat tyre					
14091	50000 Km Service	19-Mar-18	19-Mar-18	50000		
	1 50000 Km Service					Completed 22/3/18 49339 Km Twin Towns Inv JC 24021332
13733	40000 Km Service	15-Jan-18	15-Jan-18	40759		
	1 40000 Km Service					Completed 22/1/18 40759 km Twin Town Toyota Inv JC 24020794
13450	30000 Km Service	08-Nov-17	08-Nov-17	30845		
	1 30000 Km Service					Completed 8/11/17 30845 Km D Martin
	2 Replace switch for flashing light					
	3 Replace mobile antenna mount					
13022	20000 Km Service	29-Aug-17	29-Aug-17	19526		
	1 20000 Km Service					Completed 29/8/17 19526 Km D Martin
12280	10000 Km Service	19-May-17	19-May-17	9633		
	1 10000 Km Service					Completed 19/5/17 9633 Km
11588	Commission new Hi Lux	31-Jan-17	31-Jan-17			
	1 Commission new Hi Lux					
	2 Install safety equipment					Installed flashing beacon & reverse alarm
	3 Install electrical equipment					Fit 2 way. Phone kit fitted in Taree.
	4 Install signage					
	5 Install tool boxes					Fit tool boxes to vehicle.