

Certificate of inspection Trailers & Dollies over 750kg



0813

Ph 0417 600 249
ABN 97 108 243 714**SUPERIOR
MACHINERY
MAINTENANCE**

Owner and vehicle details

Vehicle Owner's name and address

WATTS
10 KOLONBO CRES
MT ISA QLD Postcode 4825

Plate No.
(if applicable) State Unit No.

311 QZH QLD TL21

VIN/Chassis no.

6T9T25NT0D2NUM091

Make

TRISTAR

Model

ST3

Body Shape

SEMI TRAILER

Badge (eg. Cargo)

Compliance type

Compliance Plate ☒ Import Plate ☐ Other ☐

Date on Plate Vehicle Colour

0513 YELLOW/BLACK

Left or Right hand drive?

Tare GVM 47000 GCM

Results of inspection

Please indicate Pass ☒ Fail ☒

	1st inspection	Final inspection
Identification	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Modifications	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Lights & Electrical Components	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Body & Chassis	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Suspension	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Wheels & Tyres	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Brakes	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Tow Coupling	<input checked="" type="checkbox"/>	<input type="checkbox"/>
1st Axle	SB <input checked="" type="checkbox"/> HB <input checked="" type="checkbox"/>	SB <input type="checkbox"/> HB <input type="checkbox"/>
2nd Axle	SB <input checked="" type="checkbox"/> HB <input checked="" type="checkbox"/>	SB <input type="checkbox"/> HB <input type="checkbox"/>
3rd Axle	SB <input checked="" type="checkbox"/> HB <input checked="" type="checkbox"/>	SB <input type="checkbox"/> HB <input type="checkbox"/>
4th Axle	SB <input type="checkbox"/> HB <input type="checkbox"/>	SB <input type="checkbox"/> HB <input type="checkbox"/>

Details of other items rejected

REPLACE REAR MARKER PLATES

1st Inspection

Result ☒

Inspection date

419118

Inspection time

9:00 am

Odometer reading

530870

Signature of Examiner

S-Pye

Examiner's no.

18904

Final inspection (must not be more than 14 days from date of 1st inspection)

Result ☒

Inspection date

1119118

Inspection time

7:00 am

Odometer reading

534453

Signature of Examiner

S-Pye

Examiner's no.

18904

Inspection Station details

Name and location

SUPERIOR MACHINERY MAINTENANCE
27 COMMERCIAL RD Postcode 4825

Approved Inspection Station Number

10588

Certification

Approved examiner - I have inspected the vehicle indicated on this form and found it had no defect that would affect its safe use of the road and it meets the requirements of the Transport Operations (Road Use Management) Act 1995.

Inspected by - Signature of Examiner

S-Pye

Date

11-9-18

Name of Examiner (please print)

SAM PYE

Examiner's no.

18904

Certificate of Inspection Reminder Notice

Transport Operations (Road Use Management) Act 1995

Customer Reference Number 102140112

16 September 2019



Queensland
Government

ABN: 39 407 690 291

Telephone: 13 23 90* (Local call cost in QLD.)

Note: All vehicles being presented for inspection must be **unladen and clean**. (Clean means free from grease, dirt, mud etc. on both upper and under body components).

Failure to comply with these conditions may result in a refusal to inspect.



/E-21 / S-3078 / I-3094

WORLD WELDING AND TRANSPORT SERVICE PTY
LTD
PO BOX 1808
MOUNT ISA DC QLD 4825


Plate number	Registration category	Registration expiry date	COI expiry date
311QZH	HTRL	01/06/2020	01/12/2019
Make	Body shape		
Tristar	Semi Trailer		

Our records indicate that a Certificate of Inspection (COI) for your vehicle is due on 01/12/2019. The owner of a registered COI vehicle must possess a current COI for the vehicle.

Failure to have a current COI can result in an on-the spot fine of 5 penalty units. You are encouraged to book an inspection early to allow time to repair any defects before your current COI expires.

- A vehicle that has a current COI may be inspected up to two months before the existing certificate expires. If so, the new certificate will not begin until the original certificate expires. If a COI vehicle is inspected after the original certificate expires the new certificate's expiry date will be calculated as if it commenced when the original certificate expired.
- To take advantage of the two month window of opportunity, please ensure you make a booking for an inspection as soon as possible. This will allow time for any identified defects to be repaired before the current COI expires.
- The following example shows how the two month window of opportunity does not affect the expiry date of the new COI.

Please note: If the vehicle does not have a current COI, the effective date will be the issue date.



Booking an inspection

- Online bookings can be made through the 'Book a vehicle inspection' Online Service at www.tmr.qld.gov.au.
*Payment is required at the time of booking.
- Phone bookings can be made by telephoning 13 23 90. Payments for phone bookings can be paid by credit card* at www.tmr.qld.gov.au or by other payment methods at a Department of Transport and Main Roads Customer Service Centre or Agency.

*Acceptable cards are MasterCard™ and Visa™. A credit card surcharge will apply.



TRAILER & DOLLY SERVICE SHEET


DATE 24/10/19 START TIME 12:00 FINISH TIME 1:30
FLEET NO 7621 KM'S 771232 HRS _____

JOB NO. _____
REGO _____

Service Items - Mechanic/Fitters to complete Initial = OK, X Repair, NA = Not Applicable		A Service	B Service	C Service
Local Trailers	40000km/365 days	7 DAYS	14 DAYS	40000KM
Linehaul Trailers	15000km 10 days 150000km/365days		15000KM	150000KM
1	Check fault repair bok and repair as necessary	✓		
2	Check fleet numbers are serviceable	✓		
3	Record Hubmeter reading	✓		
4	Lubricate Container Pins	N/A		
5	Check operation & condition of all lights/reflectors	✓		
6	Apply Air Check fvor leaks from boosters, valves & air lines	✓		
7	Adjust brakes , visually inspect components	✓		
8	Check air cells for air leaks and deterioration	✓		
9	Drain all air tanks, report if any oil is present in system	✓		
10	Grease trailer incl. brake cams, slack adjusters, landing legs, ringfeeder & other grease points	✓		
11	Check hoist mounting bolts, hoses, coupling	✓		
12	Check number plate & rego label security. Check that rego label is current	✓		
13	Check condition of front air connections, light plug base & electrical lead	✓		
14	Check security of spare wheels & spare wheel carrier/gate rack	✓		
15	Check condition & security of all mudflaps, mudguards, brackets & spray suppression	✓		
16	Check landing legs for damage & security	✓		
17	Check sub frame & cross members for cracks, damage & security	✓		
18	Check condition, position & security of all air hoses	✓		

19	Check brake linings & drums for wear. Check hub seals for leakage
20	Check security of height control valves and links & adjust if required
21	Check skid plate/king pin security & condition, check draw bar/bushes and towing eye
22	Check wheel nut tensions, check valve stem alignment
23	Check all tyre pressures and refit valve caps (including spare) report abnormal wear
24	Check condition & security of rear marker signs
25	Check ringfeeder condition, operation & security
26	Lubricate twistlocks & check operation & security of pedestals, straighten handles as required
27	Check condition & securty of rope rails, gate pockets, winch rails & straps
28	Check condition & security of floor and associated components
29	Raise trailer by rear frame & individually inspect rocker/radius bushes, wear pads, air cells for wear
30	Check security & bolt tension od airbag suspension hagers & radius rod arms
31	Raise wheel assembly & check bearings for free play by "feel" only & adjust as required
32	Indicate on below drawing wheel bearings that are replaced, checked and/or adjusted

front




rear

33	Check brake linings & drums for wear whilst hubs are removed
34	Check hubs for cracks and tapered shoulders for wear
35	Remove bearings and clean/inspect for reuse
36	Replace muflaps & decals as required
37	Remove s/cam slack adjuster pins and rotate/lubricate
38	Pack bearings with fresh grease & reassemble

Initial if adjusted - Tick if C

PLEASE COMPLETE PAGE 2

[illegible][illegible]

Tradesperson Name	Cody Lee	Signature	
		Date	26-10-19



WORLD WELDING AND TRANSPORT SERVICE

Maintenance Report

VEHICLE: TL21
~~787~~

DATE: 16-11-19 - 17-11-19

KMS: 787,781

DESCRIPTION OF MAINTENANCE:

* REPLACE LEAKING AIR BAGS ON FRONT
AXLE L & R AND REAR AXLE L & R.
* REPLACE LEAKING SHOCKS ON FRONT
AXLE L & R
* REPLACE WORN TIRES ON MIDDLE AXLE
LHS

NAME: MATT H

SIGNATURE: 

Certificate of Inspection

Transport Operations (Road Use Management) Act 1995



Queensland
Government

Date of Issue : 22/11/2019

Certificate Number: ST 31388203

Effective Date: 02/12/2019

Expiry Date: 01/12/2020

Motor Vehicle Details

Plate Number : 311QZH 1

Make : TRISTAR

Body Shape : SEMI TRAILER

VIN Number : 6T9T25NT0D2NUM091

Engine No :

ATM (Kg) : 47000

Reg Category: HEAVY TRAILER

GTM (Kg) :

Registered Operator/s Details

WORLD WELDING AND TRANSPORT SERVICE PTY LTD
8-10 KOLONGO CRESCENT
MOUNT ISA QLD 4825

Certification

This is to certify that the vehicle, particulars of which are set out in this certificate, was inspected in accordance with the provisions of the above mentioned Act and departmental guidelines on the issue date stated in this certificate and has no evident defect that would affect its safe use on the road.

This certificate is in force until the expiry date specified unless it is suspended or cancelled, or the registration of the vehicle is cancelled under the provisions of the said Act.

Inspector's Authority No: Q411

District : VIDTOWNSVI

Inspector's Signature

Note - Vehicle inspections undertaken by the Department of Transport and Main Roads are carried out to prescribed safety standards. The Department recommends an independent comprehensive assessment of the vehicle's condition prior to purchase.