

Certificate of inspection Trailers & Dollies over 750kg



Ph 0417 600 249
ABN 97 108 243 714

SUPERIOR MACHINERY MAINTENANCE

Owner and vehicle details

Vehicle Owner's name and address

WWATS
10 KOLONGO CRES
MT ISA QLD Postcode 4825

Plate No.

(if applicable)

State

Unit No.

315 QZH QLD TL25

VIN/Chassis no.

6T9T25NTOD2NUM093

Make

Model

TRISTAR ST3

Body Shape

Badge (eg. Cargo)

SEMI TRAILER

Compliance type

Compliance

☒

Import

☐

Give details

Other

☐

Date on Plate

Vehicle Colour

0513 YELLOW/BLACK

Left or Right hand drive?

Tare GVM 47000 GCM

Results of inspection

Please indicate

Pass

☒

Fail

☒

1st
inspection

Final
inspection

Identification	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Modifications	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Lights & Electrical Components	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Body & Chassis	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Suspension	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Wheels & Tyres	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Brakes	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Tow Coupling	<input checked="" type="checkbox"/>	<input type="checkbox"/>
1st Axle	SB <input checked="" type="checkbox"/> HB <input checked="" type="checkbox"/>	SB <input type="checkbox"/> HB <input type="checkbox"/>
2nd Axle	SB <input checked="" type="checkbox"/> HB <input checked="" type="checkbox"/>	SB <input type="checkbox"/> HB <input type="checkbox"/>
3rd Axle	SB <input checked="" type="checkbox"/> HB <input checked="" type="checkbox"/>	SB <input type="checkbox"/> HB <input type="checkbox"/>
4th Axle	SB <input type="checkbox"/> HB <input type="checkbox"/>	SB <input type="checkbox"/> HB <input type="checkbox"/>

Details of other items rejected

DOOR CRACKS
REPLACE WORN TYRES

1st Inspection

Result ☒

Inspection date

419118

Inspection time

11:00 am

Odometer reading

561178

Signature of Examiner

S-Py

Examiner's no.

18904

Final inspection (must not be more than 14 days from date of 1st inspection)

Result ☒

Inspection date

1119118

Inspection time

7:00 am

Odometer reading

564640

Signature of Examiner

S-Py

Examiner's no.

18904

Inspection Station details

Name and location

SUPERIOR MACHINERY MAINTENANCE
27 COMMERCIAL RD Postcode 4825

Approved Inspection Station Number

10588

Certification

Approved examiner - I have inspected the vehicle indicated on this form and found it had no defect that would affect its safe use of the road and it meets the requirements of the Transport Operations (Road Use Management) Act 1995.

Inspected by - Signature of Examiner

S-Py

Date

11-9-18

Name of Examiner (please print)

SAH PYE

Examiner's no.

18904