

MAINTANENCE MANAGEMENT RECORD			
BODY TYPE:	DOG TRAILER		
MAKE:	HAMELEX		
YEAR OF MANUFACTURE:	2017		
VEHICLE ID No. (VIN)	6F80000000B091478		
ENGINE NUMBER:			
LICENSE NUMBER:	SY43GM		
CONFIGURATION CODE:	DOG TRL - SINGLE AXLE (F)B & TANDEM AXLE (R)		
MASS:	6000		
LAST SERVICE:	08/03/2024 (148,316 km) - SCOTT CHRISTENSEN		
NEXT SERVICE DUE:	08/09/2024 (158,316 km) (WHICHEVER IS SOONER)		
NHVAS LABEL NUMBER:	AT114342 (AS OF 22/02/2017 MAINTENANCE)		
DATE	COMPANY	DESCRIPTION	KM'S
16/12/2017	SCOTT CHRISTENSEN	SERVICE TRAILER, GREASE ALL POINTS, CHECK AND ADJUST BRAKES AND WHEEL BEARINGS, TIGHTENED ALL BOLTS ON BALL RACE TURN TABLE	45,775
10/03/2018	SCOTT CHRISTENSEN	SERVICE TRAILER, CHECK AND ADJUST BRAKES, CHECK LIGHTS, GREASE ALL POINTS	54133
2/06/2018	SCOTT CHRISTENSEN	REMOVE AND REPLACE TOW EYE ON DRAW BAR, REMOVE AND REPLACE TURN TABLE BOLTS	
8/09/2018	SCOTT CHRISTENSEN	SERVICE TRAILER, CHECK AND ADJUST WHEEL BEARINGS AND BRAKES, GREASE ALL POINTS	77820
19/12/2018	TRUCK POWER AUTO ELECTRICS	SUPPLY AND FIT REVERSE CAMERA TO TRAILER	
25/01/2019	SCOTT CHRISTENSEN	SERVICE TRAILER, CHECKED AND ADJUSTED BRAKES AND WHEEL BEARINGS, CHECKED LIGHTS GREASED ALL POINTS	93510
21/05/2019	MAXI TRANS	REPLACE DAMAGED HYDRAULIC HOSE	
7/06/2019	SCOTT CHRISTENSEN	SERVICED TRAILER, CHECK AND ADJUST BRAKES AND WHEEL BEARINGS, CHECK LIGHTS, GREASE ALL POINTS	109401
18/04/2019	MAXITRANS	100,00KMS SERVICE LHR MUDGUARD POST BENT DOWN 25mm HYD HOSE & WIRE RUBBING UNDER DOLLY AREA BRAKE LINE RUBBING ON CABLE TIE (WARRANTY - NO CHARGE) RE KIT 'O' RINGS IN HYD COUPLING FIT HOOKS FOR PAVER ON REAR MUDFLAPS 1st AXLE LH & RH SIDE WORN IN SPRING EYE DROP FRONT AXLE, REPAIR AS REQUIRED REFIT AXLE REMOVE & REPLACE x 2 BUSHES (PIVOT) WITH HARDWARE 2 X SHOCKERS BOLTS AS U/S	102,873
16/11/2019	SCOTT CHRISTENSEN	SERVICE TRAILER. CHECK AND ADJUSTED WHEEL BEARINGS AND BRAKES. CHECKED LIGHTS. GREASED ALL POINTS.	129,588
6/01/2020	ADELAIDE INDEPENDENT BANDAG	X4 SUPPLY AND FIT TO FRONT AXLE	135,434
31/01/2020	SCOTT CHRISTENSEN	serviced trailer. Checked and adjusted brakes and wheel bearings. Checked lights. Greased all points	139,401

4/02/2020	SCOTT CHRISTENSEN	Seviced trailer. Checked and adjusted brakes and wheel bearings. Checked lights. Gresed all points. Replaced bent tow eye (weld in one). Replaced brocked shock strap retainer. Tightened loose shock bolt on RH front axle. Replaced drawbar bushes and pins. PARTS. x1 tow eye. x1 filler breather 1.1/2" push on. x2 pin assy equalizer. x4 bush equalizer taper. grease and consumables.	139,401
6/04/2020	SCOTT CHRISTENSEN	removed wheels, brake drums, brake linings, anchor pin bushes, slack adjusters and s cams from axles. Blew grease out from outer bearings, knocked seals and inner bearings out from hubs and blew greaseout of bearings. Washed and inspected bearings, washed hub nuts and washers. cleaned up x6 hubs, removed gaskets and buffed surfaces. cleaned grease from x1 axle stuv and sanded bearing surfaces. cleaned up x5 axles, installed x6 hub seals, fitted x3 hubs to trailer. fitted brake drums to hubs, fitted remaing bolts to grease caps. fitted wheels to trailer and tensioned wheel nuts to 500 ft/lbs. drilled holes in rear of trailer and fitted counter sunk bolt into nylon wear pad. tightened clamp bolt on lhs light bar. replaced x3 missing reflectors. Parts - brake drums x6. brake shoes x6. hubcap gaskets x6. hub seals x6. lock tabs x6. s cam washers and cir clips x6. slack adjusters x6. s cam tubes x6. l/h s cams x3. r/h s cams x3. s cam tube bracket x6. grease. nuts and bolts and washers. consumables.	147,470
21/04/2020	ADELAIDE INDEPENDENT BANDAG	rh front outer : puncture repair - 11r22.5 x1. remove and replace wheels/tyres x1.	
10/06/2020	MaxiTrans	Seal on tailgate has come adrift. Checked and found screws had worn through body. Had to weld/build up as required. Drill to suit. Fit new machine screws with thread locker as required to secure.	
19/06/2020	SCOTT CHRISTENSEN	Service trailer. Checked and adjusted brakes and wheel bearings. Greased all points checked lights.	156,378
1/09/2020	ADELAIDE INDEPENDENT BANDAG	LH Rear Outer Puncture Repair	
26/10/2020	TRUCK POWER AUTO ELECTRICS	LABOUR - Replace faulty trailer plug, check lighting, repair wiring in door	
28/04/2021	MAXITRANS	LABOUR & MATERIALS TO FIT NEW 10MM FLOORSHEET - PREP REAR OF TRAILER AS FLOOR SHEET WORN EXCESSIVELY, SECURE, WELD EDGES & PLUG WELD. CHECK TAILGATE CLEARANCE	
16/06/2021	MAXITRANS	REPLACED TAIL GATE HANDLE-REPLACED TAIL AGTE HANDLE-REPLACED REAR TAIL GATE HANDLE PIN AND BUSH	

24/06/2021	ADELAIDE INDEPENDENT BANDAG	SUPPLY AND FIT LH MIDDLE X 2	
15/06/2021	SCOTT CHRISTENSEN	CHECKED AND ADJUSTED BRAKES AND WHEEL BEARINGS, CHECKED ALL LIGHTS GREASED ALL POINTS	14491
28/06/2021	MAXI TRANS	WELD UP GRAIN HANDLES CRACKED ON RIGID TIPPER AND DOG	
17/08/2021	SCOTT CHRISTENSEN	CHECKED AND ADJUSTED BRAKES AND WHEEL BEARINGS, CHECKED ALL LIGHTS GREASED ALL POINTS	23619
2/09/2021	TRUCK POWER AUTO ELECTRICS	CHECK HYPER LINK FOR DETAILS	
29/11/2021	ADELAIDE INDEPENDENT BANDAG	SUPPLY & FIT 4 X REAR AXLE (11R22.5 RIB TRAC ELITE BANDAG - STK	
9/12/2021	SCOTT CHRISTENSEN	SERVICE TRAILER CHECKED AND ADJUSTED BRAKES AND WHEEL BEARINGS, CHECKED ALL LIGHTS GREASES ALL POINTS	39730
28/03/2022	SCOTT CHRISTENSEN	CHECKED AND ADJUSTED BRAKES AND WHEEL BEARINGS, CHECKED ALL LIGHTS, GREASED ALL POINTS	54047
6/06/2022	SCOTT CHRISTENSEN	CHECK HYPERLINK FOR DETAILS	63,110
19/08/2022	SCOTT CHRISTENSEN	CHECKED AND ADJUSTED BRAKES AND WHEEL BEARINGS, CHECKED ALL LIGHTS AND GREASED ALL POINTS	72,163
28/11/2022	SCOTT CHRISTENSEN	SERVICED TRAILER, REMOVED AND REPLACED DRAW BAR EYE, REMOVED AND REPLACED DRAW BAR AIR KIBES.	84,430
		CHECKED AND ADJUSTED BRAKES	
13/02/2023	ADELAIDE INDEPENDENT BANDAG	SUPPLY AND FIT RH FRONT	97,183
24/02/2023	TRUCK POWER AUTO ELECTRICS	FOUND WIRING LOOM CUT AS A RESULT OF DAMAGE TOP TRAILER. REPAIRED WIRING LOOM TO MARKER LIGHT. TESTED ALL OK	N/A
27/02/2023	SCOTT CHRISTENSEN	CHECK AND ADJUSTED BRAKES AND WHEEL BEARINGS. CHECKED ALL LIGHTS AND GREASE PIONTS	98,806
1/03/2023	SCOTT CHRISTENSEN	REPLACED BRAKES, SHOES AND DRUMS. RE-FITTED WHELLS AND TENSIONED WHEEL NUTS ADJUSTED ALL BRAKES. FIXED AIR LEAK IN FRONT AXLE	98,807
13/04/2023	ADELAIDE INDEPENDENT BANDAG	REPAIRS TO SY43GM: REPLACED 2 TYRES BEING LH REAR	103,255
19/04/2023	SCOTT CHRISTENSEN	CHECK AND ADJUST BRAKES AND WHEEL BEARINGS, CHECK ALL LIGHTS, GREASE ALL POINTS	104,296
5/05/2023	MAXITRANS	SUPPLY & INSTALL NEW BATTERY	
19/06/2023	ADELAIDE INDEPENDENT BANDAG	SUPPLY & FIT RH 3RD OUTER/ DISPOSAL OF TYRE	N/A

21/06/2023	SCOTT CHRISTENSEN	CHECK AND ADJUST BRAKES AND WHEEL BEARINGS, CHECK ALL LIGHTS, GREASE ALL POINTS	11489
14/07/2023	ADELAIDE INDEPENDENT BANDAG	SUPPLY AND FIT 2X TYRES RH REAR	118558
3/08/2023	ADELAIDE INDEPENDENT BANDAG	LH FRONT DOLLY RIB TRAC ELITE BANDAG OWN CASINGS X 2	122141
13/09/2023	SCOTT CHRISTENSEN	CHECK AND ADJUST BRAKES AND WHEEL BEARINGS, CHECK ALL LIGHTS AND GREASE ALL POINTS	126,584
9/10/2023	ADELAIDE INDEPENDENT BANDAG	PUNCTURE REPAIR RH REAR INNER	
2/11/2023	ADELAIDE INDEPENDENT BANDAG	SUPPLY AND FIT LH MIDDLE 2X TYRES	
15/12/2023	BATTERIES DIRECT	NEW BATTERY	
18/12/2023	SCOTT CHRISTENSEN	CHECK AND ADJUST BRAKES AND WHEEL BEARINGS, CHECK ALL LIGHTS, GREASE ALL POINTS, ADJUST 2X WHEEL BEARINGS	141506
12/02/2024	ADELAIDE INDEPENDENT BANDAG	SUPPLY AND FIT 2X TYRES TO LH REAR	
13/02/2024	MAXI TRANS	WELD CORNER IN FLOOR, REPAIR HYD AND AIR	
8/03/2024	SCOTT CHRISTENSEN	SEE HYPERLINK FOR DETAILS	148,316
10/04/2024	MAXI TRANS	REPAIR SPLASH GUARDS & FIT PATCH IN FLOOR AT FRONT	
30/04/2024	ADELAIDE INDEPENDENT BANDAG	LH MIDDLE INNER REMOVE AND REPLACE WHEELS AND BOLT ON OWN	
21/05/2024	MAXITRANS	REPLACE 2X CABLES, REPLACED 2X PULLEYS, TENSIONS TARPS	
24/05/2024	SCOTT CHRISTENSEN	CHECK AND ADJUST BRAKES AND WHEEL BEARINGS, CHECK ALL LIGHTS, GREASE ALL POINTS, REPLACED LEAKING HYDRAULIC HOSE SEALS, CHANGED 2X BROKEN CLEAR AND 1X BROKEN AMBER REFLECTOR	158566
17/06/2024	ADELAIDE INDEPENDENT BANDAG	REMOVE AND REPLACE RH MIDDLE INNER TYRES X 1	
4/07/2024	ADELAIDE INDEPENDENT BANDAG	PUNCTURE REPAIR LH FRONT OUTER X 1, TLESS VALVE X1, REMOVE AND REPLACE WHEELS	165182
19/07/2024	SCOTT CHRISTENSEN	CHECK AND ADJUST BRAKES AND WHEEL BEARINGS, CHECK ALL LIGHTS, GREASE ALL POINTS	168939
23/07/2024	ADELAIDE INDEPENDENT BANDAG	SUPPLT AND FIT TO LH FRONT 2X TYRES	169477

14/08/2024	SCOTT CHRISTENSEN	REPAIRED AIR LEAK ON TRAILER	
23/09/2024	ADELAIDE INDEPENDENT BANDAG	SUPPLY AND FIT TO RH MIDDLE & RH REAR 4X BANDAG	
5/09/2024	SCOTT CHRISTENSEN	TRAILER SERVICE, CHECK AND ADJUST BRAKES AND WHEEL BEARINGS, CHECK ALL LIGHTS, GREASE ALL POINTS, OXY CUT BENT TOW EYE FROM DRAW BAR, REPLACED 2X REFLECTORS 1X RED 1X AMBER	180212
15/10/2024	MAXITRANS	REPLACE RAZOR BRAKE AND ADJUST, CHECK OPERATION	
18/10/2024	ADELAIDE INDEPENDENT BANDAG	SUPPLY AND FIT LH FRONT - REMOVE AND REPLACE WHEELS/TYRES, BOLT ON OWN	
15/10/2024	TRUCK POWER AUTO ELECTRICS	CHECK FAULT WITH WIRING, DAMAGE TO LHS CLEARANCE LIGHTS ON TRAILER, REPAIR BROKEN WIRING, REMOVE AND REPLACE FAULTY LED SIDE MARKER LIGHT	
23/10/2024	TRUCK POWER AUTO ELECTRICS	DIAGNOSE AND REPAIR WIRING FAULT TOWARDS REAR HARNESS OF LHS MARKER LIGHTS RECHECK OPERATION	
15/10/2024	SCOTT CHRISTENSEN	CHECK AND ADJUST BRAKES AND WHEEL BEARINGS, CHECK ALL LIGHTS, GREASE ALL POINTS, REMOVED AND REPAIRED AND REFIT LH MUDFLAP GUARD	194,522
11/11/2024	TRUCK POWER AUTO ELECTRICS	CHECK FAULT WITH REAR HIGH LEVEL LIGHTS NOT WORKING ON TRAILER, REMOVE SEALED TAIL LIGHT ASSEMBLY AND CHECK VOLTAGE. FIND LOW VOLTAGE TO LIGHT, CHECK EARTH CIRCUIT LIGHTING. OK, TRACE WIRING AND LOCATE VOLTAGE DROP FAULT. FIND CORRODED CONNECTION IN CONNECTOR PLUG AT REAR OF TRAILER REPAIR WIRING AND RECHECK LIGHTING, OK. CHECK HORN FAULT IN TRUCK, REMOVE STEERING WHEEL AND BUILD UP HORN CONTACT WITH SOLDER, RECHECK, OK.	
25/11/2024	SCOTT CHRISTENSEN	CHECK AND ADJUST BRAKES AND WHEEL BEARINGS, CHECK ALL LIGHTS, GREASE ALL POINTS, REPAIRED WIRING ON RH SIDE LIGHT, FIT NEW REAR SAFETY SIGNAGE	202605
14/02/2025	SCOTT CHRISTENSEN	TRAILER SERVICE, CHECK AND ADJUST BRAKES AND WHEEL BEARINGS, CHECK ALL LIGHTS, GREASE ALL POINTS, REPLACED 4X REAR MUDFLAPS, REPLACED HYDRAULIC FITTINGS	
6/05/2025	TRUCK POWER AUTO ELECTRICS	MODIFY REVERSE CAMERA CABLE ON TRAILER TO WIRE SINGLE PLUG INTO TRUCK CONNECTION, SOLDER INTO EXISTING 5PIN CONNECTOR, RE-ROUTED CABLE THROUGH SPISAL GUARD	
6/05/2025	SCOTT CHRISTENSEN	TRAILER SERVICE, CHECK AND ADJUST BRAKES AND WHEEL BEARINGS, CHECK ALL LIGHTS, GREASE ALL POINTS, AIR LEAK FROM PIVOT VALVE ON DRAWBAR LOCK LH GUARD UNDER BODY HAS BEEN RIPPED OFF	225,403

8/05/2025	ADELAIDE INDEPENDENT BANDAG	SUPPLY AND FIT TO RH FRONT 2X RIB TRAC ELITE BANDAG, OWN CASING	
16/06/2025	SCOTT CHRISTENSEN	CHECK ADJUST BRAKES WHEELBEARINGS CHECK ALL LIGHTS GREASE ALL POINTS	236,520
22/07/2025	SCOTT CHRISTENSEN	TRAILER SERVICE: CHECK AND ADJUST BRAKES AND WHEEL BEARINGS, CHECK ALL LIGHTS, GREASE ALL POINTS	247,681
28/08/2025	SCOTT CHRISTENSEN	TRAILER SERVICE, CHECK AND ADJUST BRAKE AND WHEEL BEARINGS, CHECK ALL LIGHTS, GREASE ALL POINTS, REPLACE 5X MISSING REFLECTORS, STTRAIGHTENED BENT LIGHT BAR, FIXERD HANGING MUDFLAP	257457
04.09.2025	SCOTT CHRISTENSEN	MECHANICS REPORT, REMOVE AND FIT NEW DRAWBAR BUSHES, RERMOVE BROKEN BRAKE HOSE AND REPLACE WITH NEW HOSE AND CLAMPS	258686
23.10.2025	SCOTT CHRISTENSEN	MECHANICS REPORT: TRAILER SERVCIE, CHECK AND ADJUST BRAKES AND WHEEL BEARINGS, CHECK ALL LIGHTS, GREASE ALL POINTS, REMOVE AND FITTED NEW NUMBER PLATE	270486
5/11/2025	ADELAIDE INDEPENDENT BANDAG	POSITION, LH REAR OUTER, STRIP AND FIT OUWN 11R22.5PARTWORN, REMOVE AND REPLACE WHEELS/TRYES. CASING FOR RETREADING	272922
13/11/2025	SCOTT CHRISTENSEN	MECHANICS REPORT: REMOVED AND REPLACED BLOWN FRONT AXLE BRAKE HOSES, REMOVED AND REPLACED LH SECON AXLE AIR BAG	275806
20/11/2025	ADELAIDE INDEPENDENT BANDAG	POSITION LH FRONT INNER & RH MIDDLE OUTER, REMOVE AND REPLACE WHEELS/TYRES- BOLT ON OWN 11R22.5 PARTWORN.EPA SCRAP TYRE DISPOSAL, CASING FOR RETREADING	278010
28/11/2025	SCOTT CHRISTENSEN	MECHANICS REPORT: TRAILER SERVICE: CHECK AND ADJUST BRAKES AND WHEEL BEARINGS, CHECK ALL LIGHTS, GREASE ALL POINTS. REMOVE AND FITTED NEW TARP CABLE TO LH SIDE, WELDED ON STOPPERS TO STOP CABLE BRACKET BENDING	281019
31/12/2025	ADELAIDE INDEPENDENT BANDAG	SUPPLY & FIT, FRONT AXLE 11R22.5 RIB TRAC ELITE BANDAG, 11R55.5 STOCK CASING, REMOVE & ROTATE RH FRONT AXLE TO RH MIDDLE, 170MM VALVE EXTENSION, CASING FOR RETREAD	288676
12/01/2026	ADELAIDE INDEPENDENT BANDAG	SERVICE CALL, POSITION RH MIDDLE INNER, PUNCTURE REPAIR-11R22.5, RAD 110TL RADIAL PATCH, REMOVE AND REPLACE WHEELS/TYRES	290135
12/01/2026	SCOTT CHRISTENSEN	TRAILER SERVCIE, CHECK AND ADJUST BRAKES AND WHEEL BEARINGS, CHECK ALL LIGHTS, GREASE ALL POINTS. REPLACED DRAW BAR LOCK RAM DUE TO BEING BROKEN, REMOVED AND REPLACED 3 X MUDFLAPS, STRAIGHTENED MUDFLAP BRACKER	292716
25/02/2026	SCOTT CHRISTENSEN	MECHANICS REPORT - TRUCK SERVCIE CHECK AND ADJUST BRAKES AND WHEEL BEARINGS, CHECK ALL LIGHTS, GREASE ALL POINTS	305188

10/03/2026	ADELAIDE INDEPENDENT BANDAG	POSITION: LH FRONT DRIVE, REMOVE AND REPLACE WHEELS/TYRES, NOTE: REMOVE WHEELS FROM FRONT DRIVE AXLE WITH TYRES FROM LH FRONT AXLE OF SB77M	306460
16/04/2026	ADELAIDE INDEPENDENT BANDAG	LH FRONT OUTER - FITTED OWN REPLACEMENT TYRE	
29/04/2026	SCOTT CHRISTENSEN	SERVICE- NHVR CHECKLIST COMPLETE	315,826
21/05/2026	ADELAIDE INDEPENDENT BANDAG	SERVICE CALL- SEE HYPERLINK	
28/07/2026	SCOTT CHRISTENSEN	TRAILER SERVICE -SEE LINK	328,259