

Number	Type	Date Open	Date Closed	Kilometres	HoursClose	Fuel Usage	Fault	Repairer / Notes	Cost / Invoice
R-8846	control valve	09/04/2025	09/04/2025		2,483	0		Internal Workshop - Field Service Removed and replaced 2 x belt control valves as they were leaking and jamming and cant get seal kits Supplied by finlay crushing screening	\$0.00
R-8714	HYD Hose	07/10/2025	07/08/2025	0	2,359	0		hosepower hosepwer replaced hyd hose	\$0.00
R-7889	control valve	09/06/2024	07/03/2025		2,351	0	9025	Internal Workshop - Field Service Removed and replaced speed control valve and tightened all lever caps Sourced new valve from finlay screening and crushing	\$0.00
R-7891	Welding Repa	09/06/2024	10/29/2024		2,326	0	9027	Internal Workshop - Fabrication Cracks repaired by rob	\$0.00
R-7890	Flashing light	09/06/2024	10/29/2024		2,326	0	9026	Internal Workshop - Field Service Flashing light fitted by a grade	\$0.00
R-8072	E Stop	10/23/2024	10/04/2024		2,326	0		A Grade Auto Repair REPAIRED BROKEN WIRE TO FRONT RHS E-STOP CIRCUIT.	\$0.00
R-7793	Scrapper bar	08/28/2024	08/28/2024		2,303	0		Internal Workshop - Field Service Adjust scrapper bar on feeder out feed Replace middle out feed fines scrapper paddles and adjust Parts sourced from Finlay screening and crushing actually done at 2265	\$0.00
S-5918	A - 250	11/10/2023	12/09/2023	0	2,250	0		needs new fuel primer, doesn't lock in Full service done when machine purchased on site at keppera All lanyards looked at with a grade Various grease lines changed Belt and roller guards put on where needed Added chains and dogs to fines belt frame for support with weight All screens and plates changed to produce the right product purchased from advanced engineering	\$0.00
S-5733	C - 1000	08/15/2023	09/04/2023	0	2,000	0		*Service was a d service but hours were already over from purchase. Actual service hours at 2197Hr put back to 2000Hr to reset and align*	\$0.00
R-5304	Flashing light	10/10/2022	09/01/2023	0	0	0	5448	Other. Flashing beacon. No flashing lights fitted as yet. Based on audit conducted by Jay on 1/9/23 this repair has been completed in the last 12 months.	\$0.00