



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GN51759
Decal Expiry Date: 2027-Mar-31
Inspection Number: 21935635

Inspection Result:

PASS

FACILITY: JOHNSON RADIATOR SERVICES LTD. / S20512
INSPECTOR: GILOWSKI, TRAVIS GORDON / 200472
WORK ORDER #: 232084
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Semi-annual
INSP. START: 2026-Sep-23 01:00 PM -07
INSP. COMPLETE: 2026-Sep-28 06:30 PM -07

VEHICLE JUR: British Columbia
PLATE #:
LICENCED GVW(kg): 999999
VEHICLE YEAR: 2005
MAKE: SUPERIOR
MODEL:
REGI: 03052752
UNIT/FLEET#: LT01A
BODY STYLE: LOGGING TRAILER
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2S9SL39265T008147
OWNER/LESSEE NAME: 4 EVERGREEN RESOURCES, 4EG
ADDRESS: PO BOX 45
Moberly Lake, British Columbia
V0C1X0, Canada

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Repaired (same day)	REPLACED AXLE 1 SUSPENSION BUSHINGS
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Repaired (same day)	REPAIRED AIR LEAK AT REAR RED GLADE HAND
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Not Applicable	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Repaired (same day)	REPLACED LEFT OUTER TAIL LIGHT
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Tire Tread Depth (mm)				Steering
						Outer L	Inner L	Inner R	Outer R	
1	Clamp	30	Automatic	40	40	11	12	10	11	
2	Clamp	30	Automatic	40	40	10	10	12	12	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	30	30
2	35	25

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	19	19
Lining (Shoe)	18	18

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: GILOWSKI, TRAVIS GORDON

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Sep-28 06:37 PM -07

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 26 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and managing inspection facilities). If you have any questions about the collection of this information, please contact the Sr. Manager, NSC/MV of the Commercial Vehicle Safety Branch.

CVSE014

9-28-2024 13:07 PM -07



Commercial Vehicle Inspection Report

Decal Number: GN51760
Decal Expiry Date: 2027-Mar-31
Inspection Number: 21935650

Inspection Result:
PASS

FACILITY: JOHNSON RADIATOR SERVICES LTD. / S20512
INSPECTOR: GILOWSKI, TRAVIS GORDON / 200472
WORK ORDER #: 232085
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Semi-annual
INSP. START: 2026-Sep-23 02:00 PM -07
INSP. COMPLETE: 2026-Sep-28 06:40 PM -07
VOI-2

VEHICLE JUR: British Columbia
PLATE #:
LICENCED GVW(kg): 999999
VEHICLE YEAR: 2005
MAKE: SUPERIOR
MODEL:
REGI: 03052739
UNIT/FLEET#: LT01B
BODY STYLE: LOGGING TRAILER
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2S9SB27285T008148
OWNER/LESSEE NAME: 4 EVERGREEN RESOURCES, 4EG
ADDRESS: PO BOX 45
Moberly Lake, British Columbia
V0C1X0, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	40	40	16	16	10	12	
2	Clamp	30	Automatic	40	40	16	16	16	16	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	20	30
2	65	40

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	18	18
Lining (Shoe)	13	15

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: GILOWSKI, TRAVIS GORDON

Road Test Date:
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Sep-28 06:45 PM -07

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 29 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorizing inspectors, and designating inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC-VI at the Canadian Council of Motor Vehicle Safety, Edmonton.

CVSE0114

9/28/2026 6:45:22 PM -07