



Commercial Vehicle Inspection Report

Decal Number: PA11568
Decal Expiry Date: 2026-Nov-30
Inspection Number: 21772417

Inspection Result:
PASS

FACILITY: NORTHERN B.C. TRUCKERS' / N5398
INSPECTOR: COX, JAMES EDWARD / 110895
WORK ORDER #:
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Semi-annual
INSP. START: 2026-May-14 10:18 AM MST
INSP. COMPLETE: 2026-May-14 11:20 AM MST

VEHICLE JUR: British Columbia
PLATE #:
LICENCED GVW(kg): 0
VEHICLE YEAR: 2018
MAKE: DOEPKER
MODEL:
REGI: 12658245
UNIT/FLEET#: 213
BODY STYLE: LOGGING TRAILER
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
VIN: 2DELGFM30J4038010
OWNER/LESSEE NAME: 4 EVERGREEN RESOURCES INC.
ADDRESS: 1717 Boucher lake rd box 45
Moberly Lake, British Columbia
V0C1X0, Canada

V01-3

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Repaired (same day) Replaced axle 2 right shock
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) Tighten bunk bolt #5 right side
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	42	40	11	8	6	7	
2	Clamp	30	Automatic	40	38	13	9	10	8	
3	Clamp	30	Automatic	42	40	6	5	10	11	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	46	50
2	48	24
3	72	60

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	18	18
Lining (Shoe)	18	20
Lining (Shoe)	14	17

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: COX, JAMES EDWARD
Road Test Date:
Signature:
Road Tester:

This Inspection Report was submitted to CVSE on 2026-May-14 11:39 AM MST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCV/P at the Commercial Vehicle Safety Enforcement.

CVSE0014
5/14/2026 11:39:34 AM MST