



Commercial Vehicle Inspection Report

Decal Number: PA11569
Decal Expiry Date: 2026-Nov-30
Inspection Number: 21772412

Inspection Result:

PASS

Air Brake Camshaft Rotation (degrees)

Axes	Left	Right
1	42	58
2	60	36
3	45	82
4	68	62

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	18	17
Lining (Shoe)	16	19
Lining (Shoe)	18	13
Lining (Shoe)	15	16

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Inspector: COX, JAMES EDWARD

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026-May-14 11:34 AM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCV at the Commercial Vehicle Safety Enforcement.

CV 560014

5/14/2026 11:34:06 AM MST



Commercial Vehicle Inspection Report

Decal Number: PA11569
Decal Expiry Date: 2026-Nov-30
Inspection Number: 21772412

Inspection Result:

PASS

FACILITY: NORTHERN B.C. TRUCKERS' /
N5398
INSPECTOR: COX, JAMES EDWARD / 110895
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW
5501 kg or more
INSP. REASON: Semi-annual

INSP. START: 2026-May-14 08:55 AM MST
INSP. COMPLETE: 2026-May-14 10:18 AM MST

VEHICLE JUR: British Columbia
PLATE #:
LICENCED GVW(kg): 63500
VEHICLE YEAR: 2022
MAKE: WESTERN ST
MODEL:

REGI: 13726759
UNIT/FLEET#: 197
BODY STYLE: Truck Tractor
ODOMETER: 327659 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 5KKPBWD15NLNJB284
OWNER/LESSEE NAME: 4 EVERGREEN RESOURCES INC.,
ADDRESS: 1717 BOUCHER LAKE RD, Box 45
Moberly Lake, British Columbia
V0C1X0, Canada

VDI-4

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24	Automatic	36	34
2	Clamp	30L	Automatic	42	50
3	Clamp	30L	Automatic	40	48
4	Clamp	30L	Automatic	45	40

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
12			12	✓
15	15	11	14	
14	13	13	14	
13	13	11	12	

Comment:

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement.

CV SED014

5/14/2026 11:24:06 AM MST