

FIRST SCHEDULE: PART 1



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours
Address P.O.Box 609 (78 Sturt Street) Mount Gambler
Registration Number SB61GM
Date 23.8.2017
Odometer 293540352 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the **CODE OF PRACTICE FOR BUSES**

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓			
Wheels for Condition	✓			
Tyres for Correct Pressure	✓			
Tyre Tread for Condition & Depth	✓			
Tyre Walls (without wheel removal) for Damage	✓			
Tyre Construction for Correct Location	✓			
BRAKES				
Service & Parking Brake for Correct Operation	✓			
Brake System for Air Leaks	✓			
Drain Valves for Operation	✓			
Hydraulic Fluid for Level & Leaks	✓			
Brake Warning System for Operation	✓			
ABS & EBS Warning System for Operation	✓			
BATTERY				
Battery Terminals & Cables for Condition	✓			
Battery & Battery Carrier Security	✓			
GENERAL				
Power Steering System Leaks	✓			
Engine for Oil & Water Leaks	✓			
Exhaust System for Condition, Security & Efficiency	✓			
Gearbox & Differential Oil Leaks	✓			
Fuel System Leaks	✓			
BODY				
Glazing Condition	✓			
Body Exterior for Damage & Dangerous Projections	✓			
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			
Rear Vision Mirrors for Security & Condition	✓			
Passenger Access Doors for Security & Operation	✓			
Seats for Security	✓			
Steps, Floor & Hatches for Security & Condition	✓			
Fire Extinguisher for Presence & in Service Date	✓			
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			
Dash Lights, Step, Interior & Destination Lights for Operation	✓			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓			
Gear & Clutch Controls for Correct Operation	✓			
Steering System for Free Play & Slackness	✓			
Windscreen Wipers for Operation & Condition	✓			
Windscreen Washers for Operation	✓			
Demister for Operation	✓			
Horn for Operation	✓			

ADIFANS TRUCKS ADELAIDE PT LTD
 DANIEL TRUCKS MOUNT GAMBLER

Inspection Undertaken by Michael Signed no name Date 23/8/17

*This form must be kept for a period of at least six (6) months after the inspection.

FIRST SCHEDULE: PART 1



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours
Address P.O.Box 609 (78 Sturt Street) Mount Gambier
Registration Number SB61GM
Date 13 11 2017
Odometer 42645 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓			
Wheels for Condition	✓			
Tyres for Correct Pressure	✓			
Tyre Tread for Condition & Depth	✓			
Tyre Walls (without wheel removal) for Damage	✓			
Tyre Construction for Correct Location	✓			
BRAKES				
Service & Parking Brake for Correct Operation	✓			
Brake System for Air Leaks	✓			
Drain Valves for Operation	✓			
Hydraulic Fluid for Level & Leaks	✓			
Brake Warning System for Operation	✓			
ABS & EBS Warning System for Operation	✓			
BATTERY				
Battery Terminals & Cables for Condition	✓			
Battery & Battery Carrier Security	✓			
GENERAL				
Power Steering System Leaks	✓			
Engine for Oil & Water Leaks	✓			
Exhaust System for Condition, Security & Efficiency	✓			
Gearbox & Differential Oil Leaks	✓			
Fuel System Leaks	✓			
BODY				
Glazing Condition	✓			
Body Exterior for Damage & Dangerous Projections	✓			
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			
Rear Vision Mirrors for Security & Condition	✓			
Passenger Access Doors for Security & Operation	✓			
Seats for Security	✓			
Steps, Floor & Hatches for Security & Condition	✓			
Fire Extinguisher for Presence & in Service Date	✓			
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			
Dash Lights, Step, Interior & Destination Lights for Operation	✓			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓			
Gear & Clutch Controls for Correct Operation	✓			
Steering System for Free Play & Slackness	✓			
Windscreen Wipers for Operation & Condition	✓			
Windscreen Washers for Operation	✓			
Demister for Operation	✓			
Horn for Operation	✓			

Inspection Undertaken by JAMIE McROSE Signed [Signature] Date 13.11.17

*This form must be kept for a period of at least six (6) months after the inspection.

STRANS TRUCKS ADELAIDE PTY LTD
STRANS TRUCKS MOUNT GAMBIER

FIRST SCHEDULE: PART 1



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours
Address P.O.Box 609 (78 Sturt Street) Mount Gambier
Registration Number SB61GM
Date 19.02.18
Odometer 44558 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓			
Wheels for Condition	✓			
Tyres for Correct Pressure	✓			
Tyre Tread for Condition & Depth	✓			
Tyre Walls (without wheel removal) for Damage	✓			
Tyre Construction for Correct Location	✓			
BRAKES				
Service & Parking Brake for Correct Operation	✓			
Brake System for Air Leaks		-		
Drain Valves for Operation		-		
Hydraulic Fluid for Level & Leaks	✓			
Brake Warning System for Operation	✓			
ABS & EBS Warning System for Operation	✓			
BATTERY				
Battery Terminals & Cables for Condition	✓			
Battery & Battery Carrier Security	✓			
GENERAL				
Power Steering System Leaks	✓			
Engine for Oil & Water Leaks	✓			
Exhaust System for Condition, Security & Efficiency	✓			
Gearbox & Differential Oil Leaks	✓			
Fuel System Leaks	✓			
BODY				
Glazing Condition	✓			
Body Exterior for Damage & Dangerous Projections	✓			
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			
Rear Vision Mirrors for Security & Condition	✓			
Passenger Access Doors for Security & Operation	✓			
Seats for Security	✓			
Steps, Floor & Hatches for Security & Condition	✓			
Fire Extinguisher for Presence & in Service Date	✓			
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			
Dash Lights, Step, Interior & Destination Lights for Operation	✓			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓			
Gear & Clutch Controls for Correct Operation	✓			
Steering System for Free Play & Slackness	✓			
Windscreen Wipers for Operation & Condition	✓			
Windscreen Washers for Operation	✓			
Demister for Operation	✓			
Horn for Operation	✓			

Inspection Undertaken by *mickell* Signed *mickell* Date 19.2.18

*This form must be kept for a period of at least six (6) months after the inspection.

FIRST SCHEDULE



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours
Address P.O.Box 609 (78 Sturt Street) Mount Gambier
Registration Number SB61GM
Date 20 04 2018
Odometer 46149 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓			
Wheels for Condition	✓			
Tyres for Correct Pressure	✓			
Tyre Tread for Condition & Depth	✓			
Tyre Walls (without wheel removal) for Damage	✓			
Tyre Construction for Correct Location	✓			
BRAKES				
Service & Parking Brake for Correct Operation	✓			
Brake System for Air Leaks	✓			
Drain Valves for Operation	✓			
Hydraulic Fluid for Level & Leaks	✓			
Brake Warning System for Operation	✓			
ABS & EBS Warning System for Operation	✓			
BATTERY				
Battery Terminals & Cables for Condition	✓			
Battery & Battery Carrier Security	✓			
GENERAL				
Power Steering System Leaks	✓			
Engine for Oil & Water Leaks	✓			
Exhaust System for Condition, Security & Efficiency	✓			
Gearbox & Differential Oil Leaks	✓			
Fuel System Leaks	✓			
BODY				
Glazing Condition	✓			
Body Exterior for Damage & Dangerous Projections	✓			
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			
Rear Vision Mirrors for Security & Condition	✓			
Passenger Access Doors for Security & Operation	✓			
Seats for Security	✓			
Steps, Floor & Hatches for Security & Condition	✓			
Fire Extinguisher for Presence & in Service Date	✓			
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			
Dash Lights, Step, Interior & Destination Lights for Operation	✓			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓			
Gear & Clutch Controls for Correct Operation	✓			
Steering System for Free Play & Slackness	✓			
Windscreen Wipers for Operation & Condition	✓			
Windscreen Washers for Operation	✓			
Demister for Operation	✓			
Horn for Operation	✓			

Inspection Undertaken by ROLAND Signed LB Date 20/04/2018

ADTRANS TRUCKS ADELAIDE PTY LTD

*This form must be kept for a period of at least six (6) months after the inspection. ER TRUCKS MOUNT GAMBIER

FIRST SCHEDULE: PART 2



Government of South Australia
 Department of Planning,
 Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 2

Vehicle Inspections
 PO BOX 1533
 ADELAIDE SA 5001

MR 1090
 07/16

Company / Owner Lake City Tours
Address P.O. Box 609 (78 Sturt Street) Mount Gambier
Registration Number SB61GM
Date 13 11 2017 **Odometer** 42645 km

INSPECTION SHEET NUMBER 2

To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
SUSPENSION				
"U" Bolts & Centre Bolts for Security & Condition	✓			
Radius Rods & Joints for Condition	✓			
Front & Rear Axle Mounts for Condition & Cracks	✓			
Springs & Shackles for Condition	✓			
Shock Absorber & Joints for Condition	✓			
Air Bag System for Condition	✓			
BRAKES				
Brake Lines & Mounts for Condition	✓			
Slack Adjusters & Auto Adjusters for Operation & Condition	✓			
Brake Linings for Wear & Contamination	✓			
Air Filter for Security & Cleanliness	✓			
Air Priority System for Operation	✓			
Air or Vacuum for Correct Build Up Time	✓			
Retarder & Exhaust Brake for Operation & Control	✓			
STEERING				
Steering Box for Security & Operation	✓			
Steering System for Condition & Play	✓			
Steering Wheel & Column for Play & Security	✓			
GENERAL				
Engine Insulating Material for Contamination & Security	✓			
Starter Motor for Security	✓			
Tail Shafts & Guards for Condition & Security	✓			
Universal Joints & Splines for Condition	✓			
Fuel Tank & Fuel System for Security	✓			
Wheel Bearings for Adjustment	✓			
Axle Hub Seals for Leaks	✓			
Seat Belt Condition & Operation	✓			
Door Interlocks for Correct Operation (if fitted)	✓			
BODY				
Body Mounts Attachments for Security & Condition	✓			
Body for Visual Structural Defects & Corrosion	✓			

Inspection Undertaken by JAMIE MCDONNELL Signed [Signature] Date 13.11.17.

ADTRANS TRUCKS ADELAIDE PTY LTD
 T/A DAIMLER TRUCKS MOUNT GAMBIER

*This form must be kept for a period of at least one (1) year after the inspection.

FIRST SCHEDULE PART 2



Government of South Australia
 Department of Planning,
 Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 2

Vehicle Inspections
 PO BOX 1533
 ADELAIDE SA 5001

MR 1090
 07/16

Company / Owner Lake City Tours **Registration Number**
Address P.O. Box 609 (78 Sturt Street) Mount Gambier **SB61GM**

Date 20 04 2018 **Odometer** 46149 km

INSPECTION SHEET NUMBER 2

To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
SUSPENSION				
"U" Bolts & Centre Bolts for Security & Condition	✓			
Radius Rods & Joints for Condition	✓			
Front & Rear Axle Mounts for Condition & Cracks	✓			
Springs & Shackles for Condition	✓			
Shock Absorber & Joints for Condition	✓			
Air Bag System for Condition	-			
BRAKES				
Brake Lines & Mounts for Condition	✓			
Slack Adjusters & Auto Adjusters for Operation & Condition	✓			
Brake Linings for Wear & Contamination	✓			
Air Filter for Security & Cleanliness	✓			
Air Priority System for Operation	✓			
Air or Vacuum for Correct Build Up Time	✓			
Retarder & Exhaust Brake for Operation & Control	✓			
STEERING				
Steering Box for Security & Operation	✓			
Steering System for Condition & Play	✓			
Steering Wheel & Column for Play & Security	✓			
GENERAL				
Engine Insulating Material for Contamination & Security	✓			
Starter Motor for Security	✓			
Tail Shafts & Guards for Condition & Security	✓			
Universal Joints & Splines for Condition	✓			
Fuel Tank & Fuel System for Security	✓			
Wheel Bearings for Adjustment	✓			
Axle Hub Seals for Leaks	✓			
Seat Belt Condition & Operation	✓			
Door Interlocks for Correct Operation (if fitted)	-			
BODY				
Body Mounts Attachments for Security & Condition	✓			
Body for Visual Structural Defects & Corrosion	✓			

Inspection Undertaken by Edwards Signed KG Date 20/04/2018

*This form must be kept for a period of at least one (1) year after the inspection. ADTRANS TRUCKS ADELAIDE PTY LTD
 T/A DAIMLER TRUCKS MOUNT GAMBIER

FIRST SCHEDULE: PART 1



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours
Address P.O.Box 609 (78 Sturt Street) Mount Gambier
Registration Number ~~CB68LP~~ **SBB1CM**
Date 20.8.2018 **Odometer** 48715 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓			
Wheels for Condition	✓			
Tyres for Correct Pressure	✓			
Tyre Tread for Condition & Depth	✓			
Tyre Walls (without wheel removal) for Damage	✓			
Tyre Construction for Correct Location	✓			
BRAKES				
Service & Parking Brake for Correct Operation		X	20.8.18	S.B.L.
Brake System for Air Leaks	N/A			
Drain Valves for Operation	N/A			
Hydraulic Fluid for Level & Leaks	✓			
Brake Warning System for Operation	✓			
ABS & EBS Warning System for Operation	✓			
BATTERY				
Battery Terminals & Cables for Condition	✓			
Battery & Battery Carrier Security	✓			
GENERAL				
Power Steering System Leaks	✓			
Engine for Oil & Water Leaks	✓			
Exhaust System for Condition, Security & Efficiency	✓			
Gearbox & Differential Oil Leaks	✓			
Fuel System Leaks	✓			
BODY				
Glazing Condition	✓			
Body Exterior for Damage & Dangerous Projections	✓			
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			
Rear Vision Mirrors for Security & Condition	✓			
Passenger Access Doors for Security & Operation	✓			
Seats for Security	✓			
Steps, Floor & Hatches for Security & Condition	✓			
Fire Extinguisher for Presence & in Service Date	✓			
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			
Dash Lights, Step, Interior & Destination Lights for Operation	✓			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓			
Gear & Clutch Controls for Correct Operation	N/A			
Steering System for Free Play & Slackness	✓			
Windscreen Wipers for Operation & Condition		X	20.8.18	S.B.L.
Windscreen Washers for Operation	✓			
Demister for Operation	✓			
Horn for Operation	✓			

Inspection Undertaken by Simon Chisham Signed S.B.L. Date 20.8.18

*This form must be kept for a period of at least six (6) months after the inspection.

FIRST SCHEDULE: PART 1



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours Registration Number SB61GM
Address P.O.Box 609 (78 Sturt Street) Mount Gambier
Date 27.11.2018 Odometer 51621 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓			
Wheels for Condition	✓			
Tyres for Correct Pressure	✓			
Tyre Tread for Condition & Depth	✓			
Tyre Walls (without wheel removal) for Damage	✓			
Tyre Construction for Correct Location	✓			
BRAKES				
Service & Parking Brake for Correct Operation	✓			
Brake System for Air Leaks	✓			
Drain Valves for Operation	✓			
Hydraulic Fluid for Level & Leaks	✓			
Brake Warning System for Operation	✓			
ABS & EBS Warning System for Operation	✓			
BATTERY				
Battery Terminals & Cables for Condition	✓			
Battery & Battery Carrier Security	✓			
GENERAL				
Power Steering System Leaks		X	27/2/19	JB
Engine for Oil & Water Leaks	✓			
Exhaust System for Condition, Security & Efficiency	✓			
Gearbox & Differential Oil Leaks	✓			
Fuel System Leaks	✓			
BODY				
Glazing Condition	✓			
Body Exterior for Damage & Dangerous Projections	✓			
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			
Rear Vision Mirrors for Security & Condition	✓			
Passenger Access Doors for Security & Operation	✓			
Seats for Security	✓			
Steps, Floor & Hatches for Security & Condition	✓			
Fire Extinguisher for Presence & in Service Date	✓			
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			
Dash Lights, Step, Interior & Destination Lights for Operation	✓			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓			
Gear & Clutch Controls for Correct Operation	M/A			
Steering System for Free Play & Slackness	✓			
Windscreen Wipers for Operation & Condition	✓			
Windscreen Washers for Operation	✓			
Demister for Operation	✓			
Horn for Operation	✓			

Inspection Undertaken by ADTRANS TRUCKS ADELAIDE PTY LTD Signed [Signature] Date 27.11.2018
T/A DAMLER TRUCKS MOUNT GAMBIER

*This form must be kept for a period of at least six (6) months after the inspection.

FIRST SCHEDULE: PART 1



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours Registration Number SB61GM
Address P.O.Box 609 (78 Sturt Street) Mount Gambier
Date 25 2 2019 Odometer 53195 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓			
Wheels for Condition	✓	X	29/4/19	Trident
Tyres for Correct Pressure	✓			
Tyre Tread for Condition & Depth	✓	X	29/4/19	Trident
Tyre Walls (without wheel removal) for Damage	✓			
Tyre Construction for Correct Location	✓			
BRAKES				
Service & Parking Brake for Correct Operation	✓			
Brake System for Air Leaks	N/A			
Drain Valves for Operation	N/A			
Hydraulic Fluid for Level & Leaks	✓			
Brake Warning System for Operation	✓			
ABS & EBS Warning System for Operation	✓			
BATTERY				
Battery Terminals & Cables for Condition	✓			
Battery & Battery Carrier Security	✓			
GENERAL				
Power Steering System Leaks	✓			
Engine for Oil & Water Leaks	✓			
Exhaust System for Condition, Security & Efficiency	✓			
Gearbox & Differential Oil Leaks	✓			
Fuel System Leaks	✓			
BODY				
Glazing Condition	✓			
Body Exterior for Damage & Dangerous Projections	✓			
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			
Rear Vision Mirrors for Security & Condition	✓			
Passenger Access Doors for Security & Operation	✓			
Seats for Security	✓			
Steps, Floor & Hatches for Security & Condition	✓			
Fire Extinguisher for Presence & in Service Date	✓			
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			
Dash Lights, Step, Interior & Destination Lights for Operation	✓			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓			
Gear & Clutch Controls for Correct Operation	N/A			
Steering System for Free Play & Slackness	✓			
Windscreen Wipers for Operation & Condition	✓	X	28-2-19	M.DANILLO
Windscreen Washers for Operation	✓			
Demister for Operation	✓			
Horn for Operation	✓			

T/A DAIMLER TRUCKS ADELAIDE PTY LTD
MOUNT GAMBIER

Inspection Undertaken by M.DANILLO Signed, _____ Date 25.2.19

*This form must be kept for a period of at least six (6) months after the inspection.

FIRST SCHEDULE: PART 1



Government of South Australia
 Department of Planning,
 Transport and Infrastructure

**Code of Practice for Buses
 Mandatory Maintenance
 Procedure Part 1**

Vehicle Inspections
 PO BOX 1533
 ADELAIDE SA 5001

MR 1090
 07/16

Company / Owner Lake City Tours
Address P.O.Box 609 (78 Sturt Street) Mount Gambier

Registration Number
 SB61GM

Date 22 03 19 **Odometer** 53845 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓			
Wheels for Condition	✓			
Tyres for Correct Pressure	✓			
Tyre Tread for Condition & Depth	✓	X	29/4/19	Trident
Tyre Walls (without wheel removal) for Damage	✓			
Tyre Construction for Correct Location	✓			
BRAKES				
Service & Parking Brake for Correct Operation	✓			
Brake System for Air Leaks	✓			
Drain Valves for Operation	✓			
Hydraulic Fluid for Level & Leaks	✓			
Brake Warning System for Operation	✓			
ABS & EBS Warning System for Operation	✓			
BATTERY				
Battery Terminals & Cables for Condition	✓			
Battery & Battery Carrier Security	✓			
GENERAL				
Power Steering System Leaks	✓			
Engine for Oil & Water Leaks	✓			
Exhaust System for Condition, Security & Efficiency	✓			
Gearbox & Differential Oil Leaks	✓			
Fuel System Leaks	✓			
BODY				
Glazing Condition	✓			
Body Exterior for Damage & Dangerous Projections	✓			
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			
Rear Vision Mirrors for Security & Condition	✓			
Passenger Access Doors for Security & Operation	✓			
Seats for Security	✓			
Steps, Floor & Hatches for Security & Condition	✓			
Fire Extinguisher for Presence & in Service Date	✓			
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			
Dash Lights, Stop, Interior & Destination Lights for Operation	✓			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓			
Gear & Clutch Controls for Correct Operation	✓			
Steering System for Free Play & Slackness	✓			
Windscreen Wipers for Operation & Condition	✓			
Windscreen Washers for Operation	✓			
Demister for Operation	✓			
Horn for Operation	✓			

Inspection Undertaken by Signed *M.A. Man* Date 22 3 19

*This form must be kept for a period of at least six (6) months after the inspection.

FIRST SCHEDULE: PART 1



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner
Address

Lake city fours

Registration Number

SB61GM

Date *26. 4. 2019*

Odometer

54437 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓			
Wheels for Condition	✓			
Tyres for Correct Pressure	✓			
Tyre Tread for Condition & Depth	✓	x	<i>29/4/19</i>	<i>Trident</i>
Tyre Walls (without wheel removal) for Damage	✓			
Tyre Construction for Correct Location	✓			
BRAKES				
Service & Parking Brake for Correct Operation	✓			
Brake System for Air Leaks	<i>mlc</i> N/A			
Drain Valves for Operation	<i>mlc</i> N/A			
Hydraulic Fluid for Level & Leaks	✓			
Brake Warning System for Operation	✓			
ABS & EBS Warning System for Operation	✓			
BATTERY				
Battery Terminals & Cables for Condition	✓			
Battery & Battery Carrier Security	✓			
GENERAL				
Power Steering System Leaks	✓			
Engine for Oil & Water Leaks	✓			
Exhaust System for Condition, Security & Efficiency	✓			
Gearbox & Differential Oil Leaks	✓			
Fuel System Leaks	✓			
BODY				
Glazing Condition	✓			
Body Exterior for Damage & Dangerous Projections	✓			
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			
Rear Vision Mirrors for Security & Condition	✓			
Passenger Access Doors for Security & Operation	✓			
Seats for Security	✓			
Steps, Floor & Hatches for Security & Condition	✓			
Fire Extinguisher for Presence & in Service Date	✓			
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			
Dash Lights, Step, Interior & Destination Lights for Operation	✓			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓			
Gear & Clutch Controls for Correct Operation	N/A			
Steering System for Free Play & Slackness	✓			
Windscreen Wipers for Operation & Condition	✓			
Windscreen Washers for Operation	✓			
Demister for Operation	✓			
Horn for Operation	✓			

MOUNT GAMBIER
ISUZU & IVECO

203 Jubilee Hwy West
Mount Gambier SA 5290
Ph: 08 8725 7999
Fax: 08 8724 9712
ABN: 28 415 355 833

Inspection Undertaken by *Chris*

Signed *Wane* Date *26/4/19*

*This form must be kept for a period of at least six (6) months after the inspection.

FIRST SCHEDULE: PART 2



Government of South Australia
Department of Planning, Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 2

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours
Address P.O. Box 609 (78 Sturt Street) Mount Gambier

Registration Number
SB61GM

Date 20 8 2018

Odometer 48715 km

INSPECTION SHEET NUMBER 2

To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first
All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Table with columns: Item, Satisfactory (Yes/No), Rectified (Date/Signed). Rows include SUSPENSION, BRAKES, STEERING, GENERAL, and BODY sections.

Inspection Undertaken by Simon Chisholm Signed [Signature] Date 20/8/2018

*This form must be kept for a period of at least one (1) year after the inspection.

FIRST SCHEDULE: PART 2



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 2

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours **Registration Number**
Address P.O. Box 609 (78 Sturt Street) Mount Gambier SB61GM
Date 27.11.2018 **Odometer** 51621 km

INSPECTION SHEET NUMBER 2

To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
SUSPENSION				
"U" Bolts & Centre Bolts for Security & Condition	✓			
Radius Rods & Joints for Condition	✓			
Front & Rear Axle Mounts for Condition & Cracks	✓			
Springs & Shackles for Condition	✓			
Shock Absorber & Joints for Condition	✓			
Air Bag System for Condition	N/A			
BRAKES				
Brake Lines & Mounts for Condition	✓			
Slack Adjusters & Auto Adjusters for Operation & Condition	N/A			
Brake Linings for Wear & Contamination	✓			
Air Filter for Security & Cleanliness	✓			
Air Priority System for Operation	✓			
Air or Vacuum for Correct Build Up Time	✓			
Retarder & Exhaust Brake for Operation & Control	✓			
STEERING				
Steering Box for Security & Operation	✓			
Steering System for Condition & Play	✓			
Steering Wheel & Column for Play & Security	✓			
GENERAL				
Engine Insulating Material for Contamination & Security	✓			
Starter Motor for Security	✓			
Tail Shafts & Guards for Condition & Security	✓			
Universal Joints & Splines for Condition	✓			
Fuel Tank & Fuel System for Security	✓			
Wheel Bearings for Adjustment	✓			
Axle Hub Seals for Leaks	✓			
Seat Belt Condition & Operation	✓			
Door Interlocks for Correct Operation (if fitted)	✓			
BODY				
Body Mounts Attachments for Security & Condition	✓			
Body for Visual Structural Defects & Corrosion	✓			

ADTRANS TRUCKS ADELAIDE PTY LTD
T/A DAIMLER TRUCKS MOUNT GAMBIER

Inspection Undertaken by [Signature] Date 27.11.2018

*This form must be kept for a period of at least one (1) year after the inspection.

FIRST SCHEDULE: PART 2



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 2

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours
Address P.O. Box 609 (78 Sturt Street) Mount Gambier

Registration Number
SB61GM

Odometer 53195 km

Date 25 2 2019

INSPECTION SHEET NUMBER 2

To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first
• All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
SUSPENSION				
"U" Bolts & Centre Bolts for Security & Condition	/			
Radius Rods & Joints for Condition	/			
Front & Rear Axle Mounts for Condition & Cracks	/			
Springs & Shackles for Condition	/			
Shock Absorber & Joints for Condition	/			
Air Bag System for Condition	N/A			
BRAKES				
Brake Lines & Mounts for Condition	/			
Slack Adjusters & Auto Adjusters for Operation & Condition	N/A			
Brake Linings for Wear & Contamination	/			
Air Filter for Security & Cleanliness	/			
Air Priority System for Operation	/			
Air or Vacuum for Correct Build Up Time	/			
Retarder & Exhaust Brake for Operation & Control	/			
STEERING				
Steering Box for Security & Operation	/			
Steering System for Condition & Play	/			
Steering Wheel & Column for Play & Security	/			
GENERAL				
Engine Insulating Material for Contamination & Security	/			
Starter Motor for Security	/			
Tail Shafts & Guards for Condition & Security	/			
Universal Joints & Splines for Condition	/			
Fuel Tank & Fuel System for Security	/			
Wheel Bearings for Adjustment	/			
Axle Hub Seals for Leaks	/			
Seat Belt Condition & Operation	/			
Door Interlocks for Correct Operation (if fitted)	/			
BODY				
Body Mounts Attachments for Security & Condition	/			
Body for Visual Structural Defects & Corrosion	/			

ADTRANS TRUCKS ADELAIDE PTY LTD Inspection Undertaken by M. DANIELLO Signed... Date 25/2/19

*This form must be kept for a period of one (1) year after the inspection.

FIRST SCHEDULE: PART 2



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 2

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake city buses Registration Number SBB19M
Address
Date 26 4 2019 Odometer 54437 km

INSPECTION SHEET NUMBER 2

To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
SUSPENSION				
"U" Bolts & Centre Bolts for Security & Condition	✓			
Radius Rods & Joints for Condition	✓			
Front & Rear Axle Mounts for Condition & Cracks	✓			
Springs & Shackles for Condition	✓			
Shock Absorber & Joints for Condition	✓			
Air Bag System for Condition	N/A	N/A		
BRAKES				
Brake Lines & Mounts for Condition	✓			
Slack Adjusters & Auto Adjusters for Operation & Condition	N/A	N/A		
Brake Linings for Wear & Contamination	✓			
Air Filter for Security & Cleanliness	✓			
Air Priority System for Operation	N/A	N/A		
Air or Vacuum for Correct Build Up Time	✓			
Retarder & Exhaust Brake for Operation & Control	✓			
STEERING				
Steering Box for Security & Operation	✓			
Steering System for Condition & Play	✓			
Steering Wheel & Column for Play & Security	✓			
GENERAL				
Engine Insulating Material for Contamination & Security	✓			
Starter Motor for Security	✓			
Tail Shafts & Guards for Condition & Security	✓			
Universal Joints & Splines for Condition	✓			
Fuel Tank & Fuel System for Security	✓			
Wheel Bearings for Adjustment	✓			
Axle Hub Seals for Leaks	✓			
Seat Belt Condition & Operation	✓			
Door Interlocks for Correct Operation (if fitted)	✓			
BODY				
Body Mounts Attachments for Security & Condition	✓			
Body for Visual Structural Defects & Corrosion	✓			
MOUNT GAMBIER ISUZU & IVECO 203 Jubilee Hwy West Mount Gambier SA 5290 Ph: 08 8725 7999 Fax: 08 8724 9712 ABN: 28 415 355 833				

Inspection Undertaken by Chris Signed [Signature] Date 26/4/19

*This form must be kept for a period of at least one (1) year after the inspection.

FIRST SCHEDULE: PART 1



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours Registration Number SB61GM
Address P.O. Box 609, (78 Sturt Street)
Mount Gambier 5290
Date 6. 8. 2019 Odometer 56804 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓		6-8-19	BRS
Wheels for Condition	✓		6-8-19	BRS
Tyres for Correct Pressure	✓		6-8-19	BRS
Tyre Tread for Condition & Depth	✓		6-8-19	BRS
Tyre Walls (without wheel removal) for Damage	✓			BRS
Tyre Construction for Correct Location				
BRAKES				
Service & Parking Brake for Correct Operation	✓			BRS
Brake System for Air Leaks	N/A			
Drain Valves for Operation	N/A			
Hydraulic Fluid for Level & Leaks	✓			BRS
Brake Warning System for Operation	✓			BRS
ABS & EBS Warning System for Operation	✓			BRS
BATTERY				
Battery Terminals & Cables for Condition	✓			BRS
Battery & Battery Carrier Security	✓			BRS
GENERAL				
Power Steering System Leaks	✓			BRS
Engine for Oil & Water Leaks	✓			BRS
Exhaust System for Condition, Security & Efficiency	✓			BRS
Gearbox & Differential Oil Leaks	✓			BRS
Fuel System Leaks	✓			BRS
BODY				
Glazing Condition	✓			BRS
Body Exterior for Damage & Dangerous Projections	✓			BRS
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			BRS
Rear Vision Mirrors for Security & Condition	✓			BRS
Passenger Access Doors for Security & Operation	✓			BRS
Seats for Security	✓			BRS
Steps, Floor & Hatches for Security & Condition	✓			BRS
Fire Extinguisher for Presence & in Service Date	✓			BRS
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			BRS
Dash Lights, Step, Interior & Destination Lights for Operation	✓			BRS
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓			BRS
Gear & Clutch Controls for Correct Operation	✓			BRS
Steering System for Free Play & Slackness	✓			BRS
Windscreen Wipers for Operation & Condition	✓			BRS
Windscreen Washers for Operation	✓			BRS
Demister for Operation	✓			BRS
Horn for Operation	✓			BRS

Inspection Undertaken by BROCK Signed BRS Date 6.8.19

*This form must be kept for a period of at least six (6) months after the inspection.

FIRST SCHEDULE: PART 1



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours
Address P.O. Box 609, (78 Sturt Street)
Mount Gambier 5290
Registration Number SB61GM
Date 28-11-19
Odometer 60,856 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS	✓			
Wheel Nuts for Tightness	✓			
Wheels for Condition	✓			
Tyres for Correct Pressure	✓			
Tyre Tread for Condition & Depth	✓			
Tyre Walls (without wheel removal) for Damage	✓			
Tyre Construction for Correct Location				
BRAKES	✓			
Service & Parking Brake for Correct Operation	✓			
Brake System for Air Leaks	✓			
Drain Valves for Operation	✓			
Hydraulic Fluid for Level & Leaks	✓			
Brake Warning System for Operation	✓			
ABS & EBS Warning System for Operation				
BATTERY	✓			
Battery Terminals & Cables for Condition	✓			
Battery & Battery Carrier Security				
GENERAL				
Power Steering System Leaks	✓			
Engine for Oil & Water Leaks	✓			
Exhaust System for Condition, Security & Efficiency	✓			
Gearbox & Differential Oil Leaks	✓			
Fuel System Leaks				
BODY	✓			
Glazing Condition	✓			
Body Exterior for Damage & Dangerous Projections	✓			
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			
Rear Vision Mirrors for Security & Condition	✓			
Passenger Access Doors for Security & Operation	✓			
Seats for Security	✓			
Steps, Floor & Hatches for Security & Condition	✓			
Fire Extinguisher for Presence & in Service Date				
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			
Dash Lights, Step, Interior & Destination Lights for Operation	✓			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓			
Gear & Clutch Controls for Correct Operation	✓			
Steering System for Free Play & Slackness	✓			
Windscreen Wipers for Operation & Condition	✓			
Windscreen Washers for Operation	✓			
Demister for Operation	✓			
Horn for Operation	✓			

ADTRANS TRUCKS ADELAIDE PTY LTD
 201A Jubilee Hwy
 Mount Gambier SA 5290
 Telephone: 08 8725 3932
 ABN: 45 151 699 651

Inspection Undertaken by Liam Telford Signed [Signature] Date 28.11.19

*This form must be kept for a period of at least six (6) months after the inspection.

FIRST SCHEDULE: PART 1



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours * **Registration Number** SB61GM
Address P.O. Box 609, (78 Sturt Street)
Mount Gambier 5290
Date 24 3 20 **Odometer** 61692 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓			
Wheels for Condition	✓			left hand rear low
Tyres for Correct Pressure	✓			
Tyre Tread for Condition & Depth	✓			
Tyre Walls (without wheel removal) for Damage	✓			
Tyre Construction for Correct Location	✓			
BRAKES				
Service & Parking Brake for Correct Operation	✓			
Brake System for Air Leaks	N/A			
Drain Valves for Operation	N/A			
Hydraulic Fluid for Level & Leaks	✓			
Brake Warning System for Operation	✓			
ABS & EBS Warning System for Operation	✓			
BATTERY				
Battery Terminals & Cables for Condition	✓			
Battery & Battery Carrier Security	✓			
GENERAL				
Power Steering System Leaks	✓			
Engine for Oil & Water Leaks	✓			
Exhaust System for Condition, Security & Efficiency	✓			
Gearbox & Differential Oil Leaks	✓			
Fuel System Leaks	✓			
BODY				
Glazing Condition	✓			
Body Exterior for Damage & Dangerous Projections	✓			
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			
Rear Vision Mirrors for Security & Condition	✓			
Passenger Access Doors for Security & Operation	✓			
Seats for Security	✓			
Steps, Floor & Hatches for Security & Condition	✓			
Fire Extinguisher for Presence & in Service Date	✓		02/19	
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			
Dash Lights, Step, Interior & Destination Lights for Operation	✓			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓			
Gear & Clutch Controls for Correct Operation	✓			
Steering System for Free Play & Slackness	✓			
Windscreen Wipers for Operation & Condition	✓			
Windscreen Washers for Operation	✓			
Demister for Operation	✓			
Horn for Operation	✓			

ADTRANS TRUCKS ADELAIDE PTY LTD
T/A DAWLER TRUCKS MOUNT GAMBIER
201A Jubilee Hwy
Mount Gambier SA 5290
Telephone: 08 3725 3002
ABN: 45 157 599 661

Inspection Undertaken by Geoff Richards Signed [Signature] Date 24 3 20

*This form must be kept for a period of at least six (6) months after the inspection.

FIRST SCHEDULE: PART 1



Government of South Australia
Department of Planning,
Transport and Infrastructure

**Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1**

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours
Address P.O. Box 609, (78 Sturt Street)
Mount Gambier 5290
Registration Number SB61GM
Date 4 5 20
Odometer 61729 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓			
Wheels for Condition	✓			
Tyres for Correct Pressure	✓			
Tyre Tread for Condition & Depth	✓			
Tyre Walls (without wheel removal) for Damage	✓			
Tyre Construction for Correct Location				
BRAKES				
Service & Parking Brake for Correct Operation	✓			
Brake System for Air Leaks	N/A			
Drain Valves for Operation	N/A			
Hydraulic Fluid for Level & Leaks	✓			
Brake Warning System for Operation	✓			
ABS & EBS Warning System for Operation	✓			
BATTERY				
Battery Terminals & Cables for Condition	✓			
Battery & Battery Carrier Security	✓			
GENERAL				
Power Steering System Leaks	✓			
Engine for Oil & Water Leaks	✓			
Exhaust System for Condition, Security & Efficiency	✓			
Gearbox & Differential Oil Leaks	✓			
Fuel System Leaks	✓			
BODY				
Glazing Condition	✓			
Body Exterior for Damage & Dangerous Projections	✓			
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			
Rear Vision Mirrors for Security & Condition	✓			
Passenger Access Doors for Security & Operation	✓			
Seats for Security	✓			
Steps, Floor & Hatches for Security & Condition	✓			
Fire Extinguisher for Presence & in Service Date			April 20	
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			
Dash Lights, Step, Interior & Destination Lights for Operation	✓			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓			
Gear & Clutch Controls for Correct Operation	Auto			
Steering System for Free Play & Slackness	✓			
Windscreen Wipers for Operation & Condition	✓			
Windscreen Washers for Operation	✓			
Demister for Operation	✓			
Horn for Operation	✓			

Inspection Undertaken by *[Signature]* Signed *[Signature]* Date 4.5.20

*This form must be kept for a period of at least six (6) months after the inspection.

FIRST SCHEDULE: PART 2



Government of South Australia
Department of Planning,
Transport and Infrastructure

**Code of Practice for Buses
Mandatory Maintenance
Procedure Part 2**

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours
Address P.O. Box 609 (78 Sturt Street) Mount Gambier
Registration Number SB61GM
Date 6. 8. 2019
Odometer 56804 km

INSPECTION SHEET NUMBER 2

To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first
• All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
SUSPENSION				
"U" Bolts & Centre Bolts for Security & Condition	✓		6-8-19	BRS
Radius Rods & Joints for Condition	✓			BRS
Front & Rear Axle Mounts for Condition & Cracks	✓			BRS
Springs & Shackles for Condition	✓			BRS
Shock Absorber & Joints for Condition	✓			BRS
Air Bag System for Condition	N/A			
BRAKES				
Brake Lines & Mounts for Condition	✓			BRS
Slack Adjusters & Auto Adjusters for Operation & Condition	N/A			BRS
Brake Linings for Wear & Contamination	✓			BRS
Air Filter for Security & Cleanliness	✓			BRS
Air Priority System for Operation	✓			BRS
Air or Vacuum for Correct Build Up Time	✓			BRS
Retarder & Exhaust Brake for Operation & Control	✓			
STEERING				
Steering Box for Security & Operation	✓			BRS
Steering System for Condition & Play	✓			BRS
Steering Wheel & Column for Play & Security	✓			
GENERAL				
Engine Insulating Material for Contamination & Security	✓			BRS
Starter Motor for Security	✓			BRS
Tail Shafts & Guards for Condition & Security	✓			BRS
Universal Joints & Splines for Condition	✓			BRS
Fuel Tank & Fuel System for Security	✓			BRS
Wheel Bearings for Adjustment	✓			BRS
Axle Hub Seals for Leaks	✓			BRS
Seat Belt Condition & Operation	✓			
Door Interlocks for Correct Operation (if fitted)				
BODY				
Body Mounts Attachments for Security & Condition	✓			BRS
Body for Visual Structural Defects & Corrosion	✓			BRS

Inspection Undertaken by BROCK Signed BRS Date 6.8.19

*This form must be kept for a period of at least one (1) year after the inspection.

FIRST SCHEDULE: PART 2



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 2

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours Registration Number SB61GM
Address P.O. Box 609 (78 Sturt Street) Mount Gambier
Date 28-11-19 Odometer 60856 km

INSPECTION SHEET NUMBER 2

To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
SUSPENSION				
"U" Bolts & Centre Bolts for Security & Condition	✓			
Radius Rods & Joints for Condition	✓			
Front & Rear Axle Mounts for Condition & Cracks	✓			
Springs & Shackles for Condition	✓			
Shock Absorber & Joints for Condition	✓			
Air Bag System for Condition				
BRAKES				
Brake Lines & Mounts for Condition	✓			
Slack Adjusters & Auto Adjusters for Operation & Condition	✓			
Brake Linings for Wear & Contamination	✓			
Air Filter for Security & Cleanliness	✓			
Air Priority System for Operation	✓			
Air or Vacuum for Correct Build Up Time	✓			
Retarder & Exhaust Brake for Operation & Control				
STEERING				
Steering Box for Security & Operation	✓			
Steering System for Condition & Play	✓			
Steering Wheel & Column for Play & Security	✓			
GENERAL				
Engine Insulating Material for Contamination & Security	✓			
Starter Motor for Security	✓			
Tail Shafts & Guards for Condition & Security	✓			
Universal Joints & Splines for Condition	✓			
Fuel Tank & Fuel System for Security	✓			
Wheel Bearings for Adjustment	✓			
Axle Hub Seals for Leaks	✓			
Seat Belt Condition & Operation	✓			
Door Interlocks for Correct Operation (if fitted)				
BODY				
Body Mounts Attachments for Security & Condition	✓			
Body for Visual Structural Defects & Corrosion	✓			

ADTRANS TRUCKS ADELAIDE PTY LTD
T/A DAINILE TRUCKS MOUNT GAMBIER
231 A Jubilee Hwy
Mount Gambier SA 5290
Telephone: 08 8725 3902
ABN: 45 151 699 65

Inspection Undertaken by Liam Telford Signed [Signature] Date 28/11/19

*This form must be kept for a period of at least one (1) year after the inspection.

FIRST SCHEDULE: PART 2



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 2

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours
Address P.O. Box 609 (78 Sturt Street) Mount Gambier
Registration Number SB61GM
Date 24.3.20
Odometer 61,692 km

INSPECTION SHEET NUMBER 2

To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first
• All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
SUSPENSION				
"U" Bolts & Centre Bolts for Security & Condition	✓			
Radius Rods & Joints for Condition	✓			
Front & Rear Axle Mounts for Condition & Cracks	✓			
Springs & Shackles for Condition	✓			
Shock Absorber & Joints for Condition	✓			
Air Bag System for Condition	N/A			
BRAKES				
Brake Lines & Mounts for Condition	✓			
Slack Adjusters & Auto Adjusters for Operation & Condition	N/A			
Brake Linings for Wear & Contamination	✓			
Air Filter for Security & Cleanliness	✓			
Air Priority System for Operation	N/A			
Air or Vacuum for Correct Build Up Time	N/A			
Retarder & Exhaust Brake for Operation & Control	✓			
STEERING				
Steering Box for Security & Operation	✓			
Steering System for Condition & Play	✓			
Steering Wheel & Column for Play & Security	✓			
GENERAL				
Engine Insulating Material for Contamination & Security	✓			
Starter Motor for Security	✓			
Tail Shafts & Guards for Condition & Security	✓			
Universal Joints & Splines for Condition	✓			
Fuel Tank & Fuel System for Security	✓			
Wheel Bearings for Adjustment	✓			
Axle Hub Seals for Leaks	✓			
Seat Belt Condition & Operation	✓			
Door Interlocks for Correct Operation (if fitted)	✓			
BODY				
Body Mounts Attachments for Security & Condition	✓			
Body for Visual Structural Defects & Corrosion	✓			

ADTRANS TRUCKS ADELAIDE PTY LTD
 T/A DAVID MILLER TRUCKS MOUNT GAMBIER
 201A Jubilee Hwy
 Mount Gambier SA 5290
 Telephone: 08 8725 3992
 AGN: 40151 699 651

Inspection Undertaken by Prof. Richards Signed Prof. Richards Date 24.3.20

*This form must be kept for a period of at least one (1) year after the inspection.

FIRST SCHEDULE: PART 2



Government of South Australia
 Department of Planning,
 Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 2

Vehicle Inspections
 PO BOX 1533
 ADELAIDE SA 5001

MR 1090
 07/16

Company / Owner Lake City Tours **Registration Number** SB61GM
Address P.O. Box 609 (78 Sturt Street) Mount Gambier
Date 4 5 20 **Odometer** 61729 km

INSPECTION SHEET NUMBER 2

To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first
 • All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
SUSPENSION				
"U" Bolts & Centre Bolts for Security & Condition	✓			
Radius Rods & Joints for Condition	✓			
Front & Rear Axle Mounts for Condition & Cracks	✓			
Springs & Shackles for Condition	✓			
Shock Absorber & Joints for Condition	✓			
Air Bag System for Condition	N/A			
BRAKES				
Brake Lines & Mounts for Condition	✓			
Slack Adjusters & Auto Adjusters for Operation & Condition	N/A			
Brake Linings for Wear & Contamination	✓			
Air Filter for Security & Cleanliness	✓			
Air Priority System for Operation	✓			
Air or Vacuum for Correct Build Up Time	N/A			
Retarder & Exhaust Brake for Operation & Control	✓			
STEERING				
Steering Box for Security & Operation	✓			
Steering System for Condition & Play	✓			
Steering Wheel & Column for Play & Security	✓			
GENERAL				
Engine Insulating Material for Contamination & Security	✓			
Starter Motor for Security	✓			
Tail Shafts & Guards for Condition & Security	✓			
Universal Joints & Splines for Condition	✓			
Fuel Tank & Fuel System for Security	✓			
Wheel Bearings for Adjustment	✓			
Axle Hub Seals for Leaks	✓			
Seat Belt Condition & Operation	✓			
Door Interlocks for Correct Operation (if fitted)	✓			
BODY				
Body Mounts Attachments for Security & Condition	✓			
Body for Visual Structural Defects & Corrosion	✓			

Inspection Undertaken by Creat Signed Adriek Date 4.15.20

*This form must be kept for a period of at least one (1) year after the inspection.

FIRST SCHEDULE: PART 1



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours Registration Number 5B61AM
Address Mount Gambier SA 5290
78 Sturt Street
Date 31 8 20 Odometer 621836 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓			
Wheels for Condition	✓			
Tyres for Correct Pressure	✓			
Tyre Tread for Condition & Depth	✓			
Tyre Walls (without wheel removal) for Damage	✓			
Tyre Construction for Correct Location	✓			
BRAKES				
Service & Parking Brake for Correct Operation	✓			
Brake System for Air Leaks	✓			
Drain Valves for Operation	✓			
Hydraulic Fluid for Level & Leaks	✓			
Brake Warning System for Operation	✓			
ABS & EBS Warning System for Operation	✓			
BATTERY				
Battery Terminals & Cables for Condition	✓			
Battery & Battery Carrier Security	✓			
GENERAL				
Power Steering System Leaks	✓			
Engine for Oil & Water Leaks	✓			
Exhaust System for Condition, Security & Efficiency	✓			
Gearbox & Differential Oil Leaks	✓			
Fuel System Leaks	✓			
BODY				
Glazing Condition	✓			
Body Exterior for Damage & Dangerous Projections	✓			
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			
Rear Vision Mirrors for Security & Condition	✓			
Passenger Access Doors for Security & Operation	✓			
Seats for Security	✓			
Steps, Floor & Hatches for Security & Condition	✓			
Fire Extinguisher for Presence & in Service Date	✓			
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			
Dash Lights, Step, Interior & Destination Lights for Operation	✓			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓			
Gear & Clutch Controls for Correct Operation	✓			
Steering System for Free Play & Slackness	✓			
Windscreen Wipers for Operation & Condition	✓			
Windscreen Washers for Operation	✓			
Demister for Operation	✓			
Horn for Operation	✓			

ADTRANS TRUCKS ADELAIDE PTY LTD
 T/A DAMILER TRUCKS MOUNT GAMBIER
 201A Jubilee Hwy
 Mount Gambier SA 5290
 Telephone: 08 8725 3902
 ABN: 45 151 699 651

Inspection Undertaken by Ryan Bachman Signed R Bachman Date 31/8/20

*This form must be kept for a period of at least six (6) months after the inspection.

FIRST SCHEDULE: PART 1



Government of South Australia
 Department of Planning,
 Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
 PO BOX 1533
 ADELAIDE SA 5001

MR 1090
 07/16

Company / Owner Lake City Tours **Registration Number**
Address P.O. Box 609 (78 Sturt Street) **SB66LP- SB61GM**
 Mount Gambier, 5290
Date 19.11.20 **Odometer** 63545 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓			
Wheels for Condition	✓			
Tyres for Correct Pressure	✓			
Tyre Tread for Condition & Depth	✓			
Tyre Walls (without wheel removal) for Damage	✓			
Tyre Construction for Correct Location	✓			
BRAKES				
Service & Parking Brake for Correct Operation	✓			
Brake System for Air Leaks	N/A			
Drain Valves for Operation	N/A			
Hydraulic Fluid for Level & Leaks	✓			
Brake Warning System for Operation	✓			
ABS & EBS Warning System for Operation	✓			
BATTERY				
Battery Terminals & Cables for Condition	✓			
Battery & Battery Carrier Security	✓			
GENERAL				
Power Steering System Leaks	✓			
Engine for Oil & Water Leaks	✓			
Exhaust System for Condition, Security & Efficiency	✓			
Gearbox & Differential Oil Leaks	✓			
Fuel System Leaks	✓			
BODY				
Glazing Condition	✓			
Body Exterior for Damage & Dangerous Projections	✓			
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			
Rear Vision Mirrors for Security & Condition	✓			
Passenger Access Doors for Security & Operation	✓			
Seats for Security	✓			
Steps, Floor & Hatches for Security & Condition	✓			
Fire Extinguisher for Presence & in Service Date	✓		Oct 2020	
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			
Dash Lights, Step, Interior & Destination Lights for Operation	✓			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓			
Gear & Clutch Controls for Correct Operation	N/A			
Steering System for Free Play & Slackness	✓			
Windscreen Wipers for Operation & Condition	✓			
Windscreen Washers for Operation	✓			
Demister for Operation	✓			
Horn for Operation	✓			

Inspection Undertaken by Graff Richards Signed [Signature] Date 19.11.20

*This form must be kept for a period of at least six (6) months after the inspection.

FIRST SCHEDULE: PART 1



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours Registration Number SB61GM
Address P.O. Box 609 Mt Gambier 5290
Date 3. 2. 21 Odometer 63096 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓			
Wheels for Condition	✓			
Tyres for Correct Pressure	✓			
Tyre Tread for Condition & Depth	✓			
Tyre Walls (without wheel removal) for Damage	✓			
Tyre Construction for Correct Location	✓			
BRAKES				
Service & Parking Brake for Correct Operation	✓			
Brake System for Air Leaks	N/A			
Drain Valves for Operation	N/A			
Hydraulic Fluid for Level & Leaks	✓			
Brake Warning System for Operation	✓			
ABS & EBS Warning System for Operation	✓			
BATTERY				
Battery Terminals & Cables for Condition	✓			
Battery & Battery Carrier Security	✓			
GENERAL				
Power Steering System Leaks	✓			
Engine for Oil & Water Leaks	✓			
Exhaust System for Condition, Security & Efficiency	✓			
Gearbox & Differential Oil Leaks	✓			
Fuel System Leaks	✓			
BODY				
Glazing Condition	✓			
Body Exterior for Damage & Dangerous Projections	✓			
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			
Rear Vision Mirrors for Security & Condition	✓			
Passenger Access Doors for Security & Operation	✓			
Seats for Security	✓			
Steps, Floor & Hatches for Security & Condition	✓			
Fire Extinguisher for Presence & in Service Date	✓			
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			
Dash Lights, Step, Interior & Destination Lights for Operation	✓			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)				
Gear & Clutch Controls for Correct Operation	N/A			
Steering System for Free Play & Slackness	✓			
Windscreen Wipers for Operation & Condition	✓			
Windscreen Washers for Operation	✓			
Demister for Operation	✓			
Horn for Operation	✓			

ADTRANS TRUCKS ADELAIDE PTY LTD
T/A DAMLER TRUCKS MOUNT GAMBIER
101A Jubilee Hwy
Mount Gambier SA 5290
Telephone: 08 8725 3907
ABN: 45 151 639 651

Inspection Undertaken by Shayne Boxall Signed [Signature] Date 3. 2. 21

*This form must be kept for a period of at least six (6) months after the inspection.

FIRST SCHEDULE: PART 1



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours Registration Number SB61GM
Address P.O. Box 609 Mt Gambier 5290
Date 6.5.21 Odometer 63 784 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓			
Wheels for Condition	✓			
Tyres for Correct Pressure	✓			
Tyre Tread for Condition & Depth	✓			
Tyre Walls (without wheel removal) for Damage	✓			
Tyre Construction for Correct Location	✓			
BRAKES				
Service & Parking Brake for Correct Operation	✓			
Brake System for Air Leaks	N/A			
Drain Valves for Operation	N/A			
Hydraulic Fluid for Level & Leaks	✓			
Brake Warning System for Operation	✓			
ABS & EBS Warning System for Operation	✓			
BATTERY				
Battery Terminals & Cables for Condition	✓			
Battery & Battery Carrier Security	✓			
GENERAL				
Power Steering System Leaks	✓			
Engine for Oil & Water Leaks	✓			
Exhaust System for Condition, Security & Efficiency	✓			
Gearbox & Differential Oil Leaks	✓			
Fuel System Leaks	✓			
BODY				
Glazing Condition	✓			
Body Exterior for Damage & Dangerous Projections	✓			
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			
Rear Vision Mirrors for Security & Condition	✓			
Passenger Access Doors for Security & Operation	✓			
Seats for Security	✓			
Steps, Floor & Hatches for Security & Condition	✓			
Fire Extinguisher for Presence & in Service Date	✓		April 21	
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			
Dash Lights, Step, Interior & Destination Lights for Operation	✓			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓			
Gear & Clutch Controls for Correct Operation	✓			
Steering System for Free Play & Slackness	✓			
Windscreen Wipers for Operation & Condition	✓			
Windscreen Washers for Operation	✓			
Demister for Operation	✓			
Horn for Operation	✓			

ADTRANS TRUCKS ADELAIDE PTY LTD
 T/A DAMLER TRUCKS MOUNT GAMBIER
 201 A Justice Hwy
 Mount Gambier SA 5290
 Telephone: 08 8725 3902
 ABN: 45 151 699 651

Inspection Undertaken by Geoff Richard Signed [Signature] Date 6.5.21

*This form must be kept for a period of at least six (6) months after the inspection.

FIRST SCHEDULE PART 2



Government of South Australia
 Department of Planning,
 Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
 Procedure Part 2

Vehicle Inspections
 PO BOX 1533
 ADELAIDE SA 5001

MR 1090
 07/16

Company / Owner Lake city tours Registration Number 5B61GM
 Address Mount Gambier, SA 5290
78 Sturt Street
 Date 31.8.20 Odometer 62936 km

INSPECTION SHEET NUMBER 2

To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
SUSPENSION				
"U" Bolts & Centre Bolts for Security & Condition	✓			
Radius Rods & Joints for Condition	✓			
Front & Rear Axle Mounts for Condition & Cracks	✓			
Springs & Shackles for Condition	✓			
Shock Absorber & Joints for Condition	✓			
Air Bag System for Condition	✓			
BRAKES				
Brake Lines & Mounts for Condition	✓			
Slack Adjusters & Auto Adjusters for Operation & Condition	✓			
Brake Linings for Wear & Contamination	✓			
Air Filter for Security & Cleanliness	✓			
Air Priority System for Operation	✓			
Air or Vacuum for Correct Build Up Time	✓			
Retarder & Exhaust Brake for Operation & Control	✓			
STEERING				
Steering Box for Security & Operation	✓			
Steering System for Condition & Play	✓			
Steering Wheel & Column for Play & Security	✓			
GENERAL				
Engine Insulating Material for Contamination & Security	✓			
Starter Motor for Security	✓			
Tail Shafts & Guards for Condition & Security	✓			
Universal Joints & Splines for Condition	✓			
Fuel Tank & Fuel System for Security	✓			
Wheel Bearings for Adjustment	✓			
Axle Hub Seals for Leaks	✓			
Seat Belt Condition & Operation	✓			
Door Interlocks for Correct Operation (if fitted)	✓			
BODY				
Body Mounts Attachments for Security & Condition	✓			
Body for Visual Structural Defects & Corrosion	✓			

ADTRANS TRUCKS ADELAIDE PTY LTD
 T/A DAMLER TRUCKS MOUNT GAMBIER
 201A Jubilee Hwy
 Mount Gambier SA 5290
 Telephone: 08 8725 3902
 ABN: 45 151 699 651

Inspection Undertaken by Ryan Badman Signed Badman Date 31.8.20

*This form must be kept for a period of at least one (1) year after the inspection.

FIRST SCHEDULE: PART 2



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 2

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours
Address P.O. Box 609 (78 Sturt Street)
Mount Gambier, 5290
Registration Number SB61AM
Date 19.11.20 **Odometer** 63545 km

INSPECTION SHEET NUMBER 2

To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
SUSPENSION				
"U" Bolts & Centre Bolts for Security & Condition	✓			
Radius Rods & Joints for Condition	✓			
Front & Rear Axle Mounts for Condition & Cracks	✓			
Springs & Shackles for Condition	✓			
Shock Absorber & Joints for Condition	✓			
Air Bag System for Condition				
BRAKES				
Brake Lines & Mounts for Condition	✓			
Slack Adjusters & Auto Adjusters for Operation & Condition	✓			
Brake Linings for Wear & Contamination	✓			
Air Filter for Security & Cleanliness	✓			
Air Priority System for Operation	✓			
Air or Vacuum for Correct Build Up Time	N/A			
Retarder & Exhaust Brake for Operation & Control				
STEERING				
Steering Box for Security & Operation	✓			
Steering System for Condition & Play	✓			
Steering Wheel & Column for Play & Security	✓			
GENERAL				
Engine Insulating Material for Contamination & Security	✓			
Starter Motor for Security	✓			
Tail Shafts & Guards for Condition & Security	✓			
Universal Joints & Splines for Condition	✓			
Fuel Tank & Fuel System for Security	✓			
Wheel Bearings for Adjustment	✓			
Axle Hub Seals for Leaks	✓			
Seat Belt Condition & Operation	✓			
Door Interlocks for Correct Operation (if fitted)	✓			
BODY				
Body Mounts Attachments for Security & Condition	✓			
Body for Visual Structural Defects & Corrosion	✓			

Inspection Undertaken by *Geoff Richards* Signed *Geoff Richards* Date *19.11.20*

*This form must be kept for a period of at least one (1) year after the inspection.

FIRST SCHEDULE: PART 2



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 2

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours Registration Number _____
Address P.O. Box 609 Mt Gambier 5290 _____
Date 3. 2. 21 Odometer 63 696 km

INSPECTION SHEET NUMBER 2

To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
SUSPENSION				
"U" Bolts & Centre Bolts for Security & Condition	✓			
Radius Rods & Joints for Condition	✓			
Front & Rear Axle Mounts for Condition & Cracks	✓			
Springs & Shackles for Condition	✓			
Shock Absorber & Joints for Condition	✓			
Air Bag System for Condition	✓			
BRAKES				
Brake Lines & Mounts for Condition	✓			
Slack Adjusters & Auto Adjusters for Operation & Condition	N/A			
Brake Linings for Wear & Contamination	✓			
Air Filter for Security & Cleanliness	✓			
Air Priority System for Operation	N/A			
Air or Vacuum for Correct Build Up Time	✓			
Retarder & Exhaust Brake for Operation & Control	✓			
STEERING				
Steering Box for Security & Operation	✓			
Steering System for Condition & Play	✓			
Steering Wheel & Column for Play & Security	✓			
GENERAL				
Engine Insulating Material for Contamination & Security	✓			
Starter Motor for Security	✓			
Tail Shafts & Guards for Condition & Security	✓			
Universal Joints & Splines for Condition	✓			
Fuel Tank & Fuel System for Security	✓			
Wheel Bearings for Adjustment	✓			
Axle Hub Seals for Leaks	✓			
Seat Belt Condition & Operation	✓			
Door Interlocks for Correct Operation (if fitted)	✓			
BODY				
Body Mounts Attachments for Security & Condition	✓			
Body for Visual Structural Defects & Corrosion	✓			

ADTRANS TRUCKS ADELAIDE PTY LTD
 T/A DAIMLER TRUCKS MOUNT GAMBIER
 201A Jubilee Hwy
 Mount Gambier SA 5290
 Telephone: 08 8725 3902
 ABN: 45 151 699 851

Inspection Undertaken by Shayne Boxall Signed [Signature] Date 3.2.21

*This form must be kept for a period of at least one (1) year after the inspection.

FIRST SCHEDULE: PART 2



Government of South Australia
 Department of Planning,
 Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
 Procedure Part 2

Vehicle Inspections
 PO BOX 1533
 ADELAIDE SA 5001

MR 1090
 07/16

Company / Owner Lake City Tours Registration Number SB 61 GM
 Address P.O. BOX 609 Mt Gambier 5290
 Date 6.5.21 Odometer 63 784 km

INSPECTION SHEET NUMBER 2

To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
SUSPENSION				
"U" Bolts & Centre Bolts for Security & Condition	✓			
Radius Rods & Joints for Condition	✓			
Front & Rear Axle Mounts for Condition & Cracks	✓			
Springs & Shackles for Condition	✓			
Shock Absorber & Joints for Condition	✓			
Air Bag System for Condition	✓			
BRAKES				
Brake Lines & Mounts for Condition	✓			
Slack Adjusters & Auto Adjusters for Operation & Condition	✓			
Brake Linings for Wear & Contamination	✓			
Air Filter for Security & Cleanliness	✓			
Air Priority System for Operation	N/A			
Air or Vacuum for Correct Build Up Time	N/A			
Retarder & Exhaust Brake for Operation & Control	✓			
STEERING				
Steering Box for Security & Operation	✓			
Steering System for Condition & Play	✓			
Steering Wheel & Column for Play & Security	✓			
GENERAL				
Engine Insulating Material for Contamination & Security	✓			
Starter Motor for Security	✓			
Tail Shafts & Guards for Condition & Security	✓			
Universal Joints & Splines for Condition	✓			
Fuel Tank & Fuel System for Security	✓			
Wheel Bearings for Adjustment	✓			
Axle Hub Seals for Leaks	✓			
Seat Belt Condition & Operation	✓			
Door Interlocks for Correct Operation (if fitted)	✓			
BODY				
Body Mounts Attachments for Security & Condition	✓			
Body for Visual Structural Defects & Corrosion	✓			

ADTRANS TRUCKS ADELAIDE PTY LTD
 T/A DAMLER TRUCKS MOUNT GAMBIER
 201A Jubilee Hwy
 Mount Gambier SA 5290
 Telephone: 08 8725 3902
 ABN: 45 151 699 651

Inspection Undertaken by Graff Richards Signed Graff Richards Date 6.5.21.

*This form must be kept for a period of at least one (1) year after the inspection.

FIRST SCHEDULE: PART 1



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours
Address PO Box 609, Mount Gambier
Registration Number SB61GM

Date 25.8.21 **Odometer** 68921 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness.	✓			
Wheels for Condition	✓			
Tyres for Correct Pressure	✓			
Tyre Tread for Condition & Depth	✓			
Tyre Walls (without wheel removal) for Damage	✓			
Tyre Construction for Correct Location				
BRAKES				
Service & Parking Brake for Correct Operation	✓			
Brake System for Air Leaks	N/A			
Drain Valves for Operation	N/A			
Hydraulic Fluid for Level & Leaks	✓			
Brake Warning System for Operation	✓			
ABS & EBS Warning System for Operation	✓			
BATTERY				
Battery Terminals & Cables for Condition	✓			
Battery & Battery Carrier Security	✓			
GENERAL				
Power Steering System Leaks	✓			
Engine for Oil & Water Leaks	✓			
Exhaust System for Condition, Security & Efficiency	✓			
Gearbox & Differential Oil Leaks	✓			
Fuel System Leaks	✓			
BODY				
Glazing Condition	✓			
Body Exterior for Damage & Dangerous Projections	✓			
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			
Rear Vision Mirrors for Security & Condition	✓			
Passenger Access Doors for Security & Operation	✓			
Seats for Security	✓			
Steps, Floor & Hatches for Security & Condition	✓			
Fire Extinguisher for Presence & in Service Date	✓		April 21	
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			
Dash Lights, Step, Interior & Destination Lights for Operation	✓			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓			
Gear & Clutch Controls for Correct Operation	N/A			
Steering System for Free Play & Slackness	✓			
Windscreen Wipers for Operation & Condition	✓			
Windscreen Washers for Operation	✓			
Demister for Operation	✓			
Horn for Operation	✓			

Velocity Truck Centres Adelaide Pty Ltd
 20 SA Jubilee Hwy, Mount Gambier SA 5290
 Telephone: 08 8725 3902
 ABN 45 15 699 651

Inspection Undertaken by Geoff Richards Signed Geoff Richards Date 25/8/21

*This form must be kept for a period of at least six (6) months after the inspection.

FIRST SCHEDULE: PART 1



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours
Address PO Box 609, Mount Gambier
Registration Number SB61GM

Date 30.11.21 **Odometer** 70937 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓			
Wheels for Condition	✓			
Tyres for Correct Pressure	✓			
Tyre Tread for Condition & Depth	✓			
Tyre Walls (without wheel removal) for Damage	✓			
Tyre Construction for Correct Location	✓			
BRAKES				
Service & Parking Brake for Correct Operation	✓			
Brake System for Air Leaks	N/A			
Drain Valves for Operation	N/A			
Hydraulic Fluid for Level & Leaks	✓			
Brake Warning System for Operation	✓			
ABS & EBS Warning System for Operation	✓			
BATTERY				
Battery Terminals & Cables for Condition	✓			
Battery & Battery Carrier Security	✓			
GENERAL				
Power Steering System Leaks	✓			
Engine for Oil & Water Leaks	✓			
Exhaust System for Condition, Security & Efficiency	✓			
Gearbox & Differential Oil Leaks	✓			
Fuel System Leaks	✓			
BODY				
Glazing Condition	✓			
Body Exterior for Damage & Dangerous Projections	✓			
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			
Rear Vision Mirrors for Security & Condition	✓			
Passenger Access Doors for Security & Operation	✓			
Seats for Security	✓	✗		
Steps, Floor & Hatches for Security & Condition	✓			
Fire Extinguisher for Presence & in Service Date	✓			
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			
Dash Lights, Step, Interior & Destination Lights for Operation	✓			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓			
Gear & Clutch Controls for Correct Operation	✓			
Steering System for Free Play & Slackness	✓			
Windscreen Wipers for Operation & Condition	✓			
Windscreen Washers for Operation	✓			
Demister for Operation	✓			
Horn for Operation	✓			

Velocity Truck Centres Adelaide Pty Ltd
 T/A Dalmer Trucks Mount Gambier
 201A Jubilee Hwy Mount Gambier SA 5290
 Telephone 08 825 3902
 ABN 45 151 699 651

Inspection Undertaken by Adrian Heinrich Signed [Signature] Date 30/11/21

*This form must be kept for a period of at least six (6) months after the inspection.

FIRST SCHEDULE: PART 1



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours
Address PO Box 609, Mount Gambier
Registration Number SB61GM

Date 18 Oct 22 **Odometer** 71047 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓			
Wheels for Condition	✓			
Tyres for Correct Pressure	✓			
Tyre Tread for Condition & Depth	✓			
Tyre Walls (without wheel removal) for Damage	✓			
Tyre Construction for Correct Location	✓			
BRAKES				
Service & Parking Brake for Correct Operation	✓			
Brake System for Air Leaks	N/A			
Drain Valves for Operation	N/A			
Hydraulic Fluid for Level & Leaks	✓			
Brake Warning System for Operation	✓			
ABS & EBS Warning System for Operation	✓			
BATTERY				
Battery Terminals & Cables for Condition	✓			
Battery & Battery Carrier Security	✓			
GENERAL				
Power Steering System Leaks	✓			
Engine for Oil & Water Leaks	✓			
Exhaust System for Condition, Security & Efficiency	✓			
Gearbox & Differential Oil Leaks	✓			
Fuel System Leaks	✓			
BODY				
Glazing Condition	✓			
Body Exterior for Damage & Dangerous Projections	✓			
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			
Rear Vision Mirrors for Security & Condition	✓			
Passenger Access Doors for Security & Operation	✓			
Seats for Security	✓			
Steps, Floor & Hatches for Security & Condition	✓			
Fire Extinguisher for Presence & in Service Date	✓			
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			
Dash Lights, Step, Interior & Destination Lights for Operation	✓			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓			
Gear & Clutch Controls for Correct Operation	✓			
Steering System for Free Play & Slackness	✓			
Windscreen Wipers for Operation & Condition	✓			
Windscreen Washers for Operation	✓			
Demister for Operation	✓			
Horn for Operation	✓			

Inspection Undertaken by Ryan Badman Signed [Signature] Date 20.10.2022

*This form must be kept for a period of at least six (6) months after the inspection.

FIRST SCHEDULE: PART 1



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours
Address P.O. Box 609, (78 Sturt Street)
Mount Gambier 5290
Registration Number SB61GM
Date 09. 05. 22... **Odometer** 71082 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓			
Wheels for Condition	✓			
Tyres for Correct Pressure	✓			
Tyre Tread for Condition & Depth	✓			
Tyre Walls (without wheel removal) for Damage	✓			
Tyre Construction for Correct Location	✓			
BRAKES				
Service & Parking Brake for Correct Operation	✓			
Brake System for Air Leaks	N/A			
Drain Valves for Operation	✓			
Hydraulic Fluid for Level & Leaks	✓			
Brake Warning System for Operation	✓			
ABS & EBS Warning System for Operation	✓			
BATTERY				
Battery Terminals & Cables for Condition	✓			
Battery & Battery Carrier Security	✓			
GENERAL				
Power Steering System Leaks	✓			
Engine for Oil & Water Leaks	✓			
Exhaust System for Condition, Security & Efficiency	✓			
Gearbox & Differential Oil Leaks	✓			
Fuel System Leaks	✓			
BODY				
Glazing Condition	✓			
Body Exterior for Damage & Dangerous Projections	✓			
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			
Rear Vision Mirrors for Security & Condition	✓			
Passenger Access Doors for Security & Operation	✓			
Seats for Security	✓			
Steps, Floor & Hatches for Security & Condition	✓			
Fire Extinguisher for Presence & in Service Date	✓			
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			
Dash Lights, Step, Interior & Destination Lights for Operation	✓			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓			
Gear & Clutch Controls for Correct Operation	✓			
Steering System for Free Play & Slackness	✓			
Windscreen Wipers for Operation & Condition	✓			
Windscreen Washers for Operation	✓			
Demister for Operation	✓			
Horn for Operation	✓			

Velocity Truck Centres Adelaide Pty Ltd
 T/A Daimler Trucks Mount Gambier
 201A Jubilee Hwy Mount Gambier SA 5290
 Telephone: 08 8722 3902
 ABN 45 151 690 551

Inspection Undertaken by Ryan Badman Signed [Signature] Date 9.5.22

*This form must be kept for a period of at least six (6) months after the inspection.

FIRST SCHEDULE: PART 2



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 2

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours **Registration Number**
Address P.O. Box 609 (78 Sturt Street) **SB61GM**
Mount Gambier, 5290
Date 25 & 21 **Odometer** 68921 km

INSPECTION SHEET NUMBER 2

To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
SUSPENSION				
"U" Bolts & Centre Bolts for Security & Condition	✓			
Radius Rods & Joints for Condition	✓			
Front & Rear Axle Mounts for Condition & Cracks	✓			
Springs & Shackles for Condition	✓			
Shock Absorber & Joints for Condition	✓			
Air Bag System for Condition	N/A			
BRAKES				
Brake Lines & Mounts for Condition	✓			
Slack Adjusters & Auto Adjusters for Operation & Condition	✓			
Brake Linings for Wear & Contamination	✓			
Air Filter for Security & Cleanliness	✓			
Air Priority System for Operation	✓			
Air or Vacuum for Correct Build Up Time	✓			
Retarder & Exhaust Brake for Operation & Control	✓			
STEERING				
Steering Box for Security & Operation	✓			
Steering System for Condition & Play	✓			
Steering Wheel & Column for Play & Security	✓			
GENERAL				
Engine Insulating Material for Contamination & Security	✓			
Starter Motor for Security	✓			
Tail Shafts & Guards for Condition & Security	✓			
Universal Joints & Splines for Condition	✓			
Fuel Tank & Fuel System for Security	✓			
Wheel Bearings for Adjustment	✓			
Axle Hub Seals for Leaks	✓			
Seat Belt Condition & Operation	✓			
Door Interlocks for Correct Operation (if fitted)	✓			
BODY				
Body Mounts Attachments for Security & Condition	✓			
Body for Visual Structural Defects & Corrosion	✓			

Velocity Truck Centres Adelaide Pty Ltd
T/A Gambier Trucks Mount Gambier
201A Jubilee Hwy Mount Gambier SA 5290
Telephone 08 8725 3902
ABN 45 151 699 651

Inspection Undertaken by *Geoff Richards* Signed *Geoff Richards* Date 25/8/21

*This form must be kept for a period of at least one (1) year after the inspection.

FIRST SCHEDULE: PART 2



Government of South Australia
 Department of Planning,
 Transport and Infrastructure

**Code of Practice for Buses
 Mandatory Maintenance
 Procedure Part 2**

Vehicle Inspections
 PO BOX 1533
 ADELAIDE SA 5001

MR 1090
 07/16

Company / Owner Lake City Tours **Registration Number**
 Address P.O. Box 609 (78 Sturt Street) SB61GM
 Mount Gambier, 5290

Date 30 11 21 Odometer 70937 km

INSPECTION SHEET NUMBER 2

- To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first
- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
SUSPENSION				
"U" Bolts & Centre Bolts for Security & Condition	✓			
Radius Rods & Joints for Condition	✓			
Front & Rear Axle Mounts for Condition & Cracks	✓			
Springs & Shackles for Condition	✓			
Shock Absorber & Joints for Condition	✓			
Air Bag System for Condition	N/A			
BRAKES				
Brake Lines & Mounts for Condition	✓			
Slack Adjusters & Auto Adjusters for Operation & Condition	N/A			
Brake Linings for Wear & Contamination	✓			
Air Filter for Security & Cleanliness	✓			
Air Priority System for Operation	N/A			
Air or Vacuum for Correct Build Up Time	N/A			
Retarder & Exhaust Brake for Operation & Control	N/A			
STEERING				
Steering Box for Security & Operation	✓			
Steering System for Condition & Play	✓			
Steering Wheel & Column for Play & Security	✓			
GENERAL				
Engine Insulating Material for Contamination & Security	✓			
Starter Motor for Security	✓			
Tail Shafts & Guards for Condition & Security	✓			
Universal Joints & Splines for Condition	✓			
Fuel Tank & Fuel System for Security	✓			
Wheel Bearings for Adjustment	✓			
Axle Hub Seals for Leaks	✓			
Seat Belt Condition & Operation	✓			
Door Interlocks for Correct Operation (if fitted)	✓			
BODY				
Body Mounts Attachments for Security & Condition	✓			
Body for Visual Structural Defects & Corrosion	✓			

Velocity Truck Centres Adelaide Pty Ltd
 T/A Daimler Trucks Mount Gambier
 201A Jubilee Hwy, Mount Gambier SA 5290
 Telephone: 08 8725 3902
 Fax: 08 8725 699 651

Inspection Undertaken by Adrian Heinrich Signed [Signature] Date 30/11/21

*This form must be kept for a period of at least one (1) year after the inspection.

FIRST SCHEDULE: PART 2



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 2

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours **Registration Number** SB61GM
Address P.O. Box 609 (78 Sturt Street)
Mount Gambier, 5290
Date 28 02 22 **Odometer** 71047 km

INSPECTION SHEET NUMBER 2

To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
SUSPENSION				
"U" Bolts & Centre Bolts for Security & Condition	✓			
Radius Rods & Joints for Condition	✓			
Front & Rear Axle Mounts for Condition & Cracks	✓			
Springs & Shackles for Condition	✓			
Shock Absorber & Joints for Condition	✓			
Air Bag System for Condition	N/A			
BRAKES				
Brake Lines & Mounts for Condition	✓			
Slack Adjusters & Auto Adjusters for Operation & Condition	N/A			
Brake Linings for Wear & Contamination	✓			
Air Filter for Security & Cleanliness	✓			
Air Priority System for Operation	N/A			
Air or Vacuum for Correct Build Up Time	✓			
Retarder & Exhaust Brake for Operation & Control				
STEERING				
Steering Box for Security & Operation	✓			
Steering System for Condition & Play	✓			
Steering Wheel & Column for Play & Security	✓			
GENERAL				
Engine Insulating Material for Contamination & Security	✓			
Starter Motor for Security	✓			
Tail Shafts & Guards for Condition & Security	✓			
Universal Joints & Splines for Condition	✓			
Fuel Tank & Fuel System for Security	✓			
Wheel Bearings for Adjustment	✓			
Axle Hub Seals for Leaks	✓			
Seat Belt Condition & Operation	✓			
Door Interlocks for Correct Operation (if fitted)				
BODY				
Body Mounts Attachments for Security & Condition	✓			
Body for Visual Structural Defects & Corrosion				

Inspection Undertaken by Alan Ryan Budman Signed Al Budman Date 28.2.2022

*This form must be kept for a period of at least one (1) year after the inspection.

FIRST SCHEDULE: PART 2



Government of South Australia
 Department of Planning,
 Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 2

Vehicle Inspections
 PO BOX 1533
 ADELAIDE SA 5001

MR 1090
 07/16

Company / Owner Lake City Tours
Address P.O. Box 609 (78 Sturt Street)
 Mount Gambier, 5290
Registration Number SB61GM
Date 09.05.22 **Odometer** 71082 km

INSPECTION SHEET NUMBER 2

To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first
 • All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
SUSPENSION				
"U" Bolts & Centre Bolts for Security & Condition	✓			
Radius Rods & Joints for Condition	N/A			
Front & Rear Axle Mounts for Condition & Cracks	✓			
Springs & Shackles for Condition	✓			
Shock Absorber & Joints for Condition	✓			
Air Bag System for Condition	N/A			
BRAKES				
Brake Lines & Mounts for Condition	✓			
Slack Adjusters & Auto Adjusters for Operation & Condition	N/A			
Brake Linings for Wear & Contamination	✓			
Air Filter for Security & Cleanliness	✓			
Air Priority System for Operation	N/A			
Air or Vacuum for Correct Build Up Time	✓			
Retarder & Exhaust Brake for Operation & Control	✓			
STEERING				
Steering Box for Security & Operation	✓			
Steering System for Condition & Play	✓			
Steering Wheel & Column for Play & Security	✓			
GENERAL				
Engine Insulating Material for Contamination & Security	✓			
Starter Motor for Security	✓			
Tail Shafts & Guards for Condition & Security	✓			
Universal Joints & Splines for Condition	✓			
Fuel Tank & Fuel System for Security	✓			
Wheel Bearings for Adjustment	✓			
Axle Hub Seals for Leaks	✓			
Seat Belt Condition & Operation	✓			
Door Interlocks for Correct Operation (if fitted)	✓			
BODY				
Body Mounts Attachments for Security & Condition	✓			
Body for Visual Structural Defects & Corrosion	✓			

Velocity Truck Centres Adelaide Pty Ltd
 T/A Daimler Trucks Mount Gambier
 201A Jubilee Hwy, Mount Gambier SA 5290
 Telephone: 08 8725 3902
 ABN 45 15 699 661

Inspection Undertaken by Ryan Badman Signed [Signature] Date 9.5.22

*This form must be kept for a period of at least one (1) year after the inspection.

FIRST SCHEDULE: PART 1



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours **Registration Number**
Address P.O. Box 609, (78 Sturt Street) **SB61GM**
Mount Gambier 5290
Date 30.8.22 **Odometer** 71,153 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓			
Wheels for Condition	✓			
Tyres for Correct Pressure		X	30/8/22	
Tyre Tread for Condition & Depth	✓			
Tyre Walls (without wheel removal) for Damage	✓			
Tyre Construction for Correct Location	✓			
BRAKES				
Service & Parking Brake for Correct Operation	✓			
Brake System for Air Leaks	✓			
Drain Valves for Operation	✓			
Hydraulic Fluid for Level & Leaks	✓			
Brake Warning System for Operation	✓			
ABS & EBS Warning System for Operation	✓			
BATTERY				
Battery Terminals & Cables for Condition	✓			
Battery & Battery Carrier Security	✓			
GENERAL				
Power Steering System Leaks	✓			
Engine for Oil & Water Leaks	✓			
Exhaust System for Condition, Security & Efficiency	✓			
Gearbox & Differential Oil Leaks	✓			
Fuel System Leaks	✓			
BODY				
Glazing Condition	✓			
Body Exterior for Damage & Dangerous Projections	✓			
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			
Rear Vision Mirrors for Security & Condition	✓			
Passenger Access Doors for Security & Operation	✓			
Seats for Security	✓			
Steps, Floor & Hatches for Security & Condition	✓			
Fire Extinguisher for Presence & in Service Date	✓			
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			
Dash Lights, Step, Interior & Destination Lights for Operation	✓			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓			
Gear & Clutch Controls for Correct Operation	✓			
Steering System for Free Play & Slackness	✓			
Windscreen Wipers for Operation & Condition	✓			
Windscreen Washers for Operation	✓			
Demister for Operation	✓			
Horn for Operation	✓			

Velocity Truck Centres Adelaide Pty Ltd
 T/A Dairer Trucks Mount Gambier
 201A Jubilee Hwy, Mount Gambier SA 5290
 Telephone: 08 8 253 302
 Fax: 08 8 253 302

Inspection Undertaken by 936867 Signed [Signature] Date 30.8.22

*This form must be kept for a period of at least six (6) months after the inspection.

FIRST SCHEDULE: PART 1



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours
Address P.O. Box 609, (78 Sturt Street)
Mount Gambier 5290
Registration Number SB61GM
Date 28.11.22 **Odometer** 71201 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓			
Wheels for Condition	✓			
Tyres for Correct Pressure	✓			
Tyre Tread for Condition & Depth	✓			
Tyre Walls (without wheel removal) for Damage	✓			
Tyre Construction for Correct Location	✓			
BRAKES				
Service & Parking Brake for Correct Operation	✓			
Brake System for Air Leaks	✓			
Drain Valves for Operation	✓			
Hydraulic Fluid for Level & Leaks	✓			
Brake Warning System for Operation	✓			
ABS & EBS Warning System for Operation	✓			
BATTERY				
Battery Terminals & Cables for Condition	✓			
Battery & Battery Carrier Security	✓			
GENERAL				
Power Steering System Leaks	✓			
Engine for Oil & Water Leaks	✓			
Exhaust System for Condition, Security & Efficiency	✓			
Gearbox & Differential Oil Leaks	✓			
Fuel System Leaks	✓			
BODY				
Glazing Condition	✓			
Body Exterior for Damage & Dangerous Projections	✓			
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			
Rear Vision Mirrors for Security & Condition	✓			
Passenger Access Doors for Security & Operation	✓			
Seats for Security	✓			
Steps, Floor & Hatches for Security & Condition	✓			
Fire Extinguisher for Presence & in Service Date	✓			
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			
Dash Lights, Step, Interior & Destination Lights for Operation	✓			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓			
Gear & Clutch Controls for Correct Operation	✓			
Steering System for Free Play & Slackness	✓			
Windscreen Wipers for Operation & Condition	✓			
Windscreen Washers for Operation	✓			
Demister for Operation	✓			
Horn for Operation	✓			

Velocity Truck Centres Adelaide Pty Ltd
 T/A Daniel Trucks Mount Gambier
 201A Jubilee Hwy Mount Gambier SA 5290
 Telephone: 08 8725 8802
 Fax: 08 8725 8802
 ABN: 15 151 699 604

Inspection Undertaken by Stephen Just Signed [Signature] Date 28.11.22

*This form must be kept for a period of at least six (6) months after the inspection.

FIRST SCHEDULE: PART 1



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1007
45 151 699 651
Telephone: 08 8725 3902

Company / Owner Lake City Tours **Registration Number** SB61GM
Address P.O. Box 609, (78 Sturt Street)
Mount Gambier 5290
Date 10 3.. 2023 **Odometer** 72453 kms km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓			
Wheels for Condition	✓			
Tyres for Correct Pressure	✓			
Tyre Tread for Condition & Depth	✓			
Tyre Walls (without wheel removal) for Damage	✓			
Tyre Construction for Correct Location	✓			
BRAKES				
Service & Parking Brake for Correct Operation	✓			
Brake System for Air Leaks	✓			
Drain Valves for Operation	✓			
Hydraulic Fluid for Level & Leaks	✓			
Brake Warning System for Operation	✓			
ABS & EBS Warning System for Operation	✓			
BATTERY				
Battery Terminals & Cables for Condition	✓			
Battery & Battery Carrier Security	✓			
GENERAL				
Power Steering System Leaks	✓			
Engine for Oil & Water Leaks	✓			
Exhaust System for Condition, Security & Efficiency	✓			
Gearbox & Differential Oil Leaks	✓	X	Daimler Trucks	
Fuel System Leaks	✓			
BODY				
Glazing Condition	✓			
Body Exterior for Damage & Dangerous Projections	✓			
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			
Rear Vision Mirrors for Security & Condition	✓			
Passenger Access Doors for Security & Operation	✓			
Seats for Security	✓			
Steps, Floor & Hatches for Security & Condition	✓			
Fire Extinguisher for Presence & in Service Date	✓			
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			
Dash Lights, Step, Interior & Destination Lights for Operation	✓			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓			
Gear & Clutch Controls for Correct Operation	✓			
Steering System for Free Play & Slackness	✓			
Windscreen Wipers for Operation & Condition	✓			
Windscreen Washers for Operation	✓			
Demister for Operation	✓			
Horn for Operation	✓			

Inspection Undertaken by Stephen Just Signed [Signature] Date 10/3/23

*This form must be kept for a period of at least six (6) months after the inspection.

Velocity Truck Centres Adelaide Pty Ltd
 T/A Daimler Trucks Mount Gambier
 201A Jubilee Hwy, Mount Gambier SA 5290

FIRST SCHEDULE: PART 1



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours **Registration Number**
Address P.O. Box 609, (78 Sturt Street) **SB61GM**
Mount Gambier 5290
Date 5. 5. 2023 **Odometer** 73146 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓			
Wheels for Condition	✓			
Tyres for Correct Pressure	✓			
Tyre Tread for Condition & Depth	✓			
Tyre Walls (without wheel removal) for Damage	✓			
Tyre Construction for Correct Location	✓			
BRAKES				
Service & Parking Brake for Correct Operation	✓			
Brake System for Air Leaks	N/A			
Drain Valves for Operation	N/A			
Hydraulic Fluid for Level & Leaks	✓			
Brake Warning System for Operation	✓			
ABS & EBS Warning System for Operation	✓			
BATTERY				
Battery Terminals & Cables for Condition	✓			
Battery & Battery Carrier Security	✓			
GENERAL				
Power Steering System Leaks	✓			
Engine for Oil & Water Leaks	✓			
Exhaust System for Condition, Security & Efficiency	✓			
Gearbox & Differential Oil Leaks	✓			
Fuel System Leaks	✓			
BODY				
Glazing Condition	✓			
Body Exterior for Damage & Dangerous Projections	✓			
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			
Rear Vision Mirrors for Security & Condition	✓			
Passenger Access Doors for Security & Operation	✓			
Seats for Security	✓			
Steps, Floor & Hatches for Security & Condition	✓			
Fire Extinguisher for Presence & in Service Date	✓			
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			
Dash Lights, Step, Interior & Destination Lights for Operation	✓			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓			
Gear & Clutch Controls for Correct Operation	✓			
Steering System for Free Play & Slackness	✓			
Windscreen Wipers for Operation & Condition	✓			
Windscreen Washers for Operation	✓			
Demister for Operation	✓			
Horn for Operation	✓			

Velocity Truck Centres Adelaide Pty Ltd
 201 Jubilee Hwy, Mount Gambier SA 5290
 Telephone: 08 7253902
 ABN 45 151 99 651

Inspection Undertaken by Adrian Heinrich Signed [Signature] Date 5.5.2023

*This form must be kept for a period of at least six (6) months after the inspection.

FIRST SCHEDULE: PART 2



Government of South Australia
Department of Planning,
Transport and Infrastructure

**Code of Practice for Buses
Mandatory Maintenance
Procedure Part 2**

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours **Registration Number** SB61GM
Address P.O. Box 609 (78 Sturt Street)
 Mount Gambier, 5290
Date 30 8 22 **Odometer** 71,153 km

INSPECTION SHEET NUMBER 2

To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first
 • All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
SUSPENSION				
"U" Bolts & Centre Bolts for Security & Condition	✓			
Radius Rods & Joints for Condition	✓			
Front & Rear Axle Mounts for Condition & Cracks	✓			
Springs & Shackles for Condition	✓			
Shock Absorber & Joints for Condition	✓			
Air Bag System for Condition				
BRAKES				
Brake Lines & Mounts for Condition	✓			
Slack Adjusters & Auto Adjusters for Operation & Condition				
Brake Linings for Wear & Contamination	✓			
Air Filter for Security & Cleanliness	✓			
Air Priority System for Operation	✓			
Air or Vacuum for Correct Build Up Time	✓			
Retarder & Exhaust Brake for Operation & Control	✓			
STEERING				
Steering Box for Security & Operation	✓			
Steering System for Condition & Play	✓			
Steering Wheel & Column for Play & Security	✓			
GENERAL				
Engine Insulating Material for Contamination & Security	✓			
Starter Motor for Security	✓			
Tail Shafts & Guards for Condition & Security	✓			
Universal Joints & Splines for Condition	✓			
Fuel Tank & Fuel System for Security	✓			
Wheel Bearings for Adjustment	✓			
Axle Hub Seals for Leaks	✓			
Seat Belt Condition & Operation	✓			
Door Interlocks for Correct Operation (if fitted)	✓			
BODY				
Body Mounts Attachments for Security & Condition	✓			
Body for Visual Structural Defects & Corrosion	✓			

Velocity Truck Centres Adelaide Pty Ltd
 T/A Daimler Trucks Mount Gambier
 201 A Jubilee Hwy, Mount Gambier SA 5290
 Telephone: 08 8725 3302
 ABN 45 151 699 664

Inspection Undertaken by 956867 Signed [Signature] Date 30 8 22

*This form must be kept for a period of at least one (1) year after the inspection.

FIRST SCHEDULE: PART 2



Government of South Australia
Department of Planning,
Transport and Infrastructure

**Code of Practice for Buses
Mandatory Maintenance
Procedure Part 2**

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours **Registration Number** SB61GM
Address P.O. Box 609 (78 Sturt Street)
 Mount Gambier, 5290
Date 28 11 2022 **Odometer** 71201 km

INSPECTION SHEET NUMBER 2

- To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first
- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
SUSPENSION				
"U" Bolts & Centre Bolts for Security & Condition	✓			
Radius Rods & Joints for Condition	✓			
Front & Rear Axle Mounts for Condition & Cracks	✓			
Springs & Shackles for Condition	✓			
Shock Absorber & Joints for Condition	✓			
Air Bag System for Condition	✓			
BRAKES				
Brake Lines & Mounts for Condition	✓			
Slack Adjusters & Auto Adjusters for Operation & Condition	✓			
Brake Linings for Wear & Contamination	✓			
Air Filter for Security & Cleanliness	✓			
Air Priority System for Operation	✓			
Air or Vacuum for Correct Build Up Time	✓			
Retarder & Exhaust Brake for Operation & Control	✓			
STEERING				
Steering Box for Security & Operation	✓			
Steering System for Condition & Play	✓			
Steering Wheel & Column for Play & Security	✓			
GENERAL				
Engine Insulating Material for Contamination & Security	✓			
Starter Motor for Security	✓			
Tail Shafts & Guards for Condition & Security	✓			
Universal Joints & Splines for Condition	✓			
Fuel Tank & Fuel System for Security	✓			
Wheel Bearings for Adjustment	✓			
Axle Hub Seals for Leaks	✓			
Seat Belt Condition & Operation	✓			
Door Interlocks for Correct Operation (if fitted)	✓			
BODY				
Body Mounts Attachments for Security & Condition	✓			
Body for Visual Structural Defects & Corrosion	✓			

Validity Truck Centres Adelaide Pty Ltd
 T/A Dalmer Trucks Mount Gambier
 201A Jubilee Hwy, Mount Gambier SA 5290
 Telephone: 86725 3902

Inspection Undertaken by Stephen Just Signed [Signature] Date 28/11/22

*This form must be kept for a period of at least one (1) year after the inspection.

FIRST SCHEDULE: PART 2



Government of South Australia
 Department of Planning,
 Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 2

Vehicle Inspections
 PO BOX 1533
 ADELAIDE SA 5001

MR 1090
 07/16

Company / Owner Lake City Tours
Address P.O. Box 609 (78 Sturt Street)
 Mount Gambier, 5290

Registration Number SB81GM

Date 10 3 2023

Odometer 72453kms

201...
 Telephone: 08 8725 3902
 Fax: 08 8725 3902
 Email: 151 699 651
 Centres Adelaide Pty Ltd
 Trucks Mount Gambier
 SA 5290

INSPECTION SHEET NUMBER 2

To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first
 • All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
SUSPENSION				
"U" Bolts & Centre Bolts for Security & Condition	✓			
Radius Rods & Joints for Condition	✓			
Front & Rear Axle Mounts for Condition & Cracks	✓			
Springs & Shackles for Condition	✓			
Shock Absorber & Joints for Condition	✓			
Air Bag System for Condition	---			
BRAKES				
Brake Lines & Mounts for Condition	✓			
Slack Adjusters & Auto Adjusters for Operation & Condition	✓			
Brake Linings for Wear & Contamination	✓			
Air Filter for Security & Cleanliness	✓			
Air Priority System for Operation	---			
Air or Vacuum for Correct Build Up Time	✓			
Retarder & Exhaust Brake for Operation & Control	✓			
STEERING				
Steering Box for Security & Operation	✓			
Steering System for Condition & Play	✓			
Steering Wheel & Column for Play & Security	✓			
GENERAL				
Engine Insulating Material for Contamination & Security	✓			
Starter Motor for Security	✓			
Tail Shafts & Guards for Condition & Security	✓			
Universal Joints & Splines for Condition	✓			
Fuel Tank & Fuel System for Security	✓			
Wheel Bearings for Adjustment	✓			
Axle Hub Seals for Leaks	✓			
Seat Belt Condition & Operation	✓			
Door Interlocks for Correct Operation (if fitted)	✓			
BODY				
Body Mounts Attachments for Security & Condition	✓			
Body for Visual Structural Defects & Corrosion	✓			

Inspection Undertaken by Stephen Just Signed Date 10.3.23

*This form must be kept for a period of at least one (1) year after the inspection.

FIRST SCHEDULE: PART 1



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours **Registration Number** SB61GM
Address PO Box 609 (78 Sturt Street)
Mount Gambier 5290
Date 11. 9. 2023 **Odometer** 74091 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓			
Wheels for Condition	✓			
Tyres for Correct Pressure	✓			
Tyre Tread for Condition & Depth	✓	✓	Trident	
Tyre Walls (without wheel removal) for Damage	✓			
Tyre Construction for Correct Location	✓			
BRAKES				
Service & Parking Brake for Correct Operation	✓			
Brake System for Air Leaks	N-A			
Drain Valves for Operation	N-A			
Hydraulic Fluid for Level & Leaks	N-A			
Brake Warning System for Operation	✓			
ABS & EBS Warning System for Operation	✓			
BATTERY				
Battery Terminals & Cables for Condition	✓			
Battery & Battery Carrier Security	✓			
GENERAL				
Power Steering System Leaks	✓			
Engine for Oil & Water Leaks	✓			
Exhaust System for Condition, Security & Efficiency	✓			
Gearbox & Differential Oil Leaks	✓			
Fuel System Leaks	✓			
BODY				
Glazing Condition	✓			
Body Exterior for Damage & Dangerous Projections	✓			
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			
Rear Vision Mirrors for Security & Condition	✓			
Passenger Access Doors for Security & Operation	✓			
Seats for Security	✓			
Steps, Floor & Hatches for Security & Condition	✓			
Fire Extinguisher for Presence & in Service Date	✓			
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			
Dash Lights, Step, Interior & Destination Lights for Operation	✓			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓			
Gear & Clutch Controls for Correct Operation	N-A			
Steering System for Free Play & Slackness	✓			
Windscreen Wipers for Operation & Condition	✓			
Windscreen Washers for Operation	✓			
Demister for Operation	✓			
Horn for Operation	✓			

TRIPLES
DISTRIBUTORS

triples.accounts@ray.scottsup.com.au
Telephone: (08) 87 23 7793

Inspection Undertaken by Dylan Keillor Signed [Signature] Date 11.9.2023

*This form must be kept for a period of at least six (6) months after the inspection.

FIRST SCHEDULE: PART 1



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours **Registration Number** SB61GM
Address PO Box 609 (78 Sturt Street)
Mount Gambier 5290
Date 7. 12. 23 **Odometer** 75540 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓			
Wheels for Condition	✓	✓	Trident	✓
Tyres for Correct Pressure	✓			
Tyre Tread for Condition & Depth	✓			
Tyre Walls (without wheel removal) for Damage	✓			
Tyre Construction for Correct Location	✓			
BRAKES				
Service & Parking Brake for Correct Operation	✓			
Brake System for Air Leaks	-			
Drain Valves for Operation	-			
Hydraulic Fluid for Level & Leaks				
Brake Warning System for Operation	✓			
ABS & EBS Warning System for Operation	✓			
BATTERY				
Battery Terminals & Cables for Condition				
Battery & Battery Carrier Security				
GENERAL				
Power Steering System Leaks	✓			
Engine for Oil & Water Leaks	✓			
Exhaust System for Condition, Security & Efficiency	✓			
Gearbox & Differential Oil Leaks	✓			
Fuel System Leaks	✓			
BODY				
Glazing Condition	✓			
Body Exterior for Damage & Dangerous Projections				
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			
Rear Vision Mirrors for Security & Condition	✓			
Passenger Access Doors for Security & Operation	✓			
Seats for Security	✓			
Steps, Floor & Hatches for Security & Condition	✓			
Fire Extinguisher for Presence & in Service Date				
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			
Dash Lights, Step, Interior & Destination Lights for Operation	✓			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓			
Gear & Clutch Controls for Correct Operation	-			
Steering System for Free Play & Slackness	✓			
Windscreen Wipers for Operation & Condition	✓			
Windscreen Washers for Operation	✓			
Demister for Operation	✓			
Horn for Operation	✓			

Inspection Undertaken by Harrison Stafford Signed [Signature] Date 7.12.23

*This form must be kept for a period of at least six (6) months after the inspection.

FIRST SCHEDULE: PART 1



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours
Address PO Box 609 (78 Sturt Street)
Mount Gambier 5290
Registration Number SB61GM
Date 6. 3. 2024
Odometer 76,898 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓		6-3-24	DA
Wheels for Condition	✓		6-3-24	DA
Tyres for Correct Pressure	✓		6-3-24	DA
Tyre Tread for Condition & Depth	✓		6-3-24	DA
Tyre Walls (without wheel removal) for Damage	✓		6-3-24	DA
Tyre Construction for Correct Location	✓		6-3-24	DA
BRAKES				
Service & Parking Brake for Correct Operation	✓		6-3-24	DA
Brake System for Air Leaks	X		6-3-24	DA
Drain Valves for Operation	X		6-3-24	DA
Hydraulic Fluid for Level & Leaks	✓		6-3-24	DA
Brake Warning System for Operation	✓		6-3-24	DA
ABS & EBS Warning System for Operation	✓		6-3-24	DA
BATTERY				
Battery Terminals & Cables for Condition	✓		6-3-24	DA
Battery & Battery Carrier Security	✓		6-3-24	DA
GENERAL				
Power Steering System Leaks	✓		6-3-24	DA
Engine for Oil & Water Leaks	✓		6-3-24	DA
Exhaust System for Condition, Security & Efficiency	✓		6-3-24	DA
Gearbox & Differential Oil Leaks	✓		6-3-24	DA
Fuel System Leaks	✓		6-3-24	DA
BODY				
Glazing Condition	✓		6-3-24	DA
Body Exterior for Damage & Dangerous Projections	✓		6-3-24	DA
Engine Cover Sealing Inside Passenger Compartment for Condition	✓		6-3-24	DA
Rear Vision Mirrors for Security & Condition	✓		6-3-24	DA
Passenger Access Doors for Security & Operation	✓		6-3-24	DA
Seats for Security	✓		6-3-24	DA
Steps, Floor & Hatches for Security & Condition	✓		6-3-24	DA
Fire Extinguisher for Presence & in Service Date	✓		6-3-24	DA
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓		6-3-24	DA
Dash Lights, Step, Interior & Destination Lights for Operation	✓		6-3-24	DA
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓		6-3-24	DA
Gear & Clutch Controls for Correct Operation	X		6-3-24	DA
Steering System for Free Play & Slackness	✓		6-3-24	DA
Windscreen Wipers for Operation & Condition	✓		6-3-24	DA
Windscreen Washers for Operation	✓		6-3-24	DA
Demister for Operation	✓		6-3-24	DA
Horn for Operation	✓		6-3-24	DA

Inspection Undertaken by TRIPLES Dylan Signed DA Date 6.3.24

*This form must be kept for a period of at least six (6) months after the inspection.

FIRST SCHEDULE: PART 1



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours **Registration Number** SB61GM
Address PO Box 609 (78 Sturt Street)
Mount Gambier 5290
Date 6. 5. 24 **Odometer** 77 562 km

INSPECTION SHEET NUMBER 1

TRIPLE S DISTRIBUTORS

ALLAN 0427 897 154
JOSH 0409 895 247

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓		6.5.24	DK
Wheels for Condition	✓		6.5.24	DK
Tyres for Correct Pressure	✓		6.5.24	DK
Tyre Tread for Condition & Depth	✓		6.5.24	DK
Tyre Walls (without wheel removal) for Damage	✓		6.5.24	DK
Tyre Construction for Correct Location	✓		6.5.24	DK
BRAKES				
Service & Parking Brake for Correct Operation	✓		6.5.24	DK
Brake System for Air Leaks	N/A		6.5.24	DK
Drain Valves for Operation	N/A		6.5.24	DK
Hydraulic Fluid for Level & Leaks	✓		6.5.24	DK
Brake Warning System for Operation	✓		6.5.24	DK
ABS & EBS Warning System for Operation	✓		6.5.24	DK
BATTERY				
Battery Terminals & Cables for Condition	✓		6.5.24	DK
Battery & Battery Carrier Security	✓		6.5.24	DK
GENERAL				
Power Steering System Leaks	✓		6.5.24	DK
Engine for Oil & Water Leaks	✓		6.5.24	DK
Exhaust System for Condition, Security & Efficiency	✓		6.5.24	DK
Gearbox & Differential Oil Leaks	✓		6.5.24	DK
Fuel System Leaks	✓		6.5.24	DK
BODY				
Glazing Condition	✓		6.5.24	DK
Body Exterior for Damage & Dangerous Projections	✓		6.5.24	DK
Engine Cover Sealing Inside Passenger Compartment for Condition	✓		6.5.24	DK
Rear Vision Mirrors for Security & Condition	✓		6.5.24	DK
Passenger Access Doors for Security & Operation	✓		6.5.24	DK
Seats for Security	✓		6.5.24	DK
Steps, Floor & Hatches for Security & Condition	✓		6.5.24	DK
Fire Extinguisher for Presence & in Service Date	✓		6.5.24	DK
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓		6.5.24	DK
Dash Lights, Stop, Interior & Destination Lights for Operation	✓		6.5.24	DK
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓		6.5.24	DK
Gear & Clutch Controls for Correct Operation	✓		6.5.24	DK
Steering System for Free Play & Slackness	✓		6.5.24	DK
Windscreen Wipers for Operation & Condition	✓		6.5.24	DK
Windscreen Washers for Operation	✓		6.5.24	DK
Demister for Operation	✓		6.5.24	DK
Horn for Operation	✓		6.5.24	DK

Inspection Undertaken by Dylan Kellogg Signed DK Date 6.5.24

*This form must be kept for a period of at least six (6) months after the inspection.

FIRST SCHEDULE: PART 2



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 2

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours
Address PO Box 609 (78 Sturt Street)
Mount Gambier 5290
Registration Number SB61GM
Date 11. 9. 2023
Odometer 74091 km

INSPECTION SHEET NUMBER 2

To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
SUSPENSION				
"U" Bolts & Centre Bolts for Security & Condition	✓			
Radius Rods & Joints for Condition	✓			
Front & Rear Axle Mounts for Condition & Cracks	✓			
Springs & Shackles for Condition	✓			
Shock Absorber & Joints for Condition	✓			
Air Bag System for Condition	N-A			
BRAKES				
Brake Lines & Mounts for Condition	✓			
Slack Adjusters & Auto Adjusters for Operation & Condition	N-A			
Brake Linings for Wear & Contamination	✓			
Air Filter for Security & Cleanliness	✓			
Air Priority System for Operation	✓			
Air or Vacuum for Correct Build Up Time	✓			
Retarder & Exhaust Brake for Operation & Control	✓			
STEERING				
Steering Box for Security & Operation	✓			
Steering System for Condition & Play	✓			
Steering Wheel & Column for Play & Security	✓			
GENERAL				
Engine Insulating Material for Contamination & Security	✓			
Starter Motor for Security	✓			
Tail Shafts & Guards for Condition & Security	✓			
Universal Joints & Splines for Condition	✓			
Fuel Tank & Fuel System for Security	✓			
Wheel Bearings for Adjustment	✓			
Axle Hub Seals for Leaks	✓			
Seat Belt Condition & Operation	✓			
Door Interlocks for Correct Operation (if fitted)	✓			
BODY				
Body Mounts Attachments for Security & Condition	✓			
Body for Visual Structural Defects & Corrosion	✓			
TRIPLES				
DISTRIBUTORS				
triples.accounts@rayscottgroup.com.au				
Telephone (08) 87 232 193				

Inspection Undertaken by Dylan Kellogg Signed [Signature] Date 11/9/2023

*This form must be kept for a period of at least one (1) year after the inspection.

FIRST SCHEDULE: PART 2



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 2

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours
Address PO Box 609 (78 Sturt Street)
Mount Gambier 5290
Registration Number SB61GM
Date 7.12.23 **Odometer** 75540 km

INSPECTION SHEET NUMBER 2

To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
SUSPENSION				
"U" Bolts & Centre Bolts for Security & Condition	✓			
Radius Rods & Joints for Condition	✓			
Front & Rear Axle Mounts for Condition & Cracks	✓			
Springs & Shackles for Condition	✓			
Shock Absorber & Joints for Condition	✓			
Air Bag System for Condition	-			
BRAKES				
Brake Lines & Mounts for Condition	✓			
Slack Adjusters & Auto Adjusters for Operation & Condition	-			
Brake Linings for Wear & Contamination	✓			
Air Filter for Security & Cleanliness	✓			
Air Priority System for Operation	✓			
Air or Vacuum for Correct Build Up Time	✓			
Retarder & Exhaust Brake for Operation & Control	✓			
STEERING				
Steering Box for Security & Operation	✓			
Steering System for Condition & Play	✓			
Steering Wheel & Column for Play & Security	✓			
GENERAL				
Engine Insulating Material for Contamination & Security	✓			
Starter Motor for Security	✓			
Tail Shafts & Guards for Condition & Security	✓			
Universal Joints & Splines for Condition	✓			
Fuel Tank & Fuel System for Security	✓			
Wheel Bearings for Adjustment	✓			
Axle Hub Seals for Leaks	✓			
Seat Belt Condition & Operation	✓			
Door Interlocks for Correct Operation (if fitted)	✓			
BODY				
Body Mounts Attachments for Security & Condition	✓			
Body for Visual Structural Defects & Corrosion	✓			

Inspection Undertaken by Harrison Stafford Signed [Signature] Date 7.12.23

*This form must be kept for a period of at least one (1) year after the inspection.

FIRST SCHEDULE: PART 2



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 2

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours
Address PO Box 609 (78 Sturt Street)
Mount Gambier 5290
Registration Number SB61GM
Date 6 3 2024
Odometer 76,898 km

INSPECTION SHEET NUMBER 2

To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
SUSPENSION				
"U" Bolts & Centre Bolts for Security & Condition	✓		6-3-24	Ray
Radius Rods & Joints for Condition	✓		6-3-24	Ray
Front & Rear Axle Mounts for Condition & Cracks	✓		6-3-24	Ray
Springs & Shackles for Condition	✓		6-3-24	Ray
Shock Absorber & Joints for Condition	✓		6-3-24	Ray
Air Bag System for Condition	N/A		6-3-24	Ray
BRAKES				
Brake Lines & Mounts for Condition	✓		6-3-24	Ray
Slack Adjusters & Auto Adjusters for Operation & Condition	✓		6-3-24	Ray
Brake Linings for Wear & Contamination	✓		6-3-24	Ray
Air Filter for Security & Cleanliness	X		6-3-24	Ray
Air Priority System for Operation	N/A		6-3-24	Ray
Air or Vacuum for Correct Build Up Time	X/A		6-3-24	Ray
Retarder & Exhaust Brake for Operation & Control	✓		6-3-24	Ray
STEERING				
Steering Box for Security & Operation	✓		6-3-24	Ray
Steering System for Condition & Play	✓		6-3-24	Ray
Steering Wheel & Column for Play & Security	✓		6-3-24	Ray
GENERAL				
Engine Insulating Material for Contamination & Security	✓		6-3-24	Ray
Starter Motor for Security	✓		6-3-24	Ray
Tail Shafts & Guards for Condition & Security	✓		6-3-24	Ray
Universal Joints & Splines for Condition	✓		6-3-24	Ray
Fuel Tank & Fuel System for Security	✓		6-3-24	Ray
Wheel Bearings for Adjustment	✓		6-3-24	Ray
Axle Hub Seals for Leaks	✓		6-3-24	Ray
Seat Belt Condition & Operation	X		6-3-24	Ray
Door Interlocks for Correct Operation (if fitted)	✓		6-3-24	Ray
BODY				
Body Mounts Attachments for Security & Condition	✓		6-3-24	Ray
Body for Visual Structural Defects & Corrosion	✓		6-3-24	Ray
TRIPLE S DISTRIBUTORS				
ALLAN 0427 897 154				
JOSH 0409 895 247				
triples@rayscottgroup.com.au				
			6-3-24	
			6-3-24	
			6-3-24	
			6-3-24	
			6-3-24	
			6-3-24	
			6-3-24	
			6-3-24	

Inspection Undertaken by TRIPLES DYLAN Signed [Signature] Date 6/3/24

*This form must be kept for a period of at least one (1) year after the inspection.

FIRST SCHEDULE: PART 2



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 2

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours **Registration Number** SB61GM
Address PO Box 609 (78 Sturt Street)
Mount Gambier 5290
Date 6 5 24 **Odometer** 77 562 km

INSPECTION SHEET NUMBER 2

TRIPLE S DISTRIBUTORS
1ST FLOOR
110 GILBERT STREET
ADELAIDE SA 5001
PHONE 0427 897 154
triples@rayscottgroup.com.au

To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first
• All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
SUSPENSION				
*U" Bolts & Centre Bolts for Security & Condition	✓		6-5-24	[Signature]
Radius Rods & Joints for Condition	✓		6-5-24	[Signature]
Front & Rear Axle Mounts for Condition & Cracks	✓		6-5-24	[Signature]
Springs & Shackles for Condition	✓		6-5-24	[Signature]
Shock Absorber & Joints for Condition	✓		6-5-24	[Signature]
Air Bag System for Condition	N/A		6-5-24	[Signature]
BRAKES				
Brake Lines & Mounts for Condition	✓		6-5-24	[Signature]
Slack Adjusters & Auto Adjusters for Operation & Condition	N/A		6-5-24	[Signature]
Brake Linings for Wear & Contamination	✓		6-5-24	[Signature]
Air Filter for Security & Cleanliness	✓		6-5-24	[Signature]
Air Priority System for Operation	N/A		6-5-24	[Signature]
Air or Vacuum for Correct Build Up Time	N/A		6-5-24	[Signature]
Retarder & Exhaust Brake for Operation & Control	✓		6-5-24	[Signature]
STEERING				
Steering Box for Security & Operation	✓		6-5-24	[Signature]
Steering System for Condition & Play	✓		6-5-24	[Signature]
Steering Wheel & Column for Play & Security	✓		6-5-24	[Signature]
GENERAL				
Engine Insulating Material for Contamination & Security	✓		6-5-24	[Signature]
Starter Motor for Security	✓		6-5-24	[Signature]
Tail Shafts & Guards for Condition & Security	✓		6-5-24	[Signature]
Universal Joints & Splines for Condition	✓		6-5-24	[Signature]
Fuel Tank & Fuel System for Security	✓		6-5-24	[Signature]
Wheel Bearings for Adjustment	✓		6-5-24	[Signature]
Axle Hub Seals for Leaks	✓		6-5-24	[Signature]
Seat Belt Condition & Operation	✓		6-5-24	[Signature]
Door Interlocks for Correct Operation (if fitted)	✓		6-5-24	[Signature]
BODY				
Body Mounts Attachments for Security & Condition	✓		6-5-24	[Signature]
Body for Visual Structural Defects & Corrosion	✓		6-5-24	[Signature]

Inspection Undertaken by Dylan Kelleghy Signed [Signature] Date 6.5.24

*This form must be kept for a period of at least one (1) year after the inspection.



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner LAKE CITY TOURS
Address P.O BOX 609 (78 STURT STREET)
MOUNT GAMBIER 5290
Registration Number SB61GM
Date 23. 8. 24. **Odometer** 78 965 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓		23.8.24	OK
Wheels for Condition	✓		23.8.24	OK
Tyres for Correct Pressure	✓		23.8.24	OK
Tyre Tread for Condition & Depth	✓		23.8.24	OK
Tyre Walls (without wheel removal) for Damage	✓		23.8.24	OK
Tyre Construction for Correct Location	✓		23.8.24	OK
BRAKES				
Service & Parking Brake for Correct Operation	✓		23.8.24	OK
Brake System for Air Leaks	A/A		23.8.24	OK
Drain Valves for Operation	N/A		23.8.24	OK
Hydraulic Fluid for Level & Leaks	✓		23.8.24	OK
Brake Warning System for Operation	✓		23.8.24	OK
ABS & EBS Warning System for Operation	✓		23.8.24	OK
BATTERY				
Battery Terminals & Cables for Condition	✓		23.8.24	OK
Battery & Battery Carrier Security	✓		23.8.24	OK
GENERAL				
Power Steering System Leaks	✓		23.8.24	OK
Engine for Oil & Water Leaks	✓		23.8.24	OK
Exhaust System for Condition, Security & Efficiency	✓		23.8.24	OK
Gearbox & Differential Oil Leaks	✓		23.8.24	OK
Fuel System Leaks	✓		23.8.24	OK
BODY				
Glazing Condition	✓		23.8.24	OK
Body Exterior for Damage & Dangerous Projections	✓		23.8.24	OK
Engine Cover Sealing Inside Passenger Compartment for Condition	✓		23.8.24	OK
Rear Vision Mirrors for Security & Condition	✓		23.8.24	OK
Passenger Access Doors for Security & Operation	✓		23.8.24	OK
Seats for Security	✓		23.8.24	OK
Steps, Floor & Hatches for Security & Condition	✓		23.8.24	OK
Fire Extinguisher for Presence & in Service Date	✓		23.8.24	OK
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓		23.8.24	OK
Dash Lights, Step, Interior & Destination Lights for Operation	✓		23.8.24	OK
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓		23.8.24	OK
Gear & Clutch Controls for Correct Operation	N/A		23.8.24	OK
Steering System for Free Play & Slackness	✓		23.8.24	OK
Windscreen Wipers for Operation & Condition	✓		23.8.24	OK
Windscreen Washers for Operation	✓		23.8.24	OK
Demister for Operation	✓		23.8.24	OK
Horn for Operation	✓		23.8.24	OK

Inspection Undertaken by Dylan Kellogg Signed DK Date 23.8.24.

*This form must be kept for a period of at least six (6) months after the inspection.



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner LAKE CITY TOURS **Registration Number**
Address P.O BOX 609 (78 STURT STREET) **SB61GM**
MOUNT GAMBIER 5290
Date 22 11 24 **Odometer** 81931 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	/			
Wheels for Condition	/			
Tyres for Correct Pressure	/			
Tyre Tread for Condition & Depth	/			
Tyre Walls (without wheel removal) for Damage	/			
Tyre Construction for Correct Location	/			
BRAKES				
Service & Parking Brake for Correct Operation	/			
Brake System for Air Leaks	/			
Drain Valves for Operation	/			
Hydraulic Fluid for Level & Leaks	/			
Brake Warning System for Operation	/			
ABS & EBS Warning System for Operation	/			
BATTERY				
Battery Terminals & Cables for Condition	/			
Battery & Battery Carrier Security	/			
GENERAL				
Power Steering System Leaks	/			
Engine for Oil & Water Leaks	/			
Exhaust System for Condition, Security & Efficiency	/			
Gearbox & Differential Oil Leaks	/	X		
Fuel System Leaks	/			
BODY				
Glazing Condition	/			
Body Exterior for Damage & Dangerous Projections	/			
Engine Cover Sealing Inside Passenger Compartment for Condition	/			
Rear Vision Mirrors for Security & Condition	/	X	22/11/24	BS
Passenger Access Doors for Security & Operation	/			
Seats for Security	/	X	22/11/24	SM
Steps, Floor & Hatches for Security & Condition	/			
Fire Extinguisher for Presence & in Service Date	/			
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	/			
Dash Lights, Step, Interior & Destination Lights for Operation	/			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	/			
Gear & Clutch Controls for Correct Operation	/			
Steering System for Free Play & Slackness	/			
Windscreen Wipers for Operation & Condition	/			
Windscreen Washers for Operation	/			
Demister for Operation	/			
Horn for Operation	/			

Inspection Undertaken by Jack Signed JS Date 22/11/24

*This form must be kept for a period of at least six (6) months after the inspection.



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner LAKE CITY TOURS
Address P.O BOX 609 (78 STURT STREET)
MOUNT GAMBIER 5290
Registration Number SB61GM
Date 27/2/2025
Odometer 82814 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓			
Wheels for Condition	✓			
Tyres for Correct Pressure	✓			
Tyre Tread for Condition & Depth	✓			
Tyre Walls (without wheel removal) for Damage	✓			
Tyre Construction for Correct Location	✓			
BRAKES				
Service & Parking Brake for Correct Operation	✓			
Brake System for Air Leaks	N/A			
Drain Valves for Operation	N/A			
Hydraulic Fluid for Level & Leaks	✓			
Brake Warning System for Operation	✓			
ABS & EBS Warning System for Operation	✓			
BATTERY				
Battery Terminals & Cables for Condition	✓			
Battery & Battery Carrier Security	✓			
GENERAL				
Power Steering System Leaks	✓			
Engine for Oil & Water Leaks	✓			
Exhaust System for Condition, Security & Efficiency	✓			
Gearbox & Differential Oil Leaks	✓		27-2-25	MDM
Fuel System Leaks	✓			
BODY				
Glazing Condition	✓			
Body Exterior for Damage & Dangerous Projections	✓			
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			
Rear Vision Mirrors for Security & Condition	✓			
Passenger Access Doors for Security & Operation	✓			
Seats for Security	✓			
Steps, Floor & Hatches for Security & Condition	✓			
Fire Extinguisher for Presence & in Service Date	✓			
LIGHTING				
Headlamps, Park, Rear, Clearance; No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			
Dash Lights, Step, Interior & Destination Lights for Operation	✓			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓			
Gear & Clutch Controls for Correct Operation	N/A			
Steering System for Free Play & Slackness	✓			
Windscreen Wipers for Operation & Condition	✓			
Windscreen Washers for Operation	✓			
Demister for Operation	✓			
Horn for Operation	✓			

Inspection Undertaken by Juan Signed 23 Date 27/2/25

*This form must be kept for a period of at least six (6) months after the inspection.



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner LAKE CITY TOURS
Address P.O BOX 609 (78 STURT STREET)
MOUNT GAMBIER 5290
Registration Number SB61GM
Date 1. 5. 25
Odometer 83.682 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓			
Wheels for Condition	✓			
Tyres for Correct Pressure	✓			
Tyre Tread for Condition & Depth	✓			
Tyre Walls (without wheel removal) for Damage	✓			
Tyre Construction for Correct Location	✓			
BRAKES				
Service & Parking Brake for Correct Operation	✓			
Brake System for Air Leaks	✓			
Drain Valves for Operation	✓			
Hydraulic Fluid for Level & Leaks	✓			
Brake Warning System for Operation	✓			
ABS & EBS Warning System for Operation	✓			
BATTERY				
Battery Terminals & Cables for Condition	✓			
Battery & Battery Carrier Security	✓			
GENERAL				
Power Steering System Leaks	✓			
Engine for Oil & Water Leaks	✓			
Exhaust System for Condition, Security & Efficiency	✓			
Gearbox & Differential Oil Leaks	✓			
Fuel System Leaks	✓			
BODY				
Glazing Condition	✓			
Body Exterior for Damage & Dangerous Projections	✓			
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			
Rear Vision Mirrors for Security & Condition	✓			
Passenger Access Doors for Security & Operation	✓			
Seats for Security	✓			
Steps, Floor & Hatches for Security & Condition	✓			
Fire Extinguisher for Presence & in Service Date	✓			
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			
Dash Lights, Step, Interior & Destination Lights for Operation	✓			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓			
Gear & Clutch Controls for Correct Operation	✓			
Steering System for Free Play & Slackness	✓			
Windscreen Wipers for Operation & Condition	✓			
Windscreen Washers for Operation	✓			
Demister for Operation	✓			
Horn for Operation	✓			

TRIPLE S DISTRIBUTORS
ALLAN 0427 897 154
JOSH 0409 895 247
triples@rayscottgroup.com.au

Inspection Undertaken by Sauk Signed JS Date 1/5/25

*This form must be kept for a period of at least six (6) months after the inspection.



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 2

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner LAKE CITY TOURS
Address P.O BOX 609 (78 STURT STREET)
MOUNT GAMBIER 5290
Registration Number SB61GM
Date 23 8 24
Odometer 78965 km

INSPECTION SHEET NUMBER 2

To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
SUSPENSION				
"U" Bolts & Centre Bolts for Security & Condition	✓		23-8-24	DK
Radius Rods & Joints for Condition	✓		23-8-24	DK
Front & Rear Axle Mounts for Condition & Cracks	✓		23-8-24	DK
Springs & Shackles for Condition	✓		23-8-24	DK
Shock Absorber & Joints for Condition	✓		23-8-24	DK
Air Bag System for Condition	N/A		23-8-24	DK
BRAKES				
Brake Lines & Mounts for Condition	✓		23-8-24	DK
Slack Adjusters & Auto Adjusters for Operation & Condition	-		23-8-24	DK
Brake Linings for Wear & Contamination	✓		23-8-24	DK
Air Filter for Security & Cleanliness	✓		23-8-24	DK
Air Priority System for Operation	✓		23-8-24	DK
Air or Vacuum for Correct Build Up Time	N/A		23-8-24	DK
Retarder & Exhaust Brake for Operation & Control	✓		23-8-24	DK
STEERING				
Steering Box for Security & Operation	✓		23-8-24	DK
Steering System for Condition & Play	✓		23-8-24	DK
Steering Wheel & Column for Play & Security	✓		23-8-24	DK
GENERAL				
Engine Insulating Material for Contamination & Security	✓		23-8-24	DK
Starter Motor for Security	✓		23-8-24	DK
Tail Shafts & Guards for Condition & Security	✓		23-8-24	DK
Universal Joints & Splines for Condition	✓		23-8-24	DK
Fuel Tank & Fuel System for Security	✓		23-8-24	DK
Wheel Bearings for Adjustment	✓		23-8-24	DK
Axle Hub Seals for Leaks	✓		23-8-24	DK
Seat Belt Condition & Operation	✓		23-8-24	DK
Door Interlocks for Correct Operation (if fitted)	✓		23-8-24	DK
BODY				
Body Mounts Attachments for Security & Condition	✓		23-8-24	DK
Body for Visual Structural Defects & Corrosion	✓		23-8-24	DK

Inspection Undertaken by Dylan Kelloog Signed DK Date 23.8.24

*This form must be kept for a period of at least one (1) year after the inspection.

FIRST SCHEDULE PART 2



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 2

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner LAKE CITY TOURS
Address P.O BOX 609 (78 STURT STREET)
MOUNT GAMBIER 5290
Registration Number SB61GM
Date 22. 11. 24 Odometer 81931 km

INSPECTION SHEET NUMBER 2

To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Table with 5 columns: Item, Satisfactory (Yes/No), and Rectified (Date/Signed). Rows include categories like SUSPENSION, BRAKES, STEERING, GENERAL, and BODY with various sub-items.

Inspection Undertaken by [Signature] Signed [Signature] Date 22/11/24

*This form must be kept for a period of at least one (1) year after the inspection.

FIRST SCHEDULE PART 2



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 2

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner LAKE CITY TOURS **Registration Number**
Address P.O BOX 609 (78 STURT STREET) SB61GM
MOUNT GAMBIER 5290

Date 27 | 2 | 2025 **Odometer** 82814 km

INSPECTION SHEET NUMBER 2

To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
SUSPENSION				
"U" Bolts & Centre Bolts for Security & Condition	✓			
Radius Rods & Joints for Condition	✓			
Front & Rear Axle Mounts for Condition & Cracks	✓			
Springs & Shackles for Condition	✓			
Shock Absorber & Joints for Condition	✓			
Air Bag System for Condition	N/A			
BRAKES				
Brake Lines & Mounts for Condition	✓			
Slack Adjusters & Auto Adjusters for Operation & Condition	N/A			
Brake Linings for Wear & Contamination	✓			
Air Filter for Security & Cleanliness	✓			
Air Priority System for Operation	✓			
Air or Vacuum for Correct Build Up Time	✓			
Retarder & Exhaust Brake for Operation & Control	✓			
STEERING				
Steering Box for Security & Operation	✓			
Steering System for Condition & Play	✓			
Steering Wheel & Column for Play & Security	✓			
GENERAL				
Engine Insulating Material for Contamination & Security	✓			
Starter Motor for Security	✓			
Tail Shafts & Guards for Condition & Security	✓			
Universal Joints & Splines for Condition	✓			
Fuel Tank & Fuel System for Security	✓			
Wheel Bearings for Adjustment	✓			
Axle Hub Seals for Leaks	✓			
Seat Belt Condition & Operation	✓			
Door Interlocks for Correct Operation (if fitted)	✓			
BODY				
Body Mounts Attachments for Security & Condition	✓			
Body for Visual Structural Defects & Corrosion	✓			
<div style="border: 1px solid black; padding: 5px; width: fit-content; margin: 0 auto;"> <p>TRIPLE S DISTRIBUTORS</p> <p>ALLAN 0427 897 154</p> <p>JOSH 0409 895 247</p> <p>triples@rayscottgroup.com.au</p> </div>				

Inspection Undertaken by Jace Signed JS Date 27.2.25

*This form must be kept for a period of at least one (1) year after the inspection.

FIRST SCHEDULE: PART 2



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 2

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner LAKE CITY TOURS **Registration Number** SB61GM
Address P.O BOX 609 (78 STURT STREET)
MOUNT GAMBIER 5290
Date 1 5 25 **Odometer** 83,682 km

INSPECTION SHEET NUMBER 2

To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
SUSPENSION				
"U" Bolts & Centre Bolts for Security & Condition	✓			
Radius Rods & Joints for Condition	✓			
Front & Rear Axle Mounts for Condition & Cracks	✓			
Springs & Shackles for Condition	✓			
Shock Absorber & Joints for Condition	✓			
Air Bag System for Condition	-			
BRAKES				
Brake Lines & Mounts for Condition	✓			
Slack Adjusters & Auto Adjusters for Operation & Condition	-			
Brake Linings for Wear & Contamination	✓			
Air Filter for Security & Cleanliness	✓			
Air Priority System for Operation	✓			
Air or Vacuum for Correct Build Up Time	✓			
Retarder & Exhaust Brake for Operation & Control	✓			
STEERING				
Steering Box for Security & Operation	✓			
Steering System for Condition & Play	✓			
Steering Wheel & Column for Play & Security	✓			
GENERAL				
Engine Insulating Material for Contamination & Security	✓			
Starter Motor for Security	✓			
Tail Shafts & Guards for Condition & Security	✓			
Universal Joints & Splines for Condition	✓			
Fuel Tank & Fuel System for Security	✓			
Wheel Bearings for Adjustment	✓			
Axle Hub Seals for Leaks	✓			
Seat Belt Condition & Operation	✓			
Door Interlocks for Correct Operation (if fitted)				
BODY				
Body Mounts Attachments for Security & Condition	✓			
Body for Visual Structural Defects & Corrosion	✓			
<div style="border: 1px solid black; padding: 5px; width: fit-content; margin: 0 auto;"> <p>TRIPLE S DISTRIBUTORS ALLAN 0427 897 154 JOSH 0409 895 247 triples@rayscottgroup.com.au</p> </div>				

Inspection Undertaken by Jack Signed [Signature] Date 15/25

*This form must be kept for a period of at least one (1) year after the inspection.

FIRST SCHEDULE: PART 1



Government of South Australia
Department of Planning,
Transport and Infrastructure

**Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1**

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours **Registration Number**
Address P.O. Box 609, (78 Sturt Street) **SB61GM**
Mount Gambier 5290
Date 25/08/2025 **Odometer** 85,126 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓			
Wheels for Condition	✓			
Tyres for Correct Pressure	✓			
Tyre Tread for Condition & Depth	✓			
Tyre Walls (without wheel removal) for Damage	✓			
Tyre Construction for Correct Location	✓			
BRAKES				
Service & Parking Brake for Correct Operation	✓			
Brake System for Air Leaks	✓			
Drain Valves for Operation	✓			
Hydraulic Fluid for Level & Leaks	✓			
Brake Warning System for Operation	✓			
ABS & EBS Warning System for Operation	✓			
BATTERY				
Battery Terminals & Cables for Condition	✓			
Battery & Battery Carrier Security	✓			
GENERAL				
Power Steering System Leaks	✓			
Engine for Oil & Water Leaks	✓			
Exhaust System for Condition, Security & Efficiency	✓			
Gearbox & Differential Oil Leaks	✓			
Fuel System Leaks	✓			
BODY				
Glazing Condition	✓			
Body Exterior for Damage & Dangerous Projections	✓			
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			
Rear Vision Mirrors for Security & Condition	✓			
Passenger Access Doors for Security & Operation	✓			
Seats for Security	✓			
Steps, Floor & Hatches for Security & Condition	✓			
Fire Extinguisher for Presence & in Service Date	✓			
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			
Dash Lights, Step, Interior & Destination Lights for Operation	✓			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓			
Gear & Clutch Controls for Correct Operation	✓			
Steering System for Free Play & Slackness	✓			
Windscreen Wipers for Operation & Condition	✓			
Windscreen Washers for Operation	✓			
Demister for Operation	✓			
Horn for Operation	✓			

Inspection Undertaken by D. Halloran

Signed [Signature]

Date 25.8.25

*This form must be kept for a period of at least six (6) months after the inspection.



FIRST SCHEDULE: PART 1



Government of South Australia
Department of Planning,
Transport and Infrastructure

**Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1**

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours **Registration Number**
Address P.O. Box 609, (78 Sturt Street) SB61GM
Mount Gambier 5290
Date 11 25 **Odometer** km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness				
Wheels for Condition				
Tyres for Correct Pressure				
Tyre Tread for Condition & Depth				
Tyre Walls (without wheel removal) for Damage				
Tyre Construction for Correct Location				
BRAKES				
Service & Parking Brake for Correct Operation				
Brake System for Air Leaks				
Drain Valves for Operation				
Hydraulic Fluid for Level & Leaks				
Brake Warning System for Operation				
ABS & EBS Warning System for Operation				
BATTERY				
Battery Terminals & Cables for Condition				
Battery & Battery Carrier Security				
GENERAL				
Power Steering System Leaks				
Engine for Oil & Water Leaks				
Exhaust System for Condition, Security & Efficiency				
Gearbox & Differential Oil Leaks				
Fuel System Leaks				
BODY				
Glazing Condition				
Body Exterior for Damage & Dangerous Projections				
Engine Cover Sealing Inside Passenger Compartment for Condition				
Rear Vision Mirrors for Security & Condition				
Passenger Access Doors for Security & Operation				
Seats for Security				
Steps, Floor & Hatches for Security & Condition				
Fire Extinguisher for Presence & in Service Date				
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses				
Dash Lights, Step, Interior & Destination Lights for Operation				
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)				
Gear & Clutch Controls for Correct Operation				
Steering System for Free Play & Slackness				
Windscreen Wipers for Operation & Condition				
Windscreen Washers for Operation				
Demister for Operation				
Horn for Operation				

Sep to December 2025

Inspection Undertaken by David in Hospital. Adelaide. passed away 21/2/25 Signed..... Date/...../.....

*This form must be kept for a period of at least six (6) months after the inspection.

FIRST SCHEDULE: PART 1



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours
Address P O Box 609 (78 Sturt Street)
Mount Gambier 5290
Registration Number SB61GM
Date 12 2 26
Odometer 85671 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓			
Wheels for Condition	✓			
Tyres for Correct Pressure	✓			
Tyre Tread for Condition & Depth	✓			
Tyre Walls (without wheel removal) for Damage	✓			
Tyre Construction for Correct Location	✓			
BRAKES				
Service & Parking Brake for Correct Operation	✓			
Brake System for Air Leaks	✓			
Drain Valves for Operation	✓			
Hydraulic Fluid for Level & Leaks	✓			
Brake Warning System for Operation	✓			
ABS & EBS Warning System for Operation	✓			
BATTERY				
Battery Terminals & Cables for Condition	✓			
Battery & Battery Carrier Security	✓			
GENERAL				
Power Steering System Leaks	✓			
Engine for Oil & Water Leaks	✓			
Exhaust System for Condition, Security & Efficiency	✓			
Gearbox & Differential Oil Leaks	✓			
Fuel System Leaks	✓			
BODY				
Glazing Condition	✓			
Body/Exterior for Damage & Dangerous Projections	✓			
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			
Rear Vision Mirrors for Security & Condition	✓			
Passenger Access Doors for Security & Operation	✓	✓	16-4-26	Halloran Diesel
Seats for Security	✓			
Steps, Floor & Hatches for Security & Condition	✓			
Fire Extinguisher for Presence & in Service Date	✓			
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			
Dash Lights, Step, Interior & Destination Lights for Operation	✓			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓			
Gear & Clutch Controls for Correct Operation	✓			
Steering System for Free Play & Slackness	✓			
Windscreen Wipers for Operation & Condition	✓			
Windscreen Washers for Operation	✓			
Demister for Operation	✓			
Horn for Operation	✓			

Inspection Undertaken by *Jack*

Signed *JB* Date *2.12.26*

*This form must be kept for a period of at least six (6) months after the inspection



FIRST SCHEDULE: PART 1



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 1

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours
Address P.O. Box 609, (78 Sturt Street)
Mount Gambier 5290
Registration Number SB61GM
Date 24/4/26
Odometer 85918 km

INSPECTION SHEET NUMBER 1

To be undertaken at interval of not more than one month.

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
TYRES & WHEELS				
Wheel Nuts for Tightness	✓			
Wheels for Condition	✓			
Tyres for Correct Pressure	✓			
Tyre Tread for Condition & Depth	✓			
Tyre Walls (without wheel removal) for Damage	✓			
Tyre Construction for Correct Location	✓			
BRAKES				
Service & Parking Brake for Correct Operation	✓			
Brake System for Air Leaks	✓			
Drain Valves for Operation	✓			
Hydraulic Fluid for Level & Leaks	✓			
Brake Warning System for Operation	✓			
ABS & EBS Warning System for Operation	✓			
BATTERY				
Battery Terminals & Cables for Condition	✓			
Battery & Battery Carrier Security	✓			
GENERAL				
Power Steering System Leaks	✓			
Engine for Oil & Water Leaks	✓			
Exhaust System for Condition, Security & Efficiency	✓			
Gearbox & Differential Oil Leaks	✓			
Fuel System Leaks	✓			
BODY				
Glazing Condition	✓			
Body Exterior for Damage & Dangerous Projections	✓			
Engine Cover Sealing Inside Passenger Compartment for Condition	✓			
Rear Vision Mirrors for Security & Condition	✓			
Passenger Access Doors for Security & Operation	✓			
Seats for Security	✓			
Steps, Floor & Hatches for Security & Condition	✓			
Fire Extinguisher for Presence & in Service Date	✓			
LIGHTING				
Headlamps, Park, Rear, Clearance, No. Plate, Stop, Reverse Lights & Turn Signal for Operation & Damaged Lenses	✓			
Dash Lights, Step, Interior & Destination Lights for Operation	✓			
CONTROLS				
Neutral Safety Switch for Operation (Automatic Vehicles Only)	✓			
Gear & Clutch Controls for Correct Operation	✓			
Steering System for Free Play & Slackness	✓			
Windscreen Wipers for Operation & Condition	✓			
Windscreen Washers for Operation	✓			
Demister for Operation	✓			
Horn for Operation	✓			

Inspection Undertaken by D. Halloran Signed [Signature] Date 24/4/26

*This form must be kept for a period of at least six (6) months after the inspection.



HALLORAN
DIESEL

Ph: 0400 099 981 Page 21 of 27

dan@hallorandiesel.com.au

FIRST SCHEDULE: PART 2



Government of South Australia
Department of Planning, Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 2

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner: Lake City Tours
Address: P.O. Box 609 (78 Sturt Street), Mount Gambier, 5290
Registration Number: SB61GM
Date: 25/08/2025
Odometer: 85,126 km

INSPECTION SHEET NUMBER 2

- To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first
All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Table with columns: Item, Satisfactory (Yes/No), Rectified (Date/Signed). Rows include SUSPENSION, BRAKES, STEERING, GENERAL, and BODY sections.

Inspection Undertaken by: D. HALLORAN
Signed: [Signature]
Date: 25.8.25

*This form must be kept for a period of at least one (1) year after the inspection.



FIRST SCHEDULE: PART 2



Government of South Australia
Department of Planning,
Transport and Infrastructure

**Code of Practice for Buses
Mandatory Maintenance
Procedure Part 2**

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours **Registration Number** SB61GM
Address P.O. Box 609 (78 Sturt Street)
Mount Gambier, 5290
Date 12 2 26 **Odometer** 85671 km

INSPECTION SHEET NUMBER 2

To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
SUSPENSION				
"U" Bolts & Centre Bolts for Security & Condition	✓			
Radius Rods & Joints for Condition	/			
Front & Rear Axle Mounts for Condition & Cracks	/			
Springs & Shackles for Condition	/			
Shock Absorber & Joints for Condition	/			
Air Bag System for Condition	/			
BRAKES				
Brake Lines & Mounts for Condition	✓			
Slack Adjusters & Auto Adjusters for Operation & Condition	/			
Brake Linings for Wear & Contamination	/			
Air Filter for Security & Cleanliness	/			
Air Priority System for Operation	/			
Air or Vacuum for Correct Build Up Time	/			
Retarder & Exhaust Brake for Operation & Control	/			
STEERING				
Steering Box for Security & Operation	/			
Steering System for Condition & Play	/			
Steering Wheel & Column for Play & Security	/			
GENERAL				
Engine Insulating Material for Contamination & Security	/			
Starter Motor for Security	/			
Tail Shafts & Guards for Condition & Security	/			
Universal Joints & Splines for Condition	/			
Fuel Tank & Fuel System for Security	/			
Wheel Bearings for Adjustment	/			
Axle Hub Seals for Leaks	/			
Seat Belt Condition & Operation	/			
Door Interlocks for Correct Operation (if fitted)	/			
BODY				
Body Mounts Attachments for Security & Condition	/			
Body for Visual Structural Defects & Corrosion	/			

Inspection Undertaken by JACK Signed [Signature] Date 12.2.26

*This form must be kept for a period of at least one (1) year after the inspection.



FIRST SCHEDULE: PART 2



Government of South Australia
Department of Planning,
Transport and Infrastructure

Code of Practice for Buses
Mandatory Maintenance
Procedure Part 2

Vehicle Inspections
PO BOX 1533
ADELAIDE SA 5001

MR 1090
07/16

Company / Owner Lake City Tours
Address P.O. Box 609 (78 Sturt Street)
Mount Gambier, 5290
Registration Number SB61GM
Date 24/4/26
Odometer 85,918 km

INSPECTION SHEET NUMBER 2

To be undertaken at intervals of not more than three months or 15,000 km whichever occurs first

- All inspection procedures to be carried out in accordance with the appropriate requirements of the CODE OF PRACTICE FOR BUSES

Item	Satisfactory		Rectified	
	Yes (✓)	No (X)	Date	Signed
SUSPENSION				
"U" Bolts & Centre Bolts for Security & Condition	✓			
Radius Rods & Joints for Condition	✓			
Front & Rear Axle Mounts for Condition & Cracks	✓			
Springs & Shackles for Condition	✓			
Shock Absorber & Joints for Condition	✓			
Air Bag System for Condition	✓			
BRAKES				
Brake Lines & Mounts for Condition	✓			
Slack Adjusters & Auto Adjusters for Operation & Condition	✓			
Brake Linings for Wear & Contamination	✓			
Air Filter for Security & Cleanliness	✓			
Air Priority System for Operation	✓			
Air or Vacuum for Correct Build Up Time	✓			
Retarder & Exhaust Brake for Operation & Control	✓			
STEERING				
Steering Box for Security & Operation	✓			
Steering System for Condition & Play	✓			
Steering Wheel & Column for Play & Security	✓			
GENERAL				
Engine Insulating Material for Contamination & Security	✓			
Starter Motor for Security	✓			
Tail Shafts & Guards for Condition & Security	✓			
Universal Joints & Splines for Condition	✓			
Fuel Tank & Fuel System for Security	✓			
Wheel Bearings for Adjustment	✓			
Axle Hub Seals for Leaks	✓			
Seat Belt Condition & Operation	✓			
Door Interlocks for Correct Operation (if fitted)		X	24/4/26	[Signature]
BODY				
Body Mounts Attachments for Security & Condition	✓			
Body for Visual Structural Defects & Corrosion	✓			

Inspection Undertaken by D. Halloran Signed [Signature] Date 24/4/26

*This form must be kept for a period of at least one (1) year after the inspection.

HALLORAN
DIESEL
Page 25 of 27
Ph: 0400 093 981
dan@hallorandiesel.com.au

20130007LA24/SC/SC

10 May 2013

Les Brazier Special Vehicles
PO Box 14
Mail Centre
ELIZABETH WEST SA 5113**ADVICE OF MODIFICATION**

Pursuant to the provisions of the Road Traffic Act and Regulations, I hereby certify that the vehicle described hereon has been modified in accordance with all relevant Codes of Practice and that a Transport SA Modification Plate is affixed to the vehicle.


Vehicle Details

Modification Plate Serial No:	TS0611
Registration / Ref No:	2013.0007
Make & Model:	FUSO ROSA
VIN / Chassis No:	JLFBE64DG0RG10056
Engine No:	NOT RECORDED
Date of Manufacture:	02/2013
Tyre Size:	Front: STD Rear: STD
Max Wheel Track:	Front: STD Rear: STD
Modified:	GVM: STD GCM: STD
Modified:	GTM: N/A ATM: N/A
Modification Codes:	K1, K2, K3, K5, R2. Seats: 22 / 4w

Description of Modification: Rear door aperture widened and new outward opening hinged door installed. OEM rear door Emergency Exit labelling and release handles re-fitted. Under-floor "Ratcliffe" cassette type wheelchair lifter fitted at rear.
OEM double seating from rows 4 to 8 (RHS) and OEM single seating (row 6 inboard RHS and row 7 and 8 LHS) fitted with custom fabricated seat bases equipped with "NMI" quick release seat locking fixtures.

Raised floor sections removed in region of modified seats and "Unwin" type wheelchair restraint tracking fitted. Guide plates installed into tracking to ensure correct seat spacing when installed. Wheelchair restraints provided to permit the carriage of a maximum of 4 wheelchairs with seated occupants located on the RHS of the 4th and 6th rows and side by side in the last row. Clear aisle access to the rear Emergency Exit maintained with all configurations of seating and wheelchair occupants.

Recognised Engineering Signatory Details

Name / Position:	SJ CROSER, ASSOCIATE
Company Name:	TONKIN CONSULTING
Address:	LEVEL 2 / 66 RUNDLE STREET KENT TOWN SA 5067
Signature:	 Date: 10/05/2013

This must be sent to DPTI – Vehicle Standards to arrive within 5 working days after the last inspection.

Paid 4/3/25
Ref 633876243

SE Forest & Hydraulic Centre



C.A. & J.F. Medhurst Pty Ltd
A.B.N. 26 071 493 797
A.C.N. 071 493 797
PO Box 9107
MOUNT GAMBIER WEST SA 5291
16 Riiana Road
MOUNT GAMBIER

Phone: 08 8723 9866
Email: admin@seforest.com.au
Fax: 08 8723 9855

Tax Invoice

Invoice No: 00110151

Bill To:

Lake City Tours
PO Box 609
Mount Gambier SA 5290

Terms: Net 31
Date: 1/01/2025
Your No:

QTY	ITEM NO.	DESCRIPTION	PRICE	UNIT	DISC %	EXTENDED
	1machine	Machine: Wheel Chair Lift				
	1reg	Registration Number: SB-61-GM				
	1sn	S/N: JLFBE840GORG10056				
	1k	Kilometres: 82,269				
	1JC	Job Card Number: 18856				
	1b	Perform an Annual Service / Inspection on Wheel Chair Lift				
	1b	Remove & disassemble hydraulic cylinder as leaking hydraulic oil				
	1b	Supply & fit a new cylinder rod as chrome shaft damaged				
	1b	Reassemble with new seals & refill to unit				
	1b	Drain & refill reservoir				
	1b	Degrease & steam clean underbody & framework & clean & lube slide assemblies				
Comment:				Sale Amt..		
				GST.		
				Total Amt..		
				Paid Today.		
				Balance Due:		

How to pay



by mail

Detach this section and mail your cheque to...

SE Forest & Hydraulic Centre
PO Box 9107
MOUNT GAMBIER WEST SA 5291

From:

Lake City Tours
PO Box 609
Mount Gambier SA 5290

Or by Direct Banking to...

BSB: 186-002
Account No: 113488948
Account Name: SE Forest & Hydraulic Centre

Invoice #: 00110151 Amount Due:



SE Forest & Hydraulic Centre

C.A. & J.F. Medhurst Pty Ltd

A.B.N. 26 071 493 797

A.C.N. 071 493 797

PO Box 9107
MOUNT GAMBIER WEST SA 5291
16 Rufana Road
MOUNT GAMBIER

Phone: 08 8723 9966

Email: admin@seforest.com.au

Fax: 08 8723 9955

Tax Invoice

Invoice No: 00110151

Bill To:

Lake City Tours
PO Box 609
Mount Gambier SA 5290

Terms: Net 31

Date: 1/01/2025

Your No:

QTY	ITEM NO.	DESCRIPTION	PRICE	UNIT	DISC %	EXTENDED
	1b	Remove & repair intermittent rear door switch & cutting power to isolator switch				
	1b	Put vehicle over pit & remove covers & hydraulically straighten bent support bar causing unit to catch when extending				
	1b	Retest for smooth operation & refit covers				
	Labour	Labour				\$835.00
	1b	Sublet Repair: 1 x Cylinder				\$119.37



Property:
UP-1757 Lake City Tours
78 Sturt St Mount
Gambier SA 5290
Australia

Client:
Lake City Tours

Task:
T-46415

Issued by:
Louise Butler
29th April 2026

Performed Date:
24th April 2026

Scope of Works

10 - Portable and Wheeled Fire Extinguishers: Annual (1)

Servicing Summary

Service	Asset	Quantity
10 - Portable and Wheeled Fire Extinguishers: Annual	Fire Extinguisher	1

Maintenance

10 - Portable and Wheeled Fire Extinguishers: Annual

Asset	Base Date	Status
001 - EXT 2.5KG DCP AB(E) Extinguisher	VEHICLES, Bus SB-61-GM 27th Oct 2022	PASS

SE Battery Service Pty Ltd

120 Penola Road
Mount Gambier SA 5290

Email: admin@sebatteries.com.au

Phone: 08 8725 9911

A.B.N. 65 071 680 629

*Paid 18/12/25
Ref 786643472*

Power is our business

Tax Invoice

Invoice No: 228657

Date: 16/12/2025

Your Order #: SB61GM

Terms: Net 30th after EOM

Bill To:

Lake City Tours
PO Box 609
Mount Gambier SA 5290

Delivery Address :

Lake City Tours
PO Box 609
Mount Gambier SA 5290

QTY	ITEM CODE	DESCRIPTION	UNIT PRICE (ex GST)	TOTAL PRICE (ex GST)
2	MF31-931	MF31-931 Maintenance Free Gold Plus Supercharge Battery	\$272.725	\$545.45
1	Labour/ Fitting fee/ Call out	Labour/ Fitting fee	\$40.00	\$40.00
1	Labour/ Fitting fee/ Call out	Call out	\$40.00	\$40.00

Trading Terms : Nett 30 days - if these terms are not complied with we reserve the right to charge an administration fee of \$22 per month.

E&EO - Goods remain the property of SE Battery Service P/L until those goods have been paid in full.

Subtotal:	\$625.45
Freight (ex GST):	\$0.00
GST:	\$62.55
Total Amt (inc GST):	\$688.00
Paid Today:	\$0.00

Balance Due: \$688.00

How to Pay

by EFT

SE Battery Service Pty Ltd
BSB 065 504
Acct # 1004 8353

by mail

Detach this section and mail your cheque to...




by credit card

To pay via Mastercard or VISA

by PHONE: 08 8725 9911

SE Battery Service Pty Ltd
120 Penola Rd Mount Gambier SA 5290

**TRIDENT TRUCK TYRE
CENTRE P/L**
 **08 8723 1500**

 PO BOX 2429
 AVEY RD
 MT GAMBIER 5290
 terry@tridenttyres.com.au

 Customer Code: LAKTOU
 LAKE CITY TOURS

 PO BOX 609
 MOUNT GAMBIER SA 5290

**COPY
TAX INVOICE
211038**

ISSUED 08/02/24	SALESPERSON CRAIG WIESTRA	FINALISED BY CRAIG WIESTRA		
VEHICLE MAKE FUSO ROSA BUS	VEHICLE SERIES	YEAR	ODOMETER 76368	CUSTOMER ORDER NO.
VEHICLE MODEL	REGISTRATION NO. SB61GM	VIN NO.	PAID BY	

Product	Description	Qty	Price	Amount
KU2058516RS02	KUMHO (12) RS02 205/85R16	2	*243.64	487.28
ZZSCRAPRVLTR	SCRAP TYRES RV / LTR	2	15.00	30.00
ZBALRVLTR	BALANCE RV/LTR	2	18.18	36.36
	POS 1/2 205/85R16			
ZROTATERVLTR	ROTATE RV / LTR TYRE	2	6.82	13.64
	POS 1/2 TO 5/6			
	RIGHT REAR INNER DRIVE TO SPARE			
	J41733			

EX GST AMOUNT	\$567.28
GST	\$56.73
TOTAL	\$624.01



Goods remain the property of TRIDENT TRUCK TYRE CENTRE P/L until paid in full. Bridgestone Australia Ltd. is a participant in the Tyre Stewardship Scheme (tyrestewardship.org.au) that is supported by Governments and authorised by the ACCC (Authorisation Number AA1000409). Bridgestone and its network of retail stores recycle tyres responsibly. Bridgestone Australia Ltd. Has recommended that all Bridgestone stores are required to be Tyre Stewardship (TSA) accredited and all end of life tyres are collected from the store only by responsible recyclers who are members of the Australian Tyre Recyclers Association (ATRA). Bridgestone Australia Ltd. Terms of Sale: These goods are sold in accordance with the Terms of Sale of Bridgestone Australia Ltd. as published from time to time. Acceptance of these goods implies acceptance of such terms. See bridgestonetyres.com.au/terms-of-sale. Privacy Statement: We care about your privacy. View our Privacy Policy here at bridgestonetyres.com.au/privacy.



**AUTHORISED INSPECTION STATION
VEHICLE INSPECTION REPORT**

MR 104
07/14

Government of South Australia

Department of Planning, Transport and Infrastructure

Incorporating Passenger Transport Act 1994 – Passenger Transport Regulations 2009 – Schedule 4
Road Traffic Act 1961 – Road Traffic (Miscellaneous) Regulations 2014 – Schedule 1, Form 8

H	384939
*REG. NO.	SB61GM
*DATE	16/05/24

TAXI METER

Make of Meter

Model

Serial No.

Type of Inspection **B1**

Compliance Plate No. **2504**

Chassis No. **JLFBE640G0R610056**

Engine No.

Month and Year **02/13**

***Driver to complete (USE BLOCK LETTERS)**

*Owners Name **Bhannu** *four's tele city four's*

*Address

*Colour **White**

*Odometer Reading **77713 km**

*Make **FUSO**

*Model **Rosa**

*Type (i.e. sedan, van, etc) **BUS**

Receipt No. **V1841384** Fee

Inspectors No. **1029** Station No. **M.T.G.**

1st Insp.	2nd Insp.	1st Insp.	2nd Insp.	1st Insp.	2nd Insp.	1st Insp.	2nd Insp.
<input checked="" type="checkbox"/> Lights	<input type="checkbox"/>	<input checked="" type="checkbox"/> Mirrors	<input type="checkbox"/>	<input checked="" type="checkbox"/> 15. Tail Shaft Strap	<input type="checkbox"/>	<input checked="" type="checkbox"/> 22. Fire Extinguisher	<input type="checkbox"/>
<input checked="" type="checkbox"/> Wipers/Washers	<input type="checkbox"/>	<input checked="" type="checkbox"/> Steering	<input type="checkbox"/>	<input checked="" type="checkbox"/> 16. Service Brake	<input type="checkbox"/>	<input checked="" type="checkbox"/> 23. Noise	<input type="checkbox"/>
<input checked="" type="checkbox"/> Warning Device	<input type="checkbox"/>	<input checked="" type="checkbox"/> 10. Suspension	<input type="checkbox"/>	<input checked="" type="checkbox"/> 17. Park Brake	<input type="checkbox"/>	<input checked="" type="checkbox"/> 24. Tgw Coupling	<input type="checkbox"/>
<input checked="" type="checkbox"/> Number Plate	<input type="checkbox"/>	<input checked="" type="checkbox"/> 11. Wheels/Tyres	<input type="checkbox"/>	<input checked="" type="checkbox"/> 18. Emergency Brake	<input type="checkbox"/>	<input checked="" type="checkbox"/> 25. LPG	<input type="checkbox"/>
<input checked="" type="checkbox"/> Windscreen/Windows	<input type="checkbox"/>	<input checked="" type="checkbox"/> 12. Oil/Fuel/Leaks	<input type="checkbox"/>	<input checked="" type="checkbox"/> 19. Transmission	<input type="checkbox"/>	<input checked="" type="checkbox"/> 26. Comfort/Cleanliness	<input type="checkbox"/>
<input checked="" type="checkbox"/> Seats/Belts	<input type="checkbox"/>	<input checked="" type="checkbox"/> 13. Chassis	<input type="checkbox"/>	<input checked="" type="checkbox"/> 20. Demister	<input type="checkbox"/>	<input checked="" type="checkbox"/> 27. Air Conditioner	<input type="checkbox"/>
<input checked="" type="checkbox"/> Body	<input type="checkbox"/>	<input checked="" type="checkbox"/> 14. Exhaust/Emissions	<input type="checkbox"/>	<input checked="" type="checkbox"/> 21. Taxi Meter	<input type="checkbox"/>	<input checked="" type="checkbox"/> 28. Other	<input type="checkbox"/>

Fault Code No. **22** **fire ext to be checked every 6 months**

FAULT/DETAILS OF MODIFICATIONS

*** Note: not all seats installed at inspection (wheelchair bus). All seats should be installed in future inspections**

fire ext - see above **MMS - sighted**

IMPORTANT READ CONDITIONS OVER PAGE

PASS	CERTIFICATE OF INSPECTION	FAIL
Inspector No. 1029	Road Traffic Act 1961 Vehicles inspected under part 4A. This is to certify that the vehicle, Registration No. SB61GM , has been inspected and this certificate of inspection is issued <i>subject to the conditions attached to this certificate.</i>	Inspector No.
DATE 16/05/24	Expiry Date 31/05/24 Label No. 92988	DATE
	Seating Capacity 22 Adults or Children 21	
	Signature of Inspector or authorised person <i>[Signature]</i>	
	Date 16/05/24	
	Notes: 1. This certificate is issued on behalf of the Central Inspection Authority. 2. This certificate will remain in force up to and including the date of expiry, unless sooner cancelled by the Central Inspection Authority.	
	NEXT INSPECTION BY 31.....1.....05.....24.....	





AUTHORISED INSPECTION STATION
VEHICLE INSPECTION REPORT

MR 104
07/14

Government of South Australia
Department of Planning, Transport and Infrastructure

Incorporating Passenger Transport Act 1994 - Passenger Transport Regulations 2009 - Schedule 4
Road Traffic Act 1961 - Road Traffic (Miscellaneous) Regulations 2014 - Schedule 1, Form 8

Registration details: 340115, REG. NO. SB-61-GM, DATE 6-05-19

TAXI METER section containing fields for Make of Meter, Model, Serial No., Type of Inspection (B1), Compliance Plate No. (25042), Chassis No. (JLFBF64DGP0RG10056), Engine No., Month and Year (2/13), and vehicle details like Colour (White), Odometer Reading (84675), Make (Fuso), Model (Rosa), and Type (BUS).

Receipt No. 392676, Fee, Inspectors No. 186, Station No. Mt Gambier

Table with 8 columns for inspection items (1-28) and checkboxes for 1st and 2nd inspectors. Items include Lights, Mirrors, Steering, Suspension, etc.

FAULT/DETAILS OF MODIFICATIONS table with columns for Fault Code No. and details. Handwritten entries: - m.m.s sighted O.K., - Fire ext O.K 4/19.

IMPORTANT READ CONDITIONS OVER PAGE

CERTIFICATE OF INSPECTION section with fields for Inspector No. (186), DATE (6-05-19), Expiry Date (31-05-2020), Label No. (7575A), and Seating Capacity (22+upto 4 WKS Adults or Children 21+upto 4/WKS).



Signature of Inspector or authorised person (signature), Date (6-05-2019), Notes: 1. This certificate is issued on behalf of the Central Inspection Authority. 2. This certificate will remain in force up to and including the date of expiry, unless sooner cancelled by the Central Inspection Authority.

NEXT INSPECTION BY 31 / 05 / 2020



**AUTHORISED INSPECTION STATION
VEHICLE INSPECTION REPORT**

MR 104
07/14

Government of South Australia
Department of Planning, Transport and Infrastructure

Incorporating Passenger Transport Act 1994 – Passenger Transport Regulations 2009 – Schedule 4
Road Traffic Act 1961 – Road Traffic (Miscellaneous) Regulations 2014 – Schedule 1, Form 8

H	335927
*REG. NO.	SB61GM
*DATE	03/05/18

TAXI METER Make of Meter GVM Supply Model Serial No.	*Driver to complete (USE BLOCK LETTERS) *Owners Name David Robert Mason *Address *Colour white *Odometer Reading 46286 km *Make FUSO *Model Rosa *Type (i.e. sedan, van, etc) Bus
Type of Inspection BT Compliance Plate No. 25042 Chassis No. JLF BE64D6ORGI0056 Engine No. Month and Year 02/13	

Receipt No. **V1351976** Fee **\$264.00** Inspectors No. **1029** Station No. **Mt Garber**

Fault Code	1st Insp.	2nd Insp.	1st Insp.	2nd Insp.	1st Insp.	2nd Insp.	1st Insp.	2nd Insp.
✓ = Pass x = Fail N = Not Applicable	<input type="checkbox"/> 1. Lights	<input type="checkbox"/>	<input type="checkbox"/> 8. Mirrors	<input type="checkbox"/>	<input type="checkbox"/> 15. Tail Shaft Strap	<input type="checkbox"/>	<input type="checkbox"/> 22. Fire Extinguisher	<input type="checkbox"/>
	<input type="checkbox"/> 2. Wipers/Washers	<input type="checkbox"/>	<input type="checkbox"/> 9. Steering	<input type="checkbox"/>	<input type="checkbox"/> 16. Service Brake	<input type="checkbox"/>	<input type="checkbox"/> 23. Noise	<input type="checkbox"/>
	<input type="checkbox"/> 3. Warning Device	<input type="checkbox"/>	<input type="checkbox"/> 10. Suspension	<input type="checkbox"/>	<input type="checkbox"/> 17. Park Brake	<input type="checkbox"/>	<input type="checkbox"/> 24. Tow Coupling	<input type="checkbox"/>
	<input type="checkbox"/> 4. Number Plate	<input type="checkbox"/>	<input type="checkbox"/> 11. Wheels/Tyres	<input type="checkbox"/>	<input type="checkbox"/> 18. Emergency Brake	<input type="checkbox"/>	<input type="checkbox"/> 25. LPG	<input type="checkbox"/>
	<input type="checkbox"/> 5. Windscreen/Windows	<input type="checkbox"/>	<input type="checkbox"/> 12. Oil/Fuel/Leaks	<input type="checkbox"/>	<input type="checkbox"/> 19. Transmission	<input type="checkbox"/>	<input type="checkbox"/> 26. Comfort/Cleanliness	<input type="checkbox"/>
	<input type="checkbox"/> 6. Seats/Belts	<input type="checkbox"/>	<input type="checkbox"/> 13. Chassis	<input type="checkbox"/>	<input type="checkbox"/> 20. Demister	<input type="checkbox"/>	<input type="checkbox"/> 27. Air Conditioner	<input type="checkbox"/>
	<input type="checkbox"/> 7. Body	<input type="checkbox"/>	<input type="checkbox"/> 14. Exhaust/Emissions	<input type="checkbox"/>	<input type="checkbox"/> 21. Taxi Meter	<input type="checkbox"/>	<input type="checkbox"/> 28. Other	<input type="checkbox"/>

Fault Code No.	FAULT/DETAILS OF MODIFICATIONS
	Automatic step wiring under vehicle to be restrained, appropriately
	Fire extinguisher to be stamped after service completing
	MMS to be filled out correctly - please tick only applicable boxes

MMS signed * TSA for safety and wheel chair mod fire ext - ok - not stamped

IMPORTANT READ CONDITIONS OVER PAGE

PASS	CERTIFICATE OF INSPECTION	FAIL
1029 Inspector No. 03/05/18 DATE	Road Traffic Act 1961 Vehicles inspected under part 4A. This is to certify that the vehicle, Registration No. SB61GM has been inspected and this certificate of inspection is issued <i>subject to the conditions attached to this certificate.</i> Expiry Date 31/05/19 Label No. 71962 Seating Capacity 22 or 10 Adults or Children 21 or 9 + 4 w/c Signature of Inspector or authorized person <i>[Signature]</i> Date 03/05/18	Inspector No. DATE

Notes:
 1. This certificate is issued on behalf of the Central Inspection Authority.
 2. This certificate will remain in force up to and including the date of expiry, unless sooner cancelled by the Central Inspection Authority.

NEXT INSPECTION BY **31, 05, 19**





Government of South Australia

Department of Planning, Transport and Infrastructure

AUTHORISED INSPECTION STATION VEHICLE INSPECTION REPORT

Incorporating Passenger Transport Act 1994 - Passenger Transport Regulations 2009 - Schedule 4 Road Traffic Act 1961 - Road Traffic (Miscellaneous) Regulations 2014 - Schedule 1, Form 8

MR 104 07/14

REG. NO. 317655 SB61GM DATE 2/05/2017

TAXI METER Make of Meter Model Serial No. Type of Inspection B1 Compliance Plate No. 25642 ME Chassis No. JLFBE64D GORG10056 Engine No. Month and Year 02/13

*Driver to complete (USE BLOCK LETTERS) *Owners Name DR MASON *Address LAKE CITY TOURS *Colour WHITE *Odometer Reading 37313km *Make MITSUBISHI *Model ROSA *Type (i.e. sedan, van, etc) BUS

Receipt No. 310043 Fee \$259.00 Inspectors No. 107 Station No. MTHAMBER

Table with 4 columns of inspection items (1-28) and checkboxes for 1st and 2nd inspections.

Table for FAULT/DETAILS OF MODIFICATIONS with columns for Fault Code No. and modification details.

Fire ext 04/2011 MMS - OK - NEW MMS SYSTEM INFO SUPPLIED.

IMPORTANT READ CONDITIONS OVER PAGE

CERTIFICATE OF INSPECTION PASS/FAIL section with fields for Inspector No. (107), Date (02/05/2017), Registration No. (SB61GM), Label No. (68180), and Signature.



Notes: 1. This certificate is issued on behalf of the Central Inspection Authority. 2. This certificate will remain in force up to and including the date of expiry, unless sooner cancelled by the Central Inspection Authority.

NEXT INSPECTION BY 31.05.2018.



Government of South Australia

Department of Planning, Transport and Infrastructure

AUTHORISED INSPECTION STATION VEHICLE INSPECTION REPORT

Incorporating Passenger Transport Act 1994 - Passenger Transport Regulations 2009 - Schedule 4 Road Traffic Act 1961 - Road Traffic (Miscellaneous) Regulations 2014 - Schedule 1, Form 8

MR 104 07/14

H 302138 REG. NO. \$B61GM DATE 4/5/2016

TAXI METER Make of Meter Model Serial No. Type of Inspection B1 Compliance Plate No. 25042 ME Chassis No. JLFBE64DGORG10056 Engine No. Month and Year 02/13 *Driver to complete (USE BLOCK LETTERS) *Owners Name D R MASON *Address LAKE CITY TOURS *Colour White *Odometer Reading 28741 Km *Make MITSUBISHI *Model ROSA BE600 *Type (i.e. sedan, van, etc) BUS


Receipt No. 276 069 Fee \$255.00 Inspectors No. 107 Station No. MTPAMBK

Table with 8 columns for inspection items: 1st Insp., 2nd Insp., 1st Insp., 2nd Insp., 1st Insp., 2nd Insp., 1st Insp., 2nd Insp. Items include Lights, Mirrors, Steering, Suspension, etc.

Table for FAULT/DETAILS OF MODIFICATIONS. Includes handwritten entries: OPTI mod Plate - T\$0611 K1, K2, K3, K5, R2; Fire ext 10/15; MMS OK - New Supplied.

IMPORTANT READ CONDITIONS OVER PAGE

CERTIFICATE OF INSPECTION PASS/FAIL. Includes Inspector No. 107, Date 4/5/2016, Expiry Date 31/05/2017, Label No. 063746, Seating Capacity 22 or up to 4w/ch, Adults or Children 21 or up to 4w/ch. Signature of Inspector or authorised person. Notes: 1. This certificate is issued on behalf of the Central Inspection Authority. 2. This certificate will remain in force up to and including the date of expiry, unless sooner cancelled by the Central Inspection Authority. NEXT INSPECTION BY 31.05.2017.



DAIMLER TRUCKS MOUNT GAMBIER

OPERATED BY ADTRANS



Paid 23/11/20
Ref. 71079292.

Daimler Trucks Mount Gambier
Authorised Mercedes-Benz, Freightliner,
& Fuso Sales, Service & Parts

SERVICE TAX INVOICE

Service TAX Invoice		Page 1 of 1	Reprint No. Reprint# 1	Doc #: DGCHG19198
Customer No. 1035171	Customer Name & Address Lake City Tours Po Box 609		Advisor Barend Luus 102321	Colour
Doc. Date 21/11/20	Mount Gambier SA 5290		Year / Make / Model 16/Fuso/ROSA DELUXE AUTOMATIC	
Reg. No. SB56LP			Model No. BE64DJRMDFAD	Carlina BUS
Stock No. K30095	Driver	Contract No.	Chassis No. JLFB64DG0RK30095	Kilometres 63545
Purchase Order No.	Contract Name		Contract Exp. Kms	Prod. Date 17/06/16
Home Phone	Business Phone (08)87232991	Terms 30	Selling Dealer	Delivery Kms.
Vehicle ID. JLFB64DG0RK30095	Engine No. 4M50D94819	Date & Time Promised 19/11/20 10:00pm	Time Received 08:08am	Delivery Date 30/06/16
			Contract Exp. Date	Orig. Del. Date 30/06/16
			Exp. Date	Warr. Exp. Date 29/06/19
			Time Received	Air Pwr Turbo

Labour	Operation	Description	Units	Amount
Job# 1	00ALZZZZZMIN	MINOR SERVICE	Tech(s): 014407	299.98
CUSTOMER REQUEST TO CARRY OUT A 3MONTH INSPECTION AND OIL CHANGE BRING BUS IN SHED.COMPLETE 3 MONTH BUS INSPECTION AS PER REQUIRED CHECK LIST. COMPLETE AN ENGINE OIL CHANGE DUE TO THE 12 MONTH INTERVAL. WASH DOWN AND RETURN TO CUSTOMER'S RESIDENTS				
Total - Labour				299.98

Parts	Qty	Number	Description	Unit Price	Amount
Job# 1	1	MHME228898	ELEMENT OIL FILTER	42.56	42.56
Total - Parts					42.56

Petrol, Oils, Lubricants and Supplies	Amount
Job# 1	ALLIANCE CK-4 15w40
Total - POL	
	86.90

Miscellaneous	Amount
Job# A	CENTS
Job# A	EL
Job# A	SS
Job# A	CSS
Total - Misc	
	49.79

Total Labour	299.98
Total Parts	42.56
Total POL	86.90
Total Sublet	0.00
Total Misc	49.79
Total Tax	47.92

TOTAL AMOUNT INCLUDING GST **Total Invoice 527.15**

DAIMLER TRUCKS MOUNT GAMBIER

OPERATED BY ADTRANS



Paid 7/9/20
Ref 56332672

Daimler Trucks Mount Gambier

Authorised Mercedes-Benz, Freightliner,
& Fuso Sales, Service & Parts

SERVICE TAX INVOICE

Service TAX Invoice		Page 1 of 1	Reprint No. Reprint# 1	Doc #: DGCHG18819
Customer No. 1035171	Customer Name & Address Lake City Tours Po Box 609		Advisor Barend Luus 102321	Colour
Doc. Date 31/08/20	Mount Gambier SA 5290		Year / Make / Model 13/Fuso/ROSA BUS	Team Heavy Tr
Reg. No. SB61GM			Model No. ROSA BUS	Carline
Stock No.	Purchase Order No.		Chassis No. JLFBE64DG0RG1005	Eng./Trans. 4m50/
	Driver	Contract No.	Kilometres 62836	Prod. Date
	Home Phone	Business Phone (08)87232991	Contract Name	Contract Exp. Kms
	Vehicle ID. JLFBE64DG0RG10056	Terms 30	Selling Dealer	Exp. Date
	Engine No. 4m50d72993		Date & Time Promised 31/08/20 10:00pm	Delivery Kms.
			Time Received 08:03am	Delivery Date 26/03/13
				Warr. Exp. Date 25/03/16
				Quote Price
				Air Pwr Turbo

Labour	Operation	Description	Units	Amount
Job# 1	00ALZZZZZMIN	MINOR SERVICE	Tech(s): 211098	175.00
CUSTOMER REQUEST TO CARRY OUT 3 MONTH INPECTION. CARRY OUT MONTHLY INSPECTION AS PER REQUIRED CHECK LIST. CARRY OUT 3 MONTHLY INSPECTION AS PER REQUIRED CHECK LIST.				
Total - Labour				175.00

Total Labour	175.00
Total Parts	0.00
Total POL	0.00
Total Sublet	0.00
Total Misc	0.00
Total Tax	17.50

TOTAL AMOUNT INCLUDING GST

Total Invoice 192.50

**TRIDENT TRUCK TYRE
CENTRE P/L**

(08) 8723 1500

PO BOX 2429
AVEY RD
MT GAMBIER 5290
trident@tridenttyres.com.au

Customer Code: LAKTOU
LAKE CITY TOURS

PO BOX 609
MOUNT GAMBIER SA 5290

**ORIGINAL
TAX INVOICE
183469**

ISSUED 16/11/20 **SALESPERSON** ADAM PARSONS **FINALISED BY** ADAM PARSONS

VEHICLE MAKE FUSO ROSA BUS **VEHICLE SERIES** **YEAR** **ODOMETER** 63531 **CUSTOMER ORDER NO.**
VEHICLE MODEL **REGISTRATION NO.** SB61GM **VIN NO.** **PAID BY**

Product	Description	Qty	Price	Amount
ZROTATRVLTR	ROTATE RV / LTR TYRE <i>STEER TO RIGHT DRIVE</i>	2	9.00	18.00
KU2058516RS02	KUMHO (12) RS02 205/85R16	2	227.27	454.54
ZBALRVLTR	BALANCE RV/LTR <i>ON STEER</i>	2	18.00	36.00
ZROTATRVLTR	ROTATE RV / LTR TYRE <i>NEW SPARE TO LEFT INNER DRIVE X LEFT INNER DRIVE TO SPARE</i>	1	9.00	9.00
KU2058516RS02	KUMHO (12) RS02 205/85R16 <i>ON LEFT OUTER DRIVE</i>	1	227.27	227.27
ZZSCRAPRVLTR	SCRAP TYRES RV / LTR <i>J-25777</i>	3	6.36	19.08

EX GST AMOUNT	\$763.89
GST	\$76.39
TOTAL	\$840.28



Goods remain the property of TRIDENT TRUCK TYRE CENTRE P/L until paid in full. Bridgestone Australia Ltd. is a participant in the Tyre Stewardship Scheme (tyrestewardship.org.au) that is supported by Governments and authorised by the ACCC (Authorisation Number AA1000409). Bridgestone and its network of retail stores recycle tyres responsibly. Bridgestone Australia Ltd. Has recommended that all Bridgestone stores are required to be Tyre Stewardship (TSA) accredited and all end of life tyres are collected from the store only by responsible recyclers who are members of the Australian Tyre Recyclers Association (ATRA). Bridgestone Australia Ltd. Terms of Sale: These goods are sold in accordance with the Terms of Sale of Bridgestone Australia Ltd. as published from time to time. Acceptance of these goods implies acceptance of such terms. See bridgestonetyres.com.au/terms-of-sale. Privacy Statement: We care about your privacy. View our Privacy Policy here at bridgestonetyres.com.au/privacy.

Paid 25/8/21

Ref 133621235

DAIMLER TRUCKS MT GAMBIER



Daimler Trucks Mount Gambier

Authorised Mercedes-Benz, Freightliner, & Fuso Sales, Service & Parts

SERVICE TAX INVOICE

Service TAX Invoice		Page 1 of 1	Reprint No. Reprint# 1	Doc #: DGCHG20380
Customer No. 1035171	Customer Name & Address Lake City Tours Po Box 609		Advisor Barend Luus	Colour 102321
Doc. Date 25/08/21	Reg. No. SB61GM		Year / Make / Model 13/FUSO/ROSA BUS	Team Heavy Tr
Stock No.	Mount Gambier SA 5290		Model No. ROSA BUS	Tag No.
Purchase Order No.	Driver	Contract No.	Chassis No. JLFE64DG0RG1005	Eng./Trans. 4m50/
	Home Phone	Business Phone (08)87232991	Kilometres 68921	Prod. Date 26/03/13
	Vehicle ID. JLFB64DG0RG10056	Engine No. 4m50d72993	Contract Exp. Kms	Exp. Date
		Terms 30	Contract Name	Exp. Date
			Selling Dealer	Delivery Date 25/03/16
			Date & Time Promised 25/08/21 10:00pm	Warr. Exp. Date 25/03/16
			Time Received 09:47am	Air Pwr Turbo
			Quote Price	

Labour	Operation	Description	Units	Amount
Job# 1	00ALZZZZZMIN	MINOR SERVICE	Tech(s): 014407	175.00
	C+R 1MONTH AND 3 MONTH INSPECTION BRING BUS IN SHED.CHECK OVER ALL LIGHTS AND SIGNS CARRY OUT 1 MONTH AND 3 MONTH INSPECTION AS PER SUPPLIED INSPECTION LISTS.			
Total - Labour				175.00

Total Labour	175.00
Total Parts	0.00
Total POL	0.00
Total Sublet	0.00
Total Misc	0.00
Total Tax	17.50

TOTAL AMOUNT INCLUDING GST

Total Invoice 192.50

Paid 16/3/21
Ref 189304852



SERVICE TAX INVOICE

Daimler Trucks Mount Gambier
Authorised Mercedes-Benz, Freightliner,
& Fuso Sales, Service & Parts

Service TAX Invoice Page 1 of 1			Reprint No. Reprint# 1		Doc #: DGCHG21127	
Customer No. 1035171	Customer Name & Address LAKE CITY TOURS Po Box 609			Advisor Barend Luus 102321	Colour	Team Heavy Tr
Doc. Date 01/03/22	Mount Gambier SA 5290			Year / Make / Model 13/FUSO/ROSA BUS		Tag No.
Reg. No. SB61GM				Model No. ROSA BUS	Carlina	
Stock No.	Purchase Order No.			Chassis No. JLFBE64DG0RG1005	Kilometres 71047	Prod. Date
Driver		Contract No.		Contract Name	Contract Exp. Kms	Exp. Date
Home Phone		Business Phone (08)87232991	Terms 30	Selling Dealer	Delivery Kms.	Delivery Date 26/03/13
Vehicle ID. JLFB64DG0RG10056		Engine No. 4m50d72993		Date & Time Promised 25/02/22 10:00pm	Time Received 06:00pm	Quote Price
						Warr. Exp. Date 25/03/16
						Air Pwr Turbo

Labour	Operation	Description	Units	Amount
Job# 1	00ALZZZZZMIN	MINOR SERVICE	Tech(s): 200802	175.00
CUSTOMER REQUEST PERFORM 1 MONTH & 3 MONTH INSPECTIONS 'G21126 Job 1 Carry out and complete inspection as per 1 mont' 'hly and 3 monthly inspection sheets.200802 Adrian Heinrich'. 71047km				
Total - Labour				175.00

Total Labour	175.00
Total Parts	0.00
Total POL	0.00
Total Sublet	0.00
Total Misc	0.00
Total Tax	17.50

TOTAL AMOUNT INCLUDING GST

Total Invoice 192.50

DAIMLER TRUCKS MT GAMBIER

Paid 11/5/21
Ref 107720930



SERVICE TAX INVOICE

Daimler Trucks Mount Gambier

Authorised Mercedes-Benz, Freightliner,
& Fuso Sales, Service & Parts

Service TAX Invoice		Page 1 of 2	Reprint No. Reprint# 1	Doc #: DGCHG19919
Customer No. 1035171	Customer Name & Address Lake City Tours Po Box 609 Mount Gambier SA 5290		Advisor Barend Luus	Colour 102321
Doc. Date 06/05/21			Year / Make / Model 13/Fuso/ROSA BUS	Team Heavy Tr
Reg. No. SB61GM			Model No. ROSA BUS	Tag No.
Stock No.			Chassis No. JLFB64DG0RG1005	Eng./Trans. 4m50/
Purchase Order No.	Driver	Contract No.	Contract Name	Kilometres 63784
	Home Phone	Business Phone (08)87232991	Selling Dealer	Prod. Date 26/03/13
	Vehicle ID. JLFB64DG0RG10056	Engine No. 4m50d72993	Date & Time Promised 06/05/21 10:00pm	Exp. Date
			Time Received 10:03am	Warr. Exp. Date 25/03/16
			Quote Price	Air Pwr Turbo

Labour	Operation	Description	Units	Amount
Job# 1	00ALZZZZZMIN	MINOR SERVICE	Tech(s): 014407	50.00
CUSTOMER REQUEST TO HAVE THE 1,3 AND 12 MONTH INSPECTION DONE AS PER CHECK LIST BRING THE BUS IN THE SHED. COMPLETE ONE MONTH,3MONTH AND 12 MONTHLY INSPECTION AS PER THE REQUIRED CHECK LIST REQUIREMENTS.				
Total - Labour				50.00

Total Labour	50.00
Total Parts	0.00
Total POL	0.00
Total Sublet	0.00
Total Misc	0.00
Total Tax	5.00

TOTAL AMOUNT INCLUDING GST

Total Invoice 55.00

Paid 16/3/21
Ref 189304852



SERVICE TAX INVOICE

Daimler Trucks Mount Gambier
Authorised Mercedes-Benz, Freightliner,
& Fuso Sales, Service & Parts

Service TAX Invoice		Page 1 of 1		Reprint No. Reprint# 1		Doc #: DGCHG21127	
Customer No. 1035171	Customer Name & Address LAKE CITY TOURS Po Box 609			Advisor Barend Luus 102321	Colour	Team Heavy Tr	
Doc. Date 01/03/22	Mount Gambier SA 5290			Year / Make / Model 13/FUSO/ROSA BUS		Tag No.	
Reg. No. SB61GM				Model No. ROSA BUS	Carlina		Eng./Trans. 4m50/
Stock No.	Purchase Order No.			Chassis No. JLFBE64DG0RG1005	Kilometres 71047	Prod. Date	Orig. Del. Date
Driver		Contract No.		Contract Name	Contract Exp. Kms	Exp. Date	
Home Phone		Business Phone (08)87232991	Terms 30	Selling Dealer	Delivery Kms.	Delivery Date 26/03/13	Warr. Exp. Date 25/03/16
Vehicle ID. JLFBE64DG0RG10056		Engine No. 4m50d72993		Date & Time Promised 25/02/22 10:00pm	Time Received 06:00pm	Quote Price	Air Pwr Turbo

Labour	Operation	Description	Units	Amount
Job# 1	00ALZZZZZMIN	MINOR SERVICE	Tech(s): 200802	175.00
CUSTOMER REQUEST PERFORM 1 MONTH & 3 MONTH INSPECTIONS 'G21126 Job 1 Carry out and complete inspection as per 1 mont' 'hly and 3 monthly inspection sheets.200802 Adrian Heinrich'. 71047km				
Total - Labour				175.00

Total Labour	175.00
Total Parts	0.00
Total POL	0.00
Total Sublet	0.00
Total Misc	0.00
Total Tax	17.50

TOTAL AMOUNT INCLUDING GST

Total Invoice 192.50

DAIMLER TRUCKS MT GAMBIER

Paid
6/9/22
Ref 245077189



SB61AM.

Daimler Trucks Mt Gambier
Authorised Mercedes-Benz, Freightliner,
& Fuso Sales, Service & Parts

nk: ANZ BSB: 014 002 Acc: 8357 09675
:C NAME: Velocity Truck Centres Adelaide Pty Ltd

ence Plate Number: **SB61GM**

g Number:
Service Tax Invoice: RA972000658:01

BILL TO
LAKE CITY TOURS - 143760
PO BOX 609
MOUNT GAMBIER SA 5290
Phone: 08 8723 2991

DELIVER TO
LAKE CITY TOURS - 143760
PO BOX 609
MOUNT GAMBIER SA 5290
Phone: 08 8723 2991

DATE ARRIVED	DATE INVOICE	SALES TYPE	ADVISOR	TERMS	CUSTOMER PO#			
08/2022 11:42:01AM	30/08/2022	CT	Barend L	AR				
YEAR	MAKE	MODEL	VIN	CUSTOMER UNIT #	ENGINE HOURS	IN SERVICE	Component Serial #	ODOM OUT
2013	MH		JLFBE64DG0RG10056		0		4M50D72993	71,153

Sold Operations

JOB #1 10

Service Contracts

COMPLAINT Customer request to carry out one month and three month bus inspection
CAUSE inspections due to be carried out
CORRECTION Bring bus in shed and complete inspection sheets as per customer requirements.
 Found wiper blades perished and needs replacing.
 R+R as required.
 Found tyres way under pressure.
 Pump up all tyres as required.
 Pack up all tools used.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 10-10	Service Contracts		175.50
2	972X/ATR61020	6MM WIPER REFILLS	2.57	5.14
		Prepay: \$0.00	Parts: \$5.14	Labor: \$175.50
		Misc: \$0.00	Sublet: \$0.00	\$180.64
Sold Operations Totals		Prepay: \$0.00	Parts: \$5.14	Labor: \$175.50
		Misc: \$0.00	Sublet: \$0.00	\$180.64

DAIMLER TRUCKS MT GAMBIER

Paid 16/3/21
Ref 189304852



SERVICE TAX INVOICE

Daimler Trucks Mount Gambier
 Authorised Mercedes-Benz, Freightliner,
 & Fuso Sales, Service & Parts

Service TAX Invoice		Page 1 of 1	Reprint No. Reprint# 1	Doc #: DGCHG21127
Customer No. 1035171	Customer Name & Address LAKE CITY TOURS Po Box 609		Advisor Barend Luus 102321	Colour
Doc. Date 01/03/22	Mount Gambier SA 5290		Year / Make / Model 13/FUSO/ROSA BUS	
Reg. No. SB61GM			Model No. ROSA BUS	Carline
Stock No.	Purchase Order No.		Chassis No. JLFE64DG0RG1005	Kilometres 71047
	Driver	Contract No.	Contract Name	Contract Exp. Kms
	Home Phone	Business Phone (08)87232991	Terms 30	Selling Dealer
	Vehicle ID. JLFE64DG0RG10056	Engine No. 4m50d72993	Date & Time Promised 25/02/22 10:00pm	Time Received 06:00pm
				Delivery Kms.
				Delivery Date 26/03/13
				Warr. Exp. Date 25/03/16
				Quote Price
				Air Pwr Turbo

Labour	Operation	Description	Units	Amount
Job# 1	00ALZZZZZMIN	MINOR SERVICE	Tech(s): 200802	175.00
CUSTOMER REQUEST PERFORM 1 MONTH & 3 MONTH INSPECTIONS 'G21126 Job 1 Carry out and complete inspection as per 1 mont' 'hly and 3 monthly inspection sheets.200802 Adrian Heinrich'. 71047km				
Total - Labour				175.00

Total Labour	175.00
Total Parts	0.00
Total POL	0.00
Total Sublet	0.00
Total Misc	0.00
Total Tax	17.50

TOTAL AMOUNT INCLUDING GST

Total Invoice 192.50

DAIMLER TRUCKS MT GAMBIER

Paid 16/3/21
Ref 189304852



SERVICE TAX INVOICE

Daimler Trucks Mount Gambier
 Authorised Mercedes-Benz, Freightliner,
 & Fuso Sales, Service & Parts

Service TAX Invoice		Page 1 of 1	Reprint No. Reprint# 1	Doc #: DGCHG21127
Customer No. 1035171	Customer Name & Address LAKE CITY TOURS Po Box 609		Advisor Barend Luus 102321	Colour
Doc. Date 01/03/22	Mount Gambier SA 5290		Year / Make / Model 13/FUSO/ROSA BUS	
Reg. No. SB61GM			Model No. ROSA BUS	Carlina
Stock No.	Purchase Order No.		Chassis No. JLFE64DG0RG1005	Kilometres 71047
	Driver	Contract No.	Contract Name	Contract Exp. Kms
	Home Phone	Business Phone (08)87232991	Terms 30	Selling Dealer
	Vehicle ID. JLFE64DG0RG10056	Engine No. 4m50d72993	Date & Time Promised 25/02/22 10:00pm	Time Received 06:00pm
				Delivery Kms.
				Delivery Date 26/03/13
				Warr. Exp. Date 25/03/16
				Quote Price
				Air Pwr Turbo

Labour	Operation	Description	Units	Amount
Job# 1	00ALZZZZZMIN	MINOR SERVICE	Tech(s): 200802	175.00
CUSTOMER REQUEST PERFORM 1 MONTH & 3 MONTH INSPECTIONS 'G21126 Job 1 Carry out and complete inspection as per 1 mont' 'hly and 3 monthly inspection sheets.200802 Adrian Heinrich'. 71047km				
Total - Labour				175.00

Total Labour	175.00
Total Parts	0.00
Total POL	0.00
Total Sublet	0.00
Total Misc	0.00
Total Tax	17.50

TOTAL AMOUNT INCLUDING GST

Total Invoice 192.50

DAIMLER TRUCKS MT GAMBIER



nk: ANZ BSB: 014 002 Acc: 8357 09675
 C NAME: Velocity Truck Centres Adelaide Pty Ltd

Paid 7/12/22
 Ref 277056017

ence Plate Number: **SB61GM**
 g Number:

Daimler Trucks Mt Gambier
 Authorised Mercedes-Benz, Freightliner,
 & Fuso Sales, Service & Parts

Service Tax Invoice: RA972001021:01

BILL TO
 LAKE CITY TOURS - 143760
 PO BOX 609
 MOUNT GAMBIER SA 5290
 Phone: 08 8723 2991

DELIVER TO
 LAKE CITY TOURS - 143760
 PO BOX 609
 MOUNT GAMBIER SA 5290
 Phone: 08 8723 2991

DATE ARRIVED	DATE INVOICE	SALES TYPE	ADVISOR	TERMS	CUSTOMER PO#				
11/11/2022 3:56:06PM	28/11/2022	CT	Morgan K.	AR					
YEAR	MAKE	MODEL	VIN	CUSTOMER UNIT #	ENGINE HOURS	IN SERVICE	Component Serial #	ODOM IN	ODOM OUT
2013	MH		JLFBE64DG0RG10056		0		4M50D72993	71,201	71,201

Sold Operations

JOB #1 10 Service Contracts

COMPLAINT 1x Monthly Inspection
 1x Quarterly Inspection

CAUSE Inspections due

CORRECTION Completed Monthly and Quarterly inspections per inspection sheets, provided complimentary vehicle wash.
 937562

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 10-10	Service Contracts		174.90
		Prepay: \$0.00 Parts: \$0.00 Labor: \$174.90 Misc: \$0.00 Sublet: \$0.00		\$174.90
Sold Operations Totals		Prepay: \$0.00 Parts: \$0.00 Labor: \$174.90 Misc: \$0.00 Sublet: \$0.00		\$174.90



Tax Invoice

Reference Nbr.: 001779
 Date: 18-Sep-2023
 Due Date: 31-Oct-2023
 Customer ID: C00503
 Currency: AUD

20/09/23

Paid

Rec 386085761

Triple S Distributors Pty Ltd
 PO Box 9878
 Mount Gambier West, SA, 5291
 Phone: (08) 8725 7940
 ABN#: 56630063366

BILL TO:	SHIP TO:
Lake City Tours 78 Sturt Street Mount Gambier SA 5290 AUSTRALIA	Lake City Tours 78 Sturt Street Mount Gambier SA 5290 AUSTRALIA

CUSTOMER REF. NBR.	TERMS	CONTACT
	End of Following Month	

NO.	ITEM	QTY.	UOM	UNIT PRICE	DISC.	EXTENDED PRICE
1	LABOUR: Carry out vehicle inspection	2.00	HOUR	130.00	0%	260.00
	NOTE: SB61GM, 74091km, 11/09/2023					

Carried out vehicle inspections as required.

BANK DETAILS: BankSA
 BSB: 105002
 ACC: 137186140

NOTE:

Sales Total: 260.00
 Less Discount: 0.00
 Tax Total: 26.00
 Total (AUD): 286.00
 Cash Discount:

Please quote Invoice number as Reference



Paid 18/01/24
Ref 435512751

Tax Invoice


Triple S Distributors Pty Ltd
PO Box 9878
Mount Gambier West, SA, 5291
Phone: (08) 8725 7940
ABN#: 56630063366

Reference No.: 002653
Date: 18-Dec-2023
Due Date: 31-Jan-2024
Customer ID: C00503
Currency: AUD

BILL TO:
Lake City Tours
78 Sturt Street
Mount Gambier SA 5290
AUSTRALIA

SHIP TO:
Lake City Tours
78 Sturt Street
Mount Gambier SA 5290
AUSTRALIA

CUSTOMER REF. NUMBER	TERMS	CONTACT				
	End of Following Month					
NO.	ITEM	QTY.	UOM	UNIT PRICE	DISC.	EXTENDED PRICE
1	LABOUR: 3 Monthly Inspection NOTE: SB61GM, 76002km, 07/12/2023	2.00	HOUR	130.00	0%	260.00
	Carried out 3 monthly inspection as required. Noted down jobs that require to be done.					
2	COOLANT: Shell HD 50/50 Coolant	2.00	LITRE	8.18	0%	16.36
3	GREASE: Shell Gadus S2 V220 AC 2	2.00	KG	18.91	0%	37.82
4	CONSUMABLES: Consumables	1.00	EACH	50.00	0%	50.00
5	ENVIRONMENTALCHARGES: Environmental Charges	1.00	EACH	20.00	0%	20.00
		1.00	EACH	0.00	0%	0.00



BANK DETAILS: BankSA
BSB: 105002
ACC: 137186140

Sales Total: 384.18
Tax Total: 38.42
Total (AUD): 422.60

Please quote invoice number as Reference

DAIMLER TRUCKS MT GAMBIER

Paid 5/5/23
Ref 330931627.



Bank: ANZ BSB: 014 002 Acc: 8357 09675
 Company Name: Velocity Truck Centres Adelaide Pty Ltd
 Estimate: RA972001463
 Licence Plate Number: SB61GM
 Reg Number:

Daimler Trucks Mt Gambier
 Authorised Mercedes-Benz, Freightliner,
 & Fuso Sales, Service & Parts

Service Tax Invoice: RA972001464:01

BILL TO
 LAKE CITY TOURS - 143760
 PO BOX 609
 MOUNT GAMBIER SA 5290
 Phone: 08 8723 2991

DELIVER TO
 LAKE CITY TOURS - 143760
 PO BOX 609
 MOUNT GAMBIER SA 5290
 Phone: 08 8723 2991

DATE ARRIVED	DATE INVOICE	SALES TYPE	ADVISOR	TERMS	CUSTOMER PO#				
03/2023 8:30:00AM	20/04/2023	CT	Bianca J	AR	SB61GM				
YEAR	MAKE	MODEL	VIN	CUSTOMER UNIT #	ENGINE HOURS	IN SERVICE	Component Serial #	ODOM IN	ODOM OUT
2013	MH		JLFBE64DG0RG10056		0		4M50D72993	0	72,453

Sold Operations

JOB #1 00

Maintenance

COMPLAINT **THREE MONTH INSPECTION**
CAUSE Three monthly and one monthly inspection due
CORRECTION Complaint: Three monthly and one monthly inspection due
 Cause: Inspections due
 Correction:
 Carry out and complete one-monthly and three-monthly inspections as per inspections sheets attached to R/O.
 Pump front tires up to manufacturers specification of 550kpa, transmission pan gasket leaking, topped up fluid to avoid damage to gearbox, recommend repairs to gearbox and new fluid when gasket replaced. Fill out paperwork, drop vehicle off at customer residence, travel back to workshop, pack away tools and clean workspace.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 00-10	Maintenance		165.00
Prepay: \$0.00 Parts: \$0.00 Labor: \$165.00 Misc: \$0.00 Sublet: \$0.00				\$165.00
Sold Operations Totals				\$165.00

DAIMLER TRUCKS MT GAMBIER

Paid. 27/6/23
Ref. 351419205



Bank: ANZ BSB: 014 002 Acc: 8357 09675
Company Name: Velocity Truck Centres Adelaide Pty Ltd

Vehicle Plate Number: **SB61GM**

Daimler Trucks Mt Gambier
Authorised Mercedes-Benz, Freightliner,
& Fuso Sales, Service & Parts

Job Number:

Service Tax Invoice: RA972001351:05

BILL TO
LAKE CITY TOURS - 143760
PO BOX 609
MOUNT GAMBIER SA 5290
Phone: 08 8723 2991

DELIVER TO
LAKE CITY TOURS - 143760
PO BOX 609
MOUNT GAMBIER SA 5290
Phone: 0412 838 765

DATE ARRIVED	DATE INVOICE	SALES TYPE	ADVISOR	TERMS	CUSTOMER PO#				
03/2023 8:30:00AM	29/05/2023	CT	Bianca J	AR	SB61GM				
YEAR	MAKE	MODEL	VIN	CUSTOMER UNIT #	ENGINE HOURS	IN SERVICE	Component Serial #	ODOM IN	ODOM OUT
2013	MH		JLFB64DG0RG10056		0		4M50D72993	72,453	72,453

Sold Operations

JOB #5 18


Engine Lubrication

COMPLAINT
CAUSE
CORRECTION

APPROVED QUOTE/REPAIRS: REPLACE OIL COOLER, OIL COOLER CRACKED.
Oil cooler cracked
jacked up bus
removed trans oil cooler
removed both ATF lines
removed lower bracket
removed trans cooler
clean area
fit new trans cooler
fit both ATF lines
fit lower bracket
fit fan
start bus and check for leaks
check gearbox oil
clean area
road test bus and recheck for leaks

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	972U/QME642962	COOLER OIL	2,460.43	2,460.43
	LABOR 18-10	Engine Lubrication		495.00
Prepay: \$0.00			Parts: \$2,460.43	Labor: \$495.00
Misc: \$0.00			Sublet: \$0.00	\$2,955.43
Sold Operations Totals			Prepay: \$0.00	Parts: \$2,460.43
			Labor: \$495.00	Misc: \$0.00
			Sublet: \$0.00	\$2,955.43

Paid 29/08/24
Ref 536219950



Tax Invoice

Reference No.: 005445
Date: 28-Aug-2024
Due Date: 30-Sep-2024
Customer ID: C00503
Currency: AUD

Triple S Distributors Pty Ltd
PO Box 9878
Mount Gambier West, SA, 5291
Phone: (08) 8725 7940
ABN#: 56630063366

BILL TO:

Lake City Tours
78 Sturt Street
Mount Gambier SA 5290
AUSTRALIA

SHIP TO:

Lake City Tours
78 Sturt Street
Mount Gambier SA 5290
AUSTRALIA

CUSTOMER REF. NUMBER	TERMS	CONTACT
----------------------	-------	---------

NO.	ITEM	QTY.	UOM	UNIT PRICE	DISC.	EXTENDED PRICE
1	LABOUR: 3 MONTHLY INSPECTION NOTE: SB61GM, 78965km, 23/08/2024 Carried out 3 monthly inspection as required.	2.00	HOUR	130.00	0%	260.00
2	LABOUR: STEP DOESN'T OPEN WHEN DOOR IS OPENED, AND THEN WON'T CLOSE WHEN DOOR IS CLOSED NOTE: SB61GM, 78965km, 23/08/2024 Inspected step concern, but will have to come back for further inspection.	0.00	HOUR	130.00	0%	0.00
3	LABOUR: FLASHING LIGHTS DON'T COME ON WHEN DOOR IS OPENED, OR TURN OFF AFTER THE DOOR IS CLOSED NOTE: SB61GM, 78965km, 23/08/2024 Inspected light concern, but will have to come back for further inspection.	0.00	HOUR	130.00	0%	0.00

BANK DETAILS: BankSA
BSB: 105002
ACC: 137186140

Sales Total: 260.00
Tax Total: 26.00
Total (AUD): 286.00

Please quote invoice number as Reference

**TRIDENT TRUCK TYRE
CENTRE P/L**
 **08 8723 1500**

 PO BOX 2429
 AVEY RD
 MT GAMBIER 5290
 terry@tridenttyres.com.au

 Customer Code: LAKTOU
 LAKE CITY TOURS

 PO BOX 609
 MOUNT GAMBIER SA 5290


**COPY
TAX INVOICE
211038**

ISSUED	SALESPERSON	FINALISED BY
08/02/24	CRAIG WIESTRA	CRAIG WIESTRA

VEHICLE MAKE	VEHICLE SERIES	YEAR	ODOMETER	CUSTOMER ORDER NO.
FUSO ROSA BUS			76368	
VEHICLE MODEL	REGISTRATION NO.	VIN NO.	PAID BY	
	SB61GM			

Product	Description	Qty	Price	Amount
KU2058516RS02	KUMHO (12) RS02 205/85R16	2	243.64	487.28
ZZSCRAPRVLTR	SCRAP TYRES RV / LTR	2	15.00	30.00
ZBALRVLTR	BALANCE RV/LTR	2	18.18	36.36
	<i>POS 1/2 205/85R16</i>			
ZROTATERVLTR	ROTATE RV / LTR TYRE	2	6.82	13.64
	<i>POS 1/2 TO 5/6</i>			
	<i>RIGHT REAR INNER DRIVE TO SPARE</i>			
	<i>J41733</i>			

EX GST AMOUNT	\$567.28
GST	\$56.73
TOTAL	\$624.01



Goods remain the property of TRIDENT TRUCK TYRE CENTRE P/L until paid in full. Bridgestone Australia Ltd. is a participant in the Tyre Stewardship Scheme (tyrestewardship.org.au) that is supported by Governments and authorised by the ACCC (Authorisation Number AA1000409). Bridgestone and its network of retail stores recycle tyres responsibly. Bridgestone Australia Ltd. Has recommended that all Bridgestone stores are required to be Tyre Stewardship (TSA) accredited and all end of life tyres are collected from the store only by responsible recyclers who are members of the Australian Tyre Recyclers Association (ATRA). Bridgestone Australia Ltd. Terms of Sale: These goods are sold in accordance with the Terms of Sale of Bridgestone Australia Ltd. as published from time to time. Acceptance of these goods implies acceptance of such terms. See bridgestonetyres.com.au/terms-of-sale. Privacy Statement: We care about your privacy. View our Privacy Policy here at bridgestonetyres.com.au/privacy.

Paid Direct Debit
31/07/24 Ref 522062019



TAX INVOICE

lake city tours

SBB1GM.

Invoice Date
29 Jul 2024

Invoice Number
INV-0440

Reference
22 seater

ABN
61 794 670 952

WJCK Little Family Trust
Attention: WJ & CK
LITTLE
PO Box 2533
MOUNT GAMBIER SA
5290
AUSTRALIA
Phone: 0419809374
Email:
southernpaintandpanel@
mail.com

Description	Quantity	Unit Price	GST	Amount AUD
repairs to rear door, front panel and front bumper.	1.00	1,850.00	10%	1,850.00
			INCLUDES GST 10%	168.18
			TOTAL AUD	1,850.00

Due Date: 12 Aug 2024

Bank Details: Bank SA
BSB: 105-002
ACC: 140-906-740

Please quote invoice number as reference
Strictly 14 days
Late payment penalties will apply unless otherwise arranged.
Failure to make timely payments may result in legal action.

PAYMENT ADVICE

Customer	lake city tours
Invoice Number	INV-0440
Amount Due	1,850.00
Due Date	12 Aug 2024

Amount Enclosed

Enter the amount you are paying above

To: WJCK Little Family Trust
Attention: WJ & CK LITTLE
PO Box 2533
MOUNT GAMBIER SA 5290
AUSTRALIA
Phone: 0419809374
Email: southernpaintandpanel@gmail.com

Paid 22/3/24 Ref 463100523



Copy Tax Invoice

Triple S Distributors Pty Ltd
PO Box 9878
Mount Gambier West, SA, 5291
Phone: (08) 8725 7940
ABN#: 56630063366

Reference No.: 003579
Date: 19-Mar-2024
Due Date: 30-Apr-2024
Customer ID: C00503
Currency: AUD

BILL TO:	SHIP TO:
Lake City Tours 78 Sturt Street Mount Gambier SA 5290 AUSTRALIA	Lake City Tours 78 Sturt Street Mount Gambier SA 5290 AUSTRALIA

CUSTOMER REF. NUMBER	TERMS	CONTACT
	End of Following Month	

NO.	ITEM	QTY.	UOM	UNIT PRICE	DISC.	EXTENDED PRICE
1	LABOUR: 3 Monthly Inspection and Replace Coolant NOTE: SB61GM, 76898km, 06/03/2024	3.00	HOUR	130.00	0%	390.00
	Carried out 3 monthly inspection as required. Replaced coolant as required.					
2	COOLANT: Shell HD 50/50 Coolant	12.00	LITRE	8.18	0%	98.16
3	GREASE: Shell Gadus S2 V220 AC 2	2.00	KG	18.91	0%	37.82
4	CONSUMABLES: Consumables	1.00	EACH	50.00	0%	50.00
5	ENVIRONMENTALCHARGES: Environmental Charges	1.00	EACH	20.00	0%	20.00

BANK DETAILS: BankSA
BSB: 105002
ACC: 137186140

Sales Total: 595.98
Tax Total: 59.60
Total (AUD): 655.58

Please quote invoice number as Reference

Paid 22/05/24

Ref 489803441



Tax Invoice

Triple S Distributors Pty Ltd
PO Box 9878
Mount Gambier West, SA, 5291
Phone: (08) 8725 7940
ABN#: 56630063366

Reference No.: 004286
Date: 13-May-2024
Due Date: 30-Jun-2024
Customer ID: C00503
Currency: AUD

BILL TO:	SHIP TO:
Lake City Tours 78 Sturt Street Mount Gambier SA 5290 AUSTRALIA	Lake City Tours 78 Sturt Street Mount Gambier SA 5290 AUSTRALIA

CUSTOMER REF. NUMBER	TERMS	CONTACT
	End of Following Month	

NO.	ITEM	QTY.	UOM	UNIT PRICE	DISC.	EXTENDED PRICE
1	LABOUR: 12 Monthly Inspection NOTE: SB61GM, 77562km, 06/05/2024	2.00	HOUR	130.00	0%	260.00

Carried out 12 monthly inspection as required.

BANK DETAILS: BankSA
BSB: 105002
ACC: 137186140

Sales Total:	260.00
Tax Total:	26.00
Total (AUD):	286.00

Please quote invoice number as Reference



s.e. fire extinguisher services

H & R Schroder Family Trust T/A ACN: 619 213 053

ABN: 78 277 130 843

Phone: (08) 8723 4200 Fax: (08) 8723 4288
337 Commercial St West Mount Gambier SA 5290
E-Mail - admin@sefire.net



*Paid 13/11/24
Ref 574775504*

STATEMENT

BILL TO:

Lake City Tours
P O Box 609
Mount Gambier SA 5290

ACCOUNT ID SE0507

STATEMENT DATE
7/11/2024

DATE	INVOICE NO.	CHARGES	PAYMENTS	BALANCE
31/10/2024	INV-7697	\$27.50		\$27.50


EFT PAYMENT NOTIFICATION

Your EFT Payments may not be processed when NO BUSINESS NAME is showing on our Bank Statement. Please notify us by FAX, E-MAIL or PAYMENT SLIP when making payments

CURRENT	30 DAYS	60 DAYS	90 DAYS	BALANCE DUE:	
\$27.50	\$0.00	\$0.00	\$0.00	BALANCE DUE:	\$27.50

Please detach and return with payment

REMITTANCE

 s.e. fire extinguisher services
PO BOX 2784, MT GAMBIER SA

DIRECT DEPOSIT DETAILS
BSB 065-504 Acc # 1038 3565
BANK - CBA Mt Gambier
ACCOUNT NAME - H & R SCHRODER PTY LTD

Lake City Tours
P O Box 609
Mount Gambier SA 5290

BALANCE DUE: \$27.50

PAYMENT AMOUNT: \$ _____

If you wish us to send invoices/statements electronically to you please submit your email address to admin@sefire.net

Payment Receipt

H & R Schroder Pty Ltd	\$27.50
Osko Payment	
Status	Paid
BSB	065 504
Account No.	103 835 65
Payment Date	13 Nov 2024 at 5:24pm
Description	Inv.7697
Acknowledgement	574775504
Reference	fire extinguisher service
FROM	Business Account 633 000 / 127 562 064
Paid to	H & R Schroder Pty Ltd

TAX INVOICE

Lake City Tours

SE0507

P O Box 609

Mount Gambier

SA 5290

Invoice Number

INV-7697

Reference

-

Date Issued

31st October 2024

Date Due

28th November 2024

Property

UP-1757 Lake City Tours

Description of Works

October 2024 -Lake City Tours

Description	Quantity	Unit Price	Tax	Subtotal
6 Monthly Extinguisher Servicing	1.00	\$7.00	\$0.70	\$7.00
Attendance Maintenance Fee	1.00	\$18.00	\$1.80	\$18.00
			Subtotal	\$25.00
			Total Tax	\$2.50
			Invoice Total	\$27.50

ABN

78 277 130 843

Payment instructions

SE Fire Extinguisher Services

PO Box 2784

Mount Gambier SA 5290

DIRECT DEPOSIT DETAILS

BSB: 065 504 ACC: 1038 3565

BANK: Commonwealth

ACCOUNT NAME: H & R Schroder Pty Ltd t/a South East Fire Extinguishers

Property:
UP-1757 Lake City Tours
78 Sturt St Mount
Gambier SA 5290
Australia

Client:
Lake City Tours

Task:
T-14823

Issued by:
Louise Butler
31st October 2024

Performed Date:
30th October 2024

Scope of Works

10 - Portable and Wheeled Fire Extinguishers: Six-monthly (1)

0	Critical Defects	A defect that renders a system inoperative.
0	Non-critical Defects	A system impairment not likely to critically affect the operation of the system.
0	Non-conformances	Missing information or incorrect feature that does not affect the system operation.
0	Recommendations	A modification suggested to improve the system performance.
0	Informational Notes	Detailed advice or general comment.

Servicing Summary

Service	Asset	Quantity
10 - Portable and Wheeled Fire Extinguishers: Six-monthly	Fire Extinguisher	1


Maintenance

10 - Portable and Wheeled Fire Extinguishers: Six-monthly

Asset	Status
001 - EXT 2.5KG DCP AB(E) Extinguisher	VEHICLES, Bus SB-61-GM PASS

Lake City Tours
Lake City Tours

Paid 26-4-25.
Ref 662677401



TAX INVOICE

Lake City Tours

SE0507
P O Box 609
Mount Gambier
SA 5290

Invoice Number

INV-10095

Reference

-

Date Issued

9th April 2025

Date Due

28th May 2025

Property

UP-1757 Lake City Tours

Description of Works

Lake City Tours **April 2025**

Description	Quantity	Unit Price	Tax	Subtotal
12 Monthly Extinguisher Servicing	1.00	\$7.50	\$0.75	\$7.50
Attendance Maintenance Fee	1.00	\$20.00	\$2.00	\$20.00
			Subtotal	\$27.50
			Total Tax	\$2.75
			Invoice Total	\$30.25

ABN

78 277 130 843

Payment instructions


SE Fire Extinguisher Services
PO Box 2784
Mount Gambier SA 5290

DIRECT DEPOSIT DETAILS

BSB: 065 504 ACC: 1038 3565

BANK: Commonwealth

ACCOUNT NAME: H & R Schroder Pty Ltd t/a South East Fire Extinguishers



Property:
UP-1757 Lake City Tours
78 Sturt St Mount
Gambier SA 5290
Australia

Client:
Lake City Tours

Task:
T-21783

Issued by:
Louise Butler
9th April 2025

Performed Date:
3rd April 2025

Scope of Works

10 - Portable and Wheeled Fire Extinguishers: Annual (1)

0	Critical Defects	A defect that renders a system inoperative.
0	Non-critical Defects	A system impairment not likely to critically affect the operation of the system.
0	Non-conformances	Missing information or incorrect feature that does not affect the system operation.
0	Recommendations	A modification suggested to improve the system performance.
0	Informational Notes	Detailed advice or general comment.

Servicing Summary

Service	Asset	Quantity
10 - Portable and Wheeled Fire Extinguishers: Annual	Fire Extinguisher	1

Maintenance

10 - Portable and Wheeled Fire Extinguishers: Annual

Asset	Status
001 - EXT 2.5KG DCP AB(E) Extinguisher	VEHICLES, Bus SB-61-GM PASS

Payment Receipt

H & R Schroder Pty Ltd	\$30.25
Osko Payment	
Status	Paid
BSB	065 504
Account No.	103 835 65
Payment Date	26 Apr 2025 at 9:23pm
Description	INV.10095
Acknowledgement	662677401
Reference	SB61GM
<hr/>	
FROM	Business Account
	633 000 / 127 562 064
<hr/>	
Paid to	H & R Schroder Pty Ltd



*Paid 03/01/25
Ref 601970638*

Tax Invoice

Reference No.: 006450
Date: 10-Dec-2024
Due Date: 09-Jan-2025
Customer ID: C00503
Currency: AUD

Triple S Distributors Pty Ltd
PO Box 9878
Mount Gambier West, SA, 5291
Phone: (08) 8725 7940
ABN#: 56630063366

BILL TO:	SHIP TO:
Lake City Tours 78 Sturt Street Mount Gambier SA 5290 AUSTRALIA	Lake City Tours 78 Sturt Street Mount Gambier SA 5290 AUSTRALIA

CUSTOMER REF. NUMBER	TERMS	CONTACT			
	30 Days from Invoice Date				
NO.	ITEM	QTY. UOM	UNIT PRICE	DISC.	EXTENDED PRICE
1	LABOUR: 3 MONTHLY INSPECTION NOTE: SB61GM, 81931km, 22/11/2024 Carried out inspection as required. Found drivers mirror was loose, seats are becoming loose and there is a trans cooler leak, Removed screws to mirror, cleaned up and applied loctite and screwed back in.	2.00 HOUR	130.00	0%	260.00
2	CONSUMABLES: Consumables	1.00 EACH	50.00	0%	50.00

BANK DETAILS: BankSA
BSB: 105002
ACC: 137186140

Sales Total: 310.00
Tax Total: 31.00
Total (AUD): 341.00

Please quote invoice number as Reference

Paid 4/3/25
Ref 633876243

SE Forest & Hydraulic Centre



SE FOREST

C.A. & J.F. Medhurst Pty Ltd

A.B.N. 26 071 493 797

A.C.N. 071 493 797

PO Box 9107
MOUNT GAMBIER WEST SA 5291
16 Ritana Road
MOUNT GAMBIER

Phone: 08 8723 9966

Email: admin@seforest.com.au

Fax: 08 8723 9955

Tax Invoice

Invoice No: 00110151

Bill To:

Lake City Tours
PO Box 609
Mount Gambier SA 5290

Terms: Net 31

Date: 1/01/2025

Your No:

QTY	ITEM NO.	DESCRIPTION	PRICE	UNIT	DISC %	EXTENDED
	1machine	Machine: Wheel Chair Lift				
	1reg	Registration Number: SB-61-GM				
	1sn	S/N: JLFBE640GORG10058				
	1k	Kilometres: 82,289				
	1JC	Job Card Number: 18858				
	1b	Perform an Annual Service / Inspection on Wheel Chair Lift				
	1b	Remove & disassemble hydraulic cylinder as leaking hydraulic oil				
	1b	Supply & fit a new cylinder rod as chrome shaft damaged				
	1b	Reassemble with new seals & refit to unit				
	1b	Drain & refill reservoir				
	1b	Degrease & steam clean underbody & framework & clean & lube slide assemblies				

Comment:	Sale Amt.:	
	GST:	
	Total Amt.:	
	Paid Today:	
	Balance Due:	

How to pay



by mail

Detach this section and mail your cheque to...

SE Forest & Hydraulic Centre
PO Box 9107
MOUNT GAMBIER WEST SA 5291

From:

Lake City Tours
PO Box 609
Mount Gambier SA 5290

Or by Direct Banking to...

BSB: 105-002
Account No: 113469940
Account Name: SE Forest & Hydraulic Centre

Invoice #: 00110151 Amount Due:



SE FOREST

SE Forest & Hydraulic Centre

C.A. & J.F. Medhurst Pty Ltd

A.B.N. 26 071 493 797

A.C.N. 071 493 797

PO Box 9107
MOUNT GAMBIER WEST SA 5291
16 Ritana Road
MOUNT GAMBIER

Phone: 08 8723 9966

Email: admin@seforest.com.au

Fax: 08 8723 9955

Tax Invoice

Invoice No: 00110151

Bill To:

Lake City Tours
PO Box 609
Mount Gambier SA 5290

Terms: Net 31

Date: 1/01/2025

Your No:

QTY	ITEM NO.	DESCRIPTION	PRICE	UNIT	DISC %	EXTENDED
	1b	Remove & repair intermittent rear door switch & cutting power to isolator switch				
	1b	Put vehicle over pit & remove covers & hydraulically straighten bent support bar causing unit to catch when extending				
	1b	Retest for smooth operation & refit covers				
	labour	Labour				\$835.00
	1b	Sublet Repair: 1 x Cylinder Rod Assembly				\$119.37
1	4604000	Halite Type 601 Rod Seal	\$25.30			\$25.30
1	020X1.5N90	20 x 1.5 NBR Metric O-Ring	\$10.76			\$10.76
	1oil	Oil: 600ml ATF D3				\$16.07

Comment:	Sale Amt.:	\$1,006.50
	GST:	\$100.65
	Total Amt.:	\$1,107.15
	Paid Today:	\$0.00
	Balance Due:	\$1,107.15

How to pay



by mail

Detach this section and mail your cheque to...

SE Forest & Hydraulic Centre
PO Box 9107
MOUNT GAMBIER WEST SA 5291

From:

Lake City Tours
PO Box 609
Mount Gambier SA 5290

Or by Direct Banking to...

BSB: 105-002
Account No: 113469940
Account Name: SE Forest & Hydraulic Centre

Invoice #: 00110151 Amount Due: **\$1,107.15**

Paid 26-03-25
Ref 645066115



Tax Invoice

Reference No.: 007240
Date: 20-Mar-2025
Due Date: 19-Apr-2025
Customer ID: C00503
Currency: AUD

Triple S Distributors Pty Ltd
PO Box 9878
Mount Gambier West, SA, 5291
Phone: (08) 8725 7940
ABN#: 56630063366

BILL TO:
Lake City Tours
78 Sturt Street
Mount Gambier SA 5290
AUSTRALIA

SHIP TO:
Lake City Tours
78 Sturt Street
Mount Gambier SA 5290
AUSTRALIA

CUSTOMER REF. NUMBER	TERMS	CONTACT				
	30 Days from Invoice Date					
NO.	ITEM	QTY.	UOM	UNIT PRICE	DISC.	EXTENDED PRICE
1	LABOUR: 1 & 3 MONTHLY INSPECTION NOTE: SB61GM, 82813km, 27/02/2025	2.00	HOUR	130.00	0%	260.00
	Carried out inspection as required. Found the removable seats to have slight movement.					
2	LABOUR: INSPECT TRANS COOLER LEAK AS NOTED LAST INSPECTION, AND ORDER PARTS AS REQUIRED TO REPAIR NOTE: SB61GM, 82813km, 27/02/2025	0.00	HOUR	130.00	0%	0.00
	Inspected and found to be leaking at the fitting. Replaced the copper washers, washed down, topped up oil and checked, all ok.					
3	PARTS: 2 x COPPER WASHER 20 x 26	1.00	EACH	12.14	0%	12.14
4	OIL: Shell Spirax S3 ATF MD3	8.00	LITRE	10.98	0%	87.84
5	CONSUMABLES: Consumables	1.00	EACH	50.00	0%	50.00
6	ENVIRONMENTALCHARGES: Environmental Charges	1.00	EACH	20.00	0%	20.00

BANK DETAILS: BankSA
BSB: 105002
ACC: 137186140

Sales Total: 429.98
Tax Total: 43.00
Total (AUD): 472.98

Please quote invoice number as Reference

Paid 22/5/25
Ref 676521742



Tax Invoice

Triple S Distributors Pty Ltd
PO Box 9878
Mount Gambier West, SA, 5291
Phone: (08) 8725 7940
ABN#: 56630063366

Reference No.: 007844
Date: 21-May-2025
Due Date: 20-Jun-2025
Customer ID: C00503
Currency: AUD

BILL TO:
Lake City Tours
78 Sturt Street
Mount Gambier SA 5290
AUSTRALIA

SHIP TO:
Lake City Tours
78 Sturt Street
Mount Gambier SA 5290
AUSTRALIA

CUSTOMER REF. NUMBER	TERMS	CONTACT				
	30 Days from Invoice Date					
NO.	ITEM	QTY.	UOM	UNIT PRICE	DISC.	EXTENDED PRICE
1	LABOUR: 1 / 3 / 12 MONTH INSPECTIONS NOTE: SB61GM, 83682km, 01/05/2025	3.00	HOUR	130.00	0%	390.00
	Carried out 1, 3 and 12 month inspection as per inspection sheet. Washed down and dropped bus off when finished.					
2	CONSUMABLES: Consumables	1.00	EACH	50.00	0%	50.00

BANK DETAILS: BankSA	Sales Total:	440.00
BSB: 105002	Tax Total:	44.00
ACC: 137186140	Total (AUD):	484.00

Please quote invoice number as Reference