



Commercial Vehicle Inspection Report

Decal Number: GK85625
Decal Expiry Date: 2026-Sep-30
Inspection Number: 21510745

Inspection Result:

PASS

V03-7

FACILITY: TOTAL INSPECTION SERVICES INC. / S20320
INSPECTOR: SKAFTE, STEWART / 301627
WORK ORDER #:
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2025-Sep-26 06:00 AM MST
INSP. COMPLETE: 2025-Sep-26 07:10 AM MST

VEHICLE JUR: British Columbia
PLATE #: B5467K
LICENCED GVW(kg): 0
VEHICLE YEAR: 2017
MAKE: LODGE KING
MODEL:
REGI: 14631256
UNIT/FLEET#: T299
BODY STYLE: Bulk Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2LDHG2835HF062621
OWNER/LESSEE NAME: TIDY TRUCKING, LTD
ADDRESS: PO BOX 6767 STATION MAIN
Fort St John, British Columbia
V1J4J2, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Repaired (same day) ABS LIGHT ON A2 AIRLINES RUBBING
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Repaired (same day) A3 LH TIRES LOW TREAD
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	39	38
2	Clamp	30	Automatic	37	37
3	Clamp	30	Automatic	38	41

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
15	14	14	11	
19	17	11	11	
4	4	15	19	

Comment: A3 LHS TIRES REPLACED

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	55	55
2	60	60
3	65	70

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	14	15
Lining (Shoe)	13	14
Lining (Shoe)	12	11

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Road Tester:

Inspector: SKAFTE, STEWART

Signature:

This Inspection Report was submitted to CVSE on 2025-Sep-26 08:11 AM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement

CVSE0014

9/26/2025 8:11:27 AM MST