



# Commercial Vehicle Inspection Report

Decal Number: GK85626  
Decal Expiry Date: 2026-Sep-30  
Inspection Number: 21510791

Inspection Result:  
**PASS**

V03-2

FACILITY: TOTAL INSPECTION SERVICES INC. / S20320  
INSPECTOR: SKAFTE, STEWART / 301627  
WORK ORDER #:  
INSP. TYPE: Complete  
INSP. CLASS: Class 3 - Trailer and Semi-Trailer  
INSP. REASON: Annual  
INSP. START: 2025-Sep-26 07:05 AM MST  
INSP. COMPLETE: 2025-Sep-26 08:15 AM MST

VEHICLE JUR: British Columbia  
PLATE #: 85468K  
LICENCED GWW(kg): 0  
VEHICLE YEAR: 2017  
MAKE: LODE KING  
MODEL:  
REGI: 14631280  
UNIT/FLEET#: TP299  
BODY STYLE: Bulk Trailer  
ODOMETER:  
HUB ODOMETER:  
BRAKE TYPE: Air  
FUEL TYPE:  
VIN: 2LDHG3026HF062622  
OWNER/LESSEE NAME: TIDY TRUCKING, LTD  
ADDRESS: PO BOX 6767 STATION MAIN  
Fort St John, British Columbia  
V1J 4J2, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Repaired (same day) A1 AIRLINES RUBBING
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

### Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	39	40
2	Clamp	30	Automatic	40	36

Comment:

### Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
10	12	12	13	
12	10	15	17	

Comment:

### Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	65	60
2	66	61

Comment:

### Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	14	13
Lining (Shoe)	14	13

Comment:

### Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

### Inspection Comments:

Has this Vehicle been road tested? No

Inspector: SKAFTE, STEWART

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Sep-26 08:34 AM MST

The inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

### NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSE014

9/26/2025 8:34:38 AM MST