



Vehicle History Detail

Fleet #	R07
Registration	XO66MK
Make	Kenworth
Model	T359
VIN / Chassis #	6F5000000CA448439

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
14/05/2026	418,711 kms	A - A Service S-16582 Carried out A service as per service checklist			\$80.00
30/04/2026	418,195 kms	B S-16420 Carried out B service as per service checklist changing engine oil and filters. Changed fuel filters, checked belts and pulleys - ok. Changed air cleaner and AdBlue air filter. Greased and adjusted brakes. Steam cleaned chassis.			\$514.74
23/04/2026		Haulstar T-991 Supply and fit eight new tyres and dispose	Clarence Valley Tyres	1086607	\$2,925.00
21/04/2026	418,159 kms	A - A Service S-16378 Carried out A service as per service checklist			\$80.00
21/04/2026	189,121 kms	A - A Service S-16379 Carried out A service as per service checklist			\$80.00
16/03/2026	412,797 kms	R/H Front steer wheel bearings R-3076 Jacked up front end checking wheel bearings and kingpins finding R/H wheel bearings Knotchy. Disassembled cleaned parts and reassembled replacing wheel bearings and seal. Adjusted to spec.	Workshop		\$330.53
16/02/2026	412,797 kms	A - A Service S-16225 Carried out A service as per service checklist			\$80.00
16/02/2026	412,797 kms	C - C Service S-16490 Carried out C service as per service checklist also road tested vehicle checking max road speed set to 100kms set ok			\$0.00
02/02/2026	411,711 kms	A - A Service S-16053 Carried out A service as per service checklist			\$80.00
13/01/2026		Fit and dispose T-915 Fit and dispose of truck tyre	Clarence Valley Tyres	1082237	\$77.00
05/01/2026	409,777 kms	A - A Service S-15879 Carried out A service as per service checklist			\$80.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
20/11/2025		Puncture repair T-874 Puncture repair	Clarence Valley Tyres	1080050	\$77.00
06/11/2025	405,493 kms	A - A Service S-15614 Carried out A service as per service checklist			\$80.00
16/10/2025	403,779 kms	B S-15413 Carried out B service as per service checklist. Changed engine oil and filter, water filter and blow out air cleaner. Replaced fan bet started and tested ok. Steam cleaned chassis.	Workshop		\$486.44
16/10/2025	403,166 kms	2 x failed batteries. R-2841 Travelled to Maclean to troubleshoot. Truck will not start. Trouble shoot faulty batteries, remove and replace 3 x batteries. Started and tested checked charge rate ok.	Workshop		\$720.28
16/10/2025	403,779 kms	steering shaft R-2845 Inspected and repaired movement in steering. Shaft removed and replace 2 steering uni-joints. Reassembled and greased and tested OK. Tightened up pitman arm to steering box.	Workshop		\$162.56
15/10/2025	403,779 kms	A - A Service S-15483 Carried out A service as per service checklist	Workshop		\$80.00
09/10/2025	403,166 kms	A - A Service S-15482 Carried out A service as per service checklist	Workshop		\$80.00
02/09/2025	399,690 kms	A - A Service S-15324 Carried out A service as per service checklist			\$80.00
15/08/2025	396,324 kms	Remove and replace R/H drivers mirror. R-2742 Inspected and repaired R/H drivers mirror - removed and replaced damaged mirror and adjusted to spec. Tested OK.	Workshop		\$379.78
08/08/2025	397,347 kms	Repaired LH front lock body curtain. R-2728 Removed and repaired L/H front curtain latch. Locked, modified locking mechanism to suit. Refitted to body and tested OK.	Workshop.		\$503.00
25/07/2025	396,324 kms	A - A Service S-15323 Carried out A service as per service checklist			\$80.00
01/07/2025	394,141 kms	A - A Service S-15325 Carried out A service as per service checklist			\$80.00
17/06/2025	393,102 kms	A - A Service S-14844 Carried out A service as per service checklist also carried out curtain repairs replacing and repairing rollers and lubrication			\$240.00
02/06/2025	391,766 kms	A - A Service S-14643 Carried out A service as per service checklist			\$80.00
19/05/2025	390,294 kms	A - A Service S-14597 Carried out A service as per service checklist also steam clean chassis			\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
14/05/2025	390,061 kms	A - A Service S-14540 Carried out A service as per service checklist			\$0.00
16/04/2025	388,343 kms	B S-14436 Carry out A service as per service checklist also repaired air leaks removing and replaced 4 x 30/30 brake boosters and adjusted to spec			\$0.00
15/04/2025	388,311 kms	A - A Service S-14435 Carry out A service as per service checklist			\$0.00
17/03/2025	385,714 kms	A - A Service S-14084 Carry out A service as per service checklist			\$0.00
06/03/2025		Reverse cameras R-2488 Check reverse camera faults, supply and fit new camera	JUSTIN BAILEY	INV-0017707	\$236.50
03/03/2025	384,701 kms	A - A Service S-14081 Carryout A service also removed and replaced r/h rear curtain latch assembly tested ok	Workshop		\$0.00
26/02/2025	384,482 kms	A - A Service S-14080 Carry out A service	Workshop		\$0.00
12/02/2025	383,144 kms	A - A Service S-14079 Carry out A service	Workshop		\$0.00
10/02/2025	383,144 kms	C - C Service S-14360 Carry out C service as per service checklist also road test vehicle checking max road speed set to 100 kms ok			\$0.00
29/01/2025	382,407 kms	A - A Service S-14078 Carry out A service	Workshop		\$0.00
22/01/2025	381,736 kms	A - A Service S-13915 Carry out A service as per service checklist steam clean chassis			\$0.00
16/12/2024	379,181 kms	A - A Service S-13764 Carry out A service as per service checklist			\$0.00
03/12/2024	378,350 kms	A - A Service S-13682 Carry out A service as per service checklist also removed and replaced top bonnet mounts and steam clean chassis			\$0.00
13/11/2024	376,756 kms	A - A Service S-13464 Carry out A service as per service checklist			\$0.00
13/11/2024	376,682 kms	light globs R-2368 Inspected and repaired blown light globs removed and replaced tested ok	Workshop		\$0.00
14/10/2024	375,043 kms	B S-13463 Carry out B service as per service checklist changing engine oil and filters also jacked up front end checking steering king pins and bearings ,changed hub oils ,ok repaired air leak at horton switch air valve replacing filter cleaned and tested			\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
14/10/2024	375,043 kms	A - A Service S-13462 Carry out A service as per service checklist			\$0.00
14/10/2024	374,390 kms	clearance lights R-2352 Inspected and repaired clearance lights out replacing bulbs	Workshop		\$0.00
08/10/2024	374,644 kms	A - A Service S-13461 Carry out A service as per service checklist			\$0.00
09/09/2024		Puncture repair T-571 Puncture repair	Clarence Valley Tyres	1061906	\$77.00
05/09/2024	372,188 kms	A - A Service S-12998 Carry out A service as per service checklist			\$0.00
21/08/2024		Haulmax 275/70R 22.5 T-554 Supply and fit four new tyres and dispose of tyres	Clarence Valley Tyres	1061107	\$1,952.00
06/08/2024	369,934 kms	A - A Service S-12861 Carry out A service as per service checklist cleaned and tested			\$0.00
06/08/2024	369,934 kms	B S-12862 Carry out B service as per service checklist changing engine oil and filters also sos sample oil cleaned and tested			\$0.00
06/06/2024	365,667 kms	brake slack adjusters R-2270 Removed and replace 4x rear brake slack adjusters and adjusted brakes to spec	Workshop		\$0.00
04/06/2024	365,474 kms	A - A Service S-12860 Carry out A service as per service checklist			\$0.00
23/05/2024	364,676 kms	A - A Service S-12608 Carry out A service as per service checklist			\$0.00
13/05/2024	363,670 kms	windscreen wiper assembly R-2197 Inspected and repaired wiper arm assembly tested ok	Workshop		\$0.00
06/05/2024	363,109 kms	A - A Service S-12607 Carry out A service as per service checklist			\$0.00
08/04/2024	361,546 kms	A - A Service S-12605 Carry out A service as per service checklist			\$0.00
08/04/2024	361,546 kms	B S-12606 Carry out B service as per service checklist changing engine oil and filters steam clean chassis			\$0.00
25/03/2024	360,759 kms	A - A Service S-12604 Carry out A service as per service checklist			\$0.00
14/03/2024	359,588 kms	steer tyres R-2134 Inspected tyres ,worn out truck sent to CVT and tyres removed and replaced	Workshop		\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
11/03/2024	359,588 kms	A - A Service S-12084 Carry out A service as per service checklist also repaired at leak at seat ,and jacked up front end and checked finding king pins and bearings ok			\$0.00
07/03/2024	359,483 kms	A - A Service S-12083 Carry out A service as per service checklist			\$0.00
05/02/2024	357,051 kms	A - A Service S-11963 Carry out A service as per service checklist			\$0.00
05/02/2024	357,051 kms	C - C Service S-11981 Carry out C service as per service checklist also checking max road speed set to 100kms set ok			\$0.00
12/01/2024	355,797 kms	rear tail light assembly R-2076 Inspected and repaired rear tail lights removed and replaced 2 x units ,wiring up tested ok	Workshop		\$0.00
06/12/2023	352,862 kms	A - A Service S-11962 Carry out A service as per service checklist			\$0.00
01/11/2023	350,122 kms	A - A Service S-11355 Carry out A service as per service checklist			\$0.00
01/11/2023	350,122 kms	B S-11356 Carry out B service as per service checklist changing engine oil and filters ,also changing air cleaner and radiator vent line cleaned and tested			\$0.00
25/10/2023		Air conditioner R-1990 Check air con, locate blown o-ring and replace, supply and fit new compressor and regas		INV-0016376	\$1,032.90
25/10/2023		a/c repairs R-1992 Check air con, pressure test system, locate leaking hose, make and fit new hose, supply and fit drier and regas	JUSTIN BAILEY	INV-0016365	\$510.62
18/09/2023	346,531 kms	A - A Service S-11032 Carry out A service as per service checklist			\$0.00
28/08/2023	344,831 kms	A - A Service S-11031 Carry out A service as per service checklist			\$0.00
21/07/2023	342,121 kms	A - A S-10918 Carry out A service as per service checklist			\$0.00
22/06/2023	339,907 kms	A - A Service S-10640 Carry out A service as per service checklist also steam clean chassis			\$0.00
30/05/2023	338,177 kms	A - A Service S-10582 Carry out A service as per service checklist			\$0.00
18/04/2023	335,300 kms	A - A Service S-10580 Carry out A service as per service checklist			\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
18/04/2023	335,300 kms	B S-10581 Carry out B service as per service checklist changing engine oil and filters			\$0.00
04/04/2023	334,509 kms	A - A Service S-10579 Carry out A service as per service checklist			\$0.00
20/02/2023	330,395 kms	A - A Service S-10118 Carry out A service as per service checklist			\$0.00
20/02/2023	330,395 kms	C - C Service S-10110 Carry out C service as per service checklist			\$0.00
11/01/2023	309,225 kms	A - A Service S-9803 Carry out A service as per service checklist			\$0.00
11/01/2023	309,225 kms	B S-9804 Carry out B service as per service checklist changing engine oil and filter and also changed transmission oil and filter ,and removed and replace leaking water pump 22107715 cleaned and tested ok			\$0.00
11/01/2023	327,302 kms	A - A Service S-9802 Carry out A service as per service checklist			\$0.00
19/12/2022	325,646 kms	A - A Service S-9801 Carry out A service as per service checklist			\$0.00
07/11/2022	322,182 kms	A - A Service S-9476 Carry out A service as per service checklist			\$0.00
20/10/2022	321,017 kms	B S-9409 Carry out B service as per service checklist changing engine oil and filter also steam clean chassis			\$0.00
20/10/2022	321,017 kms	A - A Service S-9408 Carry out A service as per service checklist			\$0.00
20/10/2022	318,655 kms	A - A Service S-9410 Carry out A service as per service checklist steam clean chassis and removed and replace addblue filter in tank			\$0.00
04/10/2022	319,575 kms	A - A Service S-9324 Carry out A service as per service checklist			\$0.00
12/09/2022	318,174 kms	A - A Service S-9181 Carry out A service as per service checklist			\$0.00
10/08/2022	314,987 kms	A - A Service S-8920 Carry out A service as per service checklist			\$0.00
11/07/2022	313,947 kms	clutch , Gearbox R-1712 Investigate gearbox fault , diagnose faulty gearbox ,removed and replaced gearbox ,clutch ,also resealing sump ,rear seal , done by cummins grafton ,flywheel machined by swadlings cleaned and tested ok	Workshop		\$6,600.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
01/07/2022	312,570 kms	A - A Service S-8918 Carry out A service as per service checklist			\$0.00
26/04/2022	306,287 kms	A - A Service S-8364 Carry out A service as per service checklist			\$0.00
26/04/2022	306,287 kms	B S-8365 Carry out B service as per service checklist changing engine oil and filters also greased and adjusted clutch to spec ,jacked up and checked front wheel bearings and king pins ok ,tightened up pitman arm ,steamed cleaned			\$0.00
04/02/2022	238,823 kms	C - C Service S-9001 Carry out C service as per service checklist also road test vehicle checking max road speed limit set to 100 kms ok			\$0.00
19/01/2022	298,803 kms	air dryer rekit , tailgate lifter buttons R-1597 Inspected and repaired air dryer leaking air , removed stripped cleaned and rekitted ,also replaced a/c belt and tail gate activate buttons on top of deck	Workshop		\$0.00
19/01/2022	298,803 kms	B S-8140 Carry out B service as per service checklist changing engine oil and filters			\$0.00
19/01/2022	298,803 kms	A - A Service S-8139 Carry out A service as per service checklist			\$0.00
16/11/2021	292,568 kms	A - A Service S-7581 Carry out A service as per service checklist also steam clean chassis			
17/09/2021	287,121 kms	A - A Service S-7331 Carry out A service as per service checklist			
17/09/2021	287,121 kms	drivers seat R-1491 Inspected and repaired drivers seat ,old seat KAB ,fitted new raised seat base and new reconditioned ISRI seat from PM 15, also repaired body rollers etc	Workshop		
17/09/2021	287,121 kms	B S-7330 Carry out B service as per service checklist changing engine oil and filters also steam clean chassis			
26/08/2021		drivers seat R-1465 Repair seat	ISRI Seats	42280	\$1,435.11
09/08/2021	283,301 kms	A - A Service S-7163 Carry out A service as per service checklist also steam clean chassis			
18/06/2021	278,913 kms	batteries R-1402 Inspected and repaired slow starting diagnose faulty batteries removed and replaced 3 x batteries ,started and tested ok	Workshop		
14/05/2021	276,009 kms	B S-6789 Carry out B service as per service checklist changing engine oil and filters ,steam clean chassis also jack up front end checking pins and bushes ok			

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
14/05/2021	276,009 kms	A - A Service S-6788 Carry out A service as per service checklist			
11/02/2021	268,087 kms	A - A Service S-6419 Carry out A service as per service checklist			
11/02/2021	268,087 kms	C - C Service S-6500 Carry out C service as per service checklist also checking road speed limiter ok			
11/02/2021	268,087 kms	B S-6420 Carry out B service as per service checklist changing engine oil and filters stem clean chassis ,also repairing memory strips rear			
23/10/2020	258,120 kms	pitman arm, STEERING BOX R-1205 Inspected and repaired steering wandering ,dianose worn pitman arm spline, removing and replacing steering box and pitman arm bleed system test run ok	workshop		
22/10/2020	258,120 kms	B S-5983 Carry out B service as per service checklist changing engine oil and filters			
22/10/2020	258,120 kms	A - A Service S-5982 Carry out A service as per service checklist			
17/09/2020		Switch control R-1174 Removed dash panel, air lines, electrical plugs, switch and fitted new switch. Refitted all removed components.	Brown And Hurley	2005761	\$264.31
15/09/2020		headlight glob R-1173 Ballina depo removed and replaced r/h front drivers head light glob	Workshop		
01/07/2020	248,056 kms	B S-5561 Carry out B service as per service checklist changing engine oil and filters			
01/07/2020	248,056 kms	A - A Service S-5560 Carry out A service as per service checklist			
17/06/2020	247,158 kms	Starter Motor R-1133 trouble shoot slow wind to start dianose faulty starter remove and replace starter supplied by justin bailey	Workshop		
17/06/2020	247,158 kms	A - A Service S-5559 Carry out A service as per service checklist			
05/05/2020	244,535 kms	A - A Service S-5354 Carry out A service as per service checklist			
02/04/2020	242,815 kms	A - A Service S-5353 Carry out A service as per service checklist			
04/03/2020	240,916 kms	A - A Service S-5070 Carry out A service as per service checklist			

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
04/02/2020	238,823 kms	A - A Service S-5069 Carry out A service as per service checklist			
04/02/2020	238,823 kms	C - C Service S-5112 Carry out C service as per service checklist changing gearbox and diffs oils ,also checking road speed ok			
17/12/2019	235,305 kms	B S-4801 Carry out B service as per service checklist changing engine oil and filters also adjusting clutch			
17/12/2019	235,305 kms	A - A Service S-4800 Carry out A service as per service checklist			
04/12/2019		puncture T-326 Repair Puncture.	ctv		
26/11/2019	233,512 kms	draglink R-982 Inspected and repaired excessive movement in steering draglink ball joint ,removing and replacing grease and test run ok	Workshop		
14/11/2019	232,590 kms	A - A Service S-4802 Carry out A service as per service checklist also replacing light switch for internal light in body			
11/11/2019		tyre R-951 Truck sent to CVT tyre repaired and changed out	ctv		
22/10/2019	230,909 kms	A - A Service S-4649 Carry out A service as per service checklist			
08/08/2019	223,946 kms	A - A Service S-4404 Carry out A service as per service checklist			
03/07/2019	220,804 kms	A - A Service S-4402 Carry out A service as per service checklist			
03/07/2019	220,804 kms	B S-4403 Carry out B service as per service checklist also repairing curtain bottom roller r/h side front			
20/03/2019		wiper blades R-795 New wiper blades sent to ballina coke luke fitted	luke		
26/02/2019	209,314 kms	A - A Service S-3764 Carry out A service as per service checklist work carried out at ballina			
31/01/2019	206,519 kms	C - C Service S-4020 Carry out C service as per service checklist			
31/01/2019	206,519 kms	blinker flasher unit R-723 Inspect and repair blinker fault driver called into brown and hurley kyogle recieved parts and fitted to vehicle tested ok	Workshop		

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
31/01/2019	206,519 kms	B S-3647 Carry out B service as per service checklist changing engine oil and filters also changing air cleaner steam clean chassis			
31/01/2019	206,519 kms	A - A Service S-3646 Carry out A service as per service checklist			
06/12/2018	200,819 kms	A - A Service S-3477 Carry out A service repair carried out at Ballina			
31/10/2018		Headlight globe R-640 Replaced headlight globe	Workshop		
31/07/2018	187,784 kms	B S-2987 Carry out B service as per service check list changing engine oil and filters also adjusting clutch and repairing body door latches			
31/07/2018	187,784 kms	A - A Service S-2986 Carry out A service as per service check list			
14/06/2018	182,587 kms	A - A Service S-2854 Carry out A service as per service sheet carried out at ballina			
02/05/2018	178,364 kms	A - A Service S-2724 Carry out A service as per service checklist work carried out at ballina			
13/03/2018	173,611 kms	B S-2540 Carry out B service as per service check list changing engine oil and filters,add blue filterand gearbox oil also repairing memory strips on body clean and test ok			
13/03/2018	173,611 kms	A - A Service S-2541 Carry out A service as per service checklist			
12/01/2018	167,367 kms	C - C Service S-2574 Carry out C service as per service sheet			
12/01/2018	167,367 kms	A - A Service S-2381 Carry out A service as service sheet carried out at ballina depo			
06/11/2017	161,162 kms	BATTERIES R-447 Removed and Replaced 3 Batteries	Workshop		
02/11/2017	160,445 kms	A - A Service S-2125 Carry out A service as per service check list			
20/09/2017	158,204 kms	A - A Service S-2054 carry out A service at ballina			
24/08/2017	153,529 kms	A - A Service S-1880 Carry out A service as per service sheet			

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
24/08/2017	153,529 kms	B S-1881 Carry out B service, changing engine oil and filters			
28/06/2017	147,647 kms	A - A Service S-1687 Carry out A service carried out at Ballina depo			
31/05/2017	145,348 kms	B S-1583 Carry out B service as per service check list changing engine oil and filter also replacing addblue filter and air cleaner ,steam clean chassis			
30/05/2017	145,348 kms	EXHAUST R-348 Inspect and repair exhaust leak finding blown gasket at muffler remove and replace gasket and clamp test run ok	Workshop		
18/05/2017	143,919 kms	A - A Service S-1582 Carry out A service as per service check list carried out at Ballina depo			
19/04/2017	140,980 kms	A - A Service S-1490			
02/02/2017	129,983 kms	B S-1083			
14/12/2016		C - C Service S-1680 Carry out C service as per service check list			
20/10/2016	120,817 kms	A - A Service S-875			
20/10/2016	120,817 kms	CURTAIN LATCH, CURTAIN ROLLERS, MEMORY STRIPS R-260 REPAIR CURTAIN LATCH/. REPAIR ROLLERS/ RENEW MEMORY STRIPS WERE REQUIRED			
01/10/2016	118,942 kms	A - A Service S-789 CARRY OUT A SERVICE AT BALLINA			
22/08/2016	114,812 kms	B S-672 CHANGE ENGINE OIL /CHANGE OIL FILTER /CHANGE FUEL FILTERS BLOW OUT AIR CLEANER./ CHANGE TANK ADD BLU FILTER/			
22/08/2016	114,812 kms	A - A Service S-671			
04/08/2016	111,971 kms	ELECTRICAL R-175 Replaced sensors, ECM and electrical harness	BROWN & HURLEY	KW064009	\$3,380.82
20/06/2016	108,892 kms	A - A Service S-498 repair air dryer repair clearance lights mirrors			
15/03/2016	99,300 kms	B S-145			
26/12/2015		C - C Service S-91			
171 Records				Total:	\$22,945.59