



**BRITISH
COLUMBIA**

Commercial Vehicle Inspection Report

Decal Number: **GM63536**
Decal Expiry Date: **2026-Aug-31**
Inspection Number: **21680303**

V05-2
Inspection Result:
PASS

FACILITY:	MODERN DIESEL TRUCK REPAIR LTD. / S15400	INSP. TYPE:	Complete	INSP. START:	2026-Feb-27 05:35 PM PST
INSPECTOR:	SANDHU, GURPREET / 202678	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2026-Feb-27 07:35 PM PST
WORK ORDER #:		INSP. REASON:	Semi-annual		

VEHICLE JUR:	British Columbia	REGI:	14390223	VIN:	5KKHALBG9EPFP3085
PLATE #:	XN3497	UNIT/FLEET#:	103	OWNER/LESSEE NAME:	E2L CONSTRUCTION, LTD
LICENCED GVW(kg):	46000	BODY STYLE:	Dump Truck	ADDRESS:	234-2035 GLENAIRE DR, 234-2035 GLENAIRE DR
VEHICLE YEAR:	2014	ODOMETER:	142099 KM		North Vancouver, British Columbia
MAKE:	WESTERN	HUB ODOMETER:			V7P1Y2, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Repaired (same day) XL 2 LEFT SIDE SUPENTION BUSH REPLACED & CAB AIR LEVEL VALVE REPLACED / XL 3 BOTH SIDE AIR BAG & TORQUE ROD REPLACED
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxillary Equipment	Passed
Section 6 - Lamps	Repaired (same day) LEFT SIDE HEAD LIGHT REPAIR
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) WELDING ON BOX
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24L	Automatic	34	34	17			17	✓
2	Clamp	30L	Automatic	34	33	13	14	13	14	
3	Clamp	30L	Automatic	33	34	8	8	8	8	
Comment:				Comment:						

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	52	52	Lining (Shoe)	16	16	Drum		
2	55	56	Lining (Shoe)	17	17	Drum		
3	54	56	Lining (Shoe)	17	17	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:
Has this Vehicle been road tested? **No** Road Test Date: _____ Road Tester: _____
Inspector: SANDHU, GURPREET Signature: _____

This Inspection Report was submitted to CVSE on 2026-Feb-28 07:44 PM PST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.
The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE0014
2/28/2026 7:44:05 PM PST