

Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A133548

Station #: 71765	Station Name: Big Rack Vac Services Ltd
Technician #: 84811	Technician Name: Dustin Pikor
Signing Officer #: 84596	Signing Officer Name: Kim Tuffs

Customer Details:	
Name: D Penners Contracting	Address: Portreeve sask, p.o.box 126, Saskatchewan, s0l2a0

Inspection Completed Date: 12Apr2025	Inspection Expiry Date: 30Apr2026
--------------------------------------	-----------------------------------

Vehicle Details:	
VIN: 1TKC02424XM075235	Hubometer Reading:
Year: 1999	Vehicle Make/Model: TRAIL KING/TRAILER
Plate: n/a	Jurisdiction: Saskatchewan
Unit:	

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71765	Station Name: Big Rack Vac Services Ltd
Technician #: 84811	Technician Name: Dustin Pikor
Signing Officer #: 84596	Signing Officer Name: Kim Tuffs

Customer Details:	
Name: D Penners Contracting	Address: Portreeve sask, p.o.box 126, Saskatchewan, s0l2a0

Vehicle Details:	
VIN: 1TKC02424XM075235	Hubometer Reading:
Year: 1999	Vehicle Make/Model: TRAIL KING TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	marker light replaced
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (8)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
x				Air Brake System/Components (3.2)	
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaus/Emission System (1)	
x				Sliding Axle Assembly (If equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 10/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 9/16 in • Cam Rotation: 70.0 degrees • Brake Stroke: 1 in

Wheel2 : Tire Tread Depth: 10/32 in

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 10/32 in

Brake(1): No Brake

N/A

Wheel4-On : Tire Tread Depth: 10/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 9/16 in • Cam Rotation: 70.0 degrees • Brake Stroke: 1 in

Axle 2-Pass

Wheel1-On : Tire Tread Depth: 9/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 9/16 in • Cam Rotation: 70.0 degrees • Brake Stroke: 1 in

Wheel2 : Tire Tread Depth: 9/32 in

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 9/32 in

Brake(1): No Brake

N/A

Wheel4-On : Tire Tread Depth: 9/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 9/16 in • Cam Rotation: 70.0 degrees • Brake Stroke: 1 in

PASS - vehicle passes inspection

Decal # A133548

Inspection Completed Date: 12Apr2025