



CV8086028



80087900008086028

CERTIFICATE NUMBER**Commercial Vehicle Inspection Certificate
Traffic Safety Act****PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Trailer	Seating Capacity:		
GVW:	30000 kg	Brake Type:	Air	
Owner Name:	Solution Services Inc.			
Address:	Box 934			
City:	Sexsmith	Province:	AB	Postal Code:
Telephone Number:	(780) 814-8418			
Vehicle Identification Number:	2AEFSXKK24E000215			
Make:	quad axle	Model:	dot	
Year:	2005	Unit Number:	VW-01	
Odometer:	KM	Licence Plate Number:	CLN2855	Province:

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE**PART 2 - CERTIFICATION**

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
MVR Mechanical Ltd.	16216
Inspection Technician Name:	Technician Number:
Michael Van Rootselaar	B5527
Inspection Technician Signature:	
Inspection Date:	2024/04/26