

TransALL Motors

Address: 31-37 Alexanders Road, Morwell VIC 3840

PO Box 184 Morwell VIC 3840

Phone: (03) 5134 4383

Fax: (03) 5134 2879

Email Address: admin@transallmotors.com.au

Web Address: www.transallmotors.com.au



NAB | BSB: 083 932 | Account No.: 5021 66633

Service TAX Invoice		Page 1 of 2		Reprint# 3		Doc #: CUCS17487		
Customer No. 1524	Customer Name & Address Moloney Logging 3 Bowral Way Traralgon VIC 3844			Advisor Taylah Daly	102	Colour Green/	Team Service	
Doc. Date 31/10/22				Year / Make / Model 13/KENWORTH/T909			Tag No.	
Reg. No. ZPO586				Model No.	Carline KENWORTH		Eng./Trans.	
Stock No.				Chassis No.	Kilometres 318734	Prod. Date 01/08/13	Orig. Del. Date	
Purchase Order No.	Driver	Contract No.		Contract Name	Contract Exp. Kms	Exp. Date		
☐ CASH ☐ CHEQUE ☐ CREDIT CARD ☐ ACCOUNT	Home Phone	Business Phone (0409)749641	Terms 30	Selling Dealer	Delivery Kms.	Delivery Date	Warr. Exp. Date	
	Vehicle ID. 6F5000000DA450347	Engine No. 79665718	Date & Time Promised 06/10/22 05:00pm	Time Received 08:15am	Quote Price	Air N	Pwr N	
Driver's Mobile Number:								

Labour	Operation	Description	Units	Amount
--------	-----------	-------------	-------	--------

Job# 1	88KWZZZZZMISC1	Miscellaneous	Tech(s): 110 114	5720.00
--------	----------------	---------------	------------------	---------

- Dropped liner

Diagnose engine pushing out coolant. Drain coolant, remove radiator, cylinder head componentry and remove head. Find no. 5 liner dropped. Drain oil, remove sump, pick up pistons and liners and clean counter bores and top deck. Set up counter bore tool and cut all 6 counter bores to 30'. Fit and measure new liners, assemble pistons and fit. Assemble bottom end, clean and refit cylinder head and componentry. Time engine, carry out tune up and refit radiator. Replace horton airline and fill with oil and coolant. Start engine and wash off. Test drive and check over.

Parts	Qty	Number	Description	Unit Price	Amount
Job# 1	6	CU5298565	SHIM	292.67	1756.02
Job# 1	1	CU5693720	KIT, SERVICE LINER	4545.74	4545.74
Job# 1	6	CU2882087	SET, ROD BEARING	217.31	1303.86
Job# 1	2	CU4298242	STUD	60.97	121.94
Job# 1	4	CU4298975	NUT,LOCK	33.35	133.40
Job# 1	3	NG201-4/20RL	Truck Hose #4 3/16	8.85	26.55
Job# 1	2	WS44114S	7 16 JIC FEMALE	19.38	38.76
Job# 1	2	KWK066-177	BUSH-ANTI	42.28	84.56
Job# 1	1	KW90-0013	CLAMP-5' V-BAND	45.37	45.37
Job# 1	1	KW90-0013	CLAMP-5' V-BAND	45.37	45.37
Job# 1	1	KW3316654S	T BAR AIR INLET	8.70	8.70
Job# 1	6	NGLV3263	Dual End Cable Tie	2.00	12.00
Job# 1	1	KWLF14000NN	LUBE FILTER	58.76	58.76
Job# 1	1	CU3391271	LUBRIPLATE 105	18.02	18.02

Petrol, Oils, Lubricants and Supplies			Amount
Job# 1	Premium Blue Extreme		316.25
Job# 1	Cummins Coolant		460.60
Job# 1	Workshop degreaser		7.52

MOLONEY LOGGING PTY. LTD.

DAILY TRUCK CHECKLIST

DRIVER NAME: Stuart
REGO No: 2PD 586

SIGNATURE: [Signature]
DATE: 17.10.22

0730

FUEL lts	PLACE	KMS	HRS	MAINTENANCE RECORD
572.20	Evans BP	318,894	26,083	TRANSALL MOTORS
				* Full liner kit, rings, and bottom end bearings
DOCKET No	Mts/Tons	CONTRACT No / PLACE	DESTINATION	
10098607	41,820.	Cuthbertson RIC	Beralla	318,847 km
497000893	43,300	Chyenne MM	APM	26,082 Hrs

[✓] OK. [X] Fault identified	mon	TRUCK FAULT / DEFECT REPORT ONLY
Brakes, steering, gauges, lights, warning devices	✓	To be used to report any fault / defect identified during daily truck safety check. Work Completed within B.F.M Hrs? YES ☒ NO ☐ Method of Reporting: Telephone ☐ In person ☐ Radio ☐ This Form ☐ Date/...../..... Details of fault / defect: Does fault constitute safety hazard? YES ☐ NO ☐ Does truck require immediate repair? YES ☐ NO ☐ If YES park truck and contact Supervisor. Truck shall not be used until Supervisor gives clearance for use. If NO indicate when truck requires attention. Requires attention next few days? YES ☐ NO ☐ Requires attention at next service? YES ☐ NO ☐ WORK UNDERTAKEN TO CORRECT FAULT / DEFECT Signature: Date:/...../.....
Visibility - windscreen, wipers, washer, demister, mirrors, windows	✓	
Wheels, tyres, nuts, damage, wear, pressure (visual)	✓	
Guards - in place, secure, warning signs - lights, alarms	✓	
Excessive wear - hooks, chains, pins, pivots	✓	
Oil and Coolant levels	✓	
Miscellaneous electrical, fire extinguisher, communications	✓	
Fit for duty YES ☒ NO ☐		
Driver's Signature <u>[Signature]</u>		
Supervisor's Signature - Random Check		

White Copy: Office - Yellow Copy: Stays In Book

TransALL Motors

Address: 31-37 Alexanders Road, Morwell VIC 3840

PO Box 184 Morwell VIC 3840

Phone: (03) 5134 4383

Fax: (03) 5134 2879

Email Address: admin@transallmotors.com.au

Web Address: www.transallmotors.com.au



NAB | BSB: 083 932 | Account No.: 5021 66633

Service TAX Invoice

Page 2 of 2

Reprint# 3

Doc #: CUCS17487

Customer No. 1524	Customer Name & Address Moloney Logging 3 Bowral Way Traralgon VIC 3844			Advisor Taylah Daly	102	Colour Green/	Team Service	
Doc. Date 31/10/22				Year / Make / Model 13/KENWORTH/T909			Tag No.	
Reg. No. ZPO586				Model No.		Carline KENWORTH		Eng./Trans.
Stock No.				Chassis No.		Kilometres 318734	Prod. Date 01/08/13	Orig. Del. Date
Purchase Order No.	Driver		Contract No.	Contract Name	Contract Exp. Kms	Exp. Date		
☐ CASH ☐ CHEQUE ☐ CREDIT CARD ☐ ACCOUNT	Home Phone	Business Phone (0409)749641	Terms 30	Selling Dealer	Delivery Kms.	Delivery Date	Warr. Exp. Date	
	Vehicle ID. 6F5000000DA450347		Engine No. 79665718	Date & Time Promised 06/10/22 05:00pm	Time Received 08:15am	Quote Price	Air N	
							Pwr N	
							Turb N	

Job# 1

Cable ties

17.50

<<< Total For Job 1 >>>

14720.92

Misc: RND

RND - Rounding

-0.01

Total Labour	5720.00
Total Parts	8199.05
Total POL	801.87
Total Sublet	0.00
Total Misc	-0.01

Total Tax 1472.09

Total Invoice 16193.00

TOTAL AMOUNT INCLUDING GST