12/1/25, 10:47 AM HEM Data Dashboard



## 2018 Freightliner 106 Medium Duty

Test Information		
Engine	Cummins B6.7 (6.7)	
Engine Serial	CMMNS*6B u17D0670000000*74187049	
VIN	3ALACXFC4JDJW7741	
Driveline	Class 7 4x2	
Body	Truck MDHD: Conventional	
Test Time	Nov. 26, 2025, 1:06 p.m.	
File Length	126.189 s	

Usage			
Label	Value	Units	
Engine Odometer	235,788	mi	
Odometer (Instrument Cluster #1)	235,788	mi	
Engine Total Hours of Operation	11,569.25	h	
Aftertreatment 1 Diesel Particulate Filter Soot Load Percent	52	%	

**Engine On/Off** 

Engine running

12/1/25, 10:47 AM **HEM Data Dashboard** 

## **Check Engine Light**



MIL - Emissions malfunction



Amber Warning Lamp - Warning, but OK to drive

## **Emissions Deleted/Tampered**

No

12/1/25, 10:47 AM **HEM Data Dashboard** 

**Body Controller** 

**Body Controller** 

**Body Controller** 

**Body Controller** 

**Body Controller** 

**Body Controller** 

**Proprietary** 

Engine #1

 $\mathsf{DM}$ 

Active

Active

Active

Active

Active

Previous

Previous

Previous

Previous

Previous

Previous

Previous

**Emissions Active** 

**Emissions Active** 

**Emissions Active** 

**Emissions Active** 

**Emissions Active** 

Permanent

Permanent

Permanent

Permanent

Permanent

## **Faults Controller Name SPN Name** FMI Name Aftertreatment 1 Outlet NOx 1 Data Drifted High Engine #1 Engine #1 Engine Fuel Injection Quantity Error for Multiple Cylinders Condition Exists Engine #1 Aftertreatment 1 SCR Conversion Efficiency Condition Exists Aftertreatment 1 Diesel Exhaust Fluid Line Heater 1 State Engine #1 Voltage Below Normal Engine #1 Aftertreatment 1 Diesel Exhaust Fluid Line Heater 2 State Voltage Below Normal Previous **Body Controller** Windshield Wiper Motor ON/OFF Not Responding Properly Previous **Body Controller** Turn Signal Switch Data Error Data Error Previous **Body Controller** Unknown Previous **Body Controller** Manufacturer Assignable SPN Not Responding Properly Previous Manufacturer Assignable SPN Not Responding Properly **Body Controller**

Manufacturer Assignable SPN

Manufacturer Assignable SPN

Engine Starter Motor Relay Control

Windshield Wiper Motor Speed

High-Low Beam Switch

Manufacturer Assignable SPN

Source Address 33

Aftertreatment 1 Diesel Exhaust Fluid Line Heater 1 State

Aftertreatment 1 Outlet NOx 1

Engine Fuel Injection Quantity Error for Multiple Cylinders

Aftertreatment 1 Diesel Exhaust Fluid Line Heater 2 State

Aftertreatment 1 SCR Conversion Efficiency

Aftertreatment 1 Diesel Exhaust Fluid Line Heater 2 State

Aftertreatment 1 Outlet NOx 1

Engine Fuel Injection Quantity Error for Multiple Cylinders

Aftertreatment 1 Diesel Exhaust Fluid Line Heater 1 State

Aftertreatment 1 SCR Conversion Efficiency

Count

1

1

1

1

1

2

1

2

2

126

1

1

4 3

1 2

126

1

1

1

1

1

1

1

1

1

1

Data Error

Not Responding Properly

**Current Below Normal** 

**Current Below Normal** 

Data Error

Voltage Below Normal

Data Error

Voltage Below Normal

Data Drifted High

Condition Exists

Voltage Below Normal

Condition Exists

Voltage Below Normal

Data Drifted High

Condition Exists

Voltage Below Normal

Condition Exists