



# Commercial Vehicle Inspection Report

Decal Number: GN51662  
Decal Expiry Date: 2026-Nov-30  
Inspection Number: 21785239

V11-1  
Inspection Result:  
**PASS**

FACILITY: JOHNSON RADIATOR SERVICES LTD. / S20512  
INSPECTOR: GILOWSKI, TRAVIS GORDON / 200472  
WORK ORDER #: 225214  
INSP. TYPE: Complete  
INSP. CLASS: Class 3 - Trailer and Semi-Trailer  
INSP. REASON: Semi-annual  
INSP. START: 2026-May-21 10:30 AM -07  
INSP. COMPLETE: 2026-May-26 07:00 AM -07

VEHICLE JUR: British Columbia  
PLATE #: 68023K  
LICENCED GVW(kg): 999999  
VEHICLE YEAR: 2005  
MAKE: ARNES  
MODEL:  
REGI: 02723206  
UNIT/FLEET#: J9  
BODY STYLE: Bulk Trailer  
ODOMETER:  
HUB ODOMETER:  
BRAKE TYPE: Air  
VIN: 2A91745375A003858  
OWNER/LESSEE NAME: L.L ENTERPRISES, L.L ENTERPRISES  
ADDRESS: PO BOX 1182  
Fort Nelson, British Columbia  
VOC1R0, Canada

2005 Arnes J-9

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Repaired (same day) REPLACED AXLE 2 RIGHT AIR BAG
Section 3 - Brake System	Repaired (same day) REPLACED AXLE 1 RIGHT SLACK
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) REPAIRED CORNER MARKER LIGHTS
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

### Air Brake Chamber Type, Size and Push Rod Stroke (mm)

### Tire Tread Depth (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	30	30	6	6	5	6	
2	Clamp	30	Automatic	30	30	6	6	8	5	
3	Clamp	30	Automatic	30	30	11	12	6	5	

Comment:

Comment:

### Air Brake Camshaft Rotation (degrees)

### Brake Lining/Pad (mm)

### Rotor Thickness or Drum Inside Diameter (mm)

Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	25	85	Lining (Shoe)	19	12	Drum		
2	90	75	Lining (Shoe)	10	12	Drum		
3	65	90	Lining (Shoe)	14	12	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

### Inspection Comments:

Has this Vehicle been road tested? No  
Inspector: GILOWSKI, TRAVIS GORDON

Road Test Date:  
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026-May-26 07:14 AM -07

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

### NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

5/26/2026 7:14:42 AM -07