Job Card

Elecnor Australia

Job Card 20466

elecnor australia

Asset Information

Asset Number & Rego: EANTR061	Down Time: —
Line 1 Line 2 Line 4 Line 5 Subs 1 Subs 2 Subs 3 Camp 3	Repair Time: 1hr
Hours / Kms: —	Travel Time: —
Last Service Kms / Hours: —	Name: Brandon
Next Service Kms / Hours: —	Date: 1.11.25
Job Type: Corrective, Breakdown, General, Inspection, Modifications, Preventative (Service)	Fire Ext Date:

Fault

Annual Onboarding

Repairs Carried Out

Carry out annual onboarding Inspection

Spare Parts / Materials / Consumables Used

Trade Hours

Brandon – 1hr

ANNUAL

Plant Mobilisation – Earthmoving, Load Shifting and General Plant

elecnor australia

To record the review and mobilisation of an earthmoving, load shifting or general mobile plant item at the project.

General Details	
Project Name: PEC	
Plant Supplier / Subcontractor: EA	
Type of Plant: WATER TRAILOR	**Make:** STONESTAR
Plant ID: EAWTR061	**Rego Number:** YN14VY
Attachments To be Used:	

Principal Contractor representative (HS / Supervisory / Plant) to verify mobile plant documentation and insert current details	Verified	Not Verified	N/A
Documentation Sighted / Copied	c = copy recorded		
Operators Manual *(copy within plant or confirmed as readily available)*	☑	☐	
Plant Risk Assessment *(specific to plant item, addresses various attachments that may be used, no open actions, endorsed by operator/s)*	☑c	☐	
Non-Standard Vehicle Road Registration *(plant driven on roads)*	☑c	☐	☐
Date of last vehicle registration: 15.4.25	Date registration renewal due: 15.4.26		
Daily Prestart Checklists *(specific to the plant type, available in plant or via electronic platform)*	☑	☐	☐
Lifting Equipment Register *(equipment tagged and within inspection periods)*	☐c	☐	☑
Maintenance & Service History *(plant is within service interval, previous service details sighted)*	☑c	☐	
Plant hours at last service:	Plant hours at next service due:		
SWMS *(to address safe operations per the above documentation confirmed as readily available)*	☑c	☐	

*Subcontractor plant responsible person or Principal Contractor representative to check plant status. Note that this is **not** intended as a full compliance / fitness for use inspection*	Adequate	Not Adequate	N/A
Inspection Checklist			
Operational alarm / horn functioning and audible	☐	☐	✓
Flashing beacon functioning	☑	☐	
Emergency stop(s) fitted / visible	☑	☐	
Fire extinguisher(s) fitted and within 6-month test date	☑	☐	
Battery isolator fitted that can be positively locked	☑	☐	
Safety guards fitted with no obvious signs of removal, damage, tampering	☑	☐	
Instruments, labels, gauges appear undamaged and legible	☑	☐	
Indicators and decals legible	☑	☐	
No obvious signs of fluid leaks or damaged hoses	☑	☐	
No obvious signs of electrical damage	☑	☐	

Plant Mobilisation – Earthmoving, Load Shifting and General Plant

elecnor australia

Subcontractor plant responsible person or Principal Contractor representative to check plant status
*Note that this is **not** intended as a full compliance / fitness for use inspection*

Inspection Checklist	Adequate	Not Adequate	N/A
Roll Over Protective Structure (ROPS) fitted (including placard with serial number)	☐	☐	☑
Falling Object Protective Structure (FOPS) fitted and certified (for plant activities where falling debris, objects, tree branches, similar are possible)	☐	☐	☑
Fully automatic, double locking hydraulic quick hitch fitted (e.g. excavators, backhoes, integrated tool carriers) – for excavators 3 tonne or less, automatic double locking manual acting type hitches are acceptable	☐	☐	☑
Seat belt fitted, in good condition and within manufacturer replacement period	☐	☐	☑
No obvious signs of major wheel / rim or track damage	☑	☐	☐
Load charts & Safe work load clearly displayed (if plant to be used in a lifting capacity)	☐	☐	☑
Anti-drop valves fitted (if plant to be used in a lifting capacity where SWL is above 3000kg)	☐	☐	☑
Handrails on walkways / upper decks where personnel access is required	☑	☐	☐
Plant appears clean to prevent spread of noxious weeds and plant pathogens	☑	☐	☐
Insert any other item identified:	☐	☐	☑

Plant Modifications		
Have any modifications been made to this item of mobile plant?	☐ Yes	☑ No
If 'Yes', describe modification & confirm verification of engineer / manufacturer endorsement or certification.		

Corrective Actions ***(for any "Not Verified" or "Not Adequate" items above)***

#	Corrective Action	Responsible Person/s	Date Closed
1			
2			
3			

Subcontractor / Operator Involved ***(complete only if an operator was involved in the review)***

Name:	Signature:	Date:

Endorsement ***(Principal Contractor Representative - HS / Supervisory / Plant)***

Name: Brandon Mitchell	Signature:	Date: 1-11-25
Verification Sticker Issued: ☑ Yes ☐ No	**Verification Sticker Number:** C3916	

Note: Verification sticker not to be issued of corrective actions remain open.

Work Order Report

Secure Energy Joint Venture

Work Order No 12943

W/O Group No

Printed ☑

Requester's Information

Name:
Details:
Rego Number:
Request No:
Phone No:
Approved By:

Asset Information

Asset No: EA-WT-EAWTR061 EA - WATER TRAILER - STONESTAR - YN14VY
Criticality: Clough Responsible for Maintenance
Comments:

Contractor:
Contact:
Ph No:
Warranty Start:
Warranty Finish:

Calibrated Tools Used on Systems & Sub-sytems

Sub-System: **Tool ID:** **Tool Description:** **Serial Number:**

Last Reading:
Date:

Work Details

Job Description: Trailer coupling loose
Instructions: Inspect trailer hitch for wear check all bolts and lock tight
Safety Notes:
1. All personnel to secure their DANGER tag to the main isolator or ignition switc
2. Chock wheels front and rear, fit testing tag & carry out data download.
3. Remove testing tag & fit danger tag.
4. Use blocks or stands to support the machine.
5. Relieve all pressure in air, oil, and water systems.
6. Inspect fire extinguisher and bracket.
7. If you have any doubts regarding safety - contact your supervisor immediately.

Priority: Category A - Urgent **Job Type:** BREAK
Status: 0 - Entered
Account Code: 45860 **Reference No:** **Frequency:**
Duration: 0.00 h **Policy No:** **Department:** 45860 - LAY03 - Din

Raised: 28/02/2025 **Due Start:** 28/02/2025 **Start:** 28/02/2025 **Due Finish** 28/02/2025 **Finish:**

Work History Comments

Downtime: hrs **Repair Time** hrs
Done Reading:

Job Card

Elecnor Australia

elecnor australia

Job Card

Asset Information

Asset No / Rego: EAWTR061	Down Time:
Line 1 Line 2 Line 4 Line 5 Subs 1 Subs 2 Subs 3 Camp 3	Repair Time: 1.5 HRS.
Hours / Kms: —	Travel Time:
Last Service Kms / Hours: —	Name: Kris
Next Service Kms / Hours: —	Date: 28/2/25
Job Type: Corrective, Breakdown, General, Inspection, Modifications, Preventative (Service)	Fire Ext Date:

Fault

Trailer Coupling / Connection - Loosing Air

Repairs Carried Out

Inspected trailer losing air from connections. Cleaned all fittings. Reinspected. Still losing air Removed and replaced fitting. Resealed between 4x Joiners. Cleaned up trailer plug as needed. Reinspected. All okay.

Spare Parts / Materials / Consumables Used

1x Female Trailer Connector - Brass
Thread tape.

Trade Hours

Kris 1.5 Hours.

Work Order Report

Secure Energy Joint Venture

Work Order No 13781

W/O Group No

Printed ☑

Requester's Information

Name:
Request No:
Details:
Phone No:
Rego Number:
Approved By:

Asset Information

Asset No: EA-WT-EAWTR061 EA - WATER TRAILER - STONESTAR - YN14VY

Criticality: Clough Responsible for Maintenance

Comments:

Contractor:

Contact:
Ph No:

Warranty Start:
Warranty Finish:

Calibrated Tools Used on Systems & Sub-sytems

Sub-System:	Tool ID:	Tool Description:	Serial Number:

Last Reading:
Date:

Work Details

Job Description: Carry out Service

Instructions:
1. Machine to be CLEANED prior to all services.
2. Serviceperson to ensure all grease points are receiving lubricant and ensure lubrica
3. All S.O.S. sample labels are to be correctly filled out and sent for analysis immediate
4. All faults found are to be recorded in the comments section.
5. Refer to Service Manual for carrying out service tasks.
6. Refer to Service manual for applicable bolt torques.

Safety Notes:
1. **All personnel to secure their DANGER tag to the main isolator or ignition switc**
2. **Chock wheels front and rear, fit testing tag & carry out data download.**
3. **Remove testing tag & fit danger tag.**
4. **Use blocks or stands to support the machine.**
5. **Relieve all pressure in air, oil, and water systems.**
6. **Inspect fire extinguisher and bracket.**
7. **If you have any doubts regarding safety - contact your supervisor immediately.**

Priority: Category B - 3 Days **Job Type:** PM

Status: 0 - Entered

Account Code: 45860 **Reference No:** **Frequency:**

Duration: 2.50 h **Policy No:** **Department:** 45860 - LAY03 - Din

Raised: 11/03/2025 **Due Start:** 11/03/2025 **Start:** 11/03/2025 **Due Finish** 11/03/2025 **Finish:**

Trades Information

Trade Code	Name	Due Start	Est Duration	Date Started	Act Duration	Signature
HDF	Kristien Norman	11/03/2025	0.00	11/03/2025	2.50	

Work History Comments

Downtime: hrs **Repair Time** hrs

Done Reading:

Job Card

Elecnor Australia

Job Card

elecnor australia

Asset Information

Asset No / Rego: ~~EAFR~~ EAWTR061	Down Time:
Line 1 Line 2 Line 4 Line 5 Subs 1 Subs 2 Subs 3 Camp 3	Repair Time: 2.0Hrs
Hours / Kms: – No Hub Meter.	Travel Time: –
Last Service Kms / Hours:	Name: Kris
Next Service Kms / Hours:	Date: 11/3/25
Job Type: Corrective, Breakdown, General, Inspection, Modifications, Preventative (Service)	Fire Ext Date:

Fault

Trailer B Service.

Repairs Carried Out

- Carried out Trailer Service.
  - Greased all points
  - Adjusted all brakes.
  - Inspected under carriage
  - Inspected pump motor
  - Inspected all couplings and hoses.
  - Inspected all signage and stickers etc.

* Rebook (time restraints) Pump Motor for Service.

Spare Parts / Materials / Consumables Used

2x 450g tube GP Grease

Trade Hours

Kris 2.0 Hours.

Job Card

Elecnor Australia

elecnor australia

Job Card

Asset Information

Asset No / Rego: EAWTR061	Down Time: 0
Line 1 Line 2 Line 4 Line 5 Subs 1 Subs 2 Subs 3 Camp 3	Repair Time: 1h
Hours / Kms:	Travel Time: 0
Last Service Kms / Hours:	Name: Pat / Brandon
Next Service Kms / Hours:	Date: 30/3/25
Job Type: Corrective, Breakdown, General, Inspection, Modifications, Preventative (Service)	Fire Ext Date:

Fault

Pump Service.

Repairs Carried Out

Drain oil / blow out air filter.

Fill engine with oil

Grease legs and finger feeder

Check king pin

Spare Parts / Materials / Consumables Used

1.5L 5w 30 engine oil.

Trade Hours

Patrick - 1h

Brandon - 1h.

Job Card

Elecnor Australia

Job Card

Asset Information

Asset No / Rego: EAWT61	Down Time:
Line 1 Line 2 Line 4 Line 5 Subs 1 Subs 2 Subs 3 Camp 3	Repair Time: 2 hr
Hours / Kms:	Travel Time: 9 hr
Last Service Kms / Hours:	Name: Matt
Next Service Kms / Hours:	Date:
Job Type: Corrective, Breakdown, General, Inspection, Modifications, Preventative (Service)	Fire Ext Date:

Fault

Travel to get trailer inspections done

Repairs Carried Out

- Travel ~~to~~ to JLS denniliquin to get trailer inspection don
- Travel Back
- Tighten track rod Bolts
- ~~Tigh~~ tie up abs Wires properly
- Clean out ring feeder on Trailer

Spare Parts / Materials / Consumables Used

x

Trade Hours

5 hr Matt

Work Order Report

Secure Energy Joint Venture

elecnor australia

Work Order No **14645**

W/O Group No

Printed ☑

Requester's Information

Name:
Request No:
Details:
Phone No:
Rego Number:
Approved By:

Asset Information

Asset No: EA-WT-EAWTR061 EA - WATER TRAILER - STONESTAR - YN14VY

Criticality: Clough Responsible for Maintenance

Comments:

Contractor:
Contact:
Ph No:
Warranty Start:
Warranty Finish:

Calibrated Tools Used on Systems & Sub-sytems

Sub-System: **Tool ID:** **Tool Description:** **Serial Number:**

Last Reading:
Date:

Work Details

Job Description: Carry out service on water pump motor

Instructions: Carry out service and check over

Safety Notes:

Priority: Category B - 3 Days **Job Type:** PM

Status: 0 - Entered

Account Code: 45860 **Reference No:** **Frequency:**

Duration: 0.00 h **Policy No:** **Department:** 45860 - LAY03 - Din

Raised: 9/04/2025 **Due Start:** 9/04/2025 **Start:** 9/04/2025 **Due Finish** 9/04/2025 **Finish:**

Work History Comments

Downtime: hrs **Repair Time** hrs

Done Reading:

Job Card

Elecnor Australia

elecnor australia

Job Card

Asset Information

Asset No / Rego: EAW TR061	Down Time:
Line 1 Line 2 Line 4 Line 5 Subs 1 Subs 2 Subs 3 Camp _____	Repair Time: 1
Hours / Kms:	Travel Time: car
Last Service Kms / Hours:	Name: MATT NICK.
Next Service Kms / Hours:	Date: 9/4/25
Job Type: Corrective, Breakdown, General, Inspection, Modifications, Preventative (Service)	Fire Ext Date:

Fault

WATER PUMP SERVICE.

Repairs Carried Out

DRAIN OIL

BLOW OUT FILTERS

FILL OIL.

Spare Parts / Materials / Consumables Used

Trade Hours

1 HOUR MATT

1 HOUR NICK.

Work Order Report

Secure Energy Joint Venture

elecnor australia

Work Order No 19935

W/O Group No

Printed ☑

Requester's Information

Name:
Request No:
Details:
Phone No:
Rego Number:
Approved By:

Asset Information

Asset No: EA-WT-EAWTR061 EA - WATER TRAILER - STONESTAR - YN14VY

Criticality: Clough Responsible for Maintenance

Comments:

Contractor:
Contact:
Ph No:
Warranty Start:
Warranty Finish:

Calibrated Tools Used on Systems & Sub-sytems

Sub-System: **Tool ID:** **Tool Description:** **Serial Number:**

Last Reading:
Date:

Work Details

Job Description: Replace Left Rear Tyres and Install New Studs

Instructions: Replace Left Rear Tyres and Install New Studs

Safety Notes: **"1. All personnel to secure their DANGER tag to the main isolator or ignition swit**
2. Chock wheels front and rear, fit testing tag & carry out data download.
3. Remove testing tag & fit danger tag.
4. Use blocks or stands to support the machine.
5. Relieve all pressure in air, oil, and water systems.
6. Inspect fire extinguisher and bracket.
7. If you have any doubts regarding safety - contact your supervisor immediately.

Priority: Category B - 3 Days **Job Type:** BREAK

Status: 0 - Entered

Account Code: 45860 **Reference No:** **Frequency:**

Duration: 0.00 h **Policy No:** **Department:** 45860 - LAY03 - Din

Raised: 20/10/2025 **Due Start:** **Start:** **Due Finish** 23/10/2025 **Finish:**

Estimated Costs

Labour:	$0.00	**Material:**	$0.00	**Other:**	$0.00
				Total Cost:	

Work History Comments

Downtime: hrs **Repair Time** hrs

Done Reading:

Job Card

Elecnor Australia

elecnor australia

Job Card

Asset Information

Asset Number & Rego: E4WTR061	Down Time: —
Line 1 Line 2 Line 4 Line 5 Subs 1 Subs 2 Subs 3 Camp 3	Repair Time: 2.5hrs
Hours / Kms: —	Travel Time: —
Last Service Kms / Hours: —	Name: Brendan
Next Service Kms / Hours: —	Date: 31-10-25
Job Type: Corrective, Breakdown, General, Inspection, Modifications, Preventative (Service)	Fire Ext Date: —

Fault

3x Tyre repairs & Broken wheel stud.

Repairs Carried Out

Drive into tyre shop to pickup tyres.
replace broken wheel stud.
fit 3x tyres, torque to spec. fit Nut indicators
remove stands & jack down trailer.

Spare Parts / Materials / Consumables Used

Trade Hours

Brendan - 2.5hrs

Work Order Report

S ✓

elecnor australia

Secure Energy Joint Venture

Work Order No **20332**

W/O Group No

Printed ☐

Requester's Information

Name: **Request No:**

Details: **Phone No:**

Rego Number: **Approved By:**

Asset Information

Asset No: EA-WT-EAWTR061 EA - WATER TRAILER - STONESTAR - YN14VY

Criticality: Clough Responsible for Maintenance

Comments:

Contractor:

Contact: **Ph No:**

Warranty Start: **Warranty Finish:**

Calibrated Tools Used on Systems & Sub-sytems

Sub-System: **Tool ID:** **Tool Description:** **Serial Number:**

Last Reading: **Date:**

Work Details

Job Description: Quarterly / 90 Days - Water Trailer - Mechanical Check / Service

Instructions:
1. Machine to be CLEANED prior to all services.
2. Serviceperson to ensure all grease points are receiving lubricant and ensure lubrica
3. All S.O.S. sample labels are to be correctly filled out and sent for analysis immediate
4. All faults found are to be recorded in the comments section.
5. Refer to Service Manual for carrying out service tasks.
6. Refer to Service manual for applicable bolt torques.

Safety Notes:
1. All personnel to secure their DANGER tag to the main isolator or ignition switc
2. Chock wheels front and rear.
3. Lower/position bucket & control to release any hydraulic pressure to ensure it i
4. Use blocks or stands to support the machine.
5. Relieve all pressure in air, oil, and water systems.
6. Inspect fire extinguisher and bracket.
7. If you have any doubts regarding safety - contact your supervisor immediately.

Priority: Servicing **Job Type:** PM

Status: 1 - Scheduled

Account Code: 45860 **Reference No:** **Frequency:** 90 Days

Duration: 3.00 h **Policy No:** 483 **Department:** 45860 - LAY03 - Din

Raised: 31/10/2025 **Due Start:** 7/04/2025 **Start:** **Due Finish** **Finish:**

Estimated Costs

Labour:	$0.00	**Material:**	$0.00	**Other:**	$0.00
				Total Cost:	

Work History Comments

Downtime: hrs **Repair Time** hrs

Done Reading:

Job Card

Elecnor Australia

Job Card

Asset Information

Asset Number & Rego: EAWT2061	Down Time: —
Line 1 Line 2 Line 4 Line 5 Subs 1 Subs 2 Subs 3 Camp 3	Repair Time: 2hrs
Hours / Kms: —	Travel Time: —
Last Service Kms / Hours: —	Name: Brendan
Next Service Kms / Hours: —	Date: 1.11.21
Job Type: Corrective, Breakdown, General, Inspection, Modifications, Preventative (Service)	Fire Ext Date: —

Fault

90 Day Inspection

Repairs Carried Out

Carry out Inspection as per sheet.

Spare Parts / Materials / Consumables Used

Trade Hours

Brendan - 2hrs

Small Engine PM Form

elecnor australia

Asset NO	Model	Date	Hours
EANT2061	STONESTAR	1.11.25	—

ACCIDENT PREVENTION

READ AND UNDERSTAND SAFETY WARNING IN THE OPERATION AND MAINTENACE MANUAL

Have you completed a good to go.	YES/NO	BM
Verification Sticker Number (2024 is Red)	✓	BM

- [x] Cleaned machine prior to commencement of service ?
- [x] Positioned the machine on flat level ground?
- [x] Lowered Implements?
- [x] Made work area safe / delineation?
- [x] Attach out of Service Tags
- [x] Have you locked out machine isolator as per site regulations?
- [x] Approval sticker updated and current?
- [x] Onboarding Documents updated and current? Eg: Signed and uploaded
- [x] Is asset site compliant? Eg: HiVis stripes, Asset number, IVMS, Indicators ect

FITTER: _____

SIGN: _____

DATE: ____ / ____ / _____

SERVICEMAN: Brandon Mieallef

SIGN: _____

DATE: 1 / 11 / 25

SITE: Camp 3

Small Engine PM Form

elecnor australia

Defects / Notes & Comments Register			
Status Legend:	C = Completed	O = Outstanding	PO = Parts Ordered

Defects / Notes / Comments	Status	Initials

Small Engine PM Form

elecnor australia

	DESCRIPTION	Pass	Fail	N/A	Parts Orderd	COMMENT C = Clean R = Replace G = Grease P = Pass F = Fail
Initial Walk Around	Check tension of **battery hold down clamps**	P				
	Check engine bay for **loose / lost fasteners**	P				
	Inspect **engine mounts** for wear	P				
	Inspect **underside of unit** for oil / coolant leaks	P				
	Inspect **air intake hoses** for condition / dust entry	P				
	Inspect **radiator mounts** for wear	P				
	Wash **radiator / cooler core** externally	P				
	Clean engine **crankcase breather**	P				
Notes	Before working on and under the machinery, ensure that:					
	- Appropriate PPE is worn					
	- Out of service / danger tags are fitted					
	- Wheel chocks are in place where applicable					
	- An approved hoist or load-rated stands are being used					
	- Oil spill control measures are in place					
	Change Engine air filter	R				
	Change engine oil	R				
	Change engine oil filter	R				
	Change fuel filter	R				
	Check battery condition	P				
	Check alternator	P				
	Check for any leaks	P				
	Check motorsetup eg: standpipe, pressure washer ect	P				
	Check Belts	—				
	Check fire extinguisher / suppression test date	P				
	Clean and lubricate battery terminals	P				
	Check / tighten battery hold **down** bolts	P				
	Check coolant level	—				
	Inspect exhaust system for damage & leaks	P				
	Inspect fuel tank & lines for damage & leaks	P				
	Inspect breathers	—				

Record

elecnor australia

Asset NO	MODEL	DATE	Kms
FAWT 2061		1.11.25	—

ACCIDENT PREVENTION

READ AND UNDERSTAND SAFETY WARNING IN THE OPERATION AND MAINTENACE MANUAL

Have you completed a good to go.	YES/NO	BM
Verification Sticker Number (2024 is Red)		

- [✓] Cleaned machine prior to commencement of service ?
- [✓] Positioned the machine on flat level ground?
- [X] Lowered Implements?
- [✓] Made work area safe / delineation?
- [✓] Attach out of Service Tags
- [✓] Have you locked out machine isolator as per site regulations?
- [✓] Approval sticker updated and current?
- [✓] Onboarding Documents updated and current? Eg: Signed and uploaded
- [✓] Is asset site compliant? Eg: HiVis stripes, Asset number, IVMS, Indicators ect

FITTER: _____

SIGN: _____

DATE: ____ / ____ / _____

SERVICEMAN: Brendan Mipakat

SIGN: _____

DATE: 1 / 11 / 25

SITE: Camp 3

Record

elecnor australia

efects / Notes & Comments Register

Status Legend:	C = Completed	O = Outstanding	PO = Parts Ordered

Defects / Notes / Comments	Status	Initials

M Record

elecnor australia

	DESCRIPTION	Pass	Fail	N/A	Parts Orderd	COMMENT C = Clean R = Replace G = Grease P = Pass F = Fail
Minimum Requirements	All lights working and free of damage	P				
	Brakes operational air / hydraulic / electric	P				
	No air leaks / lines / boosters / airbags	P				
	Sufficient tyre tread / spare tyre available	P				
	Deck and chassis in good condition	P				
	Access ladders and steps free of damage	P				
	If entering deck sufficient handrails in place	P				
	Legs/Jockey wheel operational and free of damage	P				
	Gates and headboards in good condition	P				
Notes	Before working on and under the trailer, ensure that:					
	- Appropriate PPE is worn					
	- Out of service / danger tags are fitted					
	- Wheel chocks are in place where applicable					
	- An approved hoist or load-rated stands are being used					
	- Oil spill control measures are in place					
Main Frame and Body/Tray	Inspect suspensions systems inc shock absorbers, airbags	P				
	Inspect body / tray mountings for cracks and security	P				
	Inspect guards and mudflaps for serviceability	P				
	Inspect all tyres are correctly inflated	P				
	Inspect spare tyre for security and fitment	P				
	Inspect wheel nuts are fitted and correct tension,	P				
	Inspect toolboxes and gate racks for security	P				
	Inspect tow hitch, pin is serviceable	P				
	Inspect tow hitch safety chains are fitted and serviceable	P				
	Inspect electrical & airline connections	P				
	Wheel chocks fitted and secured	P				
	Check tow ball adjustment & tow ball security	✓				

Job Card

Elecnor Australia

Job Card 21493

elecnor australia

Asset Information

Asset No / Rego: EAWTR061	Down Time:
Line 1 Line 2 Line 4 Line 5 Subs 1 Subs 2 Subs 3 Camp 3	Repair Time: 5 h
Hours / Kms:	Travel Time:
Last Service Kms / Hours:	Name: DOL TJCKVED
Next Service Kms / Hours:	Date: 21-1-26
Job Type: Corrective, Breakdown, General, Inspection, Modifications, Preventative (Service)	Fire Ext Date:

Fault

Rear sprays not operating

Repairs Carried Out

Fitted new battery to engine went to CIA Type service to get battery fitted new batteries to remote still not working. checked if a.c was getting to a.c bank o.k. Coils aren't activating to control spray units make up wiring harness to bypass control unit & got top 3 spray units working Tested o.k

Spare Parts / Materials / Consumables Used

Trade Hours

Don Tjcken 5 h

SERVICE JOB CARD

MAKE	Trailer
TYPE	
YEAR/MODEL	
COLOUR	
REG. NO.	YN 14 VY
ODO.	
FUEL	E ¼ ½ ¾ F
INVOICE NO.	

Job No. _____ Date _____

Name Elecnor

Address _____

_____ Post Code _____

Mobile _____ Phone _____

Email _____

VIN. No. W 582

SERVICES ORDERED

- SCHEDULED SERVICE
- E SAFETY CHECK
- TUNE UP
- WHEEL ALIGNMENT
- WHEEL BALANCE
- AUTO TRANS. SERVICE
- EXHAUST SYSTEMS
- BRAKE SERVICE
- COOLING SYSTEM SERV.

CHARGE ☐

CASH ☐

REPAIR INSTRUCTIONS

LH clearance light between axle, Adjust all brakes ~~make plates~~, Axle 3 LH Both/RH rear track rod bushes Axle 1 RH booster nut loose, Axle 2 RH booster nut loose

SUBLET SERVICES

TYRES, BATTERIES & ACCESSORIES

FUEL OILS GREASES

TOTAL LABOUR	$
TOTAL SUBLET	$
TOTAL TB&A	$
TOTAL OILS, ETC.	$
TOTAL PARTS/MAT	$
SUB TOTAL	$
GST	$
TOTAL AMOUNT DUE	$

I authorise the work described above and agree to pay for labour, spare parts and materials required for that purpose at the repairer's current rates and prices. Liability for the loss of or damage to the vehicle, its accessories or contents while garaged or being driven in connection with the authorised work **shall be limited** to the provisions of the Competition and Consumer Act 2010 (CCA) and/or other applicable legislation.

PLEASE NOTE:

(a) During the process of repair, some or all of your stored data may be lost.
(b) Goods presented for repair may be replaced by refurbished goods of the same type rather than being repaired. Refurbished parts may be used to repair the goods.
(c) There is no warranty on Consumer Supplied parts.
(d) The repairer may receive or provide financial incentives in relation to the supply of any goods or services by the repairer.

I agree to pay to the repairer reasonable storage charges if delivery of the vehicle/goods is/are not taken within two days of notice being given by the repairer to me that the vehicle/goods is/are ready for collection.

Unless drawn specifically to the attention of the repairer, I certify that the vehicle (including its parts and equipment) is registered/licenced for use on a public road or road related area.

Signature of Owner (or agent) _____

Address of person leaving vehicle _____

Work Order Report

S ✓

elecnor australia

Secure Energy Joint Venture

Work Order No **20332**

W/O Group No

Printed ☐

Requester's Information

Name: **Request No:**

Details: **Phone No:**

Rego Number: **Approved By:**

Asset Information

Asset No: EA-WT-EAWTR061 EA - WATER TRAILER - STONESTAR - YN14VY

Criticality: Clough Responsible for Maintenance

Comments:

Contractor:

Contact: **Ph No:**

Warranty Start: **Warranty Finish:**

Calibrated Tools Used on Systems & Sub-sytems

Sub-System: **Tool ID:** **Tool Description:** **Serial Number:**

Last Reading: **Date:**

Work Details

Job Description: Quarterly / 90 Days - Water Trailer - Mechanical Check / Service

Instructions:
1. Machine to be CLEANED prior to all services.
2. Serviceperson to ensure all grease points are receiving lubricant and ensure lubrica
3. All S.O.S. sample labels are to be correctly filled out and sent for analysis immediate
4. All faults found are to be recorded in the comments section.
5. Refer to Service Manual for carrying out service tasks.
6. Refer to Service manual for applicable bolt torques.

Safety Notes:
1. All personnel to secure their DANGER tag to the main isolator or ignition switc
2. Chock wheels front and rear.
3. Lower/position bucket & control to release any hydraulic pressure to ensure it i
4. Use blocks or stands to support the machine.
5. Relieve all pressure in air, oil, and water systems.
6. Inspect fire extinguisher and bracket.
7. If you have any doubts regarding safety - contact your supervisor immediately.

Priority: Servicing **Job Type:** PM

Status: 1 - Scheduled

Account Code: 45860 **Reference No:** **Frequency:** 90 Days

Duration: 3.00 h **Policy No:** 483 **Department:** 45860 - LAY03 - Din

Raised: 31/10/2025 **Due Start:** 7/04/2025 **Start:** **Due Finish** **Finish:**

Estimated Costs

Labour:	$0.00	**Material:**	$0.00	**Other:**	$0.00
				Total Cost:	

Work History Comments

Downtime: hrs **Repair Time** hrs

Done Reading:

Job Card

Elecnor Australia

Job Card

Asset Information

Asset Number & Rego: EAWT2061	Down Time: —
Line 1 Line 2 Line 4 Line 5 Subs 1 Subs 2 Subs 3 Camp 3	Repair Time: 2hrs
Hours / Kms: —	Travel Time: —
Last Service Kms / Hours: —	Name: Brendan
Next Service Kms / Hours: —	Date: 1.11.21
Job Type: Corrective, Breakdown, General, Inspection, Modifications, Preventative (Service)	Fire Ext Date: —

Fault

90 Day Inspection

Repairs Carried Out

Carry out Inspection as per sheet.

Spare Parts / Materials / Consumables Used

Trade Hours

Brendan - 2hrs

Small Engine PM Form

elecnor australia

Asset NO	Model	Date	Hours
EANT2061	STONESTAR	1.11.25	—

ACCIDENT PREVENTION

READ AND UNDERSTAND SAFETY WARNING IN THE OPERATION AND MAINTENACE MANUAL

Have you completed a good to go.	YES/NO	BM
Verification Sticker Number (2024 is Red)	✓	BM

- [x] Cleaned machine prior to commencement of service ?
- [x] Positioned the machine on flat level ground?
- [x] Lowered Implements?
- [x] Made work area safe / delineation?
- [x] Attach out of Service Tags
- [x] Have you locked out machine isolator as per site regulations?
- [x] Approval sticker updated and current?
- [x] Onboarding Documents updated and current? Eg: Signed and uploaded
- [x] Is asset site compliant? Eg: HiVis stripes, Asset number, IVMS, Indicators ect

FITTER: _____

SIGN: _____

DATE: ____ / ____ / _____

SERVICEMAN: Brandon Mieallef

SIGN: _____

DATE: 1 / 11 / 25

SITE: Camp 3

Small Engine PM Form

elecnor australia

Defects / Notes & Comments Register			
Status Legend:	C = Completed	O = Outstanding	PO = Parts Ordered

Defects / Notes / Comments	Status	Initials

Small Engine PM Form

elecnor australia

	DESCRIPTION	Pass	Fail	N/A	Parts Orderd	COMMENT C = Clean R = Replace G = Grease P = Pass F = Fail
Initial Walk Around	Check tension of **battery hold down clamps**	P				
	Check engine bay for **loose / lost fasteners**	P				
	Inspect **engine mounts** for wear	P				
	Inspect **underside of unit** for oil / coolant leaks	P				
	Inspect **air intake hoses** for condition / dust entry	P				
	Inspect **radiator mounts** for wear	P				
	Wash **radiator / cooler core** externally	P				
	Clean engine **crankcase breather**	P				
Notes	Before working on and under the machinery, ensure that:					
	- Appropriate PPE is worn					
	- Out of service / danger tags are fitted					
	- Wheel chocks are in place where applicable					
	- An approved hoist or load-rated stands are being used					
	- Oil spill control measures are in place					
	Change Engine air filter	R				
	Change engine oil	R				
	Change engine oil filter	R				
	Change fuel filter	R				
	Check battery condition	P				
	Check alternator	P				
	Check for any leaks	P				
	Check motorsetup eg: standpipe, pressure washer ect	P				
	Check Belts	—				
	Check fire extinguisher / suppression test date	P				
	Clean and lubricate battery terminals	P				
	Check / tighten battery hold **down** bolts	P				
	Check coolant level	—				
	Inspect exhaust system for damage & leaks	P				
	Inspect fuel tank & lines for damage & leaks	P				
	Inspect breathers	—				

Record

elecnor australia

Asset NO	MODEL	DATE	Kms
FAWT 2061		1.11.25	—

ACCIDENT PREVENTION

READ AND UNDERSTAND SAFETY WARNING IN THE OPERATION AND MAINTENACE MANUAL

Have you completed a good to go.	YES/NO	BM
Verification Sticker Number (2024 is Red)		

- [✓] Cleaned machine prior to commencement of service ?
- [✓] Positioned the machine on flat level ground?
- [X] Lowered Implements?
- [✓] Made work area safe / delineation?
- [✓] Attach out of Service Tags
- [✓] Have you locked out machine isolator as per site regulations?
- [✓] Approval sticker updated and current?
- [✓] Onboarding Documents updated and current? Eg: Signed and uploaded
- [✓] Is asset site compliant? Eg: HiVis stripes, Asset number, IVMS, Indicators ect

FITTER: _____

SIGN: _____

DATE: ____ / ____ / _____

SERVICEMAN: Brendan Mipakat

SIGN: _____

DATE: 1 / 11 / 25

SITE: Camp 3

Record

elecnor australia

efects / Notes & Comments Register

Status Legend:	C = Completed	O = Outstanding	PO = Parts Ordered

Defects / Notes / Comments	Status	Initials

M Record

elecnor australia

	DESCRIPTION	Pass	Fail	N/A	Parts Orderd	COMMENT C = Clean R = Replace G = Grease P = Pass F = Fail
Minimum Requirements	All lights working and free of damage	P				
	Brakes operational air / hydraulic / electric	P				
	No air leaks / lines / boosters / airbags	P				
	Sufficient tyre tread / spare tyre available	P				
	Deck and chassis in good condition	P				
	Access ladders and steps free of damage	P				
	If entering deck sufficient handrails in place	P				
	Legs/Jockey wheel operational and free of damage	P				
	Gates and headboards in good condition	P				
Notes	Before working on and under the trailer, ensure that:					
	- Appropriate PPE is worn					
	- Out of service / danger tags are fitted					
	- Wheel chocks are in place where applicable					
	- An approved hoist or load-rated stands are being used					
	- Oil spill control measures are in place					
Main Frame and Body/Tray	Inspect suspensions systems inc shock absorbers, airbags	P				
	Inspect body / tray mountings for cracks and security	P				
	Inspect guards and mudflaps for serviceability	P				
	Inspect all tyres are correctly inflated	P				
	Inspect spare tyre for security and fitment	P				
	Inspect wheel nuts are fitted and correct tension,	P				
	Inspect toolboxes and gate racks for security	P				
	Inspect tow hitch, pin is serviceable	P				
	Inspect tow hitch safety chains are fitted and serviceable	P				
	Inspect electrical & airline connections	P				
	Wheel chocks fitted and secured	P				
	Check tow ball adjustment & tow ball security	✓				

SERVICE JOB CARD

MAKE	Trailer
TYPE	
YEAR/MODEL	
COLOUR	
REG. NO.	YN 14 VY
ODO.	
FUEL	E ¼ ½ ¾ F
INVOICE NO.	

Job No. _____ Date _____

Name Elecnor

Address _____

_____ Post Code _____

Mobile _____ Phone _____

Email _____

VIN. No. W 582

SERVICES ORDERED

- SCHEDULED SERVICE
- E SAFETY CHECK
- TUNE UP
- WHEEL ALIGNMENT
- WHEEL BALANCE
- AUTO TRANS. SERVICE
- EXHAUST SYSTEMS
- BRAKE SERVICE
- COOLING SYSTEM SERV.

CHARGE ☐

CASH ☐

REPAIR INSTRUCTIONS

LH clearance light between axle, Adjust all brakes ~~make plates~~, Axle 3 LH Both/RH rear track rod bushes Axle 1 RH booster nut loose, Axle 2 RH booster nut loose

SUBLET SERVICES

TYRES, BATTERIES & ACCESSORIES

FUEL OILS GREASES

TOTAL LABOUR	$
TOTAL SUBLET	$
TOTAL TB&A	$
TOTAL OILS, ETC.	$
TOTAL PARTS/MAT	$
SUB TOTAL	$
GST	$
TOTAL AMOUNT DUE	$

I authorise the work described above and agree to pay for labour, spare parts and materials required for that purpose at the repairer's current rates and prices. Liability for the loss of or damage to the vehicle, its accessories or contents while garaged or being driven in connection with the authorised work **shall be limited** to the provisions of the Competition and Consumer Act 2010 (CCA) and/or other applicable legislation.

PLEASE NOTE:

(a) During the process of repair, some or all of your stored data may be lost.
(b) Goods presented for repair may be replaced by refurbished goods of the same type rather than being repaired. Refurbished parts may be used to repair the goods.
(c) There is no warranty on Consumer Supplied parts.
(d) The repairer may receive or provide financial incentives in relation to the supply of any goods or services by the repairer.

I agree to pay to the repairer reasonable storage charges if delivery of the vehicle/goods is/are not taken within two days of notice being given by the repairer to me that the vehicle/goods is/are ready for collection.

Unless drawn specifically to the attention of the repairer, I certify that the vehicle (including its parts and equipment) is registered/licenced for use on a public road or road related area.

Signature of Owner (or agent) _____

Address of person leaving vehicle _____