

Work Order Report



Elecnor Australia

Work Order No

21551

W/O Group No

Printed ☒



Requester's Information

Name: Request No:
Details: Phone No:
Rego Number: Approved By:

Asset Information

Asset No: EA-PM-SEHV070 Green Light - 2023 - Volvo - FM-500 - 6X4 - Prime Mover - XW13GQ

Criticality: Clough Responsible for Maintenance

Comments:

Contractor:

Contact:

Ph No:

Warranty Start: 30/06/2023

Warranty Finish:

Calibrated Tools Used on Systems & Sub-systems

Sub-System: Tool ID: Tool Description: Serial Number:

Last Reading: 136624.30 KM

Date: 29/01/2026

Work Details

Job Description: 130.000 KM -Service - 2023 - Volvo - FM-500 - 6X4 - Prime Mover - XW13GQ

- Instructions:
1. Machine to be CLEANED prior to all services.
 2. Serviceperson to ensure all grease points are receiving lubricant and ensure lubrica
 3. All S.O.S. sample labels are to be correctly filled out and sent for analysis immediate
 4. All faults found are to be recorded in the comments section.
 5. Refer to Service Manual for carrying out service tasks.
 6. Refer to Service manual for applicable bolt torques.

- Safety Notes:
1. All personnel to secure their DANGER tag to the main isolator or ignition switc
 2. Chock wheels front and rear, fit testing tag & carry out data download.
 3. Remove testing tag & fit danger tag.
 4. Use blocks or stands to support the machine.
 5. Relieve all pressure in air, oil, and water systems.
 6. Inspect fire extinguisher and bracket.
 7. If you have any doubts regarding safety - contact your supervisor immediately.

Priority: Category B - 3 Days Job Type: PM

Status: 0 - Entered

Account Code: 45860

Reference No:

Frequency:

Duration: 8.00

h

Policy No:

Department: 45860 - LAY02 - Loc

Raised: 28/01/2026 Due Start: 29/01/2026 Start: 29/01/2026 Due Finish 31/01/2026 Finish: 29/01/2026

Trades Information

Trade Code	Name	Due Start	Est Duration	Date Started	Act Duration	Signature
HDF	Nathaniel Delacruz		0.00		4.00	
TA	Nicholas Webster		0.00		4.00	

Work History Comments

Downtime: hrs Repair Time hrs
Done Reading:

Heavy Vehicle Truck PM Record

Asset No	Model	Date	Kms & Hours
SEHV-070	X6/VO	29-1-26	136740 km / 9502 hrs

ACCIDENT PREVENTION

READ AND UNDERSTAND SAFETY WARNING IN THE OPERATION AND MAINTENANCE MANUAL

Have you completed a good to go.	YES/NO	ND
Verification Sticker Number (2024 is Red)		ND

☒	Cleaned machine prior to commencement of service ?
☒	Positioned the machine on flat level ground?
☒	Lowered Implements?
☒	Made work area safe / delineation?
☒	Attach out of Service Tags
☒	Have you locked out machine isolator as per site regulations?
☒	Approval sticker updated and current?
☒	Onboarding Documents updated and current? Eg: Signed and uploaded
☒	Is asset site compliant? Eg: HiVis stripes, Asset number, IVMS, Indicators ect

FITTER: Nathaniel Dea Cmg

SIGN: [Signature]

DATE: 29 / 1 / 26

SERVICEMAN: Nicholas Webster

SIGN: _____

DATE: 29 / 1 / 26

SITE: _____

Heavy Vehicle Truck PM Record

Defects / Notes & Comments Register

Status Legend:

C = Completed

O = Outstanding

PO = Parts Ordered

Defects / Notes / Comments

Status

Initials

Needs 2 new after tires

O

ND

Needs Wheel Alignment
sagget wheel balance

O

ND

Heavy Vehicle Truck PM Record

100,000

DESCRIPTION		30000k	60000k	90000k	120000k	150000k	COMMENT C = Clean R = Replace G = Grease P = Pass F = Fail
Initial Test Drive and Walk Around	Check operation of seats & seat belts				✓		
	Check operation of dash gauges and warning devices				✓		
	Check operation of wipers, washers, lights & indicators				✓		
	Check operation of air conditioner and heater demister				✓		
	Check operation of clutch, brakes and park brake				✓		
	Check operation of doors, locks, windows, mirrors				✓		
	Check operation of transmission and drivelines				✓		
	Check drivability – wheel alignment and tyre balance				✓		
	Check operation of pedals and gear-shift levers				✓		
	Inspect steering linkages for damage and backlash				✓		
	Inspect snorkel (when fitted) for damage				✓		
	Inspect steps, roo bars, tool boxes, tray back				✓		
Notes	Inspect tyres, pressures, rims, nut indicators, jacks and wheel braces				✓		
	Before working on and under the vehicle, ensure that:						
Engine and Under Bonnet	- Appropriate PPE is worn						
	- Out of service / danger tags are fitted						
	- Wheel chocks are in place where applicable						
	- An approved hoist or load-rated stands are being used						
	- Oil spill control measures are in place						
	Fill windscreen washer bottle						
	Check battery acid level				✓		
	Clean and lubricate battery terminals				✓		
	Check / tighten battery hold down bolts				✓		
	Check fire extinguisher / suppression test date				✓		
	Check / clean engine air pre-cleaner				✓		
	Check air intake hoses				✓		
	Check/ Replace air filter element				✓		
	Check / Replace air conditioner filter element				✓		
	Check coolant level				✓		
	Check for coolant leaks / hose clip tension				✓		
	Inspect water pump for leaks and bearing end play				✓		
	Check radiator hoses for swelling / cracks				✓		
	Check radiator / intercooler core for damage				✓		
	Replace engine oil and tighten sump plug				✓		
Replace engine oil filter				✓			
Check condition / wear of fan, and tensioner bearings				✓			
Inspect / adjust V belts				✓			
Inspect and Clean Timing Belt Cover				✓			
Replace fuel filter/s	C	C	C	C			
Check / clean water sediment trap				✓			
Check power steering fluid condition / level	C	C	C	C			
Check brake / clutch fluid levels				✓			
Check heater / air conditioner hoses				✓			
Check condition of fuel / brake hoses and lines				✓			
Replace Diff Oil				✓			
Every 90,000 Kms							

Date 11/20 - 6 month max

Replace Filter per the OEM Recommendation

Replace Oil per the OEM Recommendation

Replace Oil per the OEM Recommendation

Replace Filter per the OEM Recommendation

Replace Filters per the OEM Recommendation

Replace fluid per the OEM Recommendation

Replace fluid per the OEM Recommendation

Heavy Vehicle Truck PM Record

Power Train	Check / Replace diff oil							Replace oil per the OEM recommendation
	Inspect diff magnetic plug for particles					✓		
	Check diff breathers					✓		
	Check / Replace transmission oil					✓		
	Replace transmission filter (where fitted)					✓		Every 90,000 Kms
	Check / Replace transfer case oil					NA		
	Inspect and Grease drive shaft slip joints					✓		Replace per the OEM Recommendation
	Inspect and Grease drive shaft universal joints					✓		Grease per the OEM Recommendation
Steering, Breaks & Suspension	Check pinion backlash, and seal condition					✓		Grease per the OEM Recommendation
	Check clutch slave cylinder for leaks (Peel back dust cover)					✓		
	Check oil lines to / from Transmission Cooler for damage					NA		
	Check condition of transmission mounts					✓		
	Check transmission and driveline mounting bolts					✓		
	Check tightness of propeller shaft & wheel hub bolts					✓		
	Check condition of Load Sensing Valve when fitted					✓		Physically check shaft & hub bolts
	Check wheel hub free-play					✓		
	Check / repack wheel bearings					✓		
	Inspect front axle CV boots for damage (Hilux, Prado)					✓		Replace grease per the OEM Recommendation
	Inspect Front / Rear brake pads, disks, drums, shoes					NA		
	Check brake lines & brake hose condition					✓		
	Inspect / adjust park brake					✓		
	Check steering components for wear / damage					NA		- Air System
	Check front suspension / shock absorbers for damage					✓		
	Check front end for loose U bolts, broken springs					✓		
	Check / adjust wheel alignment					✓		
	Check rear suspension / shock absorbers for damage					✓		
	Check rear end for loose U bolts, broken coil or leaf springs					✓		
	Grease all grease points					✓		
Grease king pins					✓			
Inspect exhaust system for damage & leaks					✓			
Inspect fuel tank & lines for damage & leaks					✓			
Inspect Tow Bar mountings, bolts, ball, and electrical socket					✓			
Inspect Roo Bar mountings and bolts for damage					✓			
Final Road Test	Clean windscreen, lights and mirrors	C	C	C	C			
	Check operation of instruments, lights and air conditioner					✓		
	Check that registration sticker is current					✓		
	Check operation of road brakes & park brake					✓		
	Check operation of clutch, transmission and drivelines					✓		
	Check steering and road handling					✓		
	Check driveability - wheel alignment and balance					✓		
Complete logbook, windscreen sticker and service history					✓			

Job Card

Elecnor Australia



Job Card

Asset Information

Asset No / Rego: <u>CEN-070</u>							Down Time:	
Line 1	Line 2	Line 4	Line 5	Subs 1	Subs 2	Subs 3	Camp _____	Repair Time: <u>4</u>
Hours / Kms: <u>9502 hrs.</u> / <u>136740 km</u>							Travel Time:	
Last Service Kms / Hours:							Name: <u>Nathan</u>	
Next Service Kms / Hours: <u>150,000 kms</u>							Date: <u>29-1-20</u>	
Job Type: Corrective, Breakdown, General, Inspection, Modifications, Preventative (Service)							Fire Ext Date:	

Fault

130,000 kms Service & Mechanical Inspection

Repairs Carried Out

change Engine oil & Filter
change Air Filter
change Fuel Filter
check & service ~~brake~~ fire Extinguisher
Mechanical inspection

Spare Parts / Materials / Consumables Used

Trade Hours

Nathan Del Cury 4

Job Card

Elecnor Australia

Job Card



Asset Information

Asset No / Rego: SEHV070

Line 1 Line 2 Line 4 Line 5 Subs 1 Subs 2 Subs 3 Camp 2

Down Time: -

Hours / Kms:

Repair Time: 1hr

Last Service Kms / Hours:

Travel Time: -

Next Service Kms / Hours:

Name: Tegan / Greg

Job Type: Corrective, Breakdown, General, Inspection, Modifications, Preventative (Service)

Date: 29-6-25

Fire Ext Date: -

Fault

Flat / low air tyre

Repairs Carried Out

- ~~Re~~ Check tyre pressure of rear outer tyre on drive
- low pressure; pump up tyre.

Spare Parts / Materials / Consumables Used

Trade Hours

Tegan - 1hr

Greg - 1hr

Job Card

Elecnor Australia



Job Card

Asset Information

Asset No / Rego: <u>SEHV070</u>								Down Time:
Line 1	Line 2	Line 4	Line 5	Subs 1	Subs 2	Subs 3	Carp <u>2</u>	Repair Time:
Hours / Kms:								Travel Time:
Last Service Kms / Hours:								Name: <u>Gary / Greg</u>
Next Service Kms / Hours:								Date: <u>23-9-25</u>
Job Type: <u>Corrective</u> Breakdown, General, Inspection, Modifications, Preventative (Service)								Fire Ext Date:

Fault

Repairs Carried Out

Inspect truck for broken seat
 Found seat base came out of rails and bent up
 Straighten seat base
 put back on rails

Spare Parts / Materials / Consumables Used

Trade Hours

Gary 1 hour
 Greg 1 hour

INTEL-
JOB-
SALE-
OB-

Job Card

Elecnor Australia

Job Card

23077

elecnor
australia

Asset		5EH0070		Asset Information					
Line 1	Line 2	Line 4	Line 5	Subs 1	Subs 2	Subs 3	Camp	Down Time:	
Hours / Kms: 147534								Repair Time:	3 HRS
Last Service Kms / Hours: 140,000								Travel Time:	
Next Service Kms / Hours: 160,000								Name:	J. MITCHELL
Job Type: <u>Corrective</u> Breakdown, General, Inspection, Modifications, Preventative (Service)								Date:	8/6/26
								Fire Ext Date:	

Fault

Repairs Carried Out

- 1 DISCONNECT IUMS
- 2 OFF BOARD VEHICLE.

Spare Parts / Materials / Consumables Used

Trade Hours

- 1 2HR
- 2 1HRS

Owned Equipment Condition Report



Plant Details

Asset Type:	TRUCK
Manufacturer:	Volvo
Model:	Fm
Machine Serial Number:	615 3370
Fleet/Asset Number:	SEHU070
Machine Hours/Kms:	147534 km

General Condition

Component	Condition (Good/Fair/Poor)	Comments
Tyres/Tracks (incl. spare)	G	
Bodywork/Panels	G	
Lights/Indicators	G	
Mirrors	G	
Wipers	G	
Windscreen/Windows	G	
Seat & Restraints	G	
Horn	G	
Fire Extinguisher (if fitted)	G	
Battery Condition	G	
Fluid Leaks (oil, coolant, etc.)	G	
Rust/Corrosion	G	
Paint/Signage Condition	G	
Cleanliness (interior/exterior)	F	

Owned Equipment Condition Report

Mechanical & Functional Check

Component	Condition (Good/Fair/Poor)	Comments
Engine Performance	G	
Transmission/Drivetrain	G	
Brakes (Service/Park)	G	
Steering	G	
Hydraulics [Lift/Tilt/Extend]	-	
Boom/Arm Condition	-	
Attachment (Forks/Bucket etc.)	-	
Safety Systems (alarms, locks)	G	
Cooling System (radiator, hoses)	G	
Exhaust System	G	
Fuel System	G	
Air Intake/Filter Condition	G	
Electrical System	G	
Control Levers & Pedals	G	

Fluid Levels & Leaks

Item	OK/Needs Attention	Comments
Engine Oil	OK	
Hydraulic Oil	-	
Coolant	OK	
Transmission Oil	OK	
Brake Fluid	-	
Washer Fluid	OK	
DEF (Diesel Exhaust Fluid)	OK	
Fuel Level on Return	OK	
Visible Leaks (any area)	OK	

Owned Equipment Condition Report

Photos Taken on Return

- ☒ Front View
- ☒ Rear View
- ☒ Left Side View
- ☒ Right-Side View
- ☐ Tyres/ Tracks (All Sides)
- ☒ Hour Meter Reading
- ☒ VIN/Serial Plate
- ☐ Control Panel / Dashboard
- ☐ Overall Condition (Wide Shot)
- ☐ Any Visible Damages
- ☐ Attachments/ Accessories (if fitted)
- ☐ Load Plate/ Compliance Label)

Damage Report/ Notes

Sign-Off

Elecnor Representative

Name: JEFF MITCHELL

Signature: 

Date: 8/6/26

Job Card

Elecnor Australia



Job Card

Asset Information

Asset No / Rego: SEHV070							Down Time:	
Line 1	Line 2	Line 4	Line 5	Subs 1	Subs 2	Subs 3	Camp _____	Repair Time:
Hours / Kms:							Travel Time:	
Last Service Kms / Hours:							Name:	
Next Service Kms / Hours:							Date: 16/4/25	
Job Type: Corrective, Breakdown, General, Inspection, Modifications, Preventative (Service)							Fire Ext Date:	

Fault

* Flat Tyre

Repairs Carried Out

- * Drive To Tower 5 Near wagga Subs
- * Take Tyre To Pats Tyres & wait For New one To Be Fitted.
- * Drive Back out Line & Fit Tyre To Truck.

Spare Parts / Materials / Consumables Used

Trade Hours

- * Jack - 3 Hours
- * Ari - 3 Hours

Work Order Report



Elecnor Australia

Work Order No

21790

W/O Group No

Printed ☒



Requester's Information

Name:

Request No:

Details:

Phone No:

Rego Number:

Approved By:

Asset Information

Asset No: EA-PM-SEHV070

Green Light - 2023 - Volvo - FM-500 - 6X4 - Prime
Mover - XW13GQ

Criticality: Clough Responsible for Maintenance

Comments:

Contractor:

Contact:

Ph No:

Warranty Start: 30/06/2023

Warranty Finish:

Calibrated Tools Used on Systems & Sub-systems

Sub-System: Tool ID: Tool Description: Serial Number:

Last Reading: 139949.00 KM

Date: 13/02/2026

Work Details

Job Description: Trailer lights not working

Instructions: Inspect trailer plug and replace if needed

Safety Notes: 1. All personnel to secure their DANGER tag to the main isolator or ignition switch
2. Chock wheels front and rear, fit testing tag & carry out data download.
3. Remove testing tag & fit danger tag.
4. Use blocks or stands to support the machine.
5. Relieve all pressure in air, oil, and water systems.
6. Inspect fire extinguisher and bracket.
7. If you have any doubts regarding safety - contact your supervisor immediately.

Priority: Category A - Urgent

Job Type: BREAK

Status: 0 - Entered

Account Code: 45860

Reference No:

Frequency:

Duration: 2.00

h

Policy No:

Department: 45860 - LAY02 - Loc

Raised: 10/02/2026 Due Start: 10/02/2026 Start: 10/02/2026 Due Finish 10/02/2026 Finish: 10/02/2026

Trades Information

Trade Code	Name	Due Start	Est Duration	Date Started	Act Duration	Signature
TA	Greg Morgan	10/02/2026	0.00	10/02/2026	1.00	
HDF	Nathaniel Delacruz	10/02/2026	0.00	10/02/2026	1.00	

Work History Comments

Downtime: hrs Repair Time: hrs
Done Reading:

Job Card

Elecnor Australia



Job Card

Asset Information

Asset No / Rego: SEAN-070								Down Time:
Line 1	Line 2	Line 4	Line 5	Subs 1	Subs 2	Subs 3	Camp	Repair Time: 1
Hours / Kms: 9609 HRS. / 139105 Kms								Travel Time:
Last Service Kms / Hours:								Name: Nathaniel
Next Service Kms / Hours:								Date: 10-2-26
Job Type: Corrective, Breakdown, General, Inspection, Modifications, Preventative (Service)								Fire Ext Date:

Fault

Brake light not working
park light not working

Repairs Carried Out

→ **Troubleshoot**
 → **Trailer Broken - replace new plug**
 - **Secure Brake Coil Hese, Trailer wire**
harness & ABR harness

Spare Parts / Materials / Consumables Used

Trade Hours

Nathaniel Dcla Cms - 1

Greg Motapen 1