

Work Order Report



Elecnor Australia

Work Order No

21782

W/O Group No

Printed ☒



Requester's Information

Name:

Request No:

Details:

Phone No:

Rego Number:

Approved By:

Asset Information

Asset No: EA-BUS-SEHV003

Green Light - 2022 - Mitsubishi - Fuso Rosa - 25
Seater Bus - XO02PV

Criticality: Clough Responsible for Maintenance

Comments: FUSO BUS BREAKDOWN/REPAIRS - CALL 1800 033 557 AND LODGE FAULT REQUEST, THEY WILL CALL LOCAL SERVICE PROVIDER AND BOOK THE VEHICLE IN AND PROVIDE AUTHORITY TO DRIVE WITH IF ENGINE LIGHTS ARE ON TO ENSURE NIL IMPACT ON WARRANTY. PROCESS IS RECOMMENDED OVER CALLING DEALERSHIP TO PRIORITISE REPAIRS. MOVED TO BALRANALD - OCT 23

Contractor:

Contact:

Ph No:

Warranty Start: 23/02/2023

Warranty Finish: 23/02/2028

Calibrated Tools Used on Systems & Sub-systems

Sub-System:	Tool ID:	Tool Description:	Serial Number:
-------------	----------	-------------------	----------------

Last Reading: 162361.00 KM

Date: 17/12/2025

Work Details

Job Description: Replace front suspension

Instructions: remove front suspension and fit new one then test

Safety Notes: 1. All personnel to secure their DANGER tag to the main isolator or ignition switch
2. Chock wheels front and rear, fit testing tag & carry out data download.
3. Remove testing tag & fit danger tag.
4. Use blocks or stands to support the machine.
5. Relieve all pressure in air, oil, and water systems.
6. Inspect fire extinguisher and bracket.
7. If you have any doubts regarding safety - contact your supervisor immediately.

Priority: Category B - 3 Days

Job Type: BREAK

Status: 0 - Entered

Account Code: 45860

Reference No:

Frequency:

Duration: 12.00

h

Policy No:

Department: 45860 - LAY02 - Loc

Raised: 11/02/2026

Due Start: 11/02/2026

Start: 11/02/2026

Due Finish: 11/02/2026

Finish: 11/02/2026

Trades Information

Trade Code	Name	Due Start	Est Duration	Date Started	Act Duration	Signature
HDF	Nathaniel Delacruz	11/02/2026	0.00	11/02/2026	6.00	
TA	Nicholas Webster	11/02/2026	0.00	11/02/2026	6.00	

Work History Comments

Downtime: hrs Repair Time: hrs
Done Reading:

Job Card

Elecnor Australia



Job Card

Asset Information

Asset No / Rego: <u>4THV-003</u>							Down Time:	
Line 1	Line 2	Line 4	Line 5	Subs 1	Subs 2	Subs 3	Camp _____	Repair Time: <u>4</u>
Hours / Kms: <u>162 644 Km</u>							Travel Time:	
Last Service Kms / Hours:							Name: <u>Nathaniel</u>	
Next Service Kms / Hours:							Date: <u>11-2-20</u>	
Job Type: Corrective, Breakdown, General, Inspection, Modifications, Preventative (Service)							Fire Ext Date:	

Fault

Front Suspension Repairs LHS & RHS

Repairs Carried Out

Set-up the machine w/ Jack stands
 Remove top Ball joint
 Remove Brake line & ABS sensor
 Remove Tie rod end
 Remove & replace Coil spring & shock absorber
 Metal Ball joint, Tie rod end, ABS sensor
 & Brake line
 - Bleed the Brake
 - Test drive

Spare Parts / Materials / Consumables Used

Trade Hours

Nathaniel Dela Cruz - 4

Nick Webster - 4

Work Order Report



Secure Energy Joint Venture

Work Order No

18943

W/O Group No

Printed ☒



Requester's Information

Name:

Request No:

Details:

Phone No:

Rego Number:

Approved By:

Asset Information

Asset No: EA-BUS-SEHV003

Green Light - 2022 - Mitsubishi - Fuso Rosa - 25
Seater Bus - XO02PV

Criticality: Clough Responsible for Maintenance

Comments: FUSO BUS BREAKDOWN/REPAIRS - CALL 1800 033 557 AND LODGE FAULT REQUEST, THEY WILL CALL LOCAL SERVICE PROVIDER AND BOOK THE VEHICLE IN AND PROVIDE AUTHORITY TO DRIVE WITH IF ENGINE LIGHTS ARE ON TO ENSURE NIL IMPACT ON WARRANTY. PROCESS IS RECOMMENDED OVER CALLING DEALERSHIP TO PRIORITISE REPAIRS. MOVED TO BALRANALD - OCT 23

Contractor:

Contact:

Ph No:

Warranty Start: 23/02/2023

Warranty Finish: 23/02/2028

Calibrated Tools Used on Systems & Sub-systems

Sub-System:

Tool ID: Tool Description:

Serial Number:

Last Reading: 154634.00 KM

Date: 6/09/2025

Work Details

Job Description: Conduct service

- Instructions:
1. Machine to be CLEANED prior to all services.
 2. Serviceperson to ensure all grease points are receiving lubricant and ensure lubrica
 3. All S.O.S. sample labels are to be correctly filled out and sent for analysis immediate
 4. All faults found are to be recorded in the comments section.
 5. Refer to Service Manual for carrying out service tasks.
 6. Refer to Service manual for applicable bolt torques.

- Safety Notes:
1. All personnel to secure their DANGER tag to the main isolator or ignition switc
 2. Chock wheels front and rear, fit testing tag & carry out data download
 3. Remove testing tag and fit danger tag
 4. Use blocks or stands to support the machine
 5. Relieve all pressure in air, oil and water systems
 6. Inspect fire extinguisher and bracket
 7. If you have any doubts regarding safety - contact your supervisor immediately

Priority:

Job Type: PM

Status: 0 - Entered

Account Code: 45860

Reference No:

Frequency:

Duration: 0.00

h

Policy No:

Department: 45860 - LAY04 - Co

Raised: 9/09/2025

Due Start:

Start:

Due Finish

Finish:

Work History Comments

Downtime:

hrs

Repair Time

hrs

Done Reading:

Heavy Vehicle Truck PM Record



Asset No	Model	Date	Kms & Hours
SEAV003	FUSO BUS	7.9.25	154,977

ACCIDENT PREVENTION

READ AND UNDERSTAND SAFETY WARNING IN THE
OPERATION AND MAINTENACE MANUAL

Have you completed a good to go.	YES/NO	INITIALS
Verification Sticker Number (2024 is Red)	YES	INITIALS

- ☒ Cleaned machine prior to commencement of service ?
- ☒ Positioned the machine on flat level ground?
- ☒ Lowered Implements?
- ☒ Made work area safe / delineation?
- ☒ Attach out of Service Tags
- ☒ Have you locked out machine isolator as per site regulations?
- ☒ Approval sticker updated and current?
- ☒ Onboarding Documents updated and current? Eg: Signed and uploaded
- ☒ Is asset site compliant? Eg: HiVis stripes, Asset number, IVMS, Indicators ect

FITTER: DOMINIC FERNANDEZ

SIGN: [Signature]

DATE: 7.9.25

SERVICEMAN: NICHOLAS BOROMEO

SIGN: [Signature]

DATE: 7.9.25

SITE: C4



Status Legend:

C = Completed

O = Outstanding

PO = Parts Ordered

Page 2 of 4

Heavy Vehicle Truck PM Record



DESCRIPTION		30000k	60000k	90000k	120000k	150000k	COMMENT C = Clean R = Replace G = Grease P = Pass F = Fail
Initial Test Drive and Walk Around	Check operation of seats & seat belts					✓	
	Check operation of dash gauges and warning devices					✓	
	Check operation of wipers, washers, lights & indicators					✓	
	Check operation of air conditioner and heater demister					✓	
	Check operation of clutch, brakes and park brake					✓	
	Check operation of doors, locks, windows, mirrors					✓	
	Check operation of transmission and drivelines					✓	
	Check drivability – wheel alignment and tyre balance					✓	
	Check operation of pedals and gear-shift levers					✓	
	Inspect steering linkages for damage and backlash					✓	
	Inspect snorkel (when fitted) for damage					✓	
	Inspect steps, roof bars, tool boxes, tray back					✓	
	Inspect tyres, pressures, rims, nut indicators, jacks and wheel braces						
	Before working on and under the vehicle, ensure that:						
Notes	- Appropriate PPE is worn						
	- Out of service / danger tags are fitted						
	- Wheel chocks are in place where applicable						
	- An approved hoist or load-rated stands are being used						
	- Oil spill control measures are in place						
Engine and Under Bonnet	Fill windscreen washer bottle					✓	
	Check battery acid level					✓	
	Clean and lubricate battery terminals					✓	
	Check / tighten battery hold down bolts					✓	
	Check fire extinguisher / suppression test date					✓	Date 9/25 - 6 month max
	Check / clean engine air pre-cleaner					✓	
	Check air intake hoses					✓	
	Check/ Replace air filter element					✓	Replace Filter per the OEM Recommendation
	Check / Replace air conditioner filter element					✓	
	Check coolant level					✓	Replace Oil per the OEM Recommendation
	Check for coolant leaks / hose clip tension					✓	
	Inspect water pump for leaks and bearing end play					✓	
	Check radiator hoses for swelling / cracks					✓	
	Check radiator / intercooler core for damage					✓	
	Replace engine oil and tighten sump plug					✓	Replace Oil per the OEM Recommendation
	Replace engine oil filter					✓	Replace Filter per the OEM Recommendation
	Check condition / wear of fan, and tensioner bearings					✓	
	Inspect / adjust V belts					✓	
	Inspect and Clean Timing Belt Cover		C	C	C	C	
	Replace fuel filter/s					✓	Replace Filters per the OEM Recommendation
	Check / clean water sediment trap		C	C	C	C	
	Check power steering fluid condition / level					✓	Replace fluid per the OEM Recommendation
	Check brake / clutch fluid levels					✓	Replace fluid per the OEM Recommendation
	Check heater / air conditioner hoses					✓	
	Check condition of fuel / brake hoses and lines					✓	
	Replace Diff Oil					✓	Every 90,000 Kms

Heavy Vehicle Truck PM Record



Power Train	Check / Replace diff oil					/	Replace oil per the OEM recommendation
	Inspect diff magnetic plug for particles					/	
	Check diff breathers					/	
	Check / Replace transmission oil					/	Every 90,000 Kms
	Replace transmission filter (where fitted)					/	
	Check / Replace transfer case oil					/	Replace per the OEM Recommendation
	Inspect and Grease drive shaft slip joints					/	Grease per the OEM Recommendation
	Inspect and Grease drive shaft universal joints					/	Grease per the OEM Recommendation
	Check pinion backlash, and seal condition					/	
	Check clutch slave cylinder for leaks (Peel back dust cover)					/	
	Check oil lines to / from Transmission Cooler for damage					/	
	Check condition of transmission mounts					/	
	Check transmission and driveline mounting bolts					/	
	Check tightness of propeller shaft & wheel hub bolts					/	Physically check shaft & hub bolts
	Steering, Brakes & Suspension	Check condition of Load Sensing Valve when fitted					/
Check wheel hub free-play						/	
Check / repack wheel bearings						/	Replace grease per the OEM Recommendation
Inspect front axle CV boots for damage (Hilux, Prado)						/	
Inspect Front / Rear brake pads, disks, drums, shoes						/	
Check brake lines & brake hose condition						/	
Inspect / adjust park brake						/	
Check steering components for wear / damage						/	
Check front suspension / shock absorbers for damage						/	
Check front end for loose U bolts, broken springs						/	
Check / adjust wheel alignment						/	
Check rear suspension / shock absorbers for damage						/	
Check rear end for loose U bolts, broken coil or leaf springs						/	
Grease all grease points						/	
Final Road Test		Grease king pins					/
	Inspect exhaust system for damage & leaks					/	
	Inspect fuel tank & lines for damage & leaks					/	
	Inspect Tow Bar mountings, bolts, ball, and electrical socket					/	
	Inspect Roo Bar mountings and bolts for damage					/	
	Clean windscreen, lights and mirrors	C	C	C	C		
	Check operation of instruments, lights and air conditioner					/	
	Check that registration sticker is current					/	
	Check operation of road brakes & park brake					/	
	Check operation of clutch, transmission and drivelines					/	
	Check steering and road handling					/	
	Check driveability – wheel alignment and balance					/	
	Complete logbook, windscreen sticker and service history					/	

Job Card

Elecnor Australia



Job Card

Asset Information

Asset No / Rego: SEHV003 SEHV003								Down Time:
Line 1	Line 2	Line 4	Line 5	Subs 1	Subs 2	Subs 3	Camp <u>4</u>	Repair Time: 7 HRS.
Hours / Kms: 154,977								Travel Time:
Last Service Kms / Hours:								Name: Nick B
Next Service Kms / Hours: 170,000								Date: 7.9.25
Job Type: <u>Corrective</u> , Breakdown, General, <u>Inspection</u> , Modifications, Preventative, <u>Service</u>								Fire Ext Date: 9.25

Fault

154.977 Service Inspection

154,977 Inspection

faulty light Bar

Broken Trailer Plug.

Repairs Carried Out

Carry Out 155,000 Service Inspection As per elecnor Compliance Standards.

Carry Out 155,000 Service As per Man Specs
Elecnor Service Sheet Specifications

Diagnose Electrical wiring To FIND Electrical fault in light bar

Check Relays # plugs for Power

Locate New Power Source for Relay.

Rewire Trailer Plug with new Plug.

Spare Parts / Materials / Consumables Used

Trade Hours

DOMINLE = 4 HRS

Nick B

7.0 + 1

Work Order Report



Secure Energy Joint Venture

Work Order No

19272

W/O Group No

Printed ☒



Requester's Information

Name:

Request No:

Details:

Phone No:

Rego Number:

Approved By:

Asset Information

Asset No: EA-BUS-SEHV003

Green Light - 2022 - Mitsubishi - Fuso Rosa - 25
Seater Bus - XO02PV

Criticality: Clough Responsible for Maintenance

Comments: FUSO BUS BREAKDOWN/REPAIRS - CALL 1800 033 557 AND LODGE FAULT REQUEST, THEY WILL CALL LOCAL SERVICE PROVIDER AND BOOK THE VEHICLE IN AND PROVIDE AUTHORITY TO DRIVE WITH IF ENGINE LIGHTS ARE ON TO ENSURE NIL IMPACT ON WARRANTY. PROCESS IS RECOMMENDED OVER CALLING DEALERSHIP TO PRIORITISE REPAIRS. MOVED TO BALRANALD - OCT 23

Contractor:

Contact:

Ph No:

Warranty Start: 23/02/2023

Warranty Finish: 23/02/2028

Calibrated Tools Used on Systems & Sub-systems

Sub-System:	Tool ID:	Tool Description:	Serial Number:
-------------	----------	-------------------	----------------

Last Reading: 154977.00 KM

Date: 7/09/2025

Work Details

Job Description: Fit towbar tongue and towball

Instructions:

Safety Notes:

Priority:

Job Type: CORRECT

Status: 0 - Entered

Account Code: 45860

Reference No:

Frequency:

Duration: 0.00 h

Policy No:

Department: 45860 - LAY04 - Co

Raised: 23/09/2025

Due Start:

Start:

Due Finish

Finish:

Work History Comments

Downtime:	hrs	Repair Time	hrs
Done Reading:			

Job Card

Elecnor Australia



Job Card

19272

Asset Information

Asset No / Rego: <u>SEH003</u>								Down Time: <u>/</u>
Line 1	Line 2	Line 4	Line 5	Subs 1	Subs 2	Subs 3	Camp <u>4</u>	Repair Time: <u>/</u>
Hours / Kms:								Travel Time: <u>-</u>
Last Service Kms / Hours:								Name: <u>AB</u>
Next Service Kms / Hours:								Date: <u>18/9/25</u>
Job Type: <u>Corrective</u> , Breakdown, General, Inspection, Modifications, Preventative (Service)								Fire Ext Date:

Fault

RT Twister Tongue & Towball

Repairs Carried Out

Part Twister Tongue
RT to bus of Tongue bolts & road with part pe

Spare Parts / Materials / Consumables Used

Twister Tongue & Towball 50mm

Trade Hours

18/9/25
AB
1h
Don
0.5hrs.