[redacted]

BRITISH COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GM09822
Decal Expiry Date: 2026-Dec-31
Inspection Number: 21828156

Inspection Result: **PASS**

FACILITY:	Inland Truck & Equipment Ltd / S20218	INSP. TYPE:	Complete	INSP. START:	2026-Jun-27 11:36 AM PDT
INSPECTOR:	PRICE, JUSTIN THOMAS / 300654	INSP. CLASS:	Class 3 - Trailer and Semi-Trailer	INSP. COMPLETE:	2026-Jun-27 01:37 PM PDT
WORK ORDER #:	474	INSP. REASON:	Semi-annual		

V12-1

VEHICLE JUR:	British Columbia	REGI:	03908366	VIN:	2S9SB51417T008443
PLATE #:	44748L	UNIT/FLEET#:		OWNER/LESSEE NAME:	ROUGHRIDER TRANSPORT LTD. ROUGHRIDER
LICENCED GVW(kg):	999999	BODY STYLE:	LOGGING TRAILER	ADDRESS:	2142 BARTKOW CLOSE RD
VEHICLE YEAR:	2007	ODOMETER:			Quesnel, British Columbia
MAKE:	SUPERIOR	HUB ODOMETER:			v2j7b3, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Repaired (same day)	Installed plugs in brake pot
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Not Applicable	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	34.9	34.9
2	Clamp	30	Automatic	41.3	41.3
3	Clamp	30	Automatic	38.1	38.1

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
9	9	9	9	
7	7	7	7	
7	7	7	7	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	75	60
2	70	68
3	40	45

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	14.3	14.3
Lining (Shoe)	15.9	14.3
Lining (Shoe)	15.9	15.9

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Road Tester:

Inspector: PRICE, JUSTIN THOMAS

Signature:

[redacted]