V14-2

Commercial Vehicle Inspection Report

Decal Number: GN00609
Decal Expiry Date: 2026-Nov-30
Inspection Number: 21758149 2026282

Inspection Result: **PASS**

FACILITY:	FREEWAY HEAVY DUTY SER / S3097	**INSP. TYPE:**	Complete	**INSP. START:**	2026-May-02 11:00 AM PDT
		INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	**INSP. COMPLETE:**	2026-May-02 01:00 PM PDT
INSPECTOR:	TOOR, SURJIT SINGH / 108650				
WORK ORDER #:	103509	**INSP. REASON:**	Semi-annual		

VEHICLE JUR:	British Columbia	**REGI:**	12638611	**VIN:**	5KKHALD1XKPKA9254
PLATE #:	ML0456	**UNIT/FLEET#:**	1218	**OWNER/LESSEE NAME:**	CHEAM TRANSPORT (1992) INC., CHEAM TRANSPORT (1992) INC.
LICENCED GVW(kg):	60100	**BODY STYLE:**	Dump Truck	**ADDRESS:**	PO BOX 518 STN A, PO BOX 518 STN A
VEHICLE YEAR:	2019	**ODOMETER:**	84525 Miles		Abbotsford, British Columbia
MAKE:	WESTERN ST	**HUB ODOMETER:**			V2S 5Z5, Canada
MODEL:		**BRAKE TYPE:**	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	**Repaired (same day)**	- REPLACE L/S AND R/S REAR AXLE AIR-SPRINGS
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	**Repaired (same day)**	- REPLACE BRAKES AT L/S AND R/S 1ST AXLE
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	**Repaired (same day)**	- REPLACE L/S HIGH BEAM HEADLIGHT BULB - REPLACE 5TH CAB ROOF MARKER LIGHT BULB - REPLACE REAR LICENSE PLATE LIGHT
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24	Automatic	35	35
2	Clamp	30L	Automatic	38	38
3	Clamp	30L	Automatic	38	38

Comment: - NEW DRUMS AT L/S AND R/S 1ST AXLE

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
11.1			11.1	✔
6.4	7.9	7.9	4.8	
7.9	6.4	6.4	7.1	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	25	25
2	40	60
3	75	80

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	21	21
Lining (Shoe)	16	14
Lining (Shoe)	13	13

Comment: - NEW BRAKES AT L/S AND R/S 1ST AXLE

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:** **Road Tester:**

Inspector: TOOR, SURJIT SINGH **Signature:**

This Inspection Report was submitted to CVSE on 2026-May-02 04:28 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

5/2/2026 4:28:43 PM PDT