

Int Water TruckKM: 703.139DATE: April 4/14WHO SERVICED: GW.

- ✓ CHANGE ENGINE OIL 36 L Crescent OIL PLUG WRENCH
- ✓ REPLACE ENGINE OIL FILTER PART # & BRAND Fleetguard LF3620 (2) of them
- ✓ REPLACE AIR CLEANER BLEW OUT AIR CLEANER PART # & BRAND
- ✗ REPLACE FUEL FILTER PART # & BRAND No fuel filter.
- ✓ CHECK BRAKE FLUID
- ✓ CHECK FAN BELT/ALTERNATOR BELT
- ✓ CHECK COOLANT FREEZE POINT AND LEVEL added couple liter
- ✓ WINDSHIELD WIPER BLADES
- washer pump needed. WINDSHIELD WIPER SPRAY PUMP
- ✓ WINDSHIELD WASHER FLUID LEVEL
- ✓ LIGHTS-HI/LO BEAM, MARKER, TAIL, HAZARDS, & INTERIOR LIGHTS + TRAILOR LIGHTS
- ✓ GREASE DRIVELINE (DRIVESHAFTS, STEERING & FRONT AXLE)
- ✓ CHECK U-JOINTS
- good ✓ CHECK FRONT DIFFERENTIAL OIL
- ✓ CHECK REAR DIFFERENTIAL OIL
- ✗ CHECK TRANSFER CASE
- ✗ CHECK TRANSMISSION OIL
- ✓ CHECK BATTERY TERMINALS
- CHECK BLOCK HEATER OPERATION
- ✓ CHECK TIRES TRUCK 100PSI / TRAILER 90PSI
- ✓ CHECK EXHAUST-BROKEN HANGERS MISC
- ✓ CHECK ANY ENGINE FLUID LEAKS
- CLEAN INTERIOR
- WASH EXTERIOR
- ~~CLEAN OUT BOX~~

○ Water pump oil change 1/2 litre 10w30
 ○ Chem pump oil change 1030
 ○ Water pump new spark plug
 ○ Chem pump new spark plug
 ○ Clean air filters in both pumps.

REMARKS: OTom fixing A/C clutch.✓ GREASE SPRAYER TRAILOR BRAKES

Int Water Truck

KM: 710,253kms

Run before - 703,139

DATE: Dec 14

Net - 7,114.

WHO SERVICED: Jh

- ✓ CHANGE ENGINE OIL 36L *Crescent Wrench* OIL PLUG WRENCH
- ✓ REPLACE ENGINE OIL FILTER PART # & BRAND *Fleetguard* LF 3620 ②
- ✓ REPLACE AIR CLEANER/BLEW OUT AIR CLEANER PART # & BRAND *Donaldson* 3560734C1
- ✗ REPLACE FUEL FILTER PART # & BRAND *Camco*
- ✓ CHECK BRAKE FLUID
- ✓ CHECK FAN BELT/ALTERNATOR BELT
- added 4L ✓ CHECK COOLANT FREEZE POINT AND LEVEL
- ✓ WINDSHIELD WIPER BLADES
- ✓ WINDSHIELD WIPER SPRAY PUMP
- ✓ WINDSHIELD WASHER FLUID LEVEL
- ✓ LIGHTS-HI/LO BEAM, MARKER, TAIL, HAZARDS, & INTERIOR LIGHTS
- ✓ GREASE DRIVELINE (DRIVESHAFTS, STEERING & FRONT AXLE)
- ✓ CHECK U-JOINTS
- ~~CHECK FRONT DIFFERENTIAL OIL~~
- ✓ CHECK REAR DIFFERENTIAL OIL
- ~~CHECK TRANSFER CASE~~
- CHECK TRANSMISSION OIL
- ✓ CHECK BATTERY TERMINALS
- ✓ CHECK BLOCK HEATER OPERATION
- ✓ CHECK TIRES * *Gettin worn. 1 more season, thinkin.*
- ✓ CHECK EXHAUST-BROKEN HANGERS MISC
- ✓ CHECK ANY ENGINE FLUID LEAKS
- CLEAN INTERIOR
- ✓ WASH EXTERIOR
- ~~CLEAN OUT BOX~~
-
-
-
-
-

REMARKS: * power steering sweating at pump
*

Int Diesel Water Truck

KM: 714,521 - 710,253 = 4268 kms.

DATE: Jan 11/16

WHO SERVICED: AM

- ☒ CHANGE ENGINE OIL 36L Cresat OIL PLUG WRENCH 0d/15
- ☒ REPLACE ENGINE OIL FILTER PART # & BRAND LF3620 x2
- ☒ REPLACE AIR CLEANER BLEW OUT AIR CLEANER PART # & BRAND Donaldson- 3560734C
- ☒ REPLACE FUEL FILTER PART # & BRAND _____
- ☒ CHECK BRAKE FLUID
- ☒ CHECK FAN BELT/ALTERNATOR BELT
- ☒ CHECK COOLANT FREEZE POINT AND LEVEL
- ☒ WINDSHIELD WIPER BLADES
- ☒ WINDSHIELD WIPER SPRAY PUMP
- ☒ WINDSHIELD WASHER FLUID LEVEL
- ☒ LIGHTS-HI/LO BEAM, MARKER, TAIL, HAZARDS, & INTERIOR LIGHTS
- ☒ GREASE DRIVELINE (DRIVESHAFTS, STEERING & FRONT AXLE)
- ☒ CHECK U-JOINTS
- ☒ CHECK FRONT DIFFERENTIAL OIL
- ☒ CHECK REAR DIFFERENTIAL OIL
- ☒ CHECK TRANSFER CASE
- ☒ CHECK TRANSMISSION OIL
- ☒ CHECK BATTERY TERMINALS
- ☒ CHECK BLOCK HEATER OPERATION
- ☒ CHECK TIRES
- ☒ CHECK EXHAUST-BROKEN HANGERS MISC
- ☒ CHECK ANY ENGINE FLUID LEAKS
- ☒ CLEAN INTERIOR
- ☒ WASH EXTERIOR
- ☐ CLEAN OUT BOX
- ☐
- ☐
- ☐
- ☐
- ☐
- ☐

REMARKS:



Scanned with CamScanner

Diesel Water Truck.

KM: 718,989 was 714,521 Total 4,468 Km

DATE: Feb 17

WHO SERVICED: AW

- ☒ CHANGE ENGINE OIL 36L Crescent OIL PLUG WRENCH
- ☒ REPLACE ENGINE OIL FILTER PART # & BRAND LF 3620 X2
- ☒ REPLACE AIR CLEANER/BLW OUT AIR CLEANER PART # & BRAND Danaldson 3560734C1
- ☒ REPLACE FUEL FILTER PART # & BRAND
- ☒ CHECK BRAKE FLUID
- ☒ CHECK FAN BELT/ALTERNATOR BELT
- ☒ CHECK COOLANT FREEZE POINT AND LEVEL
- ☒ WINDSHIELD WIPER BLADES
- ☒ WINDSHIELD WIPER SPRAY PUMP
- ☒ WINDSHIELD WASHER FLUID LEVEL
- ☒ LIGHTS-HI/LO, BEAM, MARKER, TAIL, HAZARDS, & INTERIOR LIGHTS
- ☒ GREASE DRIVELINE (DRIVESHAFTS, STEERING & FRONT AXLE)
- ☒ CHECK U-JOINTS
- ☒ ~~CHECK FRONT DIFFERENTIAL OIL~~
- ☒ CHECK REAR DIFFERENTIAL OIL good
- ☒ ~~CHECK TRANSFER CASE~~
- ☒ CHECK TRANSMISSION OIL
- ☒ CHECK BATTERY TERMINALS Took 1/2 litre / battery
- ☒ CHECK BLOCK HEATER OPERATION
- ☒ CHECK TIRES
- ☒ CHECK EXHAUST-BROKEN HANGERS MISC.
- ☒ CHECK ANY ENGINE FLUID LEAKS
- ☒ CLEAN INTERIOR
- ☒ WASH EXTERIOR
- ☒ CLEAN OUT BOX 's

REMARKS:

rechanged oil in water pump & chem pump.
added light bar to front end. :)
power steering leaking. New cap on it.



Scanned with CamScanner

Diesel Water Truck.

KM: 723,365 km was 718,989 Total - 4,376 km.

DATE: March 18

WHO SERVICED: SW

First filter

- ☒ CHANGE ENGINE OIL 36 L OIL PLUG WRENCH Crescent
- ☒ REPLACE ENGINE OIL FILTER PART # & BRAND LE 3600 K 2
- ☒ REPLACE AIR CLEANER/BLOW OUT AIR CLEANER PART # & BRAND _____
- ☒ REPLACE FUEL FILTER PART # & BRAND good.
- ☐ CHECK BRAKE FLUID
- ☒ CHECK FAN BELT/ALTERNATOR BELT
- ☒ CHECK COOLANT FREEZE POINT AND LEVEL added 4L.
- ☒ WINDSHIELD WIPER BLADES
- ☒ WINDSHIELD WIPER SPRAY PUMP
- ☒ WINDSHIELD WASHER FLUID LEVEL
- ☒ LIGHTS-HI/LO BEAM, MARKER, TAIL, HAZARDS, & INTERIOR LIGHTS
- ☒ GREASE DRIVELINE (DRIVESHAFTS, STEERING & FRONT AXLE)
- ☒ CHECK U-JOINTS
- ☐ CHECK FRONT DIFFERENTIAL OIL
- ☐ CHECK REAR DIFFERENTIAL OIL
- ☐ CHECK TRANSFER CASE
- ☐ CHECK TRANSMISSION OIL
- ☒ CHECK BATTERY TERMINALS
- ☒ CHECK BLOCK HEATER OPERATION
- ☒ CHECK TIRES
- ☒ CHECK EXHAUST-BROKEN HANGERS MISC
- ☒ CHECK ANY ENGINE FLUID LEAKS
- ☒ CLEAN INTERIOR
- ☐ WASH EXTERIOR
- ☐ CLEAN OUT BOX
- ☐
- ☐
- ☐
- ☐
- ☐

REMARKS:

Oil Changed before parked for winter! *

☒ New 2" chem pump. (old one went to tanker)

☒ New dump valve by back end under frame



VEHICLE Diesel Water Truck

KM 726,606 was 723,365 total 3,241 km's.

DATE Jan 19

TECHNICIAN SM

- ☒ CHANGE ENGINE OIL OIL TYPE 15W40 36L PLUG WRENCH Crescent
- ☒ CHANGE ENGINE OIL FILTER PART # & BRAND LF 3620 X (2)
- ☒ CHANGE AIR CLEANER OR BLEW OUT PART # & BRAND 11
- ☒ REPLACE FUEL FILTER PART # & BRAND Glass. still good
- ☐ CHECK BRAKE FLUID
- ☒ CHECK FAN BELT/ALTERNATOR/AC BELTS
- ☒ CHECK COOLANT FREEZE POINT AND LEVEL added 4L.
- ☒ CHECK WINDSHIELD WASHER BLADES
- ☒ CHECK WINDSHIELD WASHER SPRAY PUMP
- ☒ CHECK WINDSHIELD WASHER FLUID LEVEL
- ☒ CHECK LIGHTS-HI/LO BEAM, MARKER, TAIL, HAZZARD, AND INTERIOR LIGHTS
- ☒ GREASE DRIVELINE (DRIVESHAFTS, STEERING AND FRONT AXLE)
- ☒ CHECK U JOINTS
- ☒ CHECK FRONT DIFFERENTIAL OIL
- ☒ CHECK REAR DIFFERENTIAL OIL
- ☒ CHECK TRANSFER CASE OIL
- ☐ CHECK TRANSMISSION OIL
- ☒ CLEAN BATTERY TERMINALS
- ☒ CHECK BATTERY WATER LEVEL good. added wee bit.
- ☒ CHECK BLOCK HEATER OPERATION
- ☐ CHECK TIRE PRESSURE
- ☒ CHECK EXHAUST- BROKEN HANGERS, ECT
- ☒ CHECK ANY ENGINE FLUID LEAKS
- ☐ CLEAN INTERIOR
- ☐ WASH EXTERIOR
- ☒ CLEAN OUT BOX'S

REMARKS/COMMENTS:

changed oil, plugs, blew out air filter's on small n
New LED lights for flood lights

VEHICLE Diesel Water Truck

MILEAGE 728,741 Km's - last - 726,606 Km's Total 2,135 Km's

DATE Dec/19

TECHNICIAN [Signature]

- ☒ CHANGE ENGINE OIL OIL TYPE 15W40 36L PLUG WRENCH Crescent
- ☒ CHANGE ENGINE OIL FILTER PART # & BRAND LF 3620 X (2)
- ☒ CHANGE AIR CLEANER OR BLEW OUT PART # & BRAND _____
- ☒ REPLACE FUEL FILTER PART # & BRAND Glass
- ☒ ~~CHECK BRAKE FLUID~~
- ☒ CHECK FAN BELT/ALTERNATOR/AC BELTS
- ☒ CHECK COOLANT FREEZE POINT AND LEVEL
- ☒ CHECK WINDSHIELD WASHER BLADES
- ☒ CHECK WINDSHIELD WASHER SPRAY PUMP
- ☒ CHECK WINDSHIELD WASHER FLUID LEVEL
- ☒ CHECK LIGHTS-HI/LO BEAM, MARKER, TAIL, HAZZARD, AND INTERIOR LIGHTS
- ☒ GREASE DRIVELINE (DRIVESHAFTS, STEERING AND FRONT AXLE)
- ☒ CHECK U JOINTS
- ☒ CHECK FRONT DIFFERENTIAL OIL
- ☒ CHECK REAR DIFFERENTIAL OIL
- ☒ ~~CHECK TRANSFER CASE OIL~~
- ☒ CHECK TRANSMISSION OIL
- ☒ CLEAN BATTERY TERMINALS
- ☒ CHECK BATTERY WATER LEVEL
- ☒ CHECK BLOCK HEATER OPERATION
- ☒ CHECK TIRE PRESSURE do when pull out spring
- ☒ CHECK EXHAUST- BROKEN HANGERS, ECT
- ☒ CHECK ANY ENGINE FLUID LEAKS
- ☒ CLEAN INTERIOR
- ☒ WASH EXTERIOR
- ☒ CLEAN OUT BOX'S

REMARKS/COMMENTS:

Service water & chem pumps.
check o-ring in 5" fill line
* Taking air filter out when parked *



Scanned with CamScanner

* started perfect after only 2 hrs plugged in *

VEHICLE Diesel Water Truck

731,592 was 728,741 = Total = 2,851 km

DATE Nov 120

TECHNICIAN FW/Cal

✓ CHANGE ENGINE OIL OIL TYPE 15W40 36L PLUG WRENCH Crescent (1 1/4)

✓ CHANGE ENGINE OIL FILTER PART # & BRAND LF 3620 x 2

* CHANGE AIR CLEANER OR BLEW OUT PART # & BRAND _____

✓ REPLACE FUEL FILTER PART # & BRAND Glass

✓ CHECK BRAKE FLUID

✓ CHECK FAN BELT/ALTERNATOR/AC BELTS

✓ CHECK COOLANT FREEZE POINT AND LEVEL

✓ CHECK WINDSHIELD WASHER BLADES

✓ CHECK WINDSHIELD WASHER SPRAY PUMP

✓ CHECK WINDSHIELD WASHER FLUID LEVEL

✓ CHECK LIGHTS-HI/LO BEAM, MARKER, TAIL, HAZZARD, AND INTERIOR LIGHTS

✓ GREASE DRIVELINE (DRIVESHAFTS, STEERING AND FRONT AXLE)

✓ CHECK U JOINTS

✓ CHECK FRONT DIFFERENTIAL OIL good

✓ CHECK REAR DIFFERENTIAL OIL good

✓ CHECK TRANSFER CASE OIL

✓ CHECK TRANSMISSION OIL

✓ CLEAN BATTERY TERMINALS

✓ CHECK BATTERY WATER LEVEL good

✓ CHECK BLOCK HEATER OPERATION

○ CHECK TIRE PRESSURE spring time

✓ CHECK EXHAUST- BROKEN HANGERS, ECT New passenger muffler. Fast Garve

✓ CHECK ANY ENGINE FLUID LEAKS

✓ CLEAN INTERIOR

○ WASH EXTERIOR

✓ CLEAN OUT BOX 1/2

REMARKS/COMMENTS:

* New Muffler on passenger side

* Used rear tires from Int Semi.

* Changed oil, blew out air filters, fuel & water pumps #



Scanned with CamScanner



Vehicle Standards and Inspection

Heavy Truck Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # M854283

Station #: 70472

Technician #: 81501

Signing Officer #: 84056

Station Name: R & H Truck Centre Ltd

Technician Name: Harley Camself

Signing Officer Name: Jerome Richard

Customer Details:

Name: Scharf Farms Partnership

Address: Box 305, Perdue, Saskatchewan, S0K 3C0

Inspection Completed Date: 31Oct2022

Inspection Expiry Date: 30Apr2023

Vehicle Details:

VIN: 2HTCHAMT9YC078509

Year: 2000

Plate: 789GWL

Unit:

Odometer Reading: 733381 km

Vehicle Make/Model: INTERNATIONAL/HEAVY VEHICLE

Jurisdiction: Saskatchewan

Message(s): VIN has been validated.

- TRUCK NOT USED SINCE SAFETY