04104841

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Out
Winnipeg, MB, R2C 5C7
1-204-985-0920

DECAL
Manitoba
C048536

Date Inspection Started: DAY 11 MO. 05 YR. 26

Date Inspection Completed: DAY 02 MO. 06 YR. 26

Inspection Expiry Date: DAY 30 MO. 06 YR. 27

Station Number: A2019 Station Name: R Lewandoski Farms City: Swan River

Mechanic Number: M9415 Mechanic Signature: [signature] Station Phone Number: 204-585-2120

Vehicle Owner: Balan Gravelling Inc.

Address: City: Province: Postal Code: Phone:

☒ Pass/Safe Vehicle
☒ Fail/Unsafe Vehicle
☐ Fail/Hazardous

Licence Number: CHX745 Prov.: MB NSC #: MB305615 Odometer Reading: 1533123 Odom. Type: ☒ km ☐ mi

Vehicle Identification Number: 1XP7DB9X66D877042 Make: Peterbilt Model: 387 Year: 06 Unit #:

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

____Truck GVWR ____ KGS X Truck Tractor ____Trailer ____Semi-Trailer ____Bus ____School Bus ____Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		**Section 1 - Power Train:** Defects (if any)
X		**Section 2 Suspension:** Defects (if any)
X	X	**Section 3 - Brake Systems:** 3H (3A) Defects (if any) Circle Brake Type: 3A(15-B) axle 2R+3L linings worn 3A(15-D) axle 2R+3L brake drums worn.
X		**Section 4 - Steering:** Defects (if any)
X		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X		**Section 6 - Lamps:** Defects (if any)
X		**Section 7 - Electrical System:** Defects (if any)
X	X	**Section 8 - Body:** Defects (if any)
X		**Section 9 - Tire & Wheel:** Defects (if any)
X		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: (A) B C D E — Circle appropriate Letter for Internal Brake Component Inspection

	mm Lining		Drum/Rotor		Stroke	
Axle	L	R	L	R	L	R
1	17	17	16.548	16.552	1.5	1.5
2	15	new	16.556	new	1.5	1.5
3	new	15	new	15.543	1.5	1.5
4						
5						
	Final Measurement					

	mm Tread Depth								Air Pressure							
	Initial				Corrected				Initial				Corrected			
Axle	L		R		L		R		L		R		L		R	
1		14	14							100	100					
2	15	19	19	19					100	100	100	100				
3	15	17	18	18					100	100	100	100				
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature

FVS0022-01-(R-06/25)

Ce document peut être obtenu en français sur demande.

PRESENT THIS COPY WHEN REGISTERING VEHICLE