

03865236

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

Vehicle Standards and Inspection
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba

A992248

Date Inspection Started 20 09 25
DAY MO. YR.

Date Inspection Completed 20 09 25
DAY MO. YR.

Inspection Expiry Date 30 09 26
DAY MO. YR.

Station Number 11138

Station Name

Red River College Winnipeg

City

Mechanic Number 17207

Mechanic Signature

Station Phone Number

Vehicle Owner Frontline Freight Systems 2020 Inc

Address

City

Province

Postal Code

Phone

☒ Pass/Safe Vehicle☐ Fail/Unsafe Vehicle☐ Fail/Hazardous

Licence Number

TBS11912

Prov. MB

NSC #

Odometer Reading

Odom. Type ☐ km ☐ mi

Vehicle Identification Number

1U1YVSR2539K314981135

Make

J6113

Model

Van

Year

2019

Unit #

FF5387

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck

GVWR

KGS

Truck Tractor

Trailer

☒ Semi-Trailer

Bus

School Bus

Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																							
X		Section 1 - Power Train: Defects (if any)																																																																							
X		Section 2 Suspension: Defects (if any)																																																																							
X		Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type																																																																							
		Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																							
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>11/16</td> <td>11/16</td> <td>16525</td> <td>16525</td> <td>1.25</td> <td>1.25</td> </tr> <tr> <td>2</td> <td>12/16</td> <td>12/16</td> <td>16540</td> <td>16534</td> <td>1.25</td> <td>1.25</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7">Final Measurement</td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	11/16	11/16	16525	16525	1.25	1.25	2	12/16	12/16	16540	16534	1.25	1.25	3							4							5							Final Measurement																						
Axle	Lining			Drum/Rotor		Stroke																																																																			
	L	R	L	R	L	R																																																																			
1	11/16	11/16	16525	16525	1.25	1.25																																																																			
2	12/16	12/16	16540	16534	1.25	1.25																																																																			
3																																																																									
4																																																																									
5																																																																									
Final Measurement																																																																									
X		Section 4 - Steering: Defects (if any)																																																																							
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																							
X		Section 6 - Lamps: Defects (if any)																																																																							
X		Section 7 - Electrical System: Defects (if any)																																																																							
X		Section 8 - Body: Defects (if any)																																																																							
X		Section 9 - Tire & Wheel: Defects (if any)																																																																							
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th></th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>10</td> <td>12</td> <td>10</td> <td>10</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>2</td> <td>5</td> <td>9</td> <td>5</td> <td>7</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	1	10	12	10	10	100	100	100	100	2	5	9	5	7	100	100	100	100	3									4									5								
Axle	Tread Depth				Air Pressure																																																																				
	Initial		Corrected		Initial		Corrected																																																																		
	L	R	L	R	L	R	L	R																																																																	
1	10	12	10	10	100	100	100	100																																																																	
2	5	9	5	7	100	100	100	100																																																																	
3																																																																									
4																																																																									
5																																																																									
		Section 10 - Coupling Devices: Defects (if any)																																																																							