

04018944

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

Vehicle Standards and Inspection
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba



C016605

Date Inspection Started DAY: 10, MO: 09, YR: 25	Station Number R6404	Station Name Bousereco Transport Repair Inc. Wpg	City Wpg
Date Inspection Completed DAY: 18, MO: 09, YR: 25	Mechanic Number M3384	Mechanic Signature Paul Chard	Station Phone Number
Inspection Expiry Date DAY: 30, MO: 09, YR: 26	Vehicle Owner 4885814 Manitoba LT.D		
Address _____ City _____ Province _____ Postal Code _____ Phone _____			
☒ Pass/Safe Vehicle ☒ Fail/Unsafe Vehicle ☐ Fail/Hazardous	Licence Number TF21216	Prov. MB	NSC # _____
☒ Confirmed legible Vehicle Identification Number on vehicle	Vehicle Identification Number 14YUS2532K3498137	Make utility	Model Van
		Year 2019	Unit # 7339
		Odometer Reading _____	Odom. Type km ☐ mi ☐

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

 Truck ☐ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☒ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																							
		Section 1 - Power Train: Defects (if any)																																																																							
X	X	Section 2 Suspension: Defects (if any) 5-b R.F & L.R Air bags																																																																							
X	X	Section 3 - Brake Systems: 3H (3A) Defects (if any) Circle Brake Type																																																																							
		Brake Inspection Type: A (B) C D E Circle appropriate Letter for Internal Brake Component Inspection <table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>7/8</td> <td>7/8</td> <td>16.500</td> <td>16.500</td> <td>1.5</td> <td>1.5</td> </tr> <tr> <td>2</td> <td>7/8</td> <td>7/8</td> <td>16.500</td> <td>16.500</td> <td>1.5</td> <td>1.5</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7">Final Measurement</td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	7/8	7/8	16.500	16.500	1.5	1.5	2	7/8	7/8	16.500	16.500	1.5	1.5	3							4							5							Final Measurement																						
Axle	Lining			Drum/Rotor		Stroke																																																																			
	L	R	L	R	L	R																																																																			
1	7/8	7/8	16.500	16.500	1.5	1.5																																																																			
2	7/8	7/8	16.500	16.500	1.5	1.5																																																																			
3																																																																									
4																																																																									
5																																																																									
Final Measurement																																																																									
		Section 4 - Steering: Defects (if any)																																																																							
X	X	Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																							
X	X	Section 6 - Lamps: Defects (if any) 1-H R.R marker light																																																																							
X		Section 7 - Electrical System: Defects (if any)																																																																							
X		Section 8 - Body: Defects (if any)																																																																							
X	X	Section 9 - Tire & Wheel: Defects (if any) 4-A Tire pressures																																																																							
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="4">Tread Depth mm</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th></th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>7</td> <td>5</td> <td>7</td> <td>9</td> <td>100</td> <td>100</td> <td>60</td> <td>100</td> </tr> <tr> <td>2</td> <td>8</td> <td>8</td> <td>10</td> <td>7</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth mm				Air Pressure				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	1	7	5	7	9	100	100	60	100	2	8	8	10	7	100	100	100	100	3									4									5								
Axle	Tread Depth mm				Air Pressure																																																																				
	Initial		Corrected		Initial		Corrected																																																																		
	L	R	L	R	L	R	L	R																																																																	
1	7	5	7	9	100	100	60	100																																																																	
2	8	8	10	7	100	100	100	100																																																																	
3																																																																									
4																																																																									
5																																																																									
X		Section 10 - Coupling Devices: Defects (if any)																																																																							

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.