

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
LV59		Toyota Hilux SR Single Cab 4X4		
	192685	10,000km Light Vehicle Service 362357 km Replaced wiper blades Secured front bumper Has bulls eye in view needs windscreen	21/04/2026	362357 KM
	191610	Pink Slip Inspection - Light Vehicle Odo: 362,357km	21/04/2026	362357 KM
	191274	New Steer Tyres	24/02/2026	KM
	60456	10,000km Light Vehicle Service 352611km * Needs tyres * Has chip in windscreen	5/02/2026	KM
	58870	Pink Slip Inspection - Light Vehicle Odo: 344,859 kms Replace LHR Brake Light & LHF Park Globe.	5/11/2025	KM
	57738	10,000km Light Vehicle Service - Replaced wiper blades - Replaced front park light - Replaced number plate light - Replaced front pads - Repaired strobe and mount bracket	16/09/2025	KM
	55662	Prep vehicle for site requires Flashing light UHF A1 stickers on the door -Fit mine spec light bar to vehicle, install beacon - bell out wires for lights, break into harness and join solder wires and heat shrink - install new switches in cab for work lights and beacons, fit unit ID numbers and company decals.	20/06/2025	KM
	55274	Tail gate replacement 332598km - remove and replace RH tailgate hinge, hinge broken	2/06/2025	KM
	54663	40,000km Light Vehicle Service 330,704km	8/05/2025	330704 KM

Asset	W/O No	Description	Finished	Done Reading	
		- fit passenger seat cover - vacuum and detail cab			
	21414	Pink Slip Inspection - Light Vehicle	10/10/2024	323670	KM
	48952	WINDSCREEN REPLACEMENT	2/10/2024		KM
	48580	REMOVE SEIZED TOW HITCH	17/09/2024		KM
	21196	Repair/Replace tailgate Replace taillight Fit new seat covers Fit pre-start sticker Fit think safe sticker Remove Jacon stickers	10/09/2024	322600	KM
	5759	Pink Slip Inspection - Light Vehicle Replace 4x tyres and front wheel alignment	8/11/2023	308174	KM
	6893	310,000km Light Vehicle Service - perform routine service - removed & replaced drive belt, timing belt & wiper blades	7/11/2023	308164	KM