

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
A1-750		Sterling LT7500 Water Truck		
	59394	off-hire, prep for hollingsworth	29/05/2026	
		- Carry out the off hire inspection - Secure left hand side 1/4 guard - Check LHS spray, replace cam dock, had to hear fitting to remove - Check out windscreen washers, locate broken wiring & repair - Repair multiple air leaks in spray system - Weed & seed truck - Clean cab - cab was filthy		
	56876	PRE PIT INSPECTION 3 Carry out pre-pit inspection Repair air leak at RH front drive axle brake booster Adjust all brakes Unblock window washer nozzle RH Replace wiper blades Replaced LH rear clearance light not working repair wiring Take vehicle to Hannafords and replace four tyres	21/05/2026	
	57754	repair water hopper *Prep and weld hopper attachment *Mark and cut hole to remove broken aluminum piece from inside tank *Modify and mount hopper *Prep and weld aluminum piece back in and seal *Weld pipe holder on n/s	21/02/2026	
	59439	Water Truck - 1000hr Service Odo: 9,135hrs	28/11/2025	
		- carry out 1000hr service as per service sheet - tighten universal clamp bolts - replace hydraulic tank site glass		
	56139	Prep for Site (CCH)	23/09/2025	
		- R+R oil pressure sensor - R+R x2 track rod bushes - fit LHS inner guard Double R - carry out repairs		