

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
NW048		Isuzu 10x4 Service Truck		
	56455	July Monthly Work order R&M - Lake Cowal Fit counter Service truck Transmission fault	30/07/2025	Hours
	55209	Service/Fuel Truck - 250hr Service 12202 hrs - Replaced RHS low beam globe - Replaced RHS fog light globe	30/05/2025	12202 Hours
P1351		Isuzu 10x4 Service Truck		
	58788	November R&M Grease bulk tank fill Pick up compressor parts Fit grease drum and fit, test compressor Bypass fuel control valve to allow full flow, assist with fueling and greasing Remove crimp bulk fuel hose New reverse camera. Order transmission speed sensor.	12/02/2026	Hours
	60414	February R&M Replace air line fitting Inspect brake issue, found rubbed air line	6/02/2026	Hours
	60032	January R&M Diagnose engine light on, machine derating (Bendalls) Scan truck and found speed sensor fault. Locate and repair speed sensor wiring as required - 6 MONTHLY FIRE SUPPRESSION TEST/INSPECTION jumpstart Blow out compressor cooler packs Start changing harness out Repair fuel pump. Repair lights Remove LV+HV hoses for repairs and refit Replace fuel hoses. Clean cab Inspect brakes locking on	30/01/2026	Hours
	60316	Replace steer tyre for tyre doctor	27/01/2026	Hours
	59437	December R&M Fill up oils in service truck	18/12/2025	Hours

Asset	W/O No	Description	Finished	Done Reading
		Repair diesel leak on low flow hose Check air leaks Get steer tyre fixed C/O steer tyres Repair air hose for compressor		
58661		New service body compressor	1/12/2025	Hours
57861		Service/Fuel Truck - 250hr Service	1/12/2025	Hours
59370		Service/Fuel Truck - 250hr Service. Parts only. Have let PJ know there is a service kit in Dubbo for this truck. 13014hrs	26/11/2025	Hours
58922		Steer Tyres Replace and rotate tyres Steer tyres	9/11/2025	Hours
58151		October R&M - CAPITAL - Fix headlight transmission fault repairs -transmission issues - fuel pump not working, repaired broken wire and organised parts - fuel nozzle failed/swapped over - inspect and diagnose trans/engine issue - replace harness and sensors on trans - remove bulk fuel reel and replace - Fit hose reel and mounting plate for bulk fuel hose, - carry out service, - diagnose issue with engine oil pump and swap pump out - check air compressor/repair door latch - grease truck and inspect driveline - diagnose air leak - get rear bulk fuel hose operation, take truck for test drive - Wire in isolator and estop on air compressor	31/10/2025	Hours
57292		September R&M - Replacement tyres - Fit hose reel - AC repairs/ trans repair/ remove oil reel for repairs - Inspect fuel gauge - Fit exhaust on - Repair headlights - Fix leaks - Bled fuel - Asses gearbox issue, connect scan tool, clear codes - Test drive failed.	30/09/2025	Hours

Asset	W/O No	Description	Finished	Done Reading
		- Swap input speed sensor with turbine speed sensor, clear codes, test drive code remained the same - Ordered parts, fitted 2 x new sensor plugs - Removed & replaced compressor - Test drive all ok! - Repaired & regas A/C system - Fit new compressor & filters - Fit new wiper blades - gear shift fault 11/09 - repair lights/trans fault 16/09 - remove hose reel-broken bolts 18/09 - put real back together and fit, re-seal fuel fittings 20/09 - chase up fuel reel 23/09 - fuel hose bulk reel 28/09 - fuel fill hose remove, top up grease tank 29/09		
	56797	August Monthly R&M - Take truck off site for scan tool - repair rear tail lights, order head light - repair wiring in 2 way - Inspect A/C not working	30/08/2025	Hours
	54997	Capital Works carry out full inspection/ prep for lake cowl - Remove air compressor - Fit air compressor, repair fuel tank & brackets - Prep for site, weld cap on bar, pull grease reel apart and replaced bearings in hose reel. - Clean up mess, remove grease hose reel, cut and make mounts, paint, fit hoses - Grease reel and quick connect fittings - Tail light repair - Cut out a 5mm plate 520mmx320mm, weld plate over the hole on top - Weld a bit off RHS in the tank to stop the baffs moving around in and two lifting lugs - FFP Lake cowl - Repairs, weed and seed - Weld 4 x lifting lugs to strap down new generator - relocate 3rd axle z-spring. - remove lid on fuel tank to inspect for contaminates. - replace all oil tanks and bladders. had to remove all hose reels and pumps to replace. - repair all diaphragm pumps for waste oil and coolant. also had to re-plumb pumps. - replace fuel hose on hose reel. - re-tensioned grease line hose reel. - repaired bulk grease drum, re-plumb air back to it. - replace front engine mounts. - replaced 2nd axle hub caps.	8/07/2025	Hours

Asset	W/O No	Description	Finished	Done Reading
		- rotate drive tyres. - fitted hi-rise tail lights. - repaired remote grease lines at rear of vehicle. - replace all rebound rollers on rear suspension. - fit reverse camera. - paint all lifting lugs green, all steps yellow. - needle gun and repair rust on top of service body. - remove rear ladder. - fit all new hi-vis tape. - replace all oil filters for service body. - fit filter lagging. - fit asset stickers and safety stickers. - cleaned out service body. - replace bowl on air regulator. - fit tracker. - fit seat covers. - replace j-brackets on fuel tank. - replace leaking air bag 4th axle lhs. - re-kit air drier. - replace ride height valves. - replace 4 oil meter gun for service body. - fit 2 new work lights. - fit new labeling for oil tanks. - replace air tank drain cocks. - fit all new taps and quick connect fittings for oil tank fill and discharge points. - test operation of all functions on service body. - filled oil tanks up, found out they were leaking, drained all oils back out. put new tanks in filled oil back up again.		