04144567

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba C100208

	DAY	MO.	YR.
Date Inspection Started	27	10	26
Date Inspection Completed	28	10	26
Inspection Expiry Date	31	10	27

Station Number: A3017 — Station Name: Lucky Star Ltd — City: Swan River

Mechanic Number: M1016 — Mechanic Signature — Station Phone Number: 204-571-1531

Vehicle Owner: Renaissance Transport LTD

Address: Site 115 Box 46 RR1 — City: Brandon — Province: MB — Postal Code: R7A 5Y1 — Phone

- [x] Pass/Safe Vehicle
- [x] Fail/Unsafe Vehicle
- [ ] Fail/Hazardous

Licence Number: SL37103 — Prov.: MB — NSC #: N/A — Odometer Reading: N/A — Odom. Type: [ ] km [ ] mi

Vehicle Identification Number: 7HWRTL98 — Make: Westank — Model: Tanker — Year: 1979 — Unit #: ACC4

[x] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

GVWR ____ KGS ____Truck ____Truck Tractor ____Trailer X Semi-Trailer ____Bus ____School Bus ____Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

P	R	
✓		**Section 1 - Power Train:** Defects (if any)
✓		**Section 2 Suspension:** Defects (if any)
✓	✓	**Section 3 - Brake Systems:** 3H (3A) Defects (if any) — Circle Brake Type: X-16C-LH LS Clevis binding
✓		**Section 4 - Steering:** Defects (if any)
✓		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
✓	✓	**Section 6 - Lamps:** Defects (if any) X-1F-CHS Rear Signal light inoperative
✓		**Section 7 - Electrical System:** Defects (if any)
✓	✓	**Section 8 - Body:** Defects (if any) X-3A-Mudflap not secure
✓		**Section 9 - Tire & Wheel:** Defects (if any)
✓		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: A (B) C D E — Circle appropriate Letter for Internal Brake Component Inspection

	Lining		Drum/Rotor		Stroke	
Axle	L	R	L	R	L	R
1	7	9	16.588	16.583	1½	1½
2	10	10	16.595	16.590	1½	1½
3						
4						
5						
	Final Measurement					

T6"

	Tread Depth								Air Pressure							
	Initial				Corrected				Initial				Corrected			
Axle	L		R		L		R		L		R		L		R	
1	15	15	15	15					100	100	100	100				
2	8	11	11	13					100	100	100	100				
3																
4																
5																

32"

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature

Ce document peut être obtenu en français sur demande.

COPY IN CAB - PLEASE ENSURE CERTIFICATE IS SIGNED - NOT FOR REGISTRATION