



Vehicle Standards and Inspection

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A341056

Station #: 71928

Station Name: Clarence Reimer's Garage Ltd.

Technician #: 85631

Technician Name: Clarence Reimer

Signing Officer #: 82605

Signing Officer Name: Pamela Bogner

Customer Details:

Name: Stoney Lake Transport

Address: Box 818, Big River, Saskatchewan, S0J 0E0

Inspection Completed Date: 12May2026

Inspection Expiry Date: 31May2027

Vehicle Details:

VIN: 2PLB03935DBC16201

Hubometer Reading:

Year: 2013

Vehicle Make/Model: PEERLESS TRAILER/TRAILER

Plate: 436 NBJ

Jurisdiction: Saskatchewan

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.

11-200



The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71928	Station Name: Clarence Reimer's Garage Ltd.
Technician #: 85631	Technician Name: Clarence Reimer
Signing Officer #: 82605	Signing Officer Name: Pamela Bogner

Customer Details:	
Name: Stoney Lake Transport	Address: Box 818, Big River, Saskatchewan, S0J 0E0

Vehicle Details:	
VIN: 2PLB03935DBC16201	Hubometer Reading:
Year: 2013	Vehicle Make/Model: PEERLESS TRAILER TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 15 mm

Brake(1): S-CAM Brake

Min Brake Lining/Pad: 11 mm • Cam Rotation: 120.0 degrees • Brake Stroke: 28 mm

Wheel2-On : Tire Tread Depth: 13 mm

Brake(1): S-CAM Brake

Min Brake Lining/Pad: 11 mm • Cam Rotation: 120.0 degrees • Brake Stroke: 28 mm

Wheel3-On : Tire Tread Depth: 14 mm

Brake(1): S-CAM Brake

Min Brake Lining/Pad: 12.5 mm • Cam Rotation: 105.0 degrees • Brake Stroke: 28 mm

Wheel4-On : Tire Tread Depth: 14 mm

Brake(1): S-CAM Brake

Min Brake Lining/Pad: 12.5 mm • Cam Rotation: 105.0 degrees • Brake Stroke: 28 mm

Axle 2-Pass

Wheel1-On : Tire Tread Depth: 15 mm

Brake(1): S-CAM Brake

Min Brake Lining/Pad: 16.5 mm • Cam Rotation: 70.0 degrees • Brake Stroke: 28 mm

Wheel2-On : Tire Tread Depth: 14 mm

Brake(1): S-CAM Brake

Min Brake Lining/Pad: 16.5 mm • Cam Rotation: 70.0 degrees • Brake Stroke: 28 mm

Wheel3-On : Tire Tread Depth: 14 mm

Brake(1): S-CAM Brake

Min Brake Lining/Pad: 15 mm • Cam Rotation: 85.0 degrees • Brake Stroke: 28 mm

Wheel4-On : Tire Tread Depth: 14 mm

Brake(1): S-CAM Brake

Min Brake Lining/Pad: 15 mm • Cam Rotation: 85.0 degrees • Brake Stroke: 28 mm

Axle 3-Pass

Wheel1-On : Tire Tread Depth: 14 mm

Brake(1): S-CAM Brake

Min Brake Lining/Pad: 18.5 mm • Cam Rotation: 55.0 degrees • Brake Stroke: 28 mm

Wheel2-On : Tire Tread Depth: 13 mm

Brake(1): S-CAM Brake

Min Brake Lining/Pad: 18.5 mm • Cam Rotation: 55.0 degrees • Brake Stroke: 28 mm

Wheel3-On : Tire Tread Depth: 14 mm

Brake(1): S-CAM Brake

Min Brake Lining/Pad: 13 mm • Cam Rotation: 103.0 degrees • Brake Stroke: 28 mm

Wheel4-On : Tire Tread Depth: 14 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 13 mm • Cam Rotation: 103.0 degrees • Brake Stroke: 28 mm

PASS - vehicle passes inspection

Decal # A341056

Inspection Completed Date: 12May2026