



Vehicle Standards and Inspection

Power Unit Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

1005-

Decal # A341065

Station #: 71928	Station Name: Clarence Reimer's Garage Ltd.
Technician #: 85631	Technician Name: Clarence Reimer
Signing Officer #: 82605	Signing Officer Name: Pamela Bogner

Customer Details:	
Name: DC North Contracting Ltd.	Address: Box 818, Big River, Saskatchewan, S0J 0E0

Inspection Completed Date: 21May2026	Inspection Expiry Date: 30Nov2026
--------------------------------------	-----------------------------------

Vehicle Details:	
VIN: 1XKDD40XX7J930801	Odometer Reading: 903612 km
Year: 2007	Vehicle Make/Model: KENWORTH/HEAVY VEHICLE
Plate: DCN 10	Jurisdiction: Saskatchewan
Unit:	

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71928	Station Name: Clarence Reimer's Garage Ltd.
Technician #: 85631	Technician Name: Clarence Reimer
Signing Officer #: 82605	Signing Officer Name: Pamela Bogner

Customer Details:	
Name: DC North Contracting Ltd.	Address: Box 818, Big River, Saskatchewan, S0J 0E0

Vehicle Details:	
VIN: 1XKDD40XX7J930801	Odometer Reading: 903612 km
Year: 2007	Vehicle Make/Model: KENWORTH HEAVY VEHICLE

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	

x				Fire Extinguisher/Hazard Kit (5)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
		x		Retro Reflective Markings (6)	
x				Body/Bumpers (8)	
x				Trailer Hitch (10)	
x				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Cab/Hood Safety Catches (8)	
x				Power Steering System (4)	
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	
x				Air Suspended Cab (8)	
x				Cab Mounts (8)	
x				Drive Belts (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	

x				Air Brake System/Components (3.2)	
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Drive Shaft/Universal Joints (1)	
x				Exhaust/Emission System (1)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 16 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15.5 mm • Cam Rotation: 75.0 degrees • Brake Stroke: 24 mm

Wheel2-On : Tire Tread Depth: 16 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15.5 mm • Cam Rotation: 75.0 degrees • Brake Stroke: 24 mm

Axle 2-Pass

Wheel1-On : Tire Tread Depth: 21 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 20 mm • Cam Rotation: 35.0 degrees • Brake Stroke: 22 mm

Wheel2-On : Tire Tread Depth: 19 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 20 mm • Cam Rotation: 35.0 degrees • Brake Stroke: 22 mm

Wheel3-On : Tire Tread Depth: 21 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 20 mm • Cam Rotation: 35.0 degrees • Brake Stroke: 22 mm

Wheel4-On : Tire Tread Depth: 21 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 20 mm • Cam Rotation: 35.0 degrees • Brake Stroke: 22 mm

Axle 3-Pass

Wheel1-On : Tire Tread Depth: 22 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 21 mm • Cam Rotation: 32.0 degrees • Brake Stroke: 22 mm

Wheel2-On : Tire Tread Depth: 21 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 21 mm • Cam Rotation: 32.0 degrees • Brake Stroke: 22 mm

Wheel3-On : Tire Tread Depth: 19 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 21 mm • Cam Rotation: 32.0 degrees • Brake Stroke: 22 mm

Wheel4-On : Tire Tread Depth: 19 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 21 mm • Cam Rotation: 32.0 degrees • Brake Stroke: 22 mm