



Vehicle Standards and Inspection

Power Unit Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

W05-4

Decal # A341061

Station #: 71928

Station Name: Clarence Reimer's Garage Ltd.

Technician #: 85631

Technician Name: Clarence Reimer

Signing Officer #: 82605

Signing Officer Name: Pamela Bogner

Customer Details:

Name: DC North Contracting Ltd.

Address: Box 818, Big River, Saskatchewan, S0J 0E0

Inspection Completed Date: 20May2026

Inspection Expiry Date: 30Nov2026

Vehicle Details:

VIN: 1NKZX4EXXKJ997357

Odometer Reading: 524235 km

Year: 2019

Vehicle Make/Model: KENWORTH/HEAVY VEHICLE

Plate: DCN 7

Jurisdiction: Saskatchewan

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Power Unit Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71928

Station Name: Clarence Reimer's Garage Ltd.

Technician #: 85631

Technician Name: Clarence Reimer

Signing Officer #: 82605

Signing Officer Name: Pamela Bogner

Customer Details:

Name: DC North Contracting Ltd.

Address: Box 818, Big River, Saskatchewan, S0J 0E0

Vehicle Details:

VIN: 1NKZX4EXXKJ997357

Odometer Reading: 524235 km

Year: 2019

Vehicle Make/Model: KENWORTH HEAVY VEHICLE

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
		x		Mirrors (8)	
x				Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	

x				Fire Extinguisher/Hazard Kit (5)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Body/Bumpers (8)	
x				Trailer Hitch (10)	
x				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Cab/Hood Safety Catches (8)	
x				Power Steering System (4)	
x				Fuel System (1)	
		x		Battery/Wiring Condition (7)	
x				Air Suspended Cab (8)	
x				Cab Mounts (8)	
x				Drive Belts (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	

x				Air Brake System/Components (3.2)	
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Drive Shaft/Universal Joints (1)	
x				Exhaust/Emission System (1)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 15 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 19 mm • Cam Rotation: 50.0 degrees • Brake Stroke: 24 mm

Wheel2-On : Tire Tread Depth: 14 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 19 mm • Cam Rotation: 50.0 degrees • Brake Stroke: 24 mm

Axle 2-Pass

Wheel1-On : Tire Tread Depth: 20 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15 mm • Cam Rotation: 80.0 degrees • Brake Stroke: 22 mm

Wheel2-On : Tire Tread Depth: 20 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15 mm • Cam Rotation: 80.0 degrees • Brake Stroke: 22 mm

Wheel3-On : Tire Tread Depth: 20 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15 mm • Cam Rotation: 78.0 degrees • Brake Stroke: 22 mm

Wheel4-On : Tire Tread Depth: 20 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15 mm • Cam Rotation: 78.0 degrees • Brake Stroke: 22 mm

Axle 3-Pass

Wheel1-On : Tire Tread Depth: 20 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 14 mm • Cam Rotation: 88.0 degrees • Brake Stroke: 22 mm

Wheel2-On : Tire Tread Depth: 20 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 14 mm • Cam Rotation: 88.0 degrees • Brake Stroke: 22 mm

Wheel3-On : Tire Tread Depth: 20 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 14 mm • Cam Rotation: 86.0 degrees • Brake Stroke: 22 mm

Wheel4-On : Tire Tread Depth: 20 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 14 mm • Cam Rotation: 86.0 degrees • Brake Stroke: 22 mm

Axle 4-Pass

Wheel1-On : Tire Tread Depth: 20 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 14 mm • Cam Rotation: 88.0 degrees • Brake Stroke: 22 mm

Wheel2-On : Tire Tread Depth: 20 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 14 mm • Cam Rotation: 88.0 degrees • Brake Stroke: 22 mm

Wheel3-On : Tire Tread Depth: 20 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 14 mm • Cam Rotation: 90.0 degrees • Brake Stroke: 22 mm

Wheel4-On : Tire Tread Depth: 20 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 14 mm • Cam Rotation: 90.0 degrees • Brake Stroke: 22 mm

PASS - vehicle passes inspection

Decal # A341061

Inspection Completed Date: 20May2026