


RITCHIE BROS. Diagnostic Report
 Auctioneers®

2021 Peterbilt 389

Test Information

Engine	PACCAR MX/MX-13 (12.9)
Engine Serial	PCAR*MX26U20D13*Y225819*00000000
VIN	1XPXDP0X4MD731374
Driveline	Class 8 6x4
Body	Truck-Tractor
Test Time	Dec. 11, 2025, 1:10 p.m.
File Length	50.1552 s

Usage

Label	Value	Units
Engine Odometer	208,958	mi
Engine Total Hours of Operation	8,086.4	h
Aftertreatment 1 Diesel Particulate Filter Soot Load Percent	71	%

Engine On/Off

Engine running

Check Engine Light

No check engine lights on

Emissions Deleted/Tampered
No

Faults				
<u>DM</u>	<u>Controller Name</u>	<u>SPN Name</u>	<u>FMI Name</u>	<u>Count</u>
Emissions Pending	Engine #1	Aftertreatment 1 Outlet NOx 1	Erratic, Intermittent, or Incorrect	1
Emissions Previous	Engine #1	Engine Exhaust Gas Recirculation System Monitor	Data Drifted Low	7
All Pending	Engine #1	Aftertreatment 1 Outlet NOx 1	Erratic, Intermittent, or Incorrect	1