



MDP Oilfield Services Ltd. Heavy Duty Truck Service Report

Date: Nov 5-2025	Complete Unit #: 5	Inspection Completed By: Kevin B
Odometer/Hour Meter Reading: 224340	Next Service hours or KM's: 232340	Type of Truck: Dodge 3500
Nature of Work Performed: Oil Changed	Plate #	Sin # 3D6WZ4CL0BG565449

Item/Part Checked	Checked	Changed	N/A	Item/Part Checked	Checked	Changed	N/A	Item/Part Checked	Checked	Changed	N/A
Engine				Fuel System				Cabs			
Oil Levels		X		Fuel Tank	x			Windows & Mirrors	x		
Air Filters		X		Filler Cap	x			A/C & Heater/Defrost	x		
Oil Leaks	X			Fuel Lines	x			Two Way Radio			
Coolant Leaks	X							Doors/Latches/Releases	x		
Hoses	X			Hydraulic				System Controls (Covers/Pedals)	x		
Transmission				Vacuum & Air Components				Horn	x		
Oil Levels	X			Mechanical Components		x		Other			
Filters/Screens	X			Brake Pedal	x			Steering Column & Box	x		
Oil Leaks	X			Air Brake System	x			Wheel Alignment	x		
Hoses	X			Parking Brake	x			Steering Linkage	x		
Final Drives				Electrical				Seats	x		
Oil Levels				Fuses	x			Body	x		
Check for Cuttings				Lamps/Lights/Reflectors	x			Exhaust System	x		
Check for Leaks				Gauges	x			Fluid Level	x		
Coolant System				Neutral Safety Starting Switch	x			Fenders	x		
Radiator	X			Wipers & Fluid	x			Bumpers	x		
Hoses	X			Truck Interior				Mudflaps	x		
Fan Belts & Fan	X			Fuel Card				Sunvisor	x		
Test & Top Collant Level	X			Invoice & Safety Meeting Book				Roadside Assistance Box			
Tires				Insurance & Registration				Fire Extinguisher			
Check Tires & Spare	X			First Aid Kit				Truck is Clean/Washed	x		
Wheel Studs	X			Check for Cracks				Visable License Plate			
Rims	X			Chassis Frame				Hydraulics			
Wheel Bearings		X	Left side	Entire Underbody				Hoses			
DATE OIL CHANGED:	Nov 5-2025			Drive Shaft				Seals			
Mileage/Hours	224359			Check for Loose Bolts							
Oil Filter		x		Hanger Brackets/Guards							
Fuel Filter		x		Suspension Items							
Air Filter		x									

Parts & Supplies: Changed Engine oil & Oil filter.air filter . DMO coop 0-40 synthetic , New wheel bearing front left and Axle , All new Brakes includes rotor calpliers and brake pads

Details of Work Completed: