



Commercial Vehicle Inspection Report

Decal Number: GM37902
Decal Expiry Date: 2026-Jul-31
Inspection Number: 21616819

W11-1
Inspection Result:
PASS

FACILITY: JOHNSON RADIATOR SERVICES LTD. / S20512
INSPECTOR: GILOWSKI, TRAVIS GORDON / 200472
WORK ORDER #: 219919
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Semi-annual
INSP. START: 2025-Dec-31 07:00 AM -07
INSP. COMPLETE: 2026-Jan-02 08:00 AM -07

Langfab L-11

VEHICLE JUR: British Columbia
PLATE #: A0V9G2
LICENCED GVW(kg): 0
VEHICLE YEAR: 2023
MAKE: LANGFAB
MODEL:
REGI: 14206441
UNIT/FLEET#: L-11
BODY STYLE: Pup Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
VIN: 2L9PPA6C3PS014236
OWNER/LESSEE NAME: 6809774 CANADA INC, L.L ENTERPRISES
ADDRESS: PO BOX 1182
Fort Nelson, British Columbia
V0C1R0, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) REPAIRED ABS,REPLACED AXLE 2 RIGHT SLACK BUSHING
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) REPAIRED MARKER LIGHTS
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	40	40
2	Clamp	30	Automatic	40	40
3	Clamp	30	Automatic	40	40

Comment:

Tire Tread Depth (mm)

	Outer L	Inner L	Inner R	Outer R	Steering
	13	14	14	14	
	11	9	14	13	
	13	15	8	8	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	35	35
2	35	35
3	35	35

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	19	19
Lining (Shoe)	19	19
Lining (Shoe)	19	19

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: GILOWSKI, TRAVIS GORDON

Road Test Date:
Signature:

Travis Gordon
[Signature]

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Jan-02 08:04 AM -07

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC V/P at the Commercial Vehicle Safety Enforcement.

CV/SE0914

12/26/25 8:04:56 AM -07