

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	65	30	Lining (Shoe)	15	18	Drum		
2	20	20	Lining (Shoe)	19	19	Drum		
3	80	20	Lining (Shoe)	10	19	Drum		
4	20	30	Lining (Shoe)	19	18	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

 Has this Vehicle been road tested? No
 Inspector: GILOWSKI, TRAVIS GORDON

 Road Test Date:
 Signature:



Road Tester:

This Inspection Report was submitted to CVSE on 2026-Apr-21 05:18 PM-07

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement.

CVSE/014

4/21/2025 5:18:23 PM -07

FACILITY: JOHNSON RADIATOR SERVICES LTD. / S20512	INSP. TYPE: Complete	INSP. START: 2026-Apr-20 11:00 AM -07
INSPECTOR: GILOWSKI, TRAVIS GORDON / 200472	INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE: 2026-Apr-21 05:00 PM -07
WORK ORDER #: 224878	INSP. REASON: Semi-annual	

W11-3
Western Star 6-18

VEHICLE JUR: British Columbia	REGI: 12767089	VIN: 5KKPALD13JPJW6682
PLATE #:	UNIT/FLEET#: L18	OWNER/LESSEE NAME: L.L ENTERPRISES, L.L ENTERPRISES
LICENCED GVW(kg): 63500	BODY STYLE: Dump Truck	ADDRESS: PO BOX 1182
VEHICLE YEAR: 2018	ODOMETER: 255492 KM	Fort Nelson, British Columbia
MAKE: WESTERN ST	HUB ODOMETER:	V0C1R0, Canada
MODEL:	BRAKE TYPE: Air	
	FUEL TYPE:	

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Repaired (same day) TIGHTEND LOSE SHOCK BOLTS AND LOSE AIR BAG AXLE 4
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) REPLACED AIR TANK ON LEFT SIDE,REPLACED AXLE 4 RIGHT SUPPLY LINE
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) REPAIRED MARKER LIGHTS
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)
Tire Tread Depth (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	40	40	15			15	✓
2	Clamp	30	Automatic	40	40	20	21	21	21	
3	Clamp	30	Automatic	40	40	17	17	18	17	
4	Clamp	30	Automatic	40	40	13	11	10	11	

Comment:
Comment:
NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 210 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement.

CVSB014

4/21/2026 5:18:23 PM -07