

RITCHIE BROS. Diagnostic Report
 Auctioneers®
2019 International LT**Test Information**

Engine	Cummins X15 Signature (15.0)
Engine Serial	CMMNS*6X1u17D1500000000*80043013*0000000000
VIN	3HCDZAPR8KL479407
Driveline	Class 8 6x4
Body	Truck-Tractor
Test Time	Sept. 10, 2026, 12:45 p.m.
File Length	42.152 s

Usage

Label	Value	Units
Engine Odometer	438,138	mi
Odometer (Instrument Cluster #1)	438,137	mi
Engine Total Hours of Operation	12,774.9	h
Aftertreatment 1 Diesel Particulate Filter Soot Load Percent	29	%

Engine On/Off

Engine running

Check Engine Light

No check engine lights on

Emissions Deleted/Tampered

No

Faults

DM	Controller Name	SPN Name	FMI Name	Count
Previous	Transmission #1	Manufacturer Assignable SPN	Voltage Below Normal	1
Previous	Transmission #1	Battery Potential / Power Input	Special Instruction	2
Previous	Transmission #1	Percent Clutch Slip	Not Responding Properly	3
Previous	Shift Console - Primary	Source Address 0	Abnormal Update Rate	2
Previous	Shift Console - Primary	Engine Retarder Selection	Out of Calibration	2
Previous	Shift Console - Primary	Transmission Requested Gear	Out of Calibration	1
Previous	Shift Console - Primary	Source Address 33	Abnormal Update Rate	8
Previous	Passenger-Operator Climate Control #1	Manufacturer Assignable SPN	Voltage Above Normal	1
Previous	Body Controller	Manufacturer Assignable SPN	Out of Calibration	2
Previous	Body Controller	Manufacturer Assignable SPN	Out of Calibration	6
Previous	Body Controller	Fifth Wheel Slider Lock Switch	Erratic, Intermittent, or Incorrect	4
Previous	Body Controller	Manufacturer Assignable SPN	Out of Calibration	1
Previous	Body Controller	Manufacturer Assignable SPN	Out of Calibration	2
Previous	Body Controller	Manufacturer Assignable SPN	Out of Calibration	1
Previous	Body Controller	Manufacturer Assignable SPN	Out of Calibration	1
Previous	Body Controller	Headlamp Low Beam Left #1	Current Below Normal	28
Previous	Body Controller	Unknown	High-most severe	20
Previous	Body Controller	Manufacturer Assignable SPN	Current Above Normal	1
Previous	Body Controller	Cab A/C Refrigerant Compressor Outlet Pressure	Low-most severe	3
Previous	Lighting - Operator Controls	Source Address 33	Abnormal Update Rate	15
Previous	Proprietary	Source Address 33	Abnormal Update Rate	15
Previous	Proprietary	Source Address 33	Abnormal Update Rate	14
Previous	Proprietary	Manufacturer Assignable SPN	Data Error	3