



PO Box 743, Highway 16 East, Lloydminster SK S9V 1C1 • www.novlanbros.com

GST# 10980 4724 RT0001

Phone: (306) 825-6141 • Fax: (306) 825-9896 • Toll Free: 1-877-344-4433

MacDon

SALFORD

BOURGAULT Pursuing Perfection

SO # 302173


SERVICE ORDER CUSTOMER COPY



Printed 07/11/2025 8:46:18 AM

User AKS Page 1

Customer No CO0142



Term CHEQUE

Advisor Damond Souster Promised 07/20/2022 9:54 AM Tag#
Shop S1 Opened 07/19/2022 10:54 AM Location
Priority Cashiered 08/18/2022 2:08 PM PO #

License Odom In Odom Out In Service Date Stock No
1391 1391
Year Make Model Model Number Colour
2022 JOB MISC JOB
Vehicle ID No Selling Dealer Extended Warranty Delivery Date
//
Engine Fleet #

Request	Description	Job	CSR	Status
MISC	REPLACE KNIFE AND GAURDS - RESTOCKING FEE FOR BOURGAULT PARTS RETURNED BY CUSTOMER	1	DCS	Original

Labour	Description	Type	Amount
MISC	LABOUR	CA	1,200.00

Part	Description	Shp	Bin	Type	Price	Amount
MCD 118344	*GUARD	67	NWALL	CSO	24.70	1,654.90
MCD 124338	* SPCL GUARD	1	I144	CSO	45.56	45.56
MCD 124344	* SPCL GUARD	1	I132	CSO	38.37	38.37
MCD 118301	*GUARD LH	1	I323	CSO	32.75	32.75
MCD 118302	*GUARD RH	1	I325	CSO	32.75	32.75
MCD 129043	*KIT SPLICE SEG KNIFE	4	J277	CSO	60.84	243.36
MCD 279431	SICKLE-TAI	2	KR10A	CSO	242.04	484.08
MCD 279433	SICKLE-TAI	2	KR17A	CSO	220.99	441.98
MCD 279405	Sickle hea	1	KR13A	CSO	231.52	231.52
MCD 279428	Knife segm	1	KR22A	CSO	231.52	231.52
MCD 279428	Knife segm	1	KR22A	CSO	231.52	231.52
MCD 279405	Sickle hea	1	KR13A	CSO	231.52	231.52
6356-26-20	SEC CPLR 5 PORT 2 SLOT DRL BK	-1		CSO	407.31	(407.31)
6356-26-30	SEC CPLR 5 PORT 3 SLOT DRL BK	-1		CSO	407.52	(407.52)
6356-26-25	SEC CPLR 5 PORT 2 SLOT DRL RED	-1		CSO	407.31	(407.31)
6356-26-35	SEC CPLR 5 PORT 3 SLOT DRL RED	-1		CSO	407.52	(407.52)
6505-89	ELB 2-1/2X35 DEG STL TRNFR	-12	CART	CSO	86.45	(1,037.40)
RES	RESTOCKING	1	XXXXXX	CSO	260.00	260.00
MCD 120558	BOLT SPECIAL	20	DR18R4	CSO	2.84	56.80
MCD 132404	BOLTS CARRIAGE	2	DR18R4	CSO	5.94	11.88
N716	NUT	22	BOLBTN	CSO	0.18	3.96
86507779	"SCREW 7/8"" BLSTR PK OF 50PCS	1	J263	CSO	23.25	23.25
MCD 279641	SECTION -	1	J161	CSO	45.10	45.10
MCD 129297	WEARPLATE	1	J213	CSO	19.68	19.68

Rate 179.00

Parts Total	1,653.44
Labour Total	1,200.00
Request Sub-total	2,853.44

INDEBTEDNESS IS ACKNOWLEDGED I THE SUM OF \$ _____ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS AND ACCESSORIES DESCRIBED IN THIS SERVICE INVOICE AND THE ACCOMPANYING WORK ORDER.

SIGNATURE

BY MAKING THIS PURCHASE, YOU ACKNOWLEDGE AND AGREE TO CNH INDUSTRIALS PRIVACY PRACTICES AS DESCRIBED IN OUR PRIVACY NOTICE AVAILABLE HERE - [HTTPS://WWW.MYCNHSTORE.COM/US/EN/DEFAULT/PRIVACYNOTICE](https://www.mycnhstore.com/us/en/default/privacynotice)



PO Box 743, Highway 16 East, Lloydminster SK S9V 1C1 • www.novlanbros.com

GST# 10980 4724 RT0001

Phone: (306) 825-6141 • Fax: (306) 825-9896 • Toll Free: 1-877-344-4433

MacDon

SALFORD

BOURGAULT Pursuing Perfection

SO # 302173


SERVICE ORDER CUSTOMER COPY



Printed 07/11/2025 8:46:18 AM

User AKS Page 2

Customer No CO0142



Term CHEQUE

Advisor Damond Souster Promised 07/20/2022 9:54 AM Tag#
Shop S1 Opened 07/19/2022 10:54 AM Location
Priority Cashiered 08/18/2022 2:08 PM PO #

License	Odom In	Odom Out	In Service Date	Stock No
	1391	1391		
Year	Make	Model	Model Number	Colour
2022	JOB	MISC JOB		
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
//				
Engine		Fleet #		

- Correction
- Removed knife cutter bars from each side of header
 - Removed all guards
 - Installed all new Macdon guards
 - Replaced one plastic skid plate
 - Put new knife sections together using Macdon kit
 - Put old knife head on new cutter bar (both sides)
 - Slid cutter bars back into each side
 - Bent guards straight
 - Put pins back in cutter bar heads
 - Set knife hold downs to specified gap
 - Set center guard to specified gap
 - Cleaned up, put old guards in boxes
 - Ran knife, was heating up in several spots
 - Ran a string along guard tips and bent the guards straight
 - Cutter bars were heating up on each end, found that the knife was too low
 - Adjusted pivot arm upwards and retightened
 - Ran again, did not heat up
 - Checked hold down gaps again
 - Cleaned up and put old parts on header canvases

Request	Description				Job	CSR	Status
MISC	REPAIR LEAKING WHEEL MOTOR				2	DCS	Original
Labour	Description					Type	Amount
MISC	LABOUR					CA	1,050.00
Part	Description	Shp	Bin	Type	Price	Amount	
MCD 30045	O RING	1		CSO	1.58	1.58	
MCD 163622	SEAL KIT *FEB8*	1		CSO	509.73	509.73	
14455280	O-RING	1	DR30R4	CSO	5.90	5.90	
MCD 163756	SEAL KIT M150	1		CSO	455.21	455.21	
Rate	179.00		Parts Total				972.42
			Labour Total				1,050.00
			Request Sub-total				2,022.42

INDEBTEDNESS IS ACKNOWLEDGED I THE SUM OF \$ _____ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS AND ACCESSORIES DESCRIBED IN THIS SERVICE INVOICE AND THE ACCOMPANYING WORK ORDER.

SIGNATURE

BY MAKING THIS PURCHASE, YOU ACKNOWLEDGE AND AGREE TO CNH INDUSTRIALS PRIVACY PRACTICES AS DESCRIBED IN OUR PRIVACY NOTICE AVAILABLE HERE - [HTTPS://WWW.MYCNHSTORE.COM/US/EN/DEFAULT/PRIVACYNOTICE](https://www.mycnhstore.com/us/en/default/privacynotice)



PO Box 743, Highway 16 East, Lloydminster SK S9V 1C1 • www.novlanbros.com

GST# 10980 4724 RT0001

Phone: (306) 825-6141 • Fax: (306) 825-9896 • Toll Free: 1-877-344-4433

MacDon

SALFORD

BOURGAULT Pursuing Perfection

SO # 302173

SERVICE ORDER CUSTOMER COPY



Printed 07/11/2025 8:46:19 AM

User AKS Page 3

Customer No CO0142



Term CHEQUE

Advisor Damond Souster Promised 07/20/2022 9:54 AM Tag#
Shop S1 Opened 07/19/2022 10:54 AM Location
Priority Cashiered 08/18/2022 2:08 PM PO #

License	Odom In	Odom Out	In Service Date	Stock No
	1391	1391		
Year	Make	Model	Model Number	Colour
2022	JOB	MISC JOB		
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
//				
Engine	Fleet #			

- Correction
- Remove wheel motor access cover
 - Washed wheel drive motor
 - Drove unit around to get oil hot
 - Inspected and found shaft seal was leaking
 - Ordered parts
 - Supported unit up off the ground
 - Removed RH wheel
 - Used crane on service truck to support planetary
 - Unbolted planetary from the leg
 - Pulled planetary and motor out
 - Disconnected hydraulic brake line and unbolted motor
 - R&R motor shaft seal
 - Appeared the oil was leaking from the brake piston as well
 - Pulled apart brake piston and ordered new seals
 - Replaced seals and reinstalled piston
 - Lifted planetary assembly back up and attached drive motor
 - Hooked up brake line again
 - Reinstalled planetary onto the leg
 - Installed the wheel and torqued to spec
 - Rest drove unit to inspect for leaks then reinstalled inspection cover

Request	Description	Job	CSR	Status
MISC	CHECK A/C (MIGHT HAVE A LEAK)	3	DCS	Approved
Labour	Description		Type	Amount
MISC	LABOUR		CA	225.00
Rate	179.00			
			Labour Total	225.00
Correction	- Recovered a/c system			
	- Performed leak test			
	- Leak test passed			
	- Recharged system to 5 lbs			
	- Checked and verified a/c operation			
			Request Sub-total	225.00

Request	Description	Job	CSR	Status		
MISC	CHECK THAT THE HEADER IS LEVEL	4	DCS	Approved		
Labour	Description	Type	Amount			
MISC	LABOUR	CA	375.00			
Part	Description	Shp	Bin	Type	Price	Amount
CB38X34	CARR BOLT	1	BOLTBN	CSO	0.35	0.35
N38L	STOVER LOC	1	BOLTBN	CSO	0.31	0.31
Rate	179.00			Parts Total		0.66
				Labour Total		375.00
				Request Sub-total		375.66

INDEBTEDNESS IS ACKNOWLEDGED I THE SUM OF \$ _____ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS AND ACCESSORIES DESCRIBED IN THIS SERVICE INVOICE AND THE ACCOMPANYING WORK ORDER.

SIGNATURE

BY MAKING THIS PURCHASE, YOU ACKNOWLEDGE AND AGREE TO CNH INDUSTRIALS PRIVACY PRACTICES AS DESCRIBED IN OUR PRIVACY NOTICE AVAILABLE HERE - [HTTPS://WWW.MYCNHSTORE.COM/US/EN/DEFAULT/PRIVACYNOTICE](https://www.mycnhstore.com/us/en/default/privacynotice)



PO Box 743, Highway 16 East, Lloydminster SK S9V 1C1 • www.novlanbros.com

GST# 10980 4724 RT0001

Phone: (306) 825-6141 • Fax: (306) 825-9896 • Toll Free: 1-877-344-4433

MacDon

SALFORD

BOURGAULT Pursuing Perfection

SO # 302173

SERVICE ORDER CUSTOMER COPY



Printed 07/11/2025 8:46:19 AM

User AKS Page 4

Customer No CO0142



Term CHEQUE

Advisor	Damond Souster	Promised	07/20/2022 9:54 AM	Tag#
Shop	S1	Opened	07/19/2022 10:54 AM	Location
Priority		Cashiered	08/18/2022 2:08 PM	PO #

License	Odom In	Odom Out	In Service Date	Stock No
	1391	1391		
Year	Make	Model	Model Number	Colour
2022	JOB	MISC JOB		
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
//				
Engine		Fleet #		

Correction

- Checked header and found RH side was lower then the left side
- Right side had four leveling shims and the left side had none
- Tried removing a shim but it got worse
- Put removed shim on the left side and that also made it worse
- Put all four shims back on the right hand side
- Built another shim and added that to the RH side
- Rechecked and header was now sitting level

Request	Description	Job	CSR	Status
MISC	CHECK THAT RETURN TO CUT IS WORKING	5	DCS	Approved
Labour	Description		Type	Amount
MISC	LABOUR		CA	112.50
Rate	179.00			
		Labour Total		112.50
Correction	- ran header and verified the return to cut was working which it was	Request Sub-total		112.50
	- auto raise would not work but was turned off in the monitor			
	- turned that on and verified that also worked			

REPLACE KNIFE AND GAURDspaid by cheque # 96

As per customer, restocking fee put on work order for returned Bourgaault parts.

Labour	2,962.50
Parts	2,626.52
Supplies	296.25
Freight	(130.00)
Sub-Total	5,755.27
GST	287.76
Total Invoice	6,043.03
CHEQUE	6,043.03

INDEBTEDNESS IS ACKNOWLEDGED I THE SUM OF \$ _____ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS AND ACCESSORIES DESCRIBED IN THIS SERVICE INVOICE AND THE ACCOMPANYING WORK ORDER.

SIGNATURE

BY MAKING THIS PURCHASE, YOU ACKNOWLEDGE AND AGREE TO CNH INDUSTRIALS PRIVACY PRACTICES AS DESCRIBED IN OUR PRIVACY NOTICE AVAILABLE HERE - [HTTPS://WWW.MYCNHSTORE.COM/US/EN/DEFAULT/PRIVACYNOTICE](https://www.mycnhstore.com/us/en/default/privacynotice)