901-4 NOV

# TARA ENERGY SERVICES

## Low Stage Work Order Inspection

•



### Low Stage Work Order Inspection

y	Good / Service Needed	Comments
3" Dirty Side Drzin Vzive (dwg #5)		
3" Dirty Side Drain Valve (dwg #5)		
3" Dirty Side Cleanout Valve (dwg #7)		
3" Clean Side Drain Valve (dwg #8)		
3" Water Bypass/Oil Box Drain/Dirty Side Blown Down (dwg #9)		
3" Water Drain Valve (dwg #10)		
3" Water Out Valve (dwg #11)		
3" Condensate Out Valve (dwg #12)		
3" Bypass Water to Condensate Valve (dwg #13)		
3" Water Leg Upstream of Y- Strainer Valve (dwg #14)		
3" Condensate Leg Upstream of Y-Strainer Valve (dwg #15)		
Condensate Leg V-Ball Valve (dwg #20)		
Condensate Leg V-Ball Valve (dwg #21)		
3" Downstream of Turbine, Condensate Leg (dwg #22)		
3" Downstream of Turbine, Water Leg (dwg #23)		
3" Condensate Bypass Valve (dwg #24)		
3" Water Bypass Valve (dwg #25)		
4" Gas Out Upstream of V-Cone Valve (dwg #26)		
2" Gas Out Upstream of V-Cone Valve		
4" Gate Valve (dwg #31)		
2" Dirty Side Sparge Valve (dwg #34)		
2" Clean Side Sparge Valve (dwg #35)		

#### Manways - Vessel Interior

	Good / Service Needed	Comments
Manway Dirty Side Platform		
Manway Clean Side Platform		
Visual of Sparge		
Visual of Steam line		
Visual of Weir		

#### Additional Notes:

Tank has been purged and no oilfield solids or liquids in vessel.



### Low Stage Work Order Inspection

Visual of Weir:

#### **Additional Photos:**





