

Brandt Tractor Ltd.
 Box 2949, Hwy 3
 Prince Albert, SK S6V 7M4
 (306) 763-6686

**Service
 Invoice**



INVOICE DATE	BRANCH	INVOICE NO.
27AUG25	325	9503649

SOLD TO:

ASPEN GROVE FARMS
 C/O SCOTT GALLOWAY
 BOX 1289
 SHELLBROOK, SK S0J 2E0

PAGE
1
SALE TYPE
Multi-use
CUSTOMER NO.
3500720

S ASPEN GROVE FARMS
 H C/O SCOTT GALLOWAY
 P BOX 1289
 T SHELLBROOK, SK S0J 2E0
 O

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN	AUTHORIZED BY
	306-747-9322	9503649	01	08MAY25		
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER		
JD	8870	RW8870H001268	4WD TRAC			

DESCRIPTION		AMOUNT
***** * FINANCIAL PLAN NO: 11495 * * Multi-use *****1338 AUTHORIZATION # 552492 * * PROD CODE # 724 DEALER BANK # 82001151* *****		
SERVICE CALL		
** TOTAL LABOR **		607.50
ENVIRONMENTAL FEE		6.08
>>--> SEG# 01 PRT .00 LAB 607.50 MSC	6.08	613.58
* GST/HST *		30.68
DIAGNOSE BLOWER MOTORS		
Key tractor on, verify customer complaint, opened fuse panel, checked fuse F21 for 12 volts- good, checked power at pressurizer blower- no voltage present, checked supply voltage to K3- good, checked voltage on F3 and F4- good 12 volts, checked 6 pin connector for pressurizer found power for pressurizer motor burnt into connector, cut wires on both ends of connector, connector had empty hole on other end, crimped new pins onto wires, moved wires to empty hole in connector, turned key on and pressurizer blower now functioned, circulating blower functioned but only in purge setting, removed blower resistor from AQS box, installed new resistor, tested function, circulating blower now had all speeds, control lever would intermittently not function in some modes, removed dash and removed micro switches that control which blower, installed new micro switches for		

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF \$1.50.	QST # 1220957240	DESCRIPTION	AMOUNT
I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.		TOTAL PARTS	
		TOTAL LABOR	
		MISC. CHARGES	
		SALES TAX	
X _____ SIGNATURE DATE		PLEASE PAY THIS TOTAL	**CONTINUED**

Brandt Tractor Ltd.
 Box 2949, Hwy 3
 Prince Albert, SK S6V 7M4
 (306) 763-6686

**Service
 Invoice**



INVOICE DATE	BRANCH	INVOICE NO.
27AUG25	325	9503649

SOLD TO:

ASPEN GROVE FARMS
 C/O SCOTT GALLOWAY
 BOX 1289
 SHELLBROOK, SK S0J 2E0

PAGE
2
SALE TYPE
Multi-use
CUSTOMER NO.
3500720

S ASPEN GROVE FARMS
 H C/O SCOTT GALLOWAY
 P BOX 1289
 T SHELLBROOK, SK S0J 2E0
 O

PURCHASE ORDER NO.		PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN
		306-747-9322	9503649	02	08MAY25	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY	
JD	8870	RW8870H001268	4WD TRAC			

DESCRIPTION	AMOUNT
lever, fans now worked as should in all settings. Repinned power connector for blower motors, replaced micro switches in control lever housing, replaced blower motor resistor.	
2 RE32763 SWITCH CY	104.72
1 AT456900 RESISTOR	252.81
1 57M7457 ELEC CO	6.77
** TOTAL LABOR **	6.77
AG SERVICE ACCESSORI	1,230.00
ENVIRONMENTAL FEE	110.70
	12.30
	12.30
>>--> SEG# 02 PRT 469.02 LAB 1,230.00 MSC	123.00
* GST/HST *	91.10
	1,822.02
DIAGNOSE CRANK NO START	
verified customer complaint, primed fuel system to pump and verified fuel is getting to injection pump, cranked machine-no start, loosened injection lines and cranked unit, no fuel coming out of injection pump, verified fuel shut off solenoid was getting 12 volts and functioning, keyed unit and recorded codes stored in unit, cleared codes, code 41 returned for start signal missing, deemed injection pump rack not moving to start position, customer said they would replace injection pump themselves. No action taken to repair injection pump as customer would replace themselves.	
** TOTAL LABOR **	110.00
AG SERVICE ACCESSORI	9.90
ENVIRONMENTAL FEE	1.10
	1.10

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF \$1.50. QST # 1226957240

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto.
 It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES	
SALES TAX	
PLEASE PAY THIS TOTAL	**CONTINUED**

X _____
 SIGNATURE DATE

Brandt Tractor Ltd.
 Box 2949, Hwy 3
 Prince Albert, SK S6V 7M4
 (306) 763-6686

**Service
 Invoice**



SOLD TO:

ASPEN GROVE FARMS
 C/O SCOTT GALLOWAY
 BOX 1289
 SHELLBROOK, SK S0J 2E0

INVOICE DATE	BRANCH	INVOICE NO.
27AUG25	325	9503649

PAGE
 3
 SALE TYPE
 Multi-use
 CUSTOMER NO.
 3500720

S ASPEN GROVE FARMS
 H C/O SCOTT GALLOWAY
 P BOX 1289
 T SHELLBROOK, SK S0J 2E0
 O

PURCHASE ORDER NO.		PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN
		306-747-9322	9503649	03	21MAY25	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY	
JD	8870	RW8870H001268	4WD TRAC			

DESCRIPTION						AMOUNT		
>>-->	SEG# 03	PRT	.00	LAB	110.00	MSC	11.00	121.00
		* GST/HST *					6.05	
* TOTAL GST/HST * - GST No. 899544779							127.83	

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF \$1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

DESCRIPTION	AMOUNT
TOTAL PARTS	469.02
TOTAL LABOR	1,947.50
MISC. CHARGES	140.08
SALES TAX	0.00
PLEASE PAY THIS TOTAL ➔	2,684.43

X _____
 SIGNATURE

 DATE