

2012 Kenworth T659 SN 446403

Work Order	Est. Start Da	Status	Type	Work Description	Finish Date
052112	1/09/2021	Complete	P2	Mt Isa signs to supply stickers as per quote	1/09/2021
052985	10/09/2021	Complete	M1	cuts plates as per Rob dean	10/09/2021
053264	16/09/2021	Complete	P2	Sign write as required	16/09/2021
053410	17/09/2021	Complete	P2	B&H replace Drive springs	17/09/2021
053427	17/09/2021	Complete	P2	rear uni on jack shaft u/s	17/09/2021
053458	17/09/2021	Complete	P2	check over before leaving	17/09/2021
053954	24/09/2021	Complete	P2	Enzed replace hydr hoses	24/09/2021
054246	5/10/2021	Complete	P2	B&H supply jackshaft, 2 x front & rear torque rods	5/10/2021
054251	5/10/2021	Complete	P2	Kennys elect repair a/c faults	5/10/2021
054309	5/10/2021	Complete	P2	B&H supply parts as per quote	5/10/2021
054380	26/09/2021	Complete	P2	Locate wire existing in cab to run fridge. Check power	26/09/2021
055674	22/10/2021	Complete	P2	Kennys Repair a/c as required	22/10/2021
055699	25/10/2021	Complete	P2	Bayswater Radiators to supply change over radiator to suit	25/10/2021
055744	26/10/2021	Complete	P2	B&H 2 x evaporators A/C	26/10/2021
055795	26/09/2021	Complete	P2	Locate wire existing in cab to run fridge, check power	26/09/2021
056033	1/11/2021	Complete	P2	B&H supply fan assem etc as per quote	1/11/2021
056298	7/11/2021	Complete	P1	C-(A) 250HR SERVICE @ 26,809 (26,750) HR TKP KENWORTH T659	3/10/2021
056686	12/11/2021	Complete	P1	C-(C) 1000HR SERVICE @ 26,997 (27,000) HR TKP KENWORTH T659	22/10/2021
056951	29/10/2021	Complete	P2	Replaced AC fans	29/10/2021
056952	29/10/2021	Complete	P2	Replaced radiator as was leaking	29/10/2021
057117	26/10/2021	Complete	P2	Replaced evaporator, replaced aluminium pipe from evaporator	26/10/2021
057555	22/11/2021	Complete	P2	SK Mech Repairs, EGR faults, valve sets	22/11/2021
057843	29/11/2021	Complete	P2	Cummins supply EGR diff pressure hose & fans for condensers	29/11/2021
057967	1/12/2021	Complete	P2	Supply 4 x N70ZZ batteries @ 27270 hours	1/12/2021
057990	2/12/2021	Complete	P2	Cummins supply exhaust rocker lever	2/12/2021
058266	6/12/2021	Complete	P2	Replace seized altinator @ 27295 hours	6/12/2021
058964	14/12/2021	Complete	P2	Fit Guardian Seeing System	14/12/2021
059026	27/11/2021	Complete	P2	Tune up. EGR Differential. pressure hose. 3684392. Crank	27/11/2021
059052	7/11/2021	Complete	P7	Remove all drive tyres. Clean Parts. Fit 2nd hand drive	7/11/2021
059054	16/11/2021	Complete	P2	Removed/replaced damaged front door ram with new fittings,	16/11/2021
059635	2/12/2021	Complete	P2	1-SV-37/ Replace crankcease pressure sensor/plug 30cm.	2/12/2021
059707	26/12/2021	Complete	P1	C-(A) 250HR SERVICE @ 27,250 (27,250) HR TKP KENWORTH T659	2/12/2021
059817	10/01/2022	Complete	P2	B&H supply steer springs, shackle pins & u bolts	10/01/2022

059906	10/01/2022	Complete	P2	Cummins to repair coolant/fuel issues	10/01/2022
061447	2/02/2022	Complete	P2	SOS Elect to repair A/C and other issues @ 27576 hrs	2/02/2022
061549	2/02/2022	Complete	P2	B&H supply A/C parts as needed	2/02/2022
062089	29/01/2022	Complete	P2	Replace RH steer spring.	29/01/2022
062090	29/01/2022	Complete	P2	RH steer hub seal.	29/01/2022
062093	29/01/2022	Complete	P2	Fit top hat and stack.	29/01/2022
062739	15/02/2022	Complete	P2	B&H supply 4 x sets drive brakes, drums, scams, all bushes	15/02/2022
063397	23/02/2022	Complete	P2	Supply RW	23/02/2022
063447	24/02/2022	Complete	P2	Global install camera	24/02/2022
063759	2/03/2022	Complete	P2	RCS supply & Install UHF radio	2/03/2022
063931	11/02/2022	Complete	P2	Changed door latch and door opener.	11/02/2022
064949	14/01/2022	Complete	P1	(A) 250HR SERVICE @ (27,500) HR TKP KENWORTH T659	14/01/2022
064957	23/02/2022	Complete	P1	(A) 250HR SERVICE @ 27,755 (27,750) HR TKP KENWORTH T659	23/02/2022
065371	11/03/2022	Complete	P1	(C) 1000HR SERVICE @ 27,939 (28,000) HR TKP KENWORTH T659	11/03/2022
065386	23/03/2022	Complete	P2	New fleet numbers for trailers.	23/03/2022
065633	29/03/2022	Complete	P2	Cummins to repair breakdown at Barkley Homestead, truck	29/03/2022
065653	12/03/2022	Complete	P2	Rose joints unserviceable.	12/03/2022
065654	12/03/2022	Complete	P2	Exhaust down pipe clamp wrong.	12/03/2022
065655	12/03/2022	Complete	P2	Steering shaft excess play	12/03/2022
065657	12/03/2022	Complete	P2	Engine fan cracked.	12/03/2022
065658	12/03/2022	Complete	P2	A/C belt tensioner Unserviceable.	12/03/2022
065660	12/03/2022	Complete	P2	Wrong engine mounts fitted.	12/03/2022
065876	29/03/2022	Complete	P1	(A) 250HR SERVICE @ 28,089 (28,250) HR TKP KENWORTH T659	29/03/2022
067293	5/04/2022	Complete	P2	Changed cab shockies.	5/04/2022
067358	26/04/2022	Complete	P2	B&H supply engine harness as quoted @ 28300hrs	26/04/2022
067672	10/04/2022	Complete	P2	Replace bonnet indicator/airbags/air regulator/grease line	10/04/2022
067921	10/04/2022	Complete	P1	(A) 250HR SERVICE @ 28,336 (28,500) HR TKP KENWORTH T659	10/04/2022
069142	11/05/2022	Complete	P2	Replacement Radiator to suit EGR	11/05/2022
069470	29/04/2022	Complete	P2	Air leak & brake adjustment	29/04/2022
070154	27/05/2022	Complete	P2	B&H supply valve bendix @ 28809hrs	27/05/2022
070613	26/04/2022	Complete	P1	Double Up(A) 250HR SERVICE @ 28,560 (28,500) HR KENWORTH	26/04/2022
071210	13/06/2022	Complete	P2	Cummins fit engine & OBD harness & radiator @ 29062hrs	13/06/2022
071281	26/05/2022	Complete	P2	TRACTION RELAY VALVE	26/05/2022
071327	18/05/2022	Complete	P1	(A) 250HR SERVICE @ 28,809 (28,750) HR TKP KENWORTH T659	18/05/2022
071731	12/05/2022	Complete	P2	GOVENOR VALVE	12/05/2022

072177	21/06/2022	Complete	P2	B&H supply 2 x red dot condenser fans and other A/C comp @	21/06/2022
072193	21/06/2022	Complete	P2	Murphys 6 spoke drive hub @ 29120hrs	21/06/2022
072387	24/06/2022	Complete	P2	Cummins supply solinoid to suit @ 29167hrs	24/06/2022
072473	27/06/2022	Complete	P2	2X HIGH BEAM 7" GREAT WHITE HEAD LIGHTS.	27/06/2022
072514	11/06/2022	Complete	P2	MAKE UP HYD HOSES	11/06/2022
072670	12/06/2022	Complete	P2	1000HR SERVICE AND REPAIRS	13/06/2022
072672	13/06/2022	Complete	P2	SERVICE AND REPAIRS	13/06/2022
073334	12/06/2022	Complete	P1	(C) 1000HR SERVICE @ 29,070 (29,000) HR TKP KENWORTH T659	12/06/2022
074017	19/06/2022	Complete	P2	ac regas	19/06/2022
074215	29/06/2022	Complete	P2	FUEL LEAK	29/06/2022
074482	23/07/2022	Complete	P2	REPLACE ROAD TRAIN SIGN	23/07/2022
074483	25/07/2022	Complete	P2	ENG OIL LEAK AT FILTER	25/07/2022
074545	26/07/2022	Complete	P2	NPR157995 supply Holland Jaw kit, pin kit, bush kit for	26/07/2022
075676	12/08/2022	Complete	P2	NPR047435 B&H supply power steering pump and gasket @ 29547	12/08/2022
075685	12/08/2022	Complete	P2	NPR047445 Enzed supply fittings for power steering pump @	12/08/2022
075971	2/07/2022	Complete	P1	(A) 250HR SERVICE @ 29,315 (29,250) HR TKP KENWORTH T659	2/07/2022
075973	26/07/2022	Complete	P1	(A) 250HR SERVICE @ 29,562 (29,500) HR TKP KENWORTH T659	26/07/2022
077002	6/09/2022	Complete	P2	NPR157198 Enzed supply hot hose @ 29710hrs	6/09/2022
077581	21/09/2022	Complete	P2	NPR157221 Cummins conduct engine repairs & air compressor @	21/09/2022
077691	26/07/2022	Complete	P2	REPLACE AIR TANK DRAIN COCKS	26/07/2022
078697	30/09/2022	Complete	P2	replace turbo and VGT	30/09/2022
078866	29/09/2022	Complete	P2	HUB LEAK, AIR LEAK	29/09/2022
079049	17/09/2022	Complete	P2	DRIVE WHEEL SEAL LEAKING	17/09/2022
079051	17/09/2022	Complete	P2	EXHAUST LEAK	17/09/2022
079377	4/10/2022	Complete	P2	AIR BRAKE VALVE FAULTY, REMOVED AND REPLACED WITH NEW VALVE	4/10/2022
079378	4/10/2022	Complete	P2	DASH CAM BRACKET BROCKEN, REMOVED AND MODIFIED BRACKET	4/10/2022
079657	13/10/2022	Complete	P2	ADJUST CLUTCH	13/10/2022
079856	16/10/2022	Complete	P3	Callout breakdown on fuel pump fault	16/10/2022
079859	16/10/2022	Complete	PM	Repairs to Icepack	16/10/2022
080007	17/10/2022	Complete	P2	REPAIR CHASSIS RAIL	17/10/2022
081019	29/10/2022	Complete	P2	Check engine light	29/10/2022
081168	1/11/2022	Complete	P7	Replace steer tyres	1/11/2022
081623	17/09/2022	Complete	P1	(C) 1000HR SERVICE @ 29,961 (30,000) HR TKP KENWORTH T659	17/09/2022
081913	1/11/2022	Complete	P2	Replaced batteries	1/11/2022
081938	8/11/2022	Complete	P7	Removed & replaced steer tyres with x2 new steers	8/11/2022

082057	10/11/2022	Complete	PM	Roadworthy inspection	10/11/2022
082125	2/11/2022	Complete	P2	Hooked up 778 to 769 trailers, changed ryco's around so	2/11/2022
083345	22/11/2022	Complete	P2	Replaced Steering Unis	22/11/2022
083653	29/11/2022	Complete	PM	supply mine sticker	29/11/2022
084788	1/11/2022	Complete	P1	(A) 250HR SERVICE @ 30,414 (30,250) HR TKP KENWORTH T659	1/11/2022
084789	1/11/2022	Complete	P1	(A) 250HR SERVICE @ 30,414 (30,500) HR TKP KENWORTH T659	1/11/2022
086435	22/11/2022	Complete	P1	(A) 250HR SERVICE @ 30,733 (30,750) HR TKP KENWORTH T659	22/11/2022
086649	22/12/2022	Complete	P2	Replaced RH Bonnet Spring	22/12/2022
086671	28/12/2022	Complete	PM	Replace uni-joints and centre bearing	28/12/2022
086694	3/01/2023	Complete	PM	Replace seat assy	3/01/2023
086736	24/12/2022	Complete	P7	Replaced 8 x drive tyres	24/12/2022
086778	28/12/2022	Complete	P2	Replace RH Windscreen	28/12/2022
086779	27/12/2022	Complete	P2	Repair taillight wiring	27/12/2022
086934	30/12/2022	Complete	P2	Oil pressure sensor fault replaced faulty sensor	30/12/2022
087251	21/12/2022	Complete	P1	(C) 1000HR SERVICE @ 31,056 (31,000) HR TKP KENWORTH T659	26/12/2022
087252	13/01/2023	Complete	P1	(A) 250HR SERVICE @ 31,437 (31,250) HR TKP KENWORTH T659	28/01/2023
087253	5/02/2023	Complete	P1	(A) 250HR SERVICE @ 31,437 (31,500) HR TKP KENWORTH T659	28/01/2023
087254	7/03/2023	Complete	P1	(A) 250HR SERVICE @ 31,963 (31,750) HR TKP KENWORTH T659	7/03/2023
087255	7/03/2023	Complete	P1	(C) 1000HR SERVICE @ 31,963 (32,000) HR TKP KENWORTH T659	7/03/2023
087256	9/04/2023	Complete	P1	(A) 250HR SERVICE @ 32,341 (32,250) HR TKP KENWORTH T659	9/04/2023
087257	6/05/2023	Complete	P1	(A) 250HR SERVICE @ 32,681 (32,500) HR TKP KENWORTH T659	6/05/2023
087258	6/05/2023	Complete	P1	(A) 250HR SERVICE @ 32,681 (32,750) HR TKP KENWORTH T659	6/05/2023
087259	23/05/2023	Complete	P1	(C) 1000HR SERVICE @ 32,992 (33,000) HR TKP KENWORTH T659	23/05/2023
087260	19/06/2023	Complete	P1	(A) 250HR SERVICE @ 33,283 (33,250) HR TKP KENWORTH T659	19/06/2023
087443	9/01/2023	Complete	PM	Replace radiator assy	9/01/2023
088326	17/01/2023	Complete	PM	Replace diff wear pads	17/01/2023
089037	24/01/2023	Complete	P2	REFURB DRIVERS SEAT	24/01/2023
089052	21/01/2023	Complete	P2	Tightened loose exhaust clamps	21/01/2023
089298	16/01/2023	Complete	P2	Both drive springs replace	16/01/2023
089299	10/01/2023	Complete	P2	Radiator leaking	10/01/2023
089300	11/01/2023	Complete	P2	Finish fitting radiator & plumbing up fit new seat and seat	11/01/2023
089939	30/01/2023	Complete	P2	Supply wheel alignment	30/01/2023
090034	26/01/2023	Complete	P2	1 x AC filter cover - gearbox filter & oil	26/01/2023
090040	28/01/2023	Complete	P2	Removed & refit new torque rod bushes front and rear diff	28/01/2023
090041	28/01/2023	Complete	P2	Inspect tie rod end on R/H side on tie rod bar and was u/s,	28/01/2023

090042	28/01/2023	Complete	P2	Replace pressure protection valve	28/01/2023
090554	2/02/2023	Complete	P2	Installed new dust blower in cab	2/02/2023
090666	7/02/2023	Complete	P2	Replace drive brakes	7/02/2023
091266	11/02/2023	Complete	P2	Brakes not holding	11/02/2023
091277	10/02/2023	Complete	P2	Derate & check engine	10/02/2023
091790	14/02/2023	Complete	P2	Leaking hubseal	14/02/2023
092262	22/02/2023	Complete	P2	Parts to repair wiper and fuel cooler faults	22/02/2023
092387	20/02/2023	Complete	P2	C/bearing	20/02/2023
092447	22/02/2023	Complete	P2	w/screen wipers n/w	22/02/2023
092458	22/02/2023	Complete	P2	Fixed Anderson plug on primer mover	22/02/2023
092949	1/03/2023	Complete	P7	Replace drive tyres	1/03/2023
093388	8/03/2023	Complete	P2	Repairs to Horton kit	8/03/2023
093409	8/03/2023	Complete	P2	Supply air fittings dkt isa512816	8/03/2023
093427	8/03/2023	Complete	P2	Repairs to driveline	8/03/2023
093611	1/03/2023	Complete	P2	Black button not working	1/03/2023
093675	28/02/2023	Complete	P2	A/C not blowing	28/02/2023
095312	24/03/2023	Complete	P2	Supply exchange EGR ISX DPF Engine	24/03/2023
095402	27/03/2023	Complete	P2	Replace clutch assy	27/03/2023
095411	27/03/2023	Complete	P2	Replace sump gasket	27/03/2023
096406	9/04/2023	Complete	P2	Replace hyd hoses dkt 20540	9/04/2023
096471	11/04/2023	Complete	P2	Replace hot hose dkt 21572	11/04/2023
096597	12/04/2023	Complete	P2	Plugging Oil Filters / High Blowby	12/04/2023
097201	21/04/2023	Complete	P2	Replace Horton fan blade	21/04/2023
097253	22/04/2023	Complete	P7	Replace drive tyres	22/04/2023
097271	24/04/2023	Complete	P2	Replace crank shaft pulley	24/04/2023
097323	26/04/2023	Complete	P2	Replace alternator	26/04/2023
097361	25/04/2023	Complete	P2	Went to Loretta & replaced alternator on prime mover as was	25/04/2023
097495	22/04/2023	Complete	P7	Replaced x 4 Drive Tyres	22/04/2023
097496	22/04/2023	Complete	P2	Replaced brake booster on right hand side 1st diff	22/04/2023
097660	18/04/2023	Complete	P2	@32478hrs swap out engine for rebuilt engine, had one put in	18/04/2023
097787	2/05/2023	Complete	P2	RE-RATE TRO 165,000T GCM	2/05/2023
097853	3/05/2023	Complete	P2	Repair Dpf fault and derating	3/05/2023
098034	8/05/2023	Complete	P2	Replace air bags	8/05/2023
098037	8/05/2023	Complete	P2	Replace Ac control panel	8/05/2023
098674	18/05/2023	Complete	P2	Replace Ac hose	18/05/2023

098676	18/05/2023	Complete	P2	Repairs to Ac fault	18/05/2023
098928	22/05/2023	Complete	P2	Replace bonnet mounts and bushes	22/05/2023
099104	27/04/2023	Complete	P2	Replace climate control module	27/04/2023
099311	24/05/2023	Complete	P2	Replace torque rod bushes	24/05/2023
099407	25/05/2023	Complete	P2	Supply and fit rops system	25/05/2023
099646	29/05/2023	Complete	P2	Replace gearbox assy	29/05/2023
099802	30/05/2023	Complete	P2	Replace hyd hoses dkt 21478	30/05/2023
100070	5/06/2023	Complete	P2	Replace seat covers and floor matts	5/06/2023
101137	22/05/2023	Complete	P2	Added 4 Litres of Engine Oil	22/05/2023
101387	20/06/2023	Complete	P2	Replaced Centre Bearing	20/06/2023
101645	11/07/2023	Complete	P1	(A) 250HR SERVICE @ 33,543 (33,500) HR TKP KENWORTH T659	11/07/2023
101646	7/08/2023	Complete	P1	(A) 250HR SERVICE @ 33,998 (33,750) HR TKP KENWORTH T659	7/08/2023
101647	7/08/2023	Complete	P1	(C) 1000HR SERVICE @ 33,998 (34,000) HR TKP KENWORTH T659	7/08/2023
101648	30/08/2023	Complete	P1	(A) 250HR SERVICE @ 34,252 (34,250) HR TKP KENWORTH T659	30/08/2023
102230	29/06/2023	Complete	P2	Replace Engine Air Filters + Blown Hose "hydraulic"	29/06/2023
102292	3/07/2023	Complete	P2	Replace turntable top	3/07/2023
102488	4/07/2023	Complete	P2	Replace torque rod	4/07/2023
102609	31/07/2023	Complete	P2	Bears Mech conduct Certificate of Inspection/NHVAS	31/07/2023
102972	27/06/2023	Complete	P3	Fabbros diagnose & repair Engine fault as attached docs.	27/06/2023
102979	12/07/2023	Complete	P2	Replace KW K048634 VALVE-SR7	12/07/2023
103401	21/07/2023	Complete	P2	NPR 101504 STEER TYRES AND BALANCE BAGS	21/07/2023
103463	23/07/2023	Complete	P2	NPR 101520 ROTATING BEACONS	23/07/2023
103826	26/07/2023	Complete	P2	Truck de-rated on Mcnamara Rd (CP7)	26/07/2023
104199	4/08/2023	Complete	P2	Replace compressor	4/08/2023
104991	2/08/2023	Complete	P2	Replaced R/H Lower Bonnet Strap	2/08/2023
104996	7/08/2023	Complete	P2	Changed bell crank bearing x 2	7/08/2023
104997	8/08/2023	Complete	P2	Front Track Rods u/s	8/08/2023
105212	12/08/2023	Complete	P2	Replace diff assy	12/08/2023
105708	19/08/2023	Complete	P7	NPR 101706 DRIVE TYRES WORN	19/08/2023
105779	18/08/2023	Complete	P7	Replaced all drive tyres with new (Remington R690II)	18/08/2023
105826	21/08/2023	Complete	P2	Quote to repair diff 161031722812	21/08/2023
106365	30/08/2023	Complete	P2	Blowby Check	30/08/2023
106383	30/08/2023	Complete	P2	Replace jack and triangles	30/08/2023
106971	6/09/2023	Complete	P7	Replace steer tyre	6/09/2023
107153	24/08/2023	Complete	P2	LHS brake booster leaking	24/08/2023

107154	24/08/2023	Complete	P2	Removed & replaced booster hose	24/08/2023
107286	11/09/2023	Complete	P2	Replace rear diff torque rod bushes	11/09/2023
107293	31/08/2023	Complete	P2	2 x new tail lights and side marker lights, rewired to the	31/08/2023
107418	12/09/2023	Complete	P2	Replace six rod bolts	12/09/2023
107634	14/09/2023	Complete	P2	Replace strip light	14/09/2023
107644	14/09/2023	Complete	P2	Rekit turntable	14/09/2023
107697	14/09/2023	Complete	P2	Replace armrest	14/09/2023
107773	15/09/2023	Complete	P2	Replace engine belts	15/09/2023
107777	13/09/2023	Complete	P1	(A) 250HR SERVICE @ 34,498 (34,500) HR TKP KENWORTH T659	13/09/2023
107778	5/10/2023	Complete	P1	(A) 250HR SERVICE @ 34,849 (34,750) HR TKP KENWORTH T659	5/10/2023
107779	8/11/2023	Complete	P1	(C) 1000HR SERVICE @ 35,245 (35,000) HR TKP KENWORTH T659	8/11/2023
107780	8/11/2023	Complete	P1	(A) 250HR SERVICE @ 35,245 (35,250) HR TKP KENWORTH T659	8/11/2023
107781	12/12/2023	Complete	P1	(A) 250HR SERVICE @ 35,819 (35,500) HR TKP KENWORTH T659	12/12/2023
107782	12/12/2023	Complete	P1	(A) 250HR SERVICE @ 35,819 (35,750) HR TKP KENWORTH T659	12/12/2023
107827	16/09/2023	Complete	P2	Replace door sill assy	16/09/2023
107912	18/09/2023	Complete	P2	Replace Starter motor and fan	18/09/2023
107935	19/09/2023	Complete	P2	Replace batteries	19/09/2023
108120	21/09/2023	Complete	P2	Replace Lubecore solenoid	21/09/2023
108923	29/09/2023	Complete	P7	Removed and replace steer tyres with x2 new tyres	29/09/2023
109397	2/10/2023	Complete	P2	Found faulty socket + harness between T3 +T4	2/10/2023
109488	16/10/2023	Complete	P2	Replace drag ling and steer booster	16/10/2023
109534	4/10/2023	Complete	P2	Front diff oil leak	4/10/2023
109535	3/10/2023	Complete	P2	R/H front drive hub seal	3/10/2023
110341	25/10/2023	Complete	P2	Suspension Air cab	25/10/2023
110910	31/10/2023	Complete	P7	Replace drive tyres	31/10/2023
111085	3/11/2023	Complete	P2	Replace air horn valve	3/11/2023
111650	8/11/2023	Complete	P2	Rerouted + repaired alt wiring	8/11/2023
111694	30/10/2023	Complete	P7	Removed & replace all 8 drive wheels + tyres	30/10/2023
111697	1/11/2023	Complete	P2	Breakdown	1/11/2023
111764	10/11/2023	Complete	P2	TEFLON TURNTABLE WEAR PLATE KIT TKP778	10/11/2023
111814	10/11/2023	Complete	P2	BATTERIS TKP778	10/11/2023
111854	10/11/2023	Complete	P2	A/C CABIN FILTER HOUSING TKP778	10/11/2023
111881	13/11/2023	Complete	P2	NPR 101404 A/C CABIN FILTER HOUSING	13/11/2023
111882	13/11/2023	Complete	P2	NPR 101054 SPRING HANGERS Q	13/11/2023
112133	10/11/2023	Complete	P2	Drag link u/s	10/11/2023

112134	10/11/2023	Complete	P2	Replace turntable + feet + bushes	10/11/2023
112144	9/11/2023	Complete	P2	Installed MT Data cam + tracking system	9/11/2023
112183	9/11/2023	Complete	P2	RHR reline	9/11/2023
112206	4/11/2023	Complete	P2	A/C not working	4/11/2023
112207	30/10/2023	Complete	P7	Remove & replace all 8 drive wheel & tyres	30/10/2023
112208	14/11/2023	Complete	P2	Install midi fuse link to Anderson plug	14/11/2023
112242	5/11/2023	Complete	P2	Tarp not working trailer 3	5/11/2023
112298	20/11/2023	Complete	P2	Replace Ac compressor	20/11/2023
112585	24/11/2023	Complete	P2	Replace steer tyre	24/11/2023
112637	26/11/2023	Complete	P2	Replace oil drain tube	26/11/2023
112651	27/11/2023	Complete	P2	Replace drive wheel studs	27/11/2023
112710	27/11/2023	Complete	P2	Replace steer tyres	27/11/2023
112809	29/11/2023	Complete	P2	Replace starter motor	29/11/2023
112839	28/11/2023	Complete	P2	Replaced 4 x batteries	28/11/2023
112988	4/12/2023	Complete	P2	Replace Spring packs and fittings	4/12/2023
112990	4/12/2023	Complete	P2	Repairs to king pins	4/12/2023
113001	26/11/2023	Complete	P2	Broken steer spring	26/11/2023
113052	24/11/2023	Complete	P7	Replaced LH & RH steer tyres	24/11/2023
113734	1/12/2023	Complete	P2	Crankcase filter	1/12/2023
114196	9/01/2025	Complete	P5	MT data - Monthly Service & Licence Fees for all *2024	9/01/2025
114413	10/12/2023	Complete	P2	Kingpins worn, removed & replaced kingpins	10/12/2023
114711	28/12/2023	Complete	P2	Recover unit back to w/shop	28/12/2023
115176	10/01/2024	Complete	P2	Quote for Engine Rebuild	10/01/2024
115243	20/12/2023	Complete	P2	Replace brake booster	20/12/2023
115324	24/12/2023	Complete	P2	Replace blocked crank case filter	24/12/2023
115834	17/01/2024	Complete	P2	Replace steer brake booster	17/01/2024
115907	26/11/2023	Complete	P2	Engine oil leaks heavy	26/11/2023
116200	21/01/2024	Complete	P2	Replace starter motor	21/01/2024
116201	21/01/2024	Complete	P7	1 x Dunlop 385/80R22.5	21/01/2024
116354	15/01/2024	Complete	P7	8 x OGreen drive tyres	15/01/2024
116355	17/01/2024	Complete	P2	LHS indicator on guard inop	17/01/2024
116371	16/01/2024	Complete	P2	1st drive LHS booster leaking	16/01/2024
116663	26/11/2023	Complete	P2	Replaced crank case oil drain hose	26/11/2023
116668	25/01/2024	Complete	P2	ALTERNATOR TKP778	25/01/2024
116760	29/01/2024	Complete	P2	BATTERIES TKP00778	29/01/2024

116894	27/01/2024	Complete	P2	Take off both LHS front to realign wheels on truck	27/01/2024
116907	24/01/2024	Complete	P2	Alternator failure	24/01/2024
117228	12/12/2023	Complete	P1	2023-2024 ** NHVAS INSPECTION - Passed 12.12.2023	12/12/2023
117662	17/01/2024	Complete	P1	(C) 1000HR SERVICE @ 36,086 (36,000) HR TKP KENWORTH T659	17/01/2024
117962	8/02/2024	Complete	P2	Replace temp sensor	8/02/2024
118084	11/02/2024	Complete	P2	Replace water pump	11/02/2024
118258	9/01/2025	Complete	P5	TMA Higher Mass Fees for all *2024	9/01/2025
118259	7/02/2024	Complete	P2	90 degree bend in exhaust just after DPF, crack around V bad	7/02/2024
118261	9/02/2024	Complete	P2	Headlight fault	9/02/2024
118697	16/02/2024	Complete	P2	Replaced tipping valve switch for 1st trailer in cab	16/02/2024
119079	16/02/2024	Complete	P7	2 x steer tyres	16/02/2024
119426	25/02/2024	Complete	P2	Repaired head light wiring and tail light wiring	25/02/2024
119427	24/02/2024	Complete	P2	Front diff torque rod bushes n/w	24/02/2024
119499	24/02/2024	Complete	P2	Remove and replace starter motor	24/02/2024
119505	19/02/2024	Complete	P2	Stop engine light	19/02/2024
119879	4/03/2024	Complete	P2	OEM ENGINE HARNESS TKP778	4/03/2024
119982	5/03/2024	Complete	P2	Recover truck back to llm	5/03/2024
120208	23/02/2024	Complete	P1	(A) 250HR SERVICE @ 36,628 (36,250) HR TKP KENWORTH T659	23/02/2024
120209	23/02/2024	Complete	P1	(A) 250HR SERVICE @ 36,628 (36,500) HR TKP KENWORTH T659	23/02/2024
120857	2/03/2024	Complete	P2	RH headlight not working, wiring connector corroded.	2/03/2024
120858	10/03/2024	Complete	P7	8 x 11r22.5 Ogreen drive tyres	10/03/2024
121170	20/03/2024	Complete	P2	Replace asst harnesses	20/03/2024
121593	20/07/2024	Complete	P1	(A) 250HR SERVICE @ 36,920 (36,750) HR TKP KENWORTH T659	20/07/2024
121594	20/07/2024	Complete	P1	(C) 1000HR SERVICE @ 36,920 (37,000) HR TKP KENWORTH T659	20/07/2024
121595	9/09/2024	Complete	P1	(A) 250HR SERVICE @ 37,184 (37,250) HR TKP KENWORTH T659	9/09/2024
121596	12/10/2024	Complete	P1	(A) 250HR SERVICE @ 37,479 (37,500) HR TKP KENWORTH T659	12/10/2024
121597	4/12/2024	Complete	P1	(A) 250HR SERVICE @ 37,761 (37,750) HR TKP KENWORTH T659	4/12/2024
126755	28/05/2024	Complete	P2	Replace lhs air tank elbow and clamps	28/05/2024
126756	28/05/2024	Complete	P2	Rewire truck after fire damage	28/05/2024
127284	3/06/2024	Complete	P2	Replace batteries n70zz	3/06/2024
128003	12/06/2024	Complete	P2	Supply hyd hoses dkt 23359	12/06/2024
128043	12/06/2024	Complete	P2	Replace hot hose	12/06/2024
129093	20/06/2024	Complete	P2	Replace coolant module and harness	20/06/2024
129541	26/06/2024	Complete	P2	Replace power steering hoses	26/06/2024
130067	3/07/2024	Complete	P2	Replace trailer valve	3/07/2024

130209	13/06/2024	Complete	P2	Get handover & continue on as required, cut, fit & secure	13/06/2024
130743	13/07/2024	Complete	P2	A/C not cold	13/07/2024
130794	5/07/2024	Complete	P2	Replace driver's seat	5/07/2024
131414	14/07/2024	Complete	P2	Find not starting, basic tests carried out & find problem in	14/07/2024
131566	23/07/2024	Complete	P2	Replace driveline front half	23/07/2024
132186	1/08/2024	Complete	P2	A/C not working	1/08/2024
132240	5/08/2024	Complete	P2	POST WORK CHECK Replace Ac condenser assy	5/08/2024
133039	14/08/2024	Complete	P2	Replace pto assy	14/08/2024
133085	15/08/2024	Complete	P2	Replace Steering box and pitman arm	15/08/2024
133195	16/08/2024	Complete	P2	Replaced tie rod due to lots of movement in ball joints	16/08/2024
133411	19/08/2024	Complete	P2	Starting fault	19/08/2024
133530	21/08/2024	Complete	P2	Replace ignition barrel	21/08/2024
134782	9/09/2024	Complete	P2	Replace sump gasket	9/09/2024
135075	10/09/2024	Complete	P2	Engine fan u/s	10/09/2024
135076	9/09/2024	Complete	P2	Sump leaking	9/09/2024
135097	10/09/2024	Complete	P2	Radiator support bracket bushes	10/09/2024
135098	10/09/2024	Complete	P2	Bonnet hinge bracket and bushes	10/09/2024
135909	21/09/2024	Complete	P2	LH rear, removed & replaced mudguard	21/09/2024
136452	18/01/2025	Complete	P1	2024-2025 ** NHVAS INSPECTION - Passed 18.01.2025	18/01/2025
136862	4/10/2024	Complete	P7	2 x roadway steer tyres	4/10/2024
137650	13/10/2024	Complete	P2	PTO line leaking, pto line replaced	13/10/2024
137778	21/10/2024	Complete	P2	Replace indicator multifunction switch	21/10/2024
137780	21/10/2024	Complete	P2	Replace slack adjusters	21/10/2024
137893	21/10/2024	Complete	P2	Critical Works Steering Toe Adjustment 21.10.2024	21/10/2024
138009	23/10/2024	Complete	P2	Repairs to Ac fault	23/10/2024
139502	12/11/2024	Complete	P7	8 x 11r22.5 roadway drive tyres	12/11/2024
139682	11/11/2024	Complete	P2	Install new guardian lte controller	11/11/2024
139920	20/11/2024	Complete	P2	Replace dog box latches	21/11/2024
140007	22/11/2024	Complete	P2	POST WORK CHECK Repair Jake brake fault	30/11/2024
140215	1/01/2025	In Progress	P5	TMA Higher Mass Fees for all *2025	
140247	27/11/2024	Complete	P2	Exhaust brake not working	27/11/2024
140332	29/11/2024	Complete	P2	Welding repairs to bullbar	29/11/2024
140365	2/12/2024	Complete	P2	Replace Turbo assy	2/12/2024
140556	1/01/2025	Planned	P5	MT data - Monthly Service & Licence Fees for all *2025	
140750	5/12/2024	Complete	P2	Replace power steering pump	4/12/2024

140775	18/01/2025	Complete	P1	(C) 1000HR SERVICE @ 38,200 (38,000) HR TKP KENWORTH T659	18/01/2025
140776	18/01/2025	Complete	P1	(A) 250HR SERVICE @ 38,200 (38,250) HR TKP KENWORTH T659	18/01/2025
141027	30/11/2024	Complete	P2	Oil in CAC lines	30/11/2024
141122	3/12/2024	Complete	P2	Replace steering link assy	3/12/2024
142298	27/12/2024	Complete	P2	STEERING LOCKS UP FULL LOCK, GREASED AL COMPONENTS,	27/12/2024
143599	17/01/2025	In Progress	P5	Guardian monitoring Monthly Fees for all *2025	
144914	4/04/2025	Complete	P1	(A) 250HR SERVICE @ 38,658 (38,500) HR TKP KENWORTH T659	4/04/2025
144915	4/04/2025	Complete	P1	(A) 250HR SERVICE @ 38,658 (38,750) HR TKP KENWORTH T659	4/04/2025
144916	8/05/2025	Complete	P1	(C) 1000HR SERVICE @ 38,985 (39,000) HR TKP KENWORTH T659	8/05/2025
146004	26/02/2025	Complete	P2	Replace park brake and trailer brake valves	26/02/2025
146084	27/02/2025	Complete	P2	Repairs to Ac fault	27/02/2025
146228	25/02/2025	Complete	P2	Replaced park brake valve	25/02/2025
147377	16/03/2025	Complete	P2	Brake adjusted and grease , spring pack check	16/03/2025
147603	18/03/2025	Complete	P2	Repair wiring ac compressor clutch	18/03/2025
147680	21/03/2025	Complete	P2	Replace power steer reservoir	21/03/2025
147700	21/03/2025	Complete	P2	Replace hyd fittings dkt 23516	21/03/2025
147703	21/03/2025	Complete	P2	Replace power steer pump	21/03/2025
147984	21/03/2025	Complete	P7	Replace 8 x by 11r/ 22.5 drive tyres	21/03/2025
147985	21/03/2025	Complete	P2	Removed hub, replaced seal, Cleared brakes + drum fit hub	21/03/2025
147986	21/03/2025	Complete	P7	Replaced 1 x by 385/65/22.5 steer tyre LHS	21/03/2025
148865	7/04/2025	Complete	P2	REPAIRS TO EGR COOLER LEAK	7/04/2025
149455	7/04/2025	Complete	P2	Replace a/c belt tensioner pulley & idler pulley	7/04/2025
149889	19/04/2025	Complete	P2	Replace wiring assy for LH headlight , connect wiring for	19/04/2025
151024	23/05/2025	Complete	P2	Repairs to Derate fault	23/05/2025
151675	19/06/2025	Complete	P1	(A) 250HR SERVICE @ 39,380 (39,250) HR TKP KENWORTH T659	19/06/2025
151676	22/08/2025	Complete	P1	(A) 250HR SERVICE @ 39,637 (39,500) HR TKP KENWORTH T659	22/08/2025
151677	22/09/2025	Complete	P1	(A) 250HR SERVICE @ 40,013 (39,750) HR TKP KENWORTH T659	22/09/2025
151779	17/05/2025	Complete	P2	Check drag link + tie rod ends add to report	17/05/2025
152117	28/07/2025	In Progress	P2	REPAIRS TO TRAILER LIGHT FAULT	28/07/2025
152319	30/05/2025	Complete	P2	Replace air compressor	30/05/2025
154307	28/07/2025	Complete	P2	UNHOOK AND UNLOAD	28/07/2025
154793	28/07/2025	Complete	P2	Wash	28/07/2025
154794	14/07/2025	Complete	P2	APPRAISAL	14/07/2025
154826	28/07/2025	Complete	P2	DPF fault	28/07/2025
155350	28/07/2025	Complete	P2	REPLACE DRIVE SPRINGS	28/07/2025

155490	5/08/2025	Complete	P2	SQUEALING DOES @ 1500RPM FROM IDLER / BELT AREA	5/08/2025
155491	28/07/2025	Complete	P2	Adjust clutch / free travel	28/07/2025
155493	28/07/2025	Complete	P2	Turntable pads u/s	28/07/2025
155494	31/07/2025	In Progress	P2	SLACK ADJUSTER CLEVIS PINS INCORRECT X2	
155496	28/07/2025	Complete	P2	Grease truck	28/07/2025
155620	25/07/2025	In Progress	P2	DONE...MT DATA NOT TRACKING. MDVR FAULT	25/07/2025
155624	28/07/2025	Complete	P2	Fit mudguards	28/07/2025
155678	25/07/2025	Complete	P2	Carry out brake test	25/07/2025
155749	31/07/2025	Complete	P2	WASH PITS AND CLEAN UP	31/07/2025
155851	28/07/2025	Complete	P2	MINOR REPAIRS BEFORE MT ISA TRIP	28/07/2025
157278	18/08/2025	Complete	P2	REPLACE POWER STEERING HOSES DKT 22388	18/08/2025
157508	8/09/2025	Complete	P2	REPAIRS TO COOLANT LEAK	8/09/2025
158193	4/09/2025	Complete	P2	REPLACE GEARBOX HARNESS	4/09/2025
158794	15/09/2025	Planned	P1	2025-2026 ** NHVAS INSPECTION	
159400	18/09/2025	Complete	P2	REPLACE EGR HEATER TAP	18/09/2025
159427	14/08/2025	Complete	P2	R&R COOKED PTO & PUMP REPLACE RELENE VALVE, FILLED HYD TANK	14/08/2025
159463	10/08/2025	Complete	P2	REPLACED PTO AND PTO PUMP	10/08/2025
159514	23/08/2025	Complete	P2	REPLACED ALL BATT & STARTER POWER & EARTH CABLES	23/08/2025
159518	22/08/2025	Complete	P2	REPLACEAD LEAKING SUMP GASKET	22/08/2025
159903	22/09/2025	Complete	P1	(C) 1000HR SERVICE @ 40,013 (40,000) HR TKP KENWORTH T659	22/09/2025
159908	15/10/2025	Forecast	P1	(A) 250HR SERVICE @ (40,250) HR TKP KENWORTH T659	
159909	9/11/2025	Forecast	P1	(A) 250HR SERVICE @ (40,500) HR TKP KENWORTH T659	
159910	4/12/2025	Forecast	P1	(A) 250HR SERVICE @ (40,750) HR TKP KENWORTH T659	
159911	28/12/2025	Forecast	P1	(C) 1000HR SERVICE @ (41,000) HR TKP KENWORTH T659	
159912	22/01/2026	Forecast	P1	(A) 250HR SERVICE @ (41,250) HR TKP KENWORTH T659	
160117	7/09/2025	Complete	P7	X1 BLOWN STEER TYRE 385.65.225 REPLACED WITH X1 NEW	7/09/2025
160118	8/09/2025	Complete	P7	X1 LOW TREAD 385.65.225 STEER REPLACED WITH X1 NEW	8/09/2025
160315	23/09/2025	Complete	P2	ADJUSTED CLUTCH	23/09/2025
160316	23/09/2025	Complete	P2	REPLACED HEATER TAP	23/09/2025
162149	10/10/2025	Complete	P2	REPLACE INTERCOOLER DUE TO LEAKING. CLEAN UP RADIATOR	10/10/2025
162174	6/10/2025	Complete	P2	INTERCOOLER	6/10/2025