



Peterbilt Pacific Inc.

PETERBILT PACIFIC INC.
3104 Hampton Street
Terrace BC, V8G 5R5
Phone: (250) 638-1433

Kab-3
Jun

Customer: REMCAN PROJECTS LTD

Account #
Phone #
Invoice Date: 03-20-20

Repair Order No:
TB34024
CUSTOMER INVOICE

Tax ID: BC04534-001

Tax ID Date:

Page 1 of 6

Table with columns: Year, Make / Model, VIN, License, Mileage, Unit / Stock, Tag Number, Open Date / Time, Delivery Date, Delivery Mileage, Engine Hours, Sell Dlr, Axle Ratio, Engine Model / Serial #, Transmission Model/Serial #, Rear Axle Model/Serial #, CPL ARRG, Complete, P.O. Number, Authorization, Service Writer, Memo.

1 DIAGNOSE/REPAIR CHECK ENGINE LIGHT ON & ENGINE D-RATED

*NOTE: ORIGINAL ENGINE NO. 79294951
T/SHOOT & FOUND #6 CYLINDER NOT FIRING, REMOVE TURBO INLET/EXHAUST SIDE CONNECTIONS & NOTED TURBINE WHEEL DAMAGE(EXHAUST SIDE).
REMOVE TURBO ASSY. & EXHAUST MANIFOLD, NOTED #6 CYLINDER EXHAUST VALVES DAMAGED/BROKEN & OIL BYPASS/INTRUSION INTO EXHAUST AFTERTREATMENT SYSTEM.
CUSTOMER ADVISED OF FINDINGS & DECISION MADE TO REPLACE ENGINE WITH RECON ASSY.

REMOVE STEER-AXLE TIRES/WHEELS, RADIATOR, CHARGE-AIR-COOLER, A/C-CONDENSER ETC. FOR ACCESS(A/C SYSTEM EVACUATED).
REMOVE ENGINE ASSY. SWAP OVER EXTERNAL COMPONENTS AS REQUIRED FROM ORIGINAL ENGINE TO RECON ASSY.
REPLACE FAN(FOUND BLADES CRACKED) & BELT-TENSIONER. REPLACE TRANSMISSION INPUT-SHAFT/BEARING, CLUTCH-ASSEMBLY, CLUTCH X-SHAFT/FORK & BUSHING, FRONT/REAR MOTOR-MOUNTS, STARTER(END-BUSHING WORN)
INSTALL RECON ENGINE ASSY. REPLACE HOSES/BELTS ETC. AS REQUIRED.
REPLACE RADIATOR MOUNTS & RE-INSTALL RADIATOR/CAC/AC-CONDENSER ETC.
EVACUATE/VACUM LEAK TEST A/C SYSTEM, RE-CHARGE REFRIGERANT.
REPLACE AIR/FUEL FILTERS, INSTALL NEW ENGINE-OIL/COOLANT, TOP-UP POWER-STEERING OIL. DOWNLOAD ECM-TEMPLATE, VERIFY PARAMETERS.
REMOVE & REPLACE DPF-FILTER(NEW SERIAL# 33006505021)
CLEAN EXHAUST PIPING/COMPONENTS BETWEEN TURBO OUTLET/DPF(OIL CONTAMINATED). RESET DPF MAINTENANCE INTERVAL AT ENGINE ECM.
START/RUN ENGINE, OK.
RE-INSTALL STEER-AXLE WHEELS/TIRES REMOVED FOR ACCESS, TORQUE WHEEL-NUTS TO SPEC.
ROAD-TEST(AFTER CVIP/MVI REPAIRS COMPLETED), OK.
PERFORM FORCED REGEN TO VERIFY AFTERTREATMENT SYSTEM OPERATION, OK.

RE-TORQUE #1 AXLE WHEEL-NUTS AT 150KM

TOTAL LABOR
TOTAL PARTS
TOTAL GAS/OIL
TOTAL SUBLET LABOR
TOTAL EHC-OIL
TOTAL EHC-FILTER

Qty Part Number Desc List Unit Extended

Invoice Date: 03-20-20

Year	Make / Model	VIN	License	Mileage	Unit / Stock	Tag Number
2009	Peterbilt / 367	1NPTX4EX89D776459		560302	TRK008	
Open Date / Time	Delivery Date	Delivery Mileage	Engine Hours	Sell Dir	Axle Ratio	
02-14-20 / 01:13PM	08-06-08	34	0.0		4.56	
Engine Model / Serial #	Transmission Model/Serial #	Rear Axle Model/Serial #				
ISX15 / 60839609	RTLO189188 / S0703534	T69-170HP HN02988585 HN02988586				
CPL ARRG	Complete	P.O. Number	Authorization	Service Writer		
	03-19-20	KKTRK008		CL*CL		
Memo						

1	DR6439RCUM	ENGINE-IS				
	ESN 60839609					
2	F04-6006	ELBOW-RUB				
4	CT9444TRP	CLAMP-CON				
1	4059172CUM	SEAL-O RI				
1	3684338CUM	GASKET-CO				
1	D84-1000-6122215	BELT-POLY				
1	D84-1000-6061620	BELT-POLY				
2	05-16401	MOUNT-ENG				
4	MR1001	MOUNT				
4	07-03286RUB	MOUNT-RAD				
1	7068PK	TIE STRAP				9
1	7068HDPK	TIE STRAP				
1	S3631V0-10	O-RING				
1	S3631V0-6	O-RING				
4	S3631V0-12	O-RING				
1	308925-25CA	EP 15.5,				
1	K3762	KIT-CLUTC				
2	D50-6039	HOSE-HUMP				5
4	B9224-0406TRP	CLAMP-T B				3
1	89440DYC	TENSIONER				1
1	350-0107	HEATER-BL				
1	D61-6005-003	STARTER-P		5		
1	3682673CUM	GASKET-TH				
1	186780	SEAL, THER				
3	3957131CUM	O-RING				
2	3682826CUM	SEAL, GROM				
1	3684355CUM	GASKET-EX				
1	90-0012	CLAMP-V B				
2	3684091CUM	GROMMET				
1	7068PK	TIE STRAP				
1	FG90011	FITTING-B				
1	3163075	PAINT				
1	GLG1446-08-10	adptr				
2	S3631V0-12	O-RING				3
1	06-00530	SHAFT				
1	06-01093	SHAFT-CLU				
1	K3341	KIT-O-RIN				
1	GLG1416-0204	FITTING	3.			
2	HHS-16-50	SIL HOSE	1			
2	9212TRP	CLAMP-HOS				
4	074.58.212	5/8-11X2-	5.			
4	373.58	5/8-11 UN				
8	422.58	SAE FLT W				
1	351-0415	HEATER-IM				
2	HWC01079	BOLT-HEX				
1	996813252-001	FAN-ENGIN				
1	4388409CUM	MODULE, PA			2,	
8	CHS-40-4	HOSE				
2	CT300LTRP	CLAMP-CON				
4	GLG7ET16	CLAMP				
6	CHS-40-4	HOSE				2.74

Invoice Date: 03-20-20

Year	Make / Model	VIN	License	Mileage	Unit / Stock	Tag Number
2009	Peterbilt / 367	1NPTX4EX89D776459		560302	TRK008	
Open Date / Time	Delivery Date	Delivery Mileage	Engine Hours	Sell Dir	Axle Ratio	
02-14-20 / 01:13PM	08-06-08	34	0.0		4.56	
Engine Model / Serial #	Transmission Model/Serial #	Rear Axle Model/Serial #				
ISX15 / 60839609	RTLO18918B / S0703534	T69-170HP HN02988585 HN02988586				
CPL ARRG	Complete	P.O. Number	Authorization	Service Writer		
	03-19-20	KKTRK008		CL*CL		
Memo						

2	CT300LTRP	CLAMP-CON	20		
1	VL2136	VALVE-DRA			
1	2866636CUM	GASKET-EX			14.00
2	2866337CUM	GASKET-EX			20.00
1	90-0012	CLAMP-V B			
1	90-0013	CLAMP-V B			
1	B9224-0406TRP	CLAMP-T B	1		7
2	2871453CUM	GASKET-DP		36	
2	2871863CUM	CLAMP-V B	22.00	14	
3	HHS-16-50	SIL HOSE			
2	RS3539JAB	ELEMENT-F			
1	FF2203FLG	FILTER-FU			
14	EC7501	COOLANT-T			
50	15W40	OIL,BULK			50
4	R134A	FREON	22.00		
2	ESTER	A/C OIL			
1	SUBLET LABOR		100.00		107.50
	RESURFACE H/D FLYWHEEL				
14	EC7501&	EHC-OIL	1.00		1
50	15W40&	EHC-OIL			
1	FF2203FLG&	EHC-FILTER	0.50		0.50

2 RE-INSTALL DRIVE-SHAFT(REMOVED BY TOWING COMPANY)
 TOTAL LABOR
 TOTAL PARTS

Qty	Part Number	Desc	List	Unit	Extended
1	250-70-18X	KIT-BEARI			3
1	232493	CLIP-BOOT			8
1	232799DAN	GREASE			

3 ** TRUCK.MVI.3 SERVICE SPECIAL **
 BC CVIP INSPECTION (MVI) 3 DRIVE AXLE TRUCK / TRACTOR
 SUPPLY DECAL
 CVIP DECAL# FH41372 ISSUED, EXPIRES 30/SEP/2020
 SERVICE SPECIAL

4 REPLACE BROKEN/LEAKING RIGHT SIDE EXHAUST PIPE ASSY.(MUFFLER)
 REMOVE & DISASSEMBLE HEAT SHIELD/CLAMPS ETC. REPLACE EXHAUST SECTION &
 PIPE/CLAMPS AS REQUIRED.
 TOTAL LABOR
 TOTAL PARTS
 TOTAL IN FREIGHT

Qty	Part Number	Desc	List	Unit	Extended
1	M101451	MUFFLER-S			
4	14-14656-4	BUSHING-R			
1	EC50PLS	CLAMP-EXH			
1	90-0013	CLAMP-V B			

Invoice Date: 03-20-20

Year	Make / Model	VIN	License	Mileage	Unit / Stock	Tag Number
2009	Peterbilt / 367	1NPTX4EX89D776459		560302	TRK008	
Open Date / Time	Delivery Date	Delivery Mileage	Engine Hours	Sell Dir	Axle Ratio	
02-14-20 / 01:13PM	08-06-08	34	0.0		4.56	
Engine Model / Serial #	Transmission Model/Serial #	Rear Axle Model/Serial #				
ISX15 / 60839609	RTLO18918B / S0703534	T69-170HP HN02988585 HN02988586				
CPL ARR	Complete	P.O. Number	Authorization	Service Writer		
	03-19-20	KKTRK008		CL*CL		
Memo						

- 1 2866337CUM GASKET-EX
- 1 EC50PLS CLAMP-EXH
- 1 IN FREIGHT

5 REPAIR AIR LEAK AT LEFT SIDE FRONT FRAME AREA UNDER CAB
 REPLACED LEAKING FITTINGS & AIR-LINE CONNECTIONS(X3), VERIFY REPAIR.
 TOTAL LABOR
 TOTAL PARTS

Qty	Part Number	Desc	List	Unit	Extended
1	1468-4A	BRASS			
1	1469-4A	BRASS	3		

6 ** MENU PB WS LEFT SERVICE SPECIAL **
 CHANGE LH PETERBILT ENCAPSULATED WINDSHIELD
 DROP VISORS EXTRA IF INSTALLED
 SERVICE SPECIAL

Qty	Part Number	Desc	List	Unit	Extended
1	DW1037-30	GLASS-PET			

7 REPLACE WORN UPPER STEERING COLUMN/SHAFT U-JOINT
 TOTAL LABOR
 TOTAL PARTS

Qty	Part Number	Desc	List	Unit	Extended
1	SK000283	KIT-U-JOI			

8 REPLACE #3 AXLE RIGHT SIDE BRAKE-CHAMBER(PIGGY-BACK)
 ADJUST BRAKE & VERIFY OPERATION.
 TOTAL LABOR
 TOTAL PARTS

Qty	Part Number	Desc	List	Unit	Extended
1	3430008X	KIT-PIGGY			

9 REPAIR MISC. LIGHTS NOT FUNCTIONING
 REPLACE RIGHT SIDE REAR MARKER LIGHT & WIRING/PIG-TAIL.
 REPLACE WIRING, LIGHT & PIGTAIL FOR LICENSE PLATE LIGHT.
 REPAIR WIRING AT REAR ID-LIGHTS.
 VERIFY ALL LIGHTS FUNCTIONING.
 TOTAL LABOR
 TOTAL PARTS

Qty	Part Number	Desc	List	Unit	Extended
1	MD1827	HARNESS-W			
1	LL045801	LAMP-LED			

Invoice Date: 03-20-20

Year	Make / Model	VIN	License	Mileage	Unit / Stock	Tag Number
2009	Peterbilt / 367	1NPTX4EX89D776459		560302	TRK008	
Open Date / Time	Delivery Date	Delivery Mileage	Engine Hours	Sell Dir	Axle Ratio	
02-14-20 / 01:13PM	08-06-08	34	0.0		4.56	
Engine Model / Serial #	Transmission Model/Serial #	Rear Axle Model/Serial #				
ISX15 / 60839609	RTLO18918B / S0703534	T69-170HP HN02988585 HN02988586				
CPL ARRG	Complete	P.O. Number	Authorization	Service Writer		
	03-19-20	KKTRK008		CL*CL		
Memo						

1 LL092010 GROMMET-2
 1 LL091710 PIGTAIL-2
 1 15208 LIGHT-SEA

10 REPLACE #2 AXLE TORQUE-ROD
 TOTAL LABOR
 TOTAL PARTS

Qty	Part Number	Desc	List	Unit	Extended
1	C65-6026-000010440	ROD-HD TR			

11 REPAIR/REPLACE LEFT SIDE AIR-SUSPENSION HEIGHT CONTROL VALVE(LEAKING AIR)
 HEIGHT-CONTROL VALVE NOT LEAKING AFTER BEING CYCLED A FEW TIMES.
 NOTED ADDITIONAL AIR LEAK AT REAR TRAIN-HITCH AIR-CYLINDER, INSPECTED & FOUND CYLINDER IS CRACKED/LEAKING.
 DOES NOT LOOK LIKE HITCH/CYLINDER HAS BEEN USED RECENTLY, PERFORM TEMPORARY REPAIR BY INSTALL OF A SHUT-OFF VALVE AT AIR-LINE INLET TO AIR-CYLINDER.
 CHECK/VERIFY NO FURTHER AIR LEAKS PRESENT.
 TOTAL LABOR
 TOTAL PARTS

Qty	Part Number	Desc	List	Unit	Extended
1	2120-B	BRASS			

12 TIGHTEN/REPLACE LOOSE BRAKE DUST COVER AT #1 AXLE LEFT SIDE
 TOTAL LABOR
 TOTAL PARTS

Qty	Part Number	Desc	List	Unit	Extended
1	K065856KBXW	DUSTSHIEL			

13 REPAIR RIGHT SIDE REAR DECK SIDE BOARD CORRODED/BROKEN ALONG BOTTOM EDGE & AT HINGE-WELD LOCATIONS.
 REMOVE RIGHT SIDE REAR DECK HINGED SIDE PANEL, CUT OFF HINGES & CUT OUT CORRODED/CRACKED SECTIONS. WELD IN PATCH PANEL ON COMPLETE LOWER SECTION, RE-WELD HINGES IN PLACE & ALSO WELD IN NEW LOCK-PIN/LATCH PIECE AT REAR.
 PAINT GLOSS BLACK AT REPAIRED AREAS.
 TOTAL LABOR
 TOTAL PARTS
 TOTAL EHC-OIL

Qty	Part Number	Desc	List	Unit	Extended
1	892.150001	High Soli			
1	892.150003	High Soli			
1	STEEL/ANGLE	FORMED			

Repair Order No:

TB34024

Page 6 of 6

Invoice Date: 03-20-20

Year	Make / Model	VIN	License	Mileage	Unit / Stock	Tag Number
2009	Peterbilt / 367	1NPTX4EX89D776459		560302	TRK008	
Open Date / Time	Delivery Date	Delivery Mileage	Engine Hours	Sell Dir	Axle Ratio	
02-14-20 / 01:13PM	08-06-08	34	0.0		4.56	
Engine Model / Serial #	Transmission Model/Serial #	Rear Axle Model/Serial #				
ISX15 / 60839609	RTLO189188 / S0703534	T69-170HP HN02988585 HN02988586				
CPL ARRG	Complete	P.O. Number	Authorization	Service Writer		
	03-19-20	KKTRK008		CL*CL		
Memo						

1 892.150003&

EHC-OIL

SUPPLIES/TECHNOLOGY

G.S.T. - REG. NO. 888250784RT0001 5 % OF

SALES-PARTS-SERVICE 4070602
 SALES-OIL & GREASE 4130602
 SALES-SUBLET 4140602
 SALES-LABOUR 4300603
 FREIGHT-RECOVERY 6510602
 SUPPLIES/TECHNOLOGY 6620603
 WASTE DISPOSAL 6660603
 P.S.T. PST-1056-8118 2140600
 G.S.T. 888250784RT00012180101
 PLEASE PAY THIS TOTAL 1110100

I, THE UNDERSIGNED, OWNER OR DULY AUTHORIZED REPRESENTATIVE, HEREBY ACKNOWLEDGE MY INDEBTEDNESS IN THE TOTAL AMOUNT SHOWN ABOVE. I HAVE READ AND UNDERSTOOD THE TERMS AND CONDITIONS LISTED BELOW.

Customer: X _____ Date: _____

- PAYMENT TERMS:** Due and payable new 15th following. It is understood and I agree to pay carrying charges of 2.25% per month (30.6% per annum) on any balance unpaid after the 15th of the following month of the date of purchase.
- WARRANTY CONSIDERATIONS:** Any portion of this repair order that is designated for warranty considerations will be submitted as a warranty claim to the manufacturer. If for any reason the manufacturer rejects the claim or a portion of the claim, it will become the immediate responsibility of the owner to pay that portion which is rejected.
- WARRANTY LIMITATION:** All service repairs carry a maximum of 30 days warranty from day of completion. Any claims must be made within 5 days of the failure date. Certain parts, products, accessories, and other items used in completing the repair and service work covered in this repair order are manufactured and supplied by others, the quality and workmanship of which are entirely outside the control of Peterbilt Pacific, Inc. With regard to such parts, products, and accessories, ect. PETERBILT PACIFIC INC. MAKES NO WARRANTIES, WHETHER EXPRESSED, IMPLIED, STATUTORY, OR OTHERWISE, INCLUDING ANY WARRANTY OF MERCHANTABILITY OR OF FITNESS FOR A PARTICULAR PURPOSE.
- RESPONSIBILITY OF EQUIPMENT:** Peterbilt Pacific Inc. will not be held responsible for the loss or damage to vehicles, or articles left in vehicles, in case of fire, theft, accident, or any other cause beyond their control.
- ALL OLD PARTS** removed will be disposed of, unless otherwise specified before repairs started.
- THE SIGNATURE** of the owner or duly authorized representative on the original work order request, authorized the repair and service work listed on this repair order, along with the necessary material.
- PRIVACY:** Personal information is collected in accordance with applicable privacy legislation and is governed by Peterbilt Pacific Inc. Privacy Policy.