

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780- -

INVOICE**37888**

Org. Est. # 054658

*217-10wb***INVOICE**

Printed Date: 09/10/2022

Work Completed: 09/10/2022

CHEMCO-OFF ROAD

3135-4 ST
NISKU, ALBERTA T9E-8L1
Office 780-436-9570

1996 Volvo - L120C UNIT#E110 -

Lic # :

Odometer In : 0

Unit # : WL-1611

VIN # : L120CV61611

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
WIPER BLADE -ORDER VOE4880700	1.00	42.07	42.07	(1) DIAGNOSE HYDRAULIC LEAK ** NOT COMPLETED AT THIS TIME **	n/c
V-BELT -ORDER VOE976487	1.00	63.12	63.12		
COOLANT FILTER -ORDER VOE20532237	1.00	68.69	68.69		
FREIGHT -ORDER FRT	1.00	31.50	31.50		
BELT TENSIONER -ORDER VOE11030542	1.00	1,195.90	1,195.90		
EXPANSION TANK -ORDER VOE11033336	1.00	353.23	353.23		
RAD HOSE -ORDER VOE4775274	1.00	104.98	104.98		

Org. Estimate 1,952.46 Revisions 0.00 Current Estimate 1,952.46

Labor:	0.00
Parts:	1,859.49
SubTotal:	1,859.49
Tax:	92.97
Total:	1,952.46
Bal Due:	\$1,952.46

[Payments -]

Vehicle Received: 9/10/2022

Customer Number : 3904

GST#865376503RT0001

Signature _____ Date _____

WRENCHHEAD MECHANICAL

3135 4 ST

NISKU, ALBERTA. T9E-8L1

Phone: 780-436-9570 Fax: 780- -

REPAIR ORDER #

037888

Org. Est. # 054658

REPAIR ORDER - RO

Scheduled : 04/13/2022 03:35 PM

Print Date : 4/13/2022

CHEMCO-OFF ROAD

3135-4 ST

NISKU, ALBERTA T9E-8L1

Office 780-436-9570

Cust ID : 3904

Last Service : 2/9/2022

1996 Volvo - L120C UNIT#E110 -

Lic # : - ALBERTA

Unit # : WL-1611

VIN # : L120CV61611

MFG Date : 5/11/2016

Previous Odom : 57466

Current Odom : 0

Elapsed : 0

Labor Requested / Part SubTotal**Extended**

(1) DIAGNOSE HYDRAULIC LEAK

65.00

Parts Subtotal 0.00

Shop Supplies

3.25

OUTSTANDING REPAIRS

Parts: 0.00

Supplies: 3.25

Tax: 3.41

Total: 71.66

Labor: 65.00

Balance: 71.66

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within ____ days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts _____. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO MY VEHICLE OR ARTICLES LEFT IN VEHICLES IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE. ALL VEHICLES LEFT MUST HAVE OWN INSURANCE. ANY VEHICLES LEFT OVER 30 DAYS WITHOUT CONSENT WILL BE PROPERTY OF WRENCHHEAD MECHANICAL.

Authorized By _____ Date _____ Time _____

Technician Work Sheet

Service Writer : GLAZIER, RUSSELL

Print Date: 4/13/2022

1996 Volvo - L120C UNIT#E110

Hat # :

VIN # : L120CV61611

Color :

Repair Order #

Engine :

Location :

037888

Lic # :

Lic. State : ALBERTA

CHEMCO-OFF ROAD

Office 780-436-9570

Schedule : 4/13/22 3:45 P.M.

Promised Date : 4/13/22 5:00 P.M.

Inspection Date : 5/11/16

Status :

Last Service : 2/09/22

Unit # : WL-1611

Current Odometer : 0

Trans :

Previous Mileage : 57,466

Brakes :

Elapsed Mileage : 0

Manufacture Date : 5/11/16

Labor Description

Charged Hours

☐ (1) DIAGNOSE HYDRAULIC LEAK

1.00

Technician : <none>

OUT ODOMETER :

Total Hours Charged :

1.00

Hours out: 0.00

Tech Notes

Labour Requisition			MTE-0131
--------------------	--	--	----------

UNIT #:	WL-1611	ODOMETER:		ENGINE HOURS:	57889	DATE:	Apr 19
---------	---------	-----------	--	---------------	-------	-------	--------

ITEM	REPAIR DESCRIPTION	QUOTED HOURS	ACTUAL HOURS
x 1	Both lift cylinders leaking		
x 2	Both steering cylinders leaking		
x 3	Bucket cylinder leaking		
✓ 4	Replace wiper blade	✓	
✓ 5	adjust wiper position on motor	✓	
x 6	Missing cab vents		
x 7	Right speaker not working		
✓ 8	Rear wiper not working		
✓ 9	Pro heat not working		
x 10	A/c unit not working on roof	Diag	
✓ 11	Right side of cab storage Needs remounting		
✓ 12	wash unit		
x 13	Gaps in window silicone		
x 14	Needs seat cover		
x 15	Ash tray Missing		
✓ 16	Needs first aid kit		
✓ 17	Beacon light not working		
x 18	Needs Hyd, trans, finals service		

Technician (Print Name)

Technicians Signature

Labour Requisition

MTE-0131

UNIT #:

ODOMETER:

ENGINE HOURS:

DATE:

ITEM	REPAIR DESCRIPTION	QUOTED HOURS	ACTUAL HOURS
✓19	Set valves - Did we do already?		
✓20	RS Battery box held on with tie strap		
✗21	Hyd leak under cap		
✓22	Quick attach broken		
✗23	LS ^{Engine} Door Shock NFG door doesn't stay open		
✓24	Needs new ground connection on Alternator		
✗25	Fuel pump leaking		
✗26	Broken cable to fuel pump		
✗27	throttle linkage worn out		
✗28	Bell housing plugs leaking		
✓29	Alternator positive lead loose but nut is tight		
✓30	upper rad hose has huge gash in it not leaking but will soon		
✓31	Needs new Rad tank about to leak		
✗32	Positive air never hooked up		
✗33	LS hood bent		
✓34	Needs new belt tensioner		
✗35	no belts to A/c compressor		
✓36	Missing 1 Alt belt		

Technician (Print Name)

Technicians Signature

MTE-0131

UNIT #:		ODOMETER:		ENGINE HOURS:		DATE:	
---------	--	-----------	--	---------------	--	-------	--

[illegible]

Technician (Print Name)

Technicians Signature



Equipment Service Request

Date: 4/8/2022 Time: 11:30 AM (-6 GMT) Unit: WL-1611
Odometer: 0 Hours: 0.0 Name: Melissa

Truck #: Na

Trailer #:

Repairs Required:

Central ram has heavy leak

Supplies Required:

Supply Picker: Dispatcher:

Melissa
Print

MJ
Sign

4/8/2022
Date

WRENCHHEAD MECHANICAL

3135 4 ST

NISKU, ALBERTA. T9E-8L1

Phone: 780-436-9570 Fax: 780- -

INVOICE**39035****INVOICE**

Ref #: 57986 HOURS

Printed Date: 08/17/2022

Work Completed: 08/17/2022

CHEMCO-OFF ROAD

3135-4 ST

NISKU, ALBERTA T9E-8L1

Office 780-436-9570

1996 Volvo - L120C UNIT#E110 -

Lic #:

Odometer In : 0

Unit # : WL-1611

VIN # : L120CV61611

Engine Hrs In : 57986.0

Engine Hours Out : 57986.0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
Shop Supplies			37.38	(1) REPAIRS AS REQUIRED AT LOGISTICS * LOWER H LINK PIN KEEPER BOLT SHEERED OFF 1/2 DEEP * TRIED EXTRACTING BOLT AND IT WONT BUDGE. CLEAN UP PIN AND H LINE. WELD PIN IN PLACE * GREASE BOOM * USING TORCH, DRILL BITS, DISC GRINDER, AIR HAMMER AND EXTRACTOR TO FISH OUT AS MUCH OF SHEERED KEEP BOLT AS POSSIBLE. PREP HOLE TO ACCEPT 5/8" BOLT WITH HEAD CUT OFF. INSERT INTO HOLE AND WELD INTO PLACE * CLEAN WELDS OFF PIN. FAB A KEEPER WASHER WITH INTEGRAL NUT. POUND PIN INTO PLACE AND INSTALL KEEPERS WASHER, CUT OFF ACCESS LENGTH FROM KEEPER STUD TO ACCOMMODATE FOR CLEARANCE THROUGH H LINK * TEST OPERATION * PIN IS TRYING HEAD TO WALK OUT. * POUND LOWER H LINK PIN 1.5" OUT. CUT OFF TABS AND GRIND BACK SIDE OF FLANGE. CLEAN AND GRIND H LINK SURFACE CLEAN,. POUND PIN BACK IN * PIN NOW FLUSH ON L/S. PREP PIN FOR WELD CUT 2 LENGTH 7" AND 5" OF 1/4" FLAT BAR. WELD 7" BAR TO BACK SIDE OF PIN, STACK AND WELD 5" LENGTH TO 7"	747.50

Org. Estimate 824.12 Revisions 0.00 Current Estimate 824.12

Labor: 747.50
Parts: 37.38SubTotal: 784.88
Tax: 39.24
Total: 824.12
Bal Due: \$824.12

[Payments -]

STK 37.38

Vehicle Received: 8/17/2022

Customer Number : 3904

GST#865376503RT0001

Signature _____ Date _____

Unit #: WL-1611 S/N:

Odometer:

Hours: 57986

[illegible]

[illegible]

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780- -

INVOICE**37149****INVOICE**

Ref # : 57802 HOURS

Date: 01/12/2022

CHEMCO-OFF ROAD

3135-4 ST
NISKU, ALBERTA T9E-8L1
Office 780-436-9570

1996 Volvo - L120C UNIT#E110 -

Lic # :

Odometer In : 0

Unit # : WL-1611

VIN # : L120CV61611

Engine Hrs In : 57802.0

Engine Hours Out : 57802.0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
3/4" GR8 NUT -ORDER FAS178016	25.00	0.66	16.50	(1) REPAIRS AS REQUIRED AT LOGISTICS	162.50
3/4" PLOW BOLT -ORDER PB.75X3.5	25.00	2.92	73.00	* REMOVE CUTTING BLADE	
3/4" FLAT WASHERS -ORDER FASFW5P8248	25.00	0.47	11.75	* INSTALL OLD CUTTING BLADE	
CENTER BUCKET EDGE-ORDER 11011153	1.00	608.00	608.00	* NEW BLADE NOT PUT ON AT THE MOMENT	
FREIGHT CHARGE-ORDER FC	1.00	145.00	145.00		
1X18.16X24.5" EDGE -ORDER 1101154MT	2.00	354.89	709.78		
Shop Supplies			8.13		

Org. Estimate 1,713.89 Revisions 0.00 Current Estimate 1,713.89

Labor:	162.50
Parts:	1,572.16
SubTotal:	1,734.66
Tax:	86.73
Total:	1,821.39
Bal Due:	\$1,821.39

[Payments -]

Vehicle Received: 1/6/2022

GST#865376503RT0001

Signature _____ Date _____

Customer Number : 3904

Unit #: WL-1611

S/N:

Odometer: n/a

Hours: 57802

[illegible]

Parts

Mechanic ID:

Mechanic Signature:

[illegible]

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780- -

INVOICE**36338**

Org. Est. # 053094

INVOICE

Date: 12/06/2021

CHEMCO-OFF ROAD

3135-4 ST
NISKU, ALBERTA T9E-8L1
Office 780-436-9570

1996 Volvo - L120C UNIT#E110 -

Lic # :

Odometer In : 0

Unit # : WL-1611

VIN # : L120CV61611

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
Shop Supplies			100.00	** SERVICE CALL** ** REPLACE 2 TIRES ** ** SUPPLY AND INSTALL 2 23.5R25 DOUBLE COIN REM -2 TIRES ** ** FOUNTAIN TIRE INVOICE 0171182108 **	6,995.15

Org. Estimate 7,449.91 Revisions 0.00 Current Estimate 7,449.91

Labor:	0.00
Parts:	100.00
Sublet:	6,995.15
SubTotal:	7,095.15
Tax:	354.76
Total:	7,449.91
Bal Due:	\$7,449.91

[Payments -]

Vehicle Received: 12/6/2021

Customer Number : 3904

GST#865376503RT0001

Signature _____ Date _____

WRENCHHEAD MECHANICAL

3135 4 ST

NISKU, ALBERTA. T9E-8L1

Phone: 780-436-9570 Fax: 780- -

REPAIR ORDER #

036338

Org. Est. # 053094

REPAIR ORDER - RO

Scheduled : 09/21/2021 08:40 AM

Print Date : 12/6/2021

CHEMCO-OFF ROAD

3135-4 ST

NISKU, ALBERTA T9E-8L1

Office 780-436-9570

Cust ID : 3904

Last Service : 9/23/2021

1996 Volvo - L120C UNIT#E110 -

Lic # : - ALBERTA

Unit # : WL-1611

VIN # : L120CV61611

MFG Date : 5/11/2016

Previous Odom : 57466

Current Odom : 0

Elapsed : 0

Labor Requested / Part SubTotal**Extended**

** SERVICE CALL **

6,995.15

** REPLACE 2 TIRES **

Parts Subtotal 0.00

Shop Supplies

100.00

Parts: 0.00

Supplies: 100.00

Labor/Sublet: 6,995.15

Tax: 354.76

Total: 7,449.91

Balance: 7,449.91

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within____days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts____. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO MY VEHICLE OR ARTICLES LEFT IN VEHICLES IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE. ALL VEHICLES LEFT MUST HAVE OWN INSURANCE. ANY VEHICLES LEFT OVER 30 DAYS WITHOUT CONSENT WILL BE PROPERTY OF WRENCHHEAD MECHANICAL.

Authorized By _____ Date _____ Time _____

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780- -

INVOICE**32029**

Org. Est. # 048756

INVOICE

Date: 02/26/2020

CHEMCO-OFF ROAD

3135-4 ST
NISKU, ALBERTA T9E-8L1
Office 780-436-9570

1996 Volvo - L120C UNIT#E110 -

Lic # :

Odometer In : 57466

Unit # : WL-1611

VIN # : L120CV61611

Engine Hrs In : 57466.0

Engine Hours Out : 57466.0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
NX-3720HGK2 VHF RADIO-STK Size: 512 CHANNEL 70-20311	1.00	515.39	515.39	(1) INSTALL GPS ** SEE TECH SHEET **	195.00
VHF ANTENNA KIT-STK VHF M	1.00	75.00	75.00	(2) INSTALL UNIT # ** SEE TECH SHEET **	32.50
OFF ROAD GPS - NO CHARGE - STK OFF ROAD GPS	1.00	0.00	n/c	(3) CHECK UNIT FOR SERVICE ** SEE TECH SHEET **	65.00
FENDER BRACKET-STK LATMB-3/4	1.00	3.74	3.74		
CONNECTOR-STK PL259	1.00	3.95	3.95		
CHEMCO DOOR DECAL-STK CD	2.00	12.00	24.00		
Shop Supplies			14.63		

Org. Estimate 870.73 Revisions 0.00 Current Estimate 870.73

Labor:	292.50
Parts:	636.71
SubTotal:	929.21
Tax:	46.46
Total:	975.67
Bal Due:	\$975.67

[Payments -]

Vehicle Received: 2020-02-24

Customer Number : 3904

GST#865376503RT0001

Signature _____ Date _____

Phone: 780-436-9570 Fax: 780- -

Org. Est. # 048756

Print Date : 2/21/2020

Elapsed : 0

<i>Labor Requested / Part SubTotal</i>	Extended
<i>(1) INSTALL GPS</i>	97.50
<i>(2) INSTALL UNIT #</i>	65.00
<i>(3) CHECK UNIT FOR SERVICE</i>	65.00
	Parts Subtotal 0.00
Shop Supplies	11.38

Balance: 250.82

Copyright (c) 2020 Mitchell Repair Information Company, LLC ropartdetai2 dj 7.2.18

Technician Work Sheet Service Writer : GLAZIER, RUSSELL

Print Date: 2/21/2020

1996 Volvo - L120C UNIT#E110

Hat # :

Repair Order #

VIN # : L120CV61611

Color :

032029

Engine :

Location :

Lic # :

Lic. State : ALBERTA

CHEMCO-OFF ROAD

Office 780-436-9570

Schedule : 2/21/20 2:30 P.M.

Promised Date : 2/21/20 5:00 P.M.

Inspection Date : 5/11/16

Status :

Last Service : 5/13/19

Unit # : WL-1611

Current Odometer : 0

Trans :

Previous Mileage : 57,314

Brakes :

Elapsed Mileage : 0

Manufacture Date : 5/11/16

Labor Description

Charged Hours

☒ (1) INSTALL GPS	1.50
Technician : <none>	
☒ (2) INSTALL UNIT #	1.00
Technician : <none>	
☒ (3) CHECK UNIT FOR SERVICE	1.00
Technician : <none>	

OUT ODOMETER :

Total Hours Charged :

3.50

Hours out: 0.00

Tech Notes

Unit #: W/L 9611 S/N: .

Odometer:

Hours: 57456

Lab#	Repair Description	Date	Location	Tech Name	Hours
3	Check Service History diff / trans / Hydraulic Syste - Due	Feb 24	SLC	BT	1.0 1.0
1	install gps / 2-way VHF				2.0
1	put Spill kit / inspection Book in cab				
2	install chance Decals				0.5
	work with Buick 77133 for 44516				
	Unit has alot of tears in Bod Sheet				

Parts

Mechanic ID:

Mechanic Signature:

Qty.	Part #	Description	STK/ORD	Qty.	Part #	Description	STK/ORD
1	91538	Coax end	✓				
1	90-10055	Coax Cable	✓				
1	ap-1227u	Antenna	✓				
1	NX-3720H	VHF Radio	✓				
1		Spill kit	✓				
1		inspection Book	✓				
2		Chance Decals	✓				
2		Unit number Decals	✓				

MTE-0131

UNIT #:

Feb - 16

ODOMETER:

ENGINE HOURS:

57466

DATE:

Feb 21

PM

Don't

131

Technician (Print Name)

Technicians Signature

UNIT #:	44-1611	ODOMETER:		ENGINE HOURS:		DATE:	Feb 21
---------	---------	-----------	--	---------------	--	-------	--------

[illegible]

137

Technician (Print Name)

Technicians Signature



REQUISITION FOR MATERIAL ORDER

Special Instructions:

Please contact Brian, Kary, or Dale so we can arrange for pickup.

Ship To: (if other than standard jobsite location)

Brian Bittner

Requisition Num: **600-E-01248**

Sheet 1 of 1

Activity Num: 600-001-001-001

Activity Name: Office

Project Name: Nisku Office

Project Location: Nisku

Date Required: 24-Feb-20



ITEM	QTY	UNIT	DESCRIPTION OF MATERIAL	SUPPLIER
1	1	EA	Volvo Loader c/w bucket & forks	
Extra Info			for yard maintenance at Valleyview shop/yard	Shipped Qty
WL 1611				

PRE-DELIVERY INSPECTION

OK N/A

- | | | |
|--------------------------|--------------------------|---------------------------------|
| ☐ | ☐ | Quantity Matches Requisition |
| ☐ | ☐ | Model/Part# Match Requisition |
| ☐ | ☐ | Overall Condition/Cleanliness |
| ☐ | ☐ | Function |
| ☐ | ☐ | Accessories/Leads/Loose Parts |
| ☐ | ☐ | Calibration Valid/Cert Included |
| ☐ | ☐ | Fuel |
| ☐ | ☐ | Openings Water Proof |

Comment:

Inspector

Date

APPROVED

By tchuhan at 8:59 am, Feb 21, 2020

Requisitioned By

Approved By

Owner's Approval

Date

Date

Date

Darryl Matchem

From: Ryan Chappell
Sent: Friday, February 21, 2020 3:54 PM
To: Darryl Matchem
Subject: WL-1611

Gps , decals , 2 way, spill kit, inspection book and send it

Ryan Chappell

chemco

rcchappell@chemco.com

www.chemco.com

This message and any attached documents are only for the use of the intended recipient(s), are confidential and may contain privileged information. Any unauthorized review, use, retransmission, or other disclosure is strictly prohibited. If you have received this message in error, notify the sender immediately, and delete the original message.

TITANGPS NON-CTS INSTALLATION REFERENCE SHEET

chemco



ESN:

CERTIFIED
TRACKING SOLUTIONS

Serial # : 193401360



IMEI # : 357649070941748



COMPLETED BY INSTALLER

VEHICLE INFORMATION - **IMPORTANT**

UNIT#/Name: @ WL-1611
Year: 1996 Make: Volvo Model: L120C Colour: Yellow
VIN#: L120C061611 LIC Plate: /
Odometer: _____ Engine Hours: 57486

Tracking Unit Location

Location 12V: _____ Ignition: fuse panel Ground: _____
Wire Color 12V: _____ Ignition: _____ Ground: _____
Antenna(s) Location: _____ Module Location: _____

FINAL TESTING: (PLEASE CALL CTS at 780-391-3800 / 1-855-287-4477)

☒ TESTED with CTS

INSTALLER NAME: Brad

Date(DD/MM/YYYY): 28/02/2020 Time: 11:45 SIGNATURE: [Signature]

PLEASE NOTE: CTS cannot be held liable for any damage to the asset or hardware when the install is performed by NON-CTS personnel. Installations performed by NON-CTS personnel are not subject to CTS warranty policies. Improper installation that causes any type of unit malfunction will void any warranty attached to the product. Charges will apply for the replacement of equipment and/or technical diagnosis of the issue.

UPON COMPLETION OF INSTALLATION PLEASE FAX ATTN:
Certified Tracking Solutions@ 780-391-3801 OR Scan and EMAIL TO:
installs@ctstracking.com

CTS Admin Use Only ☐ Updated Work Order