

POB-1
BLUE-MAR



KNEEHILL COUNTY
232 Main Street
Threehills, AB T0M 2A0
Phone: 403-443-5541 Fax: 403-443-5116

Work Order (Closed)

W.O. #: 0000542734

Issued On: Tuesday, January 28, 2025
Priority: Normal
Description: G4119 CVIP
Responsible: Dean Walker

Asset: G4119 (L.P.#5UB400) () - LOADLINE BELLY DUMP TRAILER (L.P.#5UB400)
Category: Vehicle

Service: X COMMERCIAL VEHICLE INSPECTION
Scheduled Date: 1/28/2025
Performed Date: 2/4/2025
Meter: 176146

Type	Items	Description	Unit	Quantity	Cost	Total
Labor	Dean Walker		EA	31.00	103.00	\$3,193.00
Part	16-720	Sta-Dry Socket, 7 Way	4B3 EA	1.00	23.23	\$23.23
	3030LC (FLT.BRK. # LCP3	SPRING BRAKE POT - LIFE SEAL	1A5 EA	1.00	165.91	\$165.91
	3600AX	BRAKE DRUMS 93600 (DAY 0312378800	SHOP EA	4.00	111.04	\$444.17
	40010216	1-1/2" 10 SPLINE 6" SLACK ADJ IN#11P		1.00	123.96	\$123.96
	42710563	BRACKET KIT IN#11P86397		1.00	12.22	\$12.22
	45210125	SLACK BUSHING IN#11P86397		10.00	3.40	\$34.00
	452-9270	AIR BAG IN#11P86397		1.00	147.56	\$147.56
	GC3030	3030 BRAKE POT IN#11P86407		2.00	102.27	\$204.54
	RK4707QSTD23	BRAKE SHOE Q-PLUS	SHOP EA	4.00	59.78	\$239.10

Parts: \$1,394.69
Fluids: \$0.00
Labor: \$3,193.00
Other: \$0.00

Service Total: \$4,587.69

Parts: \$1,394.69
Fluids: \$0.00
Labor: \$3,193.00
Other: \$0.00

Work Order Total: \$4,587.69



KNEEHILL COUNTY
 232 Main Street
 Threehills, AB T0M 2A0
 Phone: 403-443-5541 Fax: 403-443-5115

Work Order (Open)

W.O. #: 0000542734

Issued On: Tuesday, January 28, 2025 Responsible: Dean Walker
 Priority: Normal
 Description: G4119 CVIP

Asset: G4119 (L.P.#5UB400) () - LOADLINE BELLY DUMP TRAILER (L.P.#5UB400)
 Category: Vehicle

Service: X COMMERCIAL VEHICLE INSPECTION Scheduled Date: 1/28/2025
 Equipment Meter: 173726 as of 9/24/2024 Performed Date: 2/3/25 Meter: 176146

Type	Items	Description	Unit	Quantity	Cost	Total
Labor	Dean Walker		EA	1.00	103.00	\$103.00
Part	16-720	Sta-Dry Socket, 7 Way	EA	1.00	23.23	\$23.23

Parts: \$23.23
 Fluids: \$0.00
 Labor: \$103.00
 Other: \$0.00

Service Total: \$126.23

Feb 2/25 8.0
 Jan 30 9.0
 Jan 29 8.0
 Jan 28 6.0

Parts: \$23.23
 Fluids: \$0.00
 Labor: \$103.00
 Other: \$0.00

Work Order Total: \$126.23

Completed on: Feb 4/25 By: Dean Walker

pre form cvip inspection
 Found right signal not work
 Diagnose and change plug
 Found axle 2+3 lining low
 Do 4 wheel Brake Job with shoes + drums
 Found axle 2 LEFT slack sticking
 changed out slack adjuster
 Found Brake pods on axle 2+3 Right
 are incorrect installed 2 New Brake pods
 Axle 2 LEFT has cord exposed on Air Bag
 Note: Had to recalibrate push rods
 to stop from going over 90%

- Trailer plug
- Shoes
- Drums
- Slack
- Air Bag
- Brake pods