

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780- -

*R26-5
MAY*

INVOICE

39896

Org. Est. # 056666

INVOICE

Printed Date: 02/22/2023

Work Completed: 02/22/2023

CHEMCO-OFF ROAD
3135-4 ST
NISKU, ALBERTA T9E-8L1
Office 780-436-9570

2014 Cat - 289D SKIDSTEER UNIT#20215 -
Lic # :
Unit # : SS-0351
VIN # : A9Z00351
Odometer In : 0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
5/8X8X100 17 HOLE EDGE-ORDER 6715464	1.00	247.50	247.50	(1) REPLACE CUTTING EDGE ** SEE TECH SHEET	845.00
PLOW BOLT-ORDER .625X2.25	17.00	1.18	20.06		
PLOW BOLT NUT 5/8-ORDER .625	17.00	0.72	12.24		
H3 12V BULB-STK 12336	2.00	3.16	6.32		
Shop Supplies			42.25		

Org. Estimate 443.75 Revisions 0.00 Current Estimate 443.75

Labor:	845.00
Parts:	328.37
SubTotal:	1,173.37
Tax:	58.67
Total:	1,232.04
Bal Due:	\$1,232.04

[Payments -]

STK-49.

Vehicle Received: 2/6/2023

Customer Number : 3904

GST#865376503RT0001

Signature _____ Date _____

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780- -

REPAIR ORDER #

039896

Org. Est. # 056666

REPAIR ORDER - RO

Scheduled : 11/16/2022 10:53 AM

Print Date : 11/16/2022

CHEMCO-OFF ROAD

3135-4 ST
NISKU, ALBERTA T9E-8L1
Office 780-436-9570
Cust ID : 3904
Last Service : 7/28/2022

2014 Cat - 289D SKIDSTEER UNIT#20215 -

Lic # : - AB
Unit # : SS-0351
VIN # : A9Z00351
MFG Date : 6/17/2015
Current Odom : 0

Previous Odom : 3420

Elapsed : 0

<i>Labor Requested / Part SubTotal</i>	Extended
(1) REPLACE CUTTING EDGE	130.00
Shop Supplies	6.50
Parts Subtotal	0.00

Parts: 0.00
Labor: 130.00

Supplies: 6.50

Tax: 6.83

Total: 143.33
Balance: 143.33

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within ___ days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts ____. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO MY VEHICLE OR ARTICLES LEFT IN VEHICLES IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE. ALL VEHICLES LEFT MUST HAVE OWN INSURANCE. ANY VEHICLES LEFT OVER 30 DAYS WITHOUT CONSENT WILL BE PROPERTY OF WRENCHHEAD MECHANICAL.

Authorized By _____ Date _____ Time _____

Technician Work Sheet Service Writer : GLAZIER, RUSSELL

Print Date: 11/16/2022

2014 Cat - 289D SKIDSTEER UNIT#20215 TRA

Hat # :

Repair Order #

VIN # : A9Z00351

Color : CAT YELLOW

039896

Engine :

Location :

Lic # :

Lic. State : AB

CHEMCO-OFF ROAD

Schedule : 11/16/22 11:00 A.M.

Office 780-436-9570

Promised Date : 11/16/22 5:00 P.M.

Inspection Date : 6/17/15

Status :

Last Service : 7/28/22

Unit # : SS-0351

Current Odometer : 0

Trans :

Previous Mileage : 3,420

Brakes :

Elapsed Mileage : 0

Manufacture Date : 6/17/15

Labor Description	Charged Hours
<input checked="" type="checkbox"/> (1) REPLACE CUTTING EDGE	2.00
Technician: <none>	

OUT ODOMETER :

Total Hours Charged : 2.00

Hours out: 0.00

Tech Notes

chemco

Parts Requisition

MTE-0130

UNIT #: 55-0351

UNIT TYPE/DESCRIPTION:


Wor# 39896

ODOMETER:

ENGINE HOURS:

DATE:

Nov 16/22

ITEM	QTY	PART#	DESCRIPTION	IN STOCK	ORDER
	1		BUCKET CUTTING EDGE		
			101 1/2" OAL		
			PICTURES SENT		
					
			3 BLADES TOGETHER		
			NOV 17-22		
			839 AM		

DM

Technician (Print Name)

Technicians Signature

REQUISITION FOR MATERIAL ORDER

Special Instructions:

Dave Repko

Ship To: (if other than standard jobsite location)

Requisition Num: **600-E-01861**

Sheet 1 of 1

Activity Num: 600-001-001-001

Activity Name: Office

Project Name: Nisku Office

Project Location: Nisku

Date Required: 30-Nov-22



ITEM	QTY	UNIT	DESCRIPTION OF MATERIAL	SUPPLIER
1	1	EA	UNIT SS-03515 CAT 289D	
Extra Info			replace cutting edge on snow bucket LC20240	Shipped Qty

PRE-DELIVERY INSPECTION

OK N/A

<input type="checkbox"/>	<input type="checkbox"/>	Quantity Matches Requisition
<input type="checkbox"/>	<input type="checkbox"/>	Model/Part# Match Requisition
<input type="checkbox"/>	<input type="checkbox"/>	Overall Condition/Cleanliness
<input type="checkbox"/>	<input type="checkbox"/>	Function
<input type="checkbox"/>	<input type="checkbox"/>	Accessories/Leads/Loose Parts
<input type="checkbox"/>	<input type="checkbox"/>	Calibration Valid/Cert Included
<input type="checkbox"/>	<input type="checkbox"/>	Fuel
<input type="checkbox"/>	<input type="checkbox"/>	Openings Water Proof

Comment: _____

Inspector Date

RECEIVED
By *tchuhan* at 9:10 am, Nov 16, 2022

Requisitioned By _____

Approved By _____ Date _____

Owner's Approval _____ Date _____

REQUISITION FOR MATERIAL ORDER

Special Instructions:

Dave Repko

Requisition Num: **600-E-01861**

Sheet 1 of 1

Activity Num: 600-001-001-001

Activity Name: Office

Ship To: (if other than standard jobsite location)

Project Name: Nisku Office

Project Location: Nisku

Date Required: 30-Nov-22



ITEM	QTY	UNIT	DESCRIPTION OF MATERIAL	SUPPLIER
1	1	EA	UNIT SS-03515 CAT 289D	
Extra Info	replace cutting edge on snow bucket LC20240		Shipped Qty	

PRE-DELIVERY INSPECTION

OK N/A

- Quantity Matches Requisition
- Model/Part# Match Requisition
- Overall Condition/Cleanliness
- Function
- Accessories/Leads/Loose Parts
- Calibration Valid/Cert Included
- Fuel
- Openings Water Proof

Comment:

Inspector Date

RECEIVED
By tchuhan at 9:10 am, Nov 16, 2022

Requisitioned By _____

Approved By _____ Date _____

Owner's Approval _____ Date _____



Chemco Matting

STATUS

Done

PRIORITY

None

DESCRIPTION

4877hrs

- perform engine service - oil and filter
- replace main fuel filter
- replace outer air filter
- grease unit - could not get one nipple to take grease for rear axle - clean hole, tried hydraulicing with oil - could not get to take - track frame would have to come off and clean grease hole from both ends
- ac inop - repair wiring to compressor
- Rh side missing rear axle cap and hardware - install new
- LH rear axle cap loose - remove hardware and clean and loc tite back in
- checked planetary oils - very dark - change planet oils

Oct 21

- replace LH rear roller
- unit developed and low battery and communication issues
- test and found bad alternator- needs to be replaced

ASSIGNEES

Cory Hunt

LOCATION

General

ASSET

SS-0351

Time & Cost Tracking

PARTS USED

5/40 Synthetic Chevron Engine oil	11 units x \$7.34
Total Parts Cost	\$80.74

TIME ENTRIES

Cory Hunt	13h 30m 0s x \$43.00
Total Time Duration	13h 30m 0s
Total Time Cost	\$580.50

ADDITIONAL COSTS

Oil (Other)	\$138.50
-------------------	----------

Filters roller and end cap (Other) \$599.67
 Total Additional Costs \$738.17

Total Work Order Costs \$1,399.41


WORK ORDER INFO

Created by: Cory Hunt on 09/29/2021, 11:41 AM
 Last updated on 11/15/2021, 5:09 PM
 Completed on 11/15/2021, 5:09 PM


COMMENTS

[Order_Confirmation_CA-0024205_0045628092_SS-0351_20215-A9Z00351.pdf](#)

Commented by Cory Hunt on 09/29/2021, 11:45 AM



Commented by Cory Hunt on 10/04/2021, 6:05 AM



Commented by Cory Hunt on 10/28/2021, 10:52 AM

WRENCHHEAD MECHANICAL
 3135 4 ST
 NISKU, ALBERTA. T9E-8L1
 Phone: 780-436-9570 Fax: 780- -

RM

INVOICE
34289
 Org. Est. # 051036

INVOICE

Date: 01/06/2021

CHEMCO-OFF ROAD
 3135-4 ST
 NISKU, ALBERTA T9E-8L1
 Office 780-436-9570

2014 Cat - 289D SKIDSTEER UNIT#20215 -
 Lic # :
 Unit # : SS-0351
 VIN # : A9Z00351
 Engine Hrs In : 4653.0
 Odometer In : 0
 Engine Hours Out : 4653.0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
REVERSE ALARM-STK 73040	1.00	23.95	23.95	(1) REPAIRS AS REQUIRED (PLATINUM YARD) ** REPAIR CAB MOUNTS, REPLACE BACK UP ALARM, REPLACE TWO HOSES TO GRAPPLE **	195.00
MOUNT-ORDER 3054339	2.00	68.36	136.72		
SPACER-ORDER 0908865	2.00	10.44	20.88		
WASHER-ORDER 1657095	4.00	8.48	33.92		
BOLT-ORDER 7X2556	2.00	9.44	18.88		
LOCKNUT-ORDER 8T4778	2.00	5.65	11.30		
#6 JIC FEM SVL X 3/-STK 26711-06-06ZF	4.00	2.30	9.20		
3/8 2 WIRE SOCKET-STK 03310-06NZF	4.00	1.82	7.28		
3/8 2 WIRE HOSE-STK EC210-6	10.00	2.55	25.50		
Shop Supplies			9.75		

Org. Estimate 616.25 Revisions 0.00 Current Estimate 616.25

Labor:	195.00
Parts:	297.38
SubTotal:	492.38
Tax:	24.62
Total:	517.00
Bal Due:	\$517.00

STK-76

[Payments -]
 Vehicle Received: 1/6/2021

GST#865376503RT0001
 Signature _____ Date _____
 Customer Number : 3904

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780- -

REPAIR ORDER #

034289

Org. Est. # 051036

REPAIR ORDER - RO

Scheduled : 01/05/2021 08:15 AM

Print Date : 1/6/2021

CHEMCO-OFF ROAD

3135-4 ST
NISKU, ALBERTA T9E-8L1
Office 780-436-9570
Cust ID : 3904
Last Service : 12/3/2020

2014 Cat - 289D SKIDSTEER UNIT#20215 -
Lic # : - AB
Unit # : SS-0351
VIN # : A9Z00351
MFG Date : 6/17/2015
Current Odom : 0

Previous Odom : 3420

Elapsed : 0

Labor Requested / Part SubTotal

Extended

(1) REPAIRS AS REQUIRED (PLATINUM YARD)

325.00

Shop Supplies

Parts Subtotal 245.65

16.25

Parts: 245.65
Labor: 325.00

Supplies: 16.25

Tax: 29.35

Total: 616.25
Balance: 616.25

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within ___ days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts ____. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO MY VEHICLE OR ARTICLES LEFT IN VEHICLES IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE. ALL VEHICLES LEFT MUST HAVE OWN INSURANCE. ANY VEHICLES LEFT OVER 30 DAYS WITHOUT CONSENT WILL BE PROPERTY OF WRENCHHEAD MECHANICAL.

Authorized By _____ Date _____ Time _____

WRENCHHEAD MECHANICAL
 3135 4 ST
 NISKU, ALBERTA. T9E-8L1
 Phone: 780-436-9570 Fax: 780- -

RH

INVOICE
34324

INVOICE

Date: 01/11/2021

CHEMCO-OFF ROAD
 3135-4 ST
 NISKU, ALBERTA T9E-8L1
 Office 780-436-9570

2014 Cat - 289D SKIDSTEER UNIT#20215 -
 Lic # : Odometer In : 0
 Unit # : SS-0351
 VIN # : A9Z00351
 Engine Hrs In : 4664.0 Engine Hours Out : 4664.0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
HYD OIL ONLY CAUTION LABEL-STK LCHL551	3.00	4.41	13.23	(1) REPAIR FOR DIESEL IN HYD OIL ** CHANGE OUT CONTAMINATED HYDRAULIC OIL **	260.00
HYD OIL-STK AW-32	59.00	2.30	135.70		
Shop Supplies			13.00		

Org. Estimate 443.03 Revisions 0.00 Current Estimate 443.03

Labor:	260.00
Parts:	161.93
SubTotal:	421.93
Tax:	21.10
Total:	443.03
Bal Due:	\$443.03

STK-162

[Payments -]
 Vehicle Received: 1/11/2021

GST#865376503RT0001
 Signature _____ Date _____

Customer Number : 3904

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780- -

REPAIR ORDER #

034324

REPAIR ORDER - RO

Scheduled : 01/08/2021 02:34 PM

Print Date : 1/11/2021

CHEMCO-OFF ROAD
3135-4 ST
NISKU, ALBERTA T9E-8L1
Office 780-436-9570
Cust ID : 3904
Last Service : 1/6/2021

2014 Cat - 289D SKIDSTEER UNIT#20215 -
Lic # : - AB
Unit # : SS-0351
VIN # : A9Z00351
MFG Date : 6/17/2015

Previous Odom : 3420

Current Odom : 0

Elapsed : 0

Engine Hours In: 4664.0 Hours Out : 4664.0

<i>Labor Requested / Part SubTotal</i>	<i>Extended</i>
(1) REPAIR FOR DIESEL IN HYD OIL	260.00
Shop Supplies	13.00
Parts Subtotal	148.93

Parts: 148.93
Labor: 260.00

Supplies: 13.00

Tax: 21.10

Total: 443.03
Balance: 443.03

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within ___days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts___. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO MY VEHICLE OR ARTICLES LEFT IN VEHICLES IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE. ALL VEHICLES LEFT MUST HAVE OWN INSURANCE. ANY VEHICLES LEFT OVER 30 DAYS WITHOUT CONSENT WILL BE PROPERTY OF WRENCHHEAD MECHANICAL.

Authorized By _____ Date _____ Time _____

Unit #: SS-0351 SN:

Odometer:

Hours: 4664

Lab# Repair Description

Date

Location

Tech Name

Hours

REMOVE HYD OIL CONTAMINATED WITH
DIESEL FUEL / REFILL / RUN THROUGH /
FLUSH REARMS / REFILL INSTANT HYD CAP
LOCK AND HYD ONLY DEAL

JAN 21

SHOP

Darryl W

4

Parts

Mechanic ID:

Mechanic Signature:

Qty

Part #

Description

STK/ORD

Qty

Part #

Description

STK/ORD

1 59L A1332

HYD OIL

✓

✓

HYD OIL ONLY DEAL

1/4" x 1" RT

1/4" x STAKE NUT

✓

✓

WRENCHHEAD MECHANICAL
 3135 4 ST
 NISKU, ALBERTA. T9E-8L1
 Phone: 780-436-9570 Fax: 780- -

INVOICE

33981

Org. Est. # 050729

INVOICE

Date: 12/03/2020

CHEMCO-OFF ROAD
 3135-4 ST
 NISKU, ALBERTA T9E-8L1
 Office 780-436-9570

2014 Cat - 289D SKIDSTEER UNIT#20215 -
 Lic # : Odometer In : 0
 Unit # : SS-0351
 VIN # : A9Z00351
 Engine Hrs In : 4611.0 Engine Hours Out : 4611.0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
5/8X8X86 EDGE-STK 4T8074	1.00	184.64	184.64	(1) REPLACE TRACKS AND DIAGNOSE TURBO INSTALL NEW TRACKS ,BUSHINGS REPLACE TURBO, SERVICE ENGINE AND REPLACE BUCKET EDGE	3,250.00
TRACK-ORDER SD450/86/56BBE	2.00	1,568.00	3,136.00		
LUBE FILTER-ORDER 377-6969	1.00	18.12	18.12		
FUEL FILTER ELEMENT-ORDER 363-5819	1.00	25.08	25.08		
FUEL FILTER-ORDER 416-5884	1.00	15.11	15.11		
AIR FILTER-STK 265-6618	1.00	22.08	22.08		
AIR FILTER-ORDER 265-6619	1.00	24.82	24.82		
PLOW BOLT-ORDER .625X2.5	11.00	1.10	12.10		
PLOW BOLT NUT 5/8-ORDER .625	11.00	0.32	3.52		
BELT-ORDER 5L3979	1.00	31.12	31.12		
BELT-ORDER 1988354	1.00	29.91	29.91		
BLADE-ORDER 1466433	1.00	47.05	47.05		
SLEEVE BEARING-ORDER 356-2459	8.00	104.83	838.64		
IDLER-ORDER 536-3550	2.00	1,043.79	2,087.58		
BOLT-ORDER 8T-6430	4.00	7.62	30.48		
BEARING SLEEVE-ORDER 2549097	2.00	72.74	145.48		
PIN-ORDER 1429091	2.00	140.46	280.92		
SEAL-ORDER 3887461	1.00	2.23	2.23		
GASKET-ORDER 3887458	1.00	1.26	1.26		
GASKET-ORDER 3879870	1.00	2.06	2.06		
GASKET-ORDER	1.00	5.50	5.50		

WRENCHHEAD MECHANICAL
 3135 4 ST
 NISKU, ALBERTA. T9E-8L1
 Phone: 780-436-9570 Fax: 780- -

INVOICE

33981

Org. Est. # 050729

INVOICE

Date: 12/03/2020

CHEMCO-OFF ROAD
 3135-4 ST
 NISKU, ALBERTA T9E-8L1
 Office 780-436-9570

2014 Cat - 289D SKIDSTEER UNIT#20215 -
 Lic # :
 Unit # : SS-0351
 VIN # : A9Z00351
 Engine Hrs In : 4611.0
 Odometer In : 0
 Engine Hours Out : 4611.0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
3887456					
TURBO-ORDER	1.00	3,845.15	3,845.15		
3979979					
GASKET-ORDER	1.00	5.50	5.50		
3895353					
BOLT-ORDER	4.00	2.74	10.96		
3937587					
HANDLE-ORDER	2.00	96.59	193.18		
364-1821					
WASHER-ORDER	4.00	7.21	28.84		
87-5439					
GASKET-ORDER	4.00	6.61	26.44		
258-4075					
BUSHING-ORDER	2.00	18.73	37.46		
258-4085					
LATCH-ORDER	2.00	47.33	94.66		
258-3289					
STUD-ORDER	4.00	2.77	11.08		
397-9982					
GASKET-ORDER	1.00	11.22	11.22		
397-9984					
NUT-ORDER	4.00	2.77	11.08		
383-0199					
SPACER-ORDER	4.00	31.41	125.64		
3609052					
AIR FILTER SECONDARY-STK	1.00	19.11	19.11		
AF25558					
AIR FILTER PRIMARY-STK	1.00	45.40	45.40		
AF25557					
WINDSHIELD WASHER	4.00	0.79	3.16		
FLUID/1L-STK					
WW					
CHEMCO DOOR DECAL-STK	2.00	7.50	15.00		
CD					
75W90 SYNTHETIC GEAR OIL-STK	3.00	8.14	24.42		
75W90SYN					
SYNTHETIC 5W40 OIL-STK	13.00	5.50	71.50		
5W40SYN					
Shop Supplies			100.00		

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780- -

INVOICE

33981

Org. Est. # 050729

INVOICE

Date: 12/03/2020

CHEMCO-OFF ROAD

3135-4 ST
NISKU, ALBERTA T9E-8L1
Office 780-436-9570

2014 Cat - 289D SKIDSTEER UNIT#20215 -

Lic # :
Unit # : SS-0351
VIN # : A9Z00351
Engine Hrs In : 4611.0

Odometer In : 0

Engine Hours Out : 4611.0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
---------------------------	-----	------	-----	-------------------	-----

5
49

Org. Estimate 71.66 Revisions 0.00 Current Estimate 71.66

Labor:	3,250.00
Parts:	11,623.50
SubTotal:	14,873.50
Tax:	743.52
Total:	15,617.02
Bal Due:	\$15,617.02

SK-485

[Payments -]
Vehicle Received: 11/3/2020

Customer Number : 3904

GST#865376503RT0001

Signature _____ Date _____

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780- -

REPAIR ORDER #

033981

Org. Est. # 050729

REPAIR ORDER - RO

Scheduled : 11/03/2020 10:27 AM

Print Date : 12/3/2020

CHEMCO-OFF ROAD

3135-4 ST
NISKU, ALBERTA T9E-8L1
Office 780-436-9570
Cust ID : 3904
Last Service : 10/7/2020

2014 Cat - 289D SKIDSTEER UNIT#20215 -

Lic # : - AB
Unit # : SS-0351
VIN # : A9Z00351
MFG Date : 6/17/2015
Current Odom : 0

Previous Odom : 3420

Elapsed : 0

<i>Labor Requested / Part SubTotal</i>	<i>Extended</i>
(1) REPLACE TRACKS	65.00
Shop Supplies	3.25
Parts Subtotal	11,344.91

Parts: 11,344.91

Supplies: 3.25

Labor: 65.00

Tax: 570.66

Total: 11,983.82

Balance: 11,983.82

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within ___ days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts ____. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO MY VEHICLE OR ARTICLES LEFT IN VEHICLES IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE. ALL VEHICLES LEFT MUST HAVE OWN INSURANCE. ANY VEHICLES LEFT OVER 30 DAYS WITHOUT CONSENT WILL BE PROPERTY OF WRENCHHEAD MECHANICAL.

Authorized By _____ Date _____ Time _____

2014 Cat - 289D SKIDSTEER UNIT#20215 TRA

Hat # :

Repair Order #

VIN # : A9Z00351

Color : CAT YELLOW

033981

Engine :

Location :

Lic # :

Lic. State : AB

CHEMCO-OFF ROAD

Schedule : 11/03/20 10:45 A.M.

Office 780-436-9570

Promised Date : 11/03/20 5:00 P.M.

Inspection Date : 6/17/15

Status :

Last Service : 10/07/20

Unit # : SS-0351

Current Odometer : 0

Trans :

Previous Mileage : 3,420

Brakes :

Elapsed Mileage : 0

Manufacture Date : 6/17/15

Labor Description

Charged Hours

<input checked="" type="checkbox"/> (1) REPLACE TRACKS	1.00
Technician : <none>	

OUT ODOMETER : 4611

Total Hours Charged : 1.00

Hours out: 0.00

Tech Notes

Unit #: SS-0351

S/N:

Odometer:

Hours:

4611

Lab#	Repair Description	Date	Location	Tech Name	Hours
	Inspect unit make parts and labour quote, put on stands Remove tracks take old track outside.	Nov 5/16	14	Brady	4
	Remove track frames buff up Axles Remove Axle Bushings Remove cat and Chemco decals Install new cab/air filters	Nov 9	shop	Blennon	8
	Re install Left track Frame, remove right track frame. Grease Left track frame	Nov 10	shop	Shad McR2	2
	put on cat decals. found they were old and showed signs of water damage. edges are expected to peel up. installed unit numbers and chemco decals.	Nov 16, 2020	shop	Taylor	2
	Started replacing turbo. many sized bolts and nuts and studs installed new studs . found all parts lying around. cleaned all surfaces. installed new studs. and gaskets. found intake was oily before turbo. think it could be from "breather" on top of engine. no one into ask today.	Nov 16, 2020	shop	Taylor	6
	give Taylor a hand with Turbo	Nov 16	shop	Preston	1

Parts

Mechanic ID:

Mechanic Signature:

23.0

Qty.	Part #	Description	STK/ORD	Qty.	Part #	Description	STK/ORD
1	AF25558	inner air filter	stk	2	356-2459	Bushing	ord
1	AF25557	outer air filter	stk	4	8T-6430	Bolt	ord
1	265-6619	cab filter	stk	2	254-9097	Bushing	ord
1	265-6618	cab filter	stk	2	142-9091	Pin	ord
1		Fire extinguisher	stk	1	798-8354	Belt	ord
1		Jug washer fluid	stk	1	5L-3979	Belt	ord
1	363-5819	fuel element	stk	1	389-5353	Gasket	ord
1	377-6969	oil filter	stk	1	388-7458	Gasket	ord
1	416-5884	fuel filter	stk	1	388-7461	O-ring	

Unit #: 55-0351 S/N:

Lab#	Repair Description	Odometer:	Date	Location	Tech Name	Hours
	Remove RS track frame		Nov 10	Shop	Brennan	10
	Replace Rear Idler					
	Remove track frame bushings & Install New ones		Nov 17	Shop	Brennan	3
	Replace wiper blade		Nov 18	Shop	Brennan	10
	Replace A/C and Alternator belts		Nov 19	Shop	Brennan	2
	Replace Bushings on the LS & Install track frame					
	Replace track spacer on both tracks					
	Service engine and final drives					24.0
	Install New bucket edge					
	Install New tracks and tighten					
	Replace tilt cylinder pins					
	Test unit					

Parts			Mechanic ID:		Mechanic Signature:		
Qty.	Part #	Description	STK/ORD	Qty.	Part #	Description	STK/ORD
1	393-7587	Bolt Flange	ord	4	258-4075	Gasket	
1	387-9870	Gasket	ord	4	383-0199	Nut	
1	388-7456	Gasket	ord	1	397-9984	Gasket	
1	146-6433	wiper	ord	4	397-9982	Stud	
1	397-9979	turbo	ord	2	258-3289	latch	
2	536-3550	Idler	ord	4	8.T-5439	washer	
2	364-1821	handle	ord	2			
2	258-4085	Bushing	ord	2			
				2		cut unit stickers	
						unit numbers	

Labour Requisition MTE-0131

UNIT #:	SS-0351	ODOMETER:	ENGINE HOURS:	4610	DATE:	Nov 5/20
---------	---------	-----------	---------------	------	-------	----------

ITEM	REPAIR DESCRIPTION	QUOTED HOURS	ACTUAL HOURS
✓ 1	Rechemcoize (unit numbers/decals)		
✓ 2	Replace fire Ext		
✓ 3	Replace tracks		
✓ 4	front window safety locks Replaced By Bolts		
✓ 5	Radar Ripped off		
6	Needs wash		
✓ 7	Needs Belts		
X 8	Alternator fully worn out		
✓ 9	oil coming out of positive Air, Recomend Removing intake tube to check		
✓ 10	hyd oil low		
✓ 11	Hyd hose leaking Between cab and Eng Comp.		
✓ 12	Replace or Remove CAT Decals.		
✓ 13	Replace wiper Blade top up washer fluid.		
✓ 14	Service Decal Reads N/S 3537HR HR on unit 4610HR		
✓ 15	Track frame torsion Spring Bushings worn out.		
✓ 16	Bucket cylinder Red End Pins/Bushings worn out		
✓ 17	Both rear Idlers cow Belled.		
✓ 18	Replace bucket edge		

Bredy _____ Technicians Signature
Technician (Print Name)

WO# 0282

Date APR 21-23

Requested by KOD

Welder/Mechanic Comp

chemco Access Matting

Unit # SS0351 Location INLET STOP Machine Hrs 4480

Reported Problem

- FRONT DOOR HINGE BOLT MISSING
- RUNNING BUTLESS - LOTS OF SMOKE - NO LOW
- CONTINUED:
- MOUNT 2WAY
- REPLACE RU FRONT LIGHT BULB.

Work Performed

- FOUND WASHERS + RUBBERS FOR LOCK HINGE - MAKE A SPACE + INSTALL W/ NEW BOLT.
- RAN UNIT WITH NO WASHER + STILL SPITS + SPITTERS FOR A SEC + CLEAN'S UP - TVRADO FEELS + LOOK GOOD - FILTERS LOOK GOOD - ~~REPLACE~~ REPLACE FUEL + GARBAGE FUEL FILTERS - IN LINE FILTER W/TS INSTALLED BACKWARDS
- ↳ STILL RUNS BAD - BETTER BUT NOT GOOD ENOUGH
- FOUND PIN MISSING @ POSITIVE AIR - INSTALL BOLT + LOCK NUT - GOOD
- ↳ POSITIVE AIR WOULD RATTLE + GET SUCKED INTO AIR FLOW CAUSING TEMPORARILY KICK + THEN RATTLE OUT OF FLOW AND RUN AGAIN.

Parts Used

- 1x 416-5884 - FUEL FILTER.
- 1x 363-5819 - FUEL FILTER
- 1x IN LINE FILTER.

Total Hours Worked: _____

Travel Hours: _____

WO# 0110

Date NOV 21/19

Requested by _____

Welder/Mechanic Coung

chemco Access Matting

Unit # SS-0351 Location DETROIT YARD Machine Hrs 4101

Reported Problem

LIGHTS FUSE KEEPS BLOWING.
SERVICE DUE

Work Performed

SERVICE
REPLACE ALL LIGHT BULBS.

Parts Used

1x 3776969 - OIL FILTER
1x 3635819 - FUEL " "
1x 3635823 - FUEL " "
1x 2656618 - CAB AIR
1x 2656619 - CAB AIR
4x H3 BULBS.

Total Hours Worked: 2

Travel Hours: 1

A9200351

chemco	Parts Requisition	MTE-0130
---------------	-------------------	----------

UNIT #:	SS-0351	UNIT TYPE/DESCRIPTION:	289D CAT		
	ODOMETER:		ENGINE HOURS:		DATE: Nov 5/20

ITEM	QTY	PART#	DESCRIPTION	IN STOCK	ORDER
	2	364-1821	handle.		
	2	8T-5439	washer		
	4	258-4075	gasket.		
	2	258-4085	Bushing.		
	2	258-3289	latch.		
	1	437-2564	Belt. 5L 3979		
	1	198-8354	Belt.		
	1	146-6433	wiper blade.		
	8	356-2459	Bushing.		
	2	536-3550	Idler.		
	4	8T-6430	Bolt.		
✓	4	8T-5439	washer.		
	2	254-9097	Bushing.		
	2	142-9091	Pin.		
	1		Alternator pully.		
	1		20 lbs fire Ext.		
	1	388-7461	O-Ring		

NOV 9-20
8:48 AM

Brelj

Technician (Print Name)

Technicians Signature

