

WRENCHHEAD MECHANICAL

3135 4 ST
 NISKU, ALBERTA. T9E-8L1
 Phone: 780-436-9570 Fax: 780-

INVOICE

31948

Org. Est. # 048674

INVOICE

Date: 02/26/2020

CHEMCO ELECTRICAL-EQUIPMENT

3135-4th ST
 NISKU, AB T9E-8L1
 Office 780-436-9570 -- Fax 780-434-0811

2016 TRAILTECH - TRI AXLE TILT UNIT#08814 -

Lic # : 5FL945
 Unit # : TR-8451
 VIN # : 46UFU2437 G1178451

Odometer In : 0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
TRAILER SPRING BUSHING-STK NB2	6.00	0.95	5.70	(1) PERFORM CVIP ON TANDEM AXLE TRAILER * SEE TECH SHEET	975.00
EQUALIZER SPRING BOLT/NUT-STK DX07-017	12.00	3.75	45.00	(2) CHANGE UNIT # TO TR-8451 * SEE TECH SHEET	65.00
TRAILER SEAL 2.25"-STK DX10-036	6.00	3.95	23.70		
BREAKAWAY SWITCH-STK 2010-B	1.00	10.06	10.06		
BEARING CONE-STK 25580	1.00	26.77	26.77		
BEARING CUP-STK 25520	1.00	14.26	14.26		
BEARING CUP-STK 14276	1.00	9.54	9.54		
BEARING CONE-STK 14125A	1.00	25.06	25.06		
ROAD RIDER ST235/80R16-ORDER 425823-99	4.00	110.36	441.44		
TIRE TAX-ORDER TTT	4.00	4.00	16.00		
Shop Supplies			52.00		

Org. Estimate 250.82 Revisions 0.00 Current Estimate 250.82

Labor:	1,040.00
Parts:	669.53
SubTotal:	1,709.53
Tax:	85.48
Total:	1,795.01
Bal Due:	\$1,795.01

STK-212

[Payments -]
 Vehicle Received: -4713-01-01

Customer Number : 2548

GST#865376503RT0001

Signature _____ Date _____

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780- -

REPAIR ORDER #

031948

Org. Est. # 048674

REPAIR ORDER - RO

Scheduled : 02/11/2020 09:09 AM

Print Date : 2/11/2020

CHEMCO ELECTRICAL-EQUIPMENT

3135-4th ST
NISKU, AB T9E-8L1
Office 780-436-9570 --- Fax 780-434-0811
Cust ID :
Last Service : 2018-02-21

2016 TRAILTECH - TRI AXLE TILT UNIT#08814 -

Lic # : 5FL945 - AB
Unit # : TR-8451
VIN # : 46UFU2437 **G1178451**
MFG Date : 11/8/2017
Current Odom : 0

Elapsed : 0

<i>Labor Requested / Part SubTotal</i>	Extended
(1) PERFORM CVIP ON TANDEM AXLE TRAILER	162.50
(2) CHANGE UNIT # TO TR-8451	65.00
(3) REMOVE PLATINUM DECALS, INSTALL CHEMCO Shop Supplies	Parts Subtotal 0.00 11.38
(4) Remove Tool Box.	

Parts: 0.00
Labor: 227.50

Supplies: 11.38

Tax: 11.94

Total: 250.82
Balance: 250.82

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within ___ days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts ____. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO MY VEHICLE OR ARTICLES LEFT IN VEHICLES IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE. ALL VEHICLES LEFT MUST HAVE OWN INSURANCE. ANY VEHICLES LEFT OVER 30 DAYS WITHOUT CONSENT WILL BE PROPERTY OF WRENCHHEAD MECHANICAL.

Authorized By _____ Date _____ Time _____

2016 TRAILTECH - TRI AXLE TILT UNIT#08814

Hat # :

Repair Order #

VIN # : 46UFU2437 G1178451

Color :

031948

Engine :

Location :

Lic # : 5FL945

Lic. State : AB

CHEMCO ELECTRICAL-EQUIPMENT

Schedule : 2/11/20 9:15 A.M.

Office 780-436-9570 --- Fax 780-434-0811

Promised Date : 2/11/20 5:00 P.M.

Inspection Date : 11/08/17

Status :

Last Service : 2/21/18

Unit # : TR-8451

Current Odometer : 0

Trans :

Previous Mileage : 0

Brakes :

Elapsed Mileage : 0

Manufacture Date : 11/08/17

Labor Description

Charged Hours

(1) PERFORM CVIP ON TANDEM AXLE TRAILER 2.50
Technician : <none>

(2) CHANGE UNIT # TO TR-8451 1.00
Technician : <none>

(3) Remove PLAXINAM DECALS, INSTALL CHEMCO

OUT ODOMETER : Total Hours Charged : 3.50

Hours out: 0.00 **(4) Remove Tool Box .**

Tech Notes

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY AND CONVERTER DOLLY**

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle		Gross Vehicle Weight Registered	
Trailer <input checked="" type="checkbox"/> Converter <input type="checkbox"/>			
Vehicle Information			
VIN <u>46UFU2437G1178451</u>			
Unit Number <u>TR-8451</u>	Year <u>2016</u>	Make <u>TRAILTECH</u>	Model <u>TRI AXLE TILT</u>
Registered Owner's Name		Signature	
Address		Postal Code	Phone Number

		LEFT	FRONT	RIGHT		
80 psi	6 mm	304.85 mm 5mm	Drums Linings Push Rod Travel Cam Rotation	305.03 mm 5mm	80 psi	5 mm
80 psi	9 mm	305.20 mm 5mm	Drums Linings Push Rod Travel Cam Rotation	305.71 mm 5mm	80 psi	9 mm
80 psi	9 mm	305.74 mm 5mm	Drums Linings Push Rod Travel Cam Rotation	305.29 5mm	80 psi	9 mm
/	/	/	Drums Linings Push Rod Travel Cam Rotation	/	/	/
/	/	/	Drums Linings Push Rod Travel Cam Rotation	/	/	/
/	/	/	Drums Linings Push Rod Travel Cam Rotation	/	/	/
		Park Brake Lining	Left \emptyset mm	Right \emptyset mm	Trans \emptyset mm	
		Wheel Torque Checked <input type="checkbox"/>	Inner \emptyset ft lbs	Outer <u>120</u> ft lbs		


Component	P	F	NA	Component	P	F	NA
9.1 Tread Depth	✓			9.7 Wheel/Rim	✓		
9.2 Tread Section of Tire	✓			9.8 Multi-Piece Wheel/Rim			✓
9.3 Sidewalls	✓			9.9 Spoke Wheel/Demountable Rim System			✓
9.4 Tire Pressure	✓			9.10 Disc Wheel System	✓		
9.5 Hubs	✓			9.11 Wheel Fasteners	✓		
9.6 Wheel Bearings	✓						

Section 10 – Couplers and Hitches

Component	P	F	NA	Component	P	F	NA
10.1 Upper Fifth Wheel			✓	10.4 Secondary Attachments	✓		
10.2 Trailer Hitch	✓			10.5 Fifth Wheel Coupler & Converter Dolly			✓
10.3 No Slack Hitch			✓	10.6 Oscillating Fifth Wheel			✓

Certification

The vehicle for which this Record of Inspection is issued has PASSED (Certificate # _____) FAILED the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, *Alberta Regulation 211/2006* and the applicable Inspection Manual.

Date of Inspection <i>FEB 12 / 2020</i>	Technician Number	Facility Number	Signature 
--	-------------------	-----------------	--

Customer Acknowledgment

I understand that any failed item(s) must be repaired and re-inspected within 10 days from the date of inspection. I also understand that, if the vehicle is presented to any Alberta Vehicle Inspection Facility within 10 days of the date of inspection, only the failed items identified on this Record of Inspection need to be re-inspected. Additionally, if my vehicle is not presented within 10 days from the date of inspection, I understand the whole vehicle must be re-inspected.

Date (Year/Month/Day)
Customer Signature

✓ P = Pass F = Fail R = Repaired N/A = Not Applicable

UNIT #:		HUBOMETER:				DATE:					
TR-8451						FEB 11 / 2020					
		P	F	R	N/A			P	F	R	N/A
1	Test That The Brakes Are Operational	✓	X			9	Check CHEMCO Decaling and Numbers / VIN Plate / ID Plate / License Plate	✓	X	✓	
2	Check Breakaway System: Battery Charge, and Switch / Air System	✓	X			10	Check Overall Condition of Deck and Frame	✓			
3	Check the Tires: Inflation and Condition / Check Wheel Torque	✓	X	✓		11	Check Hydraulics (if Equipped)				
4	Check All Lighting for Operation & Condition	✓				12	Check Beaver Tail / Ramps (if Equipped)				✓
5	Deck Condition	✓				13	Check Hinge Points (if Tilt Deck)				
6	Check Suspension Parts: Wear, Loose Bolts, and Binding	✓	X	✓		14	Check Safety Braces or Arms (if Equipped)				✓
7	Check the Brake Linings: Wear and Contamination / Wheel Seals	✓	X	✓		15	Check brake chambers / S-Cam travel, slacks				✓
8	Check The Pintle Hitch: Wear, Loose Bolts, Latching, Pin, Plate	✓				16	Overall Cleanliness	✓			

TIRE PRESSURE (If not recorded on prescribed Alberta Inspection Record) <input checked="" type="checkbox"/> psi [] kPa							
LF:	80	RF:	80	LR:	80	RR:	80

MAINTENANCE REQUIRED/REMARKS:

INSPECTION REPORT SIGN-OFF		
 Technician (Print Name)	 Technicians Signature	Supervisors Signature