



WELDING & SUPPLY LTD.

71 Liberty Road, Sherwood Park AB T8H 2V2
Phone: 780-467-1486

T14-5
SEP

Invoice

Date	Invoice No.
06/26/2026	36592

Invoice To:


NORTH OF 55 OILFIELD HAULING LTD.
BOX 618
SLAVE LAKE, AB T0G 2A0

Ship To:

NORTH OF 55 OILFIELD HAULING LTD.
500 BIRCH ROAD NE
SLAVE LAKE, AB T0G2A0

PO NO.	TERMS	SHIP VIA	SALES	UNIT
	Net 30	LA CRETE	Tori	TH01
DESCRIPTION		QUANTITY	RATE	AMOUNT
22212 Bearing - Centre Roll		2	235.70	471.40
GST			5.00%	23.57

TH01



Subtotal CAD 471.40

Total CAD 494.97

TERMS & CONDITIONS

30 DAYS. INTEREST CHARGED @ 1.5% PER MONTH ON ALL OVERDUE ACCOUNTS.

PURCHASER AGREES TO PAY ALL COSTS, CHARGES AND EXPENSES INCURRED BY LENNOX WELDING & SUPPLY LTD. (INCLUDING, BUT WITHOUT RESTRICTING THE GENERALITY OF THE FOREGOING, LEGAL FEES BETWEEN A SOLICITOR AND CLIENT ON A FULL INDEMNITY BASIS), IN ENFORCING OR COLLECTING MONIES OWED TO LENNOX PURSUANT TO THIS AGREEMENT.

PARTS RETURN POLICY

NO RETURNS UNLESS AUTHORIZED BY AN RGA#. A 15% RESTOCKING CHARGE WILL APPLY TO ALL RETURNS. ALL CLAIMS FOR RETURNS AND SHORTAGES MUST BE ACCOMPANIED BY A COPY OF THE INVOICE WITHIN 30 DAYS.

Maintenance Record

Company Name: NBS Date: 2026 Jun 25

Company Address: _____

Repairs Made By: _____
Print Name

Scheduled Maintenance: Yes or No (Please Circle)

If no, use this form for all work performed on vehicles, equipment, etc. If yes, ensure the scheduled maintenance on your commercial vehicle is according to your maintenance schedule within your Alberta Transportation Manual and/or manufacturer's specifications.

Unit # or Vin # or Plate #: TH01

Odometer Reading: _____ kms OR Hub Reading: 43093 hours
(If Applicable) (If Applicable)

Description of work performed: 2013 Buick C22 load 28951 FT 31D 1001400"

- CUIP inspection
- ✓ - 2 tires #1R
- ✓ - wheels off brake insp
- ✓ - Outigger lights
- ✓ - ABS pump supply cord repair
- Kick Roll Bearing out on Rt End.
- BRR = NACH 22212EX W33
- Hub's 22212EX = 430"
- Bolt = 60mm CD = 110mm W = 28 Tori Lennex
- ✓ - ABS sensor L #2

Signature: _____
Signature Of Repair Person

(If more than one repair person please print name, sign, and date on bottom of maintenance record)